

ASS. REC. BY:

REF:

CS/SMO19012943/Usf3

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Ruth Chua Gek Tang of SMODate/Time: 23.7.19 8.45a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKP 8625E

Insured:

SLI 67357at Workshop m/s ZNN Auto Works

Tel:

94507920of 130 Bedok Reservoir RoadPolicy No: D19MTPR01003582

Claim No:

CMTD1903507

Sum Insured:

Excess:

Make of Veh:

D.O.A 20.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 23.7.19 9.41a.m

Person Contacted:

EinVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 15 Kaki Bukit Road 4 # 01-53
	SKP 8625E NA/INC19012858/24 DOA = 20/7/19
24/07/19 @ 11:05 am	revert pending estimate from repair to Ruth via meime.

REF: SMO

ASSIGNMENT

From:

Date:

23.7.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKP 8625E

at Workshop m/s Zoom Automotiks

of 15 Kari Bukit Road 4 # 01-53

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

62k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp"

711C

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKP 8625E

Yr Regn:

1014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Volkswagen Touran

C.C

1598

Colour:

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading:

73064

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WUAX22K1T2FW009564

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

20/7/19

D.O.I.

23/7/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rpt 0158

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12-11-15771

LIA 46228

Symp. 2nd. Rep. 10/2000

Zoe aligned out.

2/5 \$8000 car found with 51%.

(\$12,557.19

Red - 61%)

RECEIVED 19 AUG 2019

Date/Time, File Pass to?

19/8/19

1)

Type 4

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

S + RS, \$

Photos

Others

TOTAL

450

11

461

Report Format:

Lump Sum / I.B.I. (\$ 8,000/- 45)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jul 2019		23 Jul 2019 08:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JERALD ONG WEN JUIN, ID: S8473651A								
Main Claimant:	CHING AI LING IRENE, ID: S1713711E								
Vehicle Reg. No.:	SKP8625E	Date of Loss:	20/07/2019 15:00 - :59						
Claim Type:	TP / CMTD1903501	Policy/Cover Note No.:	D19MTPV01003582 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLL6735T	Policy No. (Claimant):							
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339, 470130 Bedok - Tel: 94507920								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/08/2019]								
Adj Asg. Remarks:	WS: Elin Cai 9450 7920								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SKP8625E (CMTD1903501)**
[SLL6735T]

TP
CHING AI LING IRENE
Jul 20 2019 3:00PM
[JERALD ONG WEN JUIN]
Zoom Autowerks Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 24/07/2019 11:05 AM.
To ruth.chua@sompo.com.sg
CC sur@lkkauto.com
Subject SKP8625E (CMTD1903501) [SLL6735T] TP

Dear Ruth,

Please be informed that we have inspected the vehicle SKP 8625E on 23/07/2019.

We are pending estimate from repairer.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)

Bidded Car Plate Number for sale

Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.

touran

Price Range ▼

Depreciation ▼

2014 ▼

Vehicle Type ▼

[Home](#) » [Used Cars](#) » [Highline Automotive](#) » [Volkswagen Touran Diesel 1.6A TDI Comfort](#)

Volkswagen Touran Diesel 1.6A TDI Comfort

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$61,800	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation ⓘ	\$10,590 /yr View models with similar depre	Reg Date	01-Aug-2014 (5yrs 8days COE left)
Mileage	70,000 km (14.1k /yr)	Manufactured ⓘ	2014
Road Tax ⓘ	\$1,282 /yr	Transmission	Auto
Dereg Value ⓘ	\$44,466 as of today (change)	OMV ⓘ	\$25,094
COE ⓘ	\$62,890	ARF ⓘ	\$17,132
Engine Cap	1,598 cc	Power	77.0 kW (103 bhp)
Curb Weight ⓘ	1,601 kg	No. of Owners ⓘ	1
Type of Vehicle	MPV		

Features

Torquey TDI Engine, Responsive 7 Speed Auto, Steering Controls, Auto Headlights, Cruise Control, Auto Start/Stop, ABS, ESP And 10 SRS Airbags. View specs of the Volkswagen Touran Sport (2008-2009)

Accessories

Climatic A/C With Rear Vents, Reverse Cam, AUX/USB Input, Roof Rail, Multiple Storage Space, Individually Adjustable & Fully Removable 2nd Row Seats.

Description

Fully Agent Serviced. Only 1 Owner, Very Low Mileage And Well Maintained. Best Selling Diesel MPV, High Paper Value, Full Panoramic Glass Roof, Beautiful Interior, Trade-In And High Loan Available. Don't Miss.

Category

PARF Car

Status

Available

[Compare](#)

Location Map

Price Chart



Click on the point to view

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	711E
Vehicle Details	
Vehicle No.:	SKP8625E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jul 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.6 TDI AT 1T332Z
Primary Colour:	Brown
Manufacturing Year:	2014
Engine No.:	CAYAE7831
Chassis No.:	WVGZZZ1TZFW009564
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$25,088.00
Original Registration Date:	16 Oct 2014
First Registration Date:	16 Oct 2014
Transfer Count:	1
Actual ARF Paid:	\$17,124.00 <i>8562</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Oct 2024
PARF Rebate Amount:	\$12,843.00
Intended COE Rebate Details	
COE Expiry Date:	15 Oct 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$63,880.00
COE Rebate Amount:	\$33,386.00
Total Rebate Amount:	\$46,229.00

The information contained herein is correct as at 23 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/07/2019 12:43
Date Of Accident	20/07/2019 15:10
Exact Location Of Accident	TAMPINES AVE 12 TWDS PASIR RIS AFTER TPE (SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP8625E
Insured/Policyholder	
Name Of Registered Owner	CHANG AI LING IRENE
NRIC No	S1713711E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93825878
Alternative Phone No	OFFICE-93825878

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	TOURAN 1.6 TDI AT 1T332Z
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109742248
Cover Note Number	

Driver

Name of Driver	LEE CHEE KONG GEORGE
NRIC No	S1525733D
Date Of Birth	12/09/1962
Occupation	INDOOR
Date Of Driving Pass	19/09/1980
Driving Experience	38 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93825878
Fax Number	
Contact Number	OFFICE-93825878
Email Address	NOEMAIL

Address	BLK 145 PASIR RIS STREET 11 #02-81
Postcode	510145
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE JUN WEI JUSTIN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL6735T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date & time, I, vehicle 'A', CKP8625E, was travelling straight along the stated venue. As it was green light in my favour, I proceeded straight. Vehicle 'B', CLL6735T, turned out from the opposite direction on my right despite me having honk at her and her vehicle then collided onto my vehicles front right portion.

My passenger: Name: Lee Jun Wei Justin
NRIC: S9723704B

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/ID No.



TRUST TOWING LEON H/P: 8776 8868

Biz. Reg. No.: 53380183D

**CASH SALE
JOB ORDER**

No.: 10285

Call's Zoom Auto park

Date: 22/07/19

Vehicle No. <u>SKP 8625 E</u>	Model <u>VW Jetta</u>
Destination <u>Zoom Auto park to paya ubi 51 Lk back Zoom Auto park</u>	
Time In <u>1115 am</u>	Time Out <u>1140 am</u>
Remarks <u>Amount \$ <u>850</u></u>	
☐ Accident	☐ Basement / Multi Carpark
☐ After 2359	☐ Change Spare Tyre / Jumpstart
☐ Open Door	☐ Dismantle Shaft / Brake / Equipment
☐ Change Battery	☐ Loaded With Goods
	☐ Crane Up / Winch Out
	☐ Using King Dolly (Extra Trailer)
	☐ Lowered Bodykit / Suspension

SRH37351

Received By

Date: 23-Jul-19 5:17 PM - 23-Jul-19 5:20

Customer: SKP8625E

Company:

License NO:

Idometer:

VIN

Technician:

Order NO:

VEHICLE ALIGNMENT REPORT

VOLKSWAGEN, TIGUAN [5N], 10-12, (G06) Blue Motion [with FC]

Primary Angles

Primary Angles		Initial	Specifications		Final
			Min.	Max.	
Front	Caster	Left	7.3°	8.3°	—
		Right	7.3°	8.3°	—
	Camber	Left	-1.3°	-0.3°	-0.7°
		Right	-1.3°	-0.3°	-1.2°
	Toe	Left	0.00°	0.15°	0.35°
		Right	-1.00°	0.15°	-1.00°
Total		-0.65°	0.35°	-0.65°	
Rear	Camber	Left	-1.8°	-0.8°	-1.5°
		Right	-1.8°	-0.8°	-1.5°
	Toe	Left	-0.10°	0.15°	-0.10°
		Right	0.00°	0.15°	0.00°
		Total	-0.10°	0.35°	-0.10°
	Max Thrust Angle		0.1°	0.2°	0.1°

Secondary Angles

	Initial	Specifications		Final
		Min.	Max.	
SAI	—	—	—	—
Included Angle	Left	—	—	—
	Right	—	—	—
Toe Out On Turns	Left	1.2°	1.9°	—
	Right	1.2°	1.9°	—
Max Turn Inside	Left	—	—	—
	Right	—	—	—
Toe Curve Change	Left	—	—	—
	Right	—	—	—

Customer: SKP8625E Date: 02-Aug-19 12:54 PM - 02-Aug-19

Company:
 License NO:
 Odometer:

VEHICLE ALIGNMENT REPORT
 VOLKSWAGEN, TIGUAN [5N], 10-12, (G06) Blue Motion [with FC]

Primary Angles		Initial	Specifications Min. Max.	Final
Front	Caster	—	7.3° 8.3°	—
		—	7.3° 8.3°	—
	Camber	-0.7°	-1.3° -0.3°	-0.7°
		-1.2°	-1.3° -0.3°	-1.3°
Rear	Toe	0.35°	0.00° 0.15°	0.15°
		-1.00°	0.00° 0.15°	0.10°
		-0.65°	0.00° 0.35°	0.25°
	Max Thrust Angle	0.1°	0.2°	0.1°

Secondary Angles		Initial	Specifications Min. Max.	Final
SAI	Left	—	—	—
	Right	—	—	—
Included Angle	Left	—	—	—
	Right	—	—	—
Toe Out On Turns	Left	—	1.2° 1.9°	—
	Right	—	1.2° 1.9°	—
Max Turn Inside	Left	—	—	—
	Right	—	—	—
Toe Curve Change	Left	—	—	—
	Right	—	—	—



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

22 July 2019

REG NO.: SKP 8625 E
MAKE/MODEL: VOLKSWAGEN TOURAN

Not Allowed

1/5 \$8000/
23/7/19

5dy.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet	\$ 2/3uc 1,432.60
2	Front bonnet dampers	\$ 11 190.40 X
2	Front bonnet hinge	\$ 11 206.60 X
1	Front bonnet lock	\$ 11 78.70 X
1	Front bonnet rubber	\$ 12 78.50 X
1	Front headlamp -R/H	\$ 520 1,634.00
1	Front headlamp top panel -R/H	\$ 3uf 44.70
1	Front grille assy	\$ 019 377.90
1	Front grille logo	\$ 11 80.00 X
1	Front bumper	\$ 703 974.00
1	Front bumper clip (1 set)	\$ 22 60.00
1	Front bumper fog lamp	\$ 01 188.60
1	Front bumper fog lamp cover	\$ 113.70
1	Front bumper lower beam	\$ 21 240.10 X
1	Front bumper reinforcement	\$ 2 558.80 X
1	Front bumper lower centre grille	\$ 227.80
1	Front bumper chrome moulding	\$ 11 175.00 X
2	Front bumper side retainers	\$ 0150 124.00
1	Front bumper tow hook cover	\$ 43.00
1	Front fender -R/H	\$ 703 498.00
1	Front fender bracket	\$ 32 32.00
1	Front fender inner shield	\$ 70.1 139.30
1	Front fender inner shield clip (1 set)	\$ 22 50.00
1	Front fender sponge	\$ 70.1 107.40
1	Front fender glass w/moulding	\$ 990.10
1	Wiper washer fork	\$ 331.90
1	Front alloy wheel -R/H	\$ 953.90
1	Front wheel hub with bearing	\$ 815.40
1	Front shock absorber	\$ 352.50 X
1	Front knuckle arm	\$ 582.20
1	Front lower arm	\$ 11 329.00 X
1	Front drive shaft	\$ 11 2,075.80 X
1	Front tie rod	\$ 11 127.70 X
1	Front door -R/H	\$ 2 1,978.40 X
1	Front door rubber	\$ 11 187.30 X
1	Front door hinge -upper	\$ 11 95.20 X
1	Front door hinge -lower	\$ 11 163.30 X
1	Front door lock	\$ 11 636.30 X
1	Front door protector	\$ 11 145.00 X
		\$ 17,419.10
		Less 10% \$ 1,741.91
		\$ 15,677.19

27882

SPECIAL NETT ITEMS

- 1 Front number plate with holder
1 Front tyre

\$	17	50.00	X
\$	su	450.00	X
\$		500.00	

S/N LABOUR CHARGES

- 1 To check wiring and reset headlamps focusing.
2 To remove and refit front undercarriage.
3 To conduct wheel alignment.
4 To remove, refit doors fittings and replace damaged parts, transfer all fittings to new door.
5 To apply undercoating.
6 Panel beating.
7 To re-spray painting on the affected areas.

\$		80.00	30
\$		400.00	120
\$		150.00	80
\$	17	150.00	X
\$		200.00	60
\$		1,800.00	700
\$		1,600.00	200
\$		4,380.00	

2190

GRAND TOTAL :

\$	20,557.19
----	-----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19012943/USF3N2

Date: 20/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01003582
Claimant Vehicle No :	SKP8625E	Insured Vehicle No :	SLL6735T
Date of Loss:	20/07/2019	Nature of Claim:	TP
		Claim No:	CMTD1903501

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8625E	Engine No:	CAYAE7831
Make & Model:	VOLKSWAGEN TOURAN, 1.6 TDI (A)	Chassis No:	WVGZZZ1TZFW009564
Reg. Date:	16/10/2014 (Man. Year: 2014)	Odometer:	73064 km
Colour:	Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,177.19	7,909.94	8,267.25	51.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,190.00	2,190.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,557.19	10,099.94	10,457.25	50.87
Approved Total (Overridden) (\$\$)		8,000.00		
Nett Amount (\$\$)	20,557.19	8,000.00	12,557.19	61.08

INSPECTION

Date of Assignment:	23/07/2019	
Date Inspected:	23/07/2019	Inspected At:
		15 Kaki Bukit Road 4 #01-53
		Zoom Autowerks Pte Ltd
		130 Bedok Reservoir Road, Eunos
		Spring, #08-1339
		Singapore 470130

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2019)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.6 TDI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP8625E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented/Buckled	1,432.60 FL	*1,312.62 FL
2	2		*FRONT BONNET DAMPERS	Not Necessary	190.40 FL	*- FL
3	2		*FRONT BONNET HINGE	Not Necessary	206.60 FL	*- FL
4	1		*FRONT BONNET LOCK	Not Necessary	78.70 FL	*- FL
5	1		*FRONT BONNET RUBBER	Not Necessary	78.50 FL	*- FL
6	1		*FRONT HEADLAMP-R/H	Broken	1,634.00 FL	*1,634.00 FL
7	1		*FRONT HEADLAMP TOP PANEL-R/H	Bent	44.70 FL	*44.70 FL
8	1		*FRONT GRILLE ASSY	Cracked	377.90 FL	*377.90 FL
9	1		*FRONT GRILLE LOGO	Not Necessary	80.00 FL	*- FL
10	1		*FRONT BUMPER	Distorted	974.00 FL	*974.00 FL
11	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FL	*50.00 FL
12	1		*FRONT BUMPER FOG LAMP	Cracked	188.60 FL	*188.60 FL
13	1		*FRONT BUMPER FOG LAMP COVER	Grazed	113.70 FL	*113.70 FL
14	1		*FRONT BUMPER LOWER BEAM	Not Necessary	240.10 FL	*- FL
15	1		*FRONT BUMPER REINFORCEMENT	Repair	558.80 FL	*- FL
16	1		*FRONT BUMPER LOWER CENTRE GRILLE	Twisted/Torn	227.80 FL	*227.80 FL
17	1		*FRONT BUMPER CHROME MOULDING	Not Necessary	175.00 FL	*- FL
18	1		*FRONT BUMPER SIDE RETAINERS	O/s Cracked	124.00 FL	*62.00 FL
19	1		*FRONT BUMPER TOW HOOK COVER	Missing	43.00 FL	*43.00 FL
20	1		*FRONT FENDER-R/H	Distorted	498.00 FL	*498.00 FL
21	1		*FRONT FENDER BRACKET	Bent	32.00 FL	*32.00 FL
22	1		*FRONT FENDER INNER SHIELD	Torn	139.30 FL	*139.30 FL
23	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FL	*50.00 FL
24	1		*FRONT FENDER SPONGE	Torn	107.40 FL	*107.40 FL
25	1		*FRONT FENDER GLASS W/MOULDING O/S	Twisted	990.10 FL	*615.30 FL
26	1		*WIPER WASHER TANK	Distorted	331.90 FL	*331.90 FL
27	1		*FRONT ALLOY WHEEL-R/H	Cut/Bent	953.90 FL	*953.90 FL
28	1		*FRONT WHEEL HUB WITH BEARING	Damaged	815.40 FL	*450.50 FL
29	1		*FRONT SHOCK ABSORBER	Serviceable	352.50 FL	*- FL
30	1		*FRONT KNUCKLE ARM	Bent	582.20 FL	*582.20 FL
31	1		*FRONT LOWER ARM	Not Necessary	329.00 FL	*- FL
32	1		*FRONT DRIVE SHAFT	Not Necessary	2,075.80 FL	*- FL
33	1		*FRONT TIE ROD	Not Necessary	127.70 FL	*- FL
34	1		*FRONT DOOR-R/H	Repair	1,978.40 FL	*- FL
35	1		*FRONT DOOR HINGE-UPPER	Not Necessary	95.20 FL	*- FL
36	1		*FRONT DOOR RUBBER	Not Necessary	187.30 FL	*- FL
37	1		*FRONT DOOR HINGE-LOWER	Not Necessary	163.30 FL	*- FL
38	1		*FRONT DOOR LOCK	Not Necessary	636.30 FL	*- FL
39	1		*FRONT DOOR PROTECTOR	Not Necessary	145.00 FL	*- FL
40	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
41	1		*FRONT TYRE	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **17,919.10** **8,788.82**
 - List Item Discount on L Items 10.00/10.00% (\$\$) **1,741.91** **878.88**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	16,177.19
						7,909.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	400.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO REMOVE,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL FITTINGS TO NEW DOOR	New	150.00	0.00
5	TO APPLY UNDERCOATING	New	200.00	60.00
6	PANEL BEATING	New	1,800.00	700.00
7	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	1,200.00
Gross Labour Cost (\$\$)			4,380.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >