

Kw



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SJP 8345 A

Parts (a) Cost / List Price Items

Finalised
\$ 6612.00 7,779.60

Plus/Less 20%

\$ 1322.40 1,555.92

Total of Cost / List

\$ 5289.60 6,223.68

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

\$ 105.00 135.00

Total Parts Cost

\$ 5394.60 6,358.68

Labour

\$ 1670.00 3,070.00

Total

\$ 7064.60 9,428.68

The above total will be subjected to 7% G.S.T.

-20.1
= \$5651.68 lump sum

11 Rm @ 5650/h
6 days

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SJP 8345 A
Make & Model : HYUNDAI AVANTE
Chassis No : KMH DU41BR9U728564

Submit By : JENNY
Year Manufacture : 2009
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	25/11
2	Front number plate garnish	1	N/A		X
3	Front windscreen	1	\$923.00		—
4	Front windscreen moulding	1	\$59.00		—
5	Front windscreen sealant	1	\$50.00	S.N	40/11
6	Private hirer Sticker	1	\$20.00	S.N	—
7	Bonnet	1	\$1017.00		—
8	Bonnet lock	1	\$49.80		—
9	Bonnet hinge LH	1	\$65.20		X
10	Bonnet hinge RH	1	\$65.20		X
11	Bonnet heat insulator	1	\$191.50		X
12	Bonnet heat insulator clip	10	\$60.00		X
13	Headlamp LH	1	\$480.20		—
14	Headlamp RH	1	\$480.20		—
15	Headlamp clip	10	\$45.00		—
16	Front support panel (complete)	1	\$791.00		—
17	Brace panel	1			X
18	Condenser	1	\$911.50		27/11
19	Condenser fan motor	1			7
20	Condenser fan blade	1	\$199.00		X
21	Condenser fan cowling	1			X
22	Radiator	1	\$565.00		X
23	Radiator fan motor	1	N/A		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

Not within
61 Rmp 87
Penny After Rainy
4756.70
85.00 SN
6 days

Spare Parts

Vehicle No. : _____
 Make & Model : SJP 8345 A
 Chassis No. : HYUNDAI AVANTE
KMH DU41BR9U728564

Submit By : Carmen Lim
 Year Manufacture : 2009
 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade	1	N/A		X
25	Radiator fan cowling	1	N/A		X
26	Coolant	1	\$20.00	S.N	✓
27	Front bumper	1	\$445.00		✓
28	Front bumper clip	10	\$45.00		✓
29	Front bumper reinforcement	1	\$254.00		✓
30	Front bumper side retainer LH	1	\$34.00		✓
31	Front bumper side retainer RH	1	\$34.00		✓
32	Front bumper bracket LH	1	\$31.00		X
33	Front bumper bracket RH	1	\$31.00		X
34	Front bumper sponge	1	\$119.00		✓
35	Front bumper tow cover	1	\$16.00		X
36	Front bumper upper grille	1	\$380.00		✓
37	Front bumper upper grille chrome	1			X
38	Front bumper emblem	1	\$21.00		✓
39	Front bumper lower grille	1	\$19.00		✓
40	Front bumper lower grille garnish LH	1	\$39.00		X
41	Front bumper lower grille garnish RH	1	\$39.00		X
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Submit By : Carmen Lim
Year of Manufacture : 2009

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SJP 8345 A

HYUNDAI AVANTE

KMH DU41BR9U728564

Submit By :

Year Manufacture :

Engine No. :

Cost / List

CARMEN LIM

2009

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RHF FENDER <i>Bu</i>	1	\$434.30		✓
2		1			
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

434.30