



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SJP 8345 A**
Make & Model : **HYUNDAI AVANTE**
Chassis No : **KMHU41BR9U728564**

Submit By : **JENNY**
Year Manufacture : **2009**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>By</i>	1	\$45.00	S.N	<i>25/12</i>
2	Front number plate garnish <i>NSP</i>	1			<i>X</i>
3	Front windscreen <i>CM</i>	1			<i>—</i>
4	Front windscreen moulding <i>in</i>	1			<i>✓</i>
5	Front windscreen sealant <i>in</i>	1	\$50.00	S.N	<i>40/12</i>
6	Private hirer Sticker <i>in</i>	1	\$20.00	S.N	<i>✓</i>
7	Bonnet <i>BU</i>	1			<i>✓</i>
8	Bonnet lock <i>Di</i>	1			<i>—</i>
9	Bonnet hinge LH <i>K</i>	1			<i>X</i>
10	Bonnet hinge RH <i>K</i>	1			<i>X</i>
11	Bonnet heat insulator <i>in</i>	1			<i>X</i>
12	Bonnet heat insulator clip <i>in</i>	10			<i>X</i>
13	Headlamp LH <i>Gr</i>	1			<i>✓</i>
14	Headlamp RH <i>in/CM</i>	1			<i>✓</i>
15	Headlamp clip <i>in</i>	10			<i>✓</i>
16	Front support panel (complete) <i>BU</i>	1			<i>—</i>
17	Brace panel	1			<i>?</i>
18	Condenser	1			<i>?</i>
19	Condenser fan motor	1			<i>?</i>
20	Condenser fan blade	1			<i>?</i>
21	Condenser fan cowling	1			<i>?</i>
22	Radiator	1			<i>?</i>
23	Radiator fan motor	1			<i>?</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-251/ 259, Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

- LKK Auto Consultants hence notify
the repairer of the following:
- To resurvey before/after spray painting
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not withstanding
1/12/09
Resurvey After Repair
6 days

Spare Parts

Vehicle No. : **SJP 8345 A**
Make & Model : **HYUNDAI AVANTE**
Chassis No : **KMHJU41BR9U728564**

Submit By : **Carmen Lim**
Year Manufacture : **2009**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade	1			?
25	Radiator fan cowling	1			?
26	Coolant	1	\$20.00	S.N	✓
27	Front bumper	1			✓
28	Front bumper clip	10			✓
29	Front bumper reinforcement	1			✓
30	Front bumper side retainer LH	1			✓
31	Front bumper side retainer RH	1			✓
32	Front bumper bracket LH	1			?
33	Front bumper bracket RH	1			?
34	Front bumper sponge	1			✓
35	Front bumper tow cover	1			X
36	Front bumper upper grille	1			✓
37	Front bumper upper grille chrome	1			?
38	Front bumper emblem	1			✓
39	Front bumper lower grille	1			✓
40	Front bumper lower grille garnish LH	1			?
41	Front bumper lower grille garnish RH	1			X
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. : SJP 8345 A Submit By : Carmen Lim
Make & Model : HYUNDAI AVANTE Year of Manufacture : 2009

[illegible]

Company Reg No. 200005485N / GST No. 20-0005485-N