

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Eileen Bay

Date: 26 Jul 2019

## Preliminary Advice

Insured Vehicle No	: SGK8321E	Accident Date	: 05/07/2019
TP Vehicle No	: SHD8617C	Assignment Date	: 24/07/2019
Make	: HYUNDAI IONIQ HYBRID	Est. Duration of Repair	: 4/Days
Date of Inspection	: 25/07/2019		
Inspection At	: DING AUTOMOTIVE PTE LTD		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,640.96
Revised Amount	:S\$	2,113.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,113.52

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :We have not authorized repairs.