

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19012969/EGA3Q2

Date: 29/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : SLK6412E	Insured Vehicle No :	SHA4513K	
Date of Loss: 09/04/2018	Nature of Claim: TP	Claim No:	MCT18040191

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK6412E		
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Engine No:	HRA2345419A
Reg. Date:	23/01/2017 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1808844
Colour:	Grey	Odometer:	65023 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,668.30	1,618.30	50.00	3.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	765.00	15.00	750.00	98.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,433.30	1,633.30	800.00	32.88
+ GST 7.00/7.00% (S\$)	170.33	114.33	56.00	32.88
Nett Amount (S\$)	2,603.63	1,747.63	856.00	32.88
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	24/07/2019		
Date Inspected:	24/07/2019	Inspected At:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623
Estimated Period of Repair:	1.0 days		

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2020)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK6412E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER ARC MLDG RH	Cut	483.00 FN	*483.00 FN
2	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
3	1		*WEHEL RIM REAR RH	Cut	1,231.90 FS	*1,231.90 FS
					Sub Total (\$\$)	1,764.90
					- Nett Item Discount on N Items 20.00/20.00% (\$\$)	96.60
					Total Parts (\$\$)	1,668.30

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR RH REAR FENDER	New	400.00	0.00
2	CHARGES TO SPRAY PAINTING SAME	New	350.00	0.00
3	RENEW RH REAR WHEEL RIM AND WHEEL BALANCING	New	15.00	15.00
Gross Labour Cost (\$\$)			765.00	15.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >