AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0215/18

DATE : 11-APR-2018

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET #04-05 IOB BUILDING

S(049711) TEL: 63476100 FAX: 62244174

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : SOH LI LOONG RONALD

ADDRESS : BLK 851 YISHUN STREET 81

#09-50 \$(760851)

TELEPHONE NO : 97492371

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : \*

VEHICLE NO : SLK6412E

MODEL CODE : FRLARBZJ11UEA--A--

MODEL/YEAR : NISSAN QASHQAI 1.2 ENGINE NO : HRA2345419A

CHASSIS NO : SJNFEAJ11U1808844

MILEAGE : 37631 KM DATE IN : 11/04/2018 LIABILITY : 0.00
EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH - 96450079

ACCIDENT DATE : 09/04/2018

AUTOLUTION INDUSTRIAL PTE LTD SINGAPORE 408623

TEL: 6490 9666 FAX: 6846 7483



## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLK6412E

S/N0	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR RH REAR FENDER.	400.00	X
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	350.00	X
3	ZZ/003	RENEW RH REAR WHEEL RIM AND WHEEL BALANCING.	15.00	/
		TOTAL LABOUR CHARGES	765.00	

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLK6412E

PARTS DESCRIPTION	PARTS NUMBER	NETT			REMARKS	
SUNDRIES	NPN			50.00	X	
WHEEL RIM REAR RH / CMT	D0300-4EA1A			1231.90		
REAR FENDER ARC MLDG RH / C M	93828-4EA0A	483.00				
SUB TOTAL		483.00	0.00	1281.90		
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT0	00%)	96.60	0.00	0.00		
GRAND TOTAL		386.40	0.00	1281.90		
OVERALL TOTAL		1668.30				
	REAR FENDER ARC MLDG RH  C VT  SUB TOTAL LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT0	SUNDRIES  WHEEL RIM REAR RH  CM  D0300-4EA1A  REAR FENDER ARC MLDG RH  CM  93828-4EA0A  SUB TOTAL  LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT00%)  GRAND TOTAL	PARTS DESCRIPTION PARTS NUMBER NETT  SUNDRIES NPN  WHEEL RIM REAR RH CM D0300-4EA1A  REAR FENDER ARC MLDG RH CM 93828-4EA0A 483.00  SUB TOTAL LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT00%) 96.60  GRAND TOTAL 386.40  OVERALL TOTAL 1668.30	PARTS DESCRIPTION PARTS NUMBER NETT LIST  SUNDRIES NPN  WHEEL RIM REAR RH / C/T D0300-4EA1A  REAR FENDER ARC MLDG RH / C/T 93828-4EA0A 483.00  SUB TOTAL  LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT00%) 96.60 0.00  GRAND TOTAL 386.40 0.00  OVERALL TOTAL 1668.30	SUNDRIES NPN 50.00  WHEEL RIM REAR RH CM D0300-4EA1A 1231.90  REAR FENDER ARC MLDG RH CM 93828-4EA0A 483.00  SUB TOTAL 483.00 0.00 1281.90  LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT00%) 96.60 0.00 0.00  GRAND TOTAL 386.40 0.00 1281.90  OVERALL TOTAL 1668.30	

DAMAGED PARTS & PRICES

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

## SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLK6412E

TOTAL LABOUR CHARGES

TOTAL SPARE PARTS CHARGES 1668.30

GRAND TOTAL

2433.30 \*

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : 24/7/19, 10.99 am M

SURVEYED DATE : 24/7/19, 10.99 am M

EXCESS CLAUSE : 0.00

LIABILITY : 0.00

REMARKS

REMARKS

WIL PAPUL

1 days

Recy Bef Spy

P/P

Steve Chan @ IKK gulo-com

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: