



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM YOK TEE	Cust No/Name LCV07650/LIM YOK TEE
6 CHOA CHU KANG GROVE	Reg No/Reg Date SMG2654J / 13/12/201
#08-13	Date In/Mileage / 0
SINGAPORE 688240	Chassis No KNAF1416MK5022837
Contact No	Engine No G4FGJH712628
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV07650	CRDVCH	08/07/2019/ 17:50	Bod	442 / CocoLu	53557			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 550.00
RENEW REAR BUMPER								
E PNT98000								A20 500.00
SPRAY PAINT FOR REAR BUMPER								
E PNT88000								✓ 60.00
REMOVE & INSTALL PARKING SENSOR								
M SUNDRY								✓ 20.00
Sundry								
M COVER-RR BUMPER					1.00	688.00	00.00	de ✓ 688.00

Estimate

SURVEYOR NAME: Tan Jiah 97495749SURVEYOR SIGNATURE: [Signature]DATE: 17/8/19 11:50 PMREMARKS: 03 daysResurvey before paintsurellants.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	1,818.00
7% GST on	1818.00	127.26
Total Payable		1,945.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.