

22/03/2002

ASS. REC. BY:

REF: CS/INC19012980/T14f362h Special Instruction:

Surveyor: Tan KahASSIGNMENT (Office)From (Person): Hazalyssaof INCDate/Time: 23/7/19 9.52am

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 6051KInsured: SJT 4209R

at Workshop m/s

BP AutoTel: 62660555

of

48 Joh Gueh Rd East #01-121

Policy No:

Claim No:

MT/1054291-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.45am 23/7/19

Person Contacted:

YvetteVehicle IN / OUT

Date/Time	Action/Instruction
	<u>Tan Kah</u> ✓
	<u>SLB 6051K-X</u>
	<u>SJT 4209R- NA/AG 1300 3042/-1</u>
	<u>ROA: 14/01/2012</u>
	<u>COR Lump Sum \$5150, 5 days confirmed. (Red: 7873.07, 60%)</u>

No
photos
upload
25/7

ASS. REC. BY: Tanffk

REF: INC

ASSIGNMENT

From: _____ Date: 24/7/19

Estimated Cost: _____

GE / TP / WS / TP RES / OD RES / EVA / INV / RV

To Inspect Vehicle No: SLB 6051K
at Workshop m/s: BP Auto
of 48 Joh Cuen Rd East # 01-121

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 6051K Yr Regn: 2016, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz A180 C.C. 1595

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 48384 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPD 17604225449917

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

SS / DUN / EXNOVA / CYLES / LIZA / MIC / CHITSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 24/7/19 @ pm

Survey held at BP Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

RECEIVED 05 SEP 2019

Date/Time, File Pass to?

59 Typist

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.E.R. is

TP

5150/-

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Insp (\$ _____)

☐ Wheel end (\$ _____)

Survey Fee: 240

Transportation: _____

S + RS: _____

Photos _____

Others _____

TOTAL

240

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 4 September 2019 10:33 AM
To: bpauto_wkshop; Taufikh (LKKAUTO)
Subject: RE: SLB6051K - Request for Finalization
Attachments: estimate SLB 6051K.pdf

Dear Yvette,

Offer lump sum 5,150/- , 5 Days.

Please check and get back on confirmation

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: bpauto_wkshop <bpauto_wkshp@yahoo.com>
Sent: Tuesday, 27 August 2019 6:26 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: SLB6051K - Request for Finalization

Dear Taufikh

Kindly help to finalized below vehicle. The after photo attached.

TP NTUC	SLB6051K	Lumpsum	\$5,280.00
---------	----------	---------	------------

Repair days: 5 Days

Thanks & Regards,

Yvette Zhao

BP Auto
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555

Nivitha (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Tuesday, 23 July 2019 3:47 PM
To: Admin-D (LKKAuto); assignments
Cc: Hazalysa Binte Ibrahim
Subject: FW: TP CASES FARMED OUT TO LKK ON 23/7/2019

Dear Nivitha,

Re-sent.

Thank you.

Warmest Regards

Hazalysa Bte Ibrahim

Admin Assistant

Motor Department

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 23 July 2019 12:10 PM
To: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 23/7/2019

Dear Hazalysa,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalysa Binte Ibrahim [mailto:hazalysa.ibrahim@income.com.sg]
Sent: Tuesday, 23 July 2019 9:52 AM
To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 23/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1050055-001	23/7/2019	SLD5291E	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	JOE TAN / 6631 1874	10:00-12:00	PC2161A	20/06/19	OWNER WAITING
2	Charlotte Chew	MT/1054291-002	23/7/2019	SLB6051K	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	YVETTE ZHAO / 62660555		SJT4209R	18/07/19	
3	Cyndie Yong	MT/1052989-002	23/7/2019	GX2882Z	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	YVETTE ZHAO / 62660555		YM9229J	08/07/19	
4	Jared Liu	MT/1052420-002	23/7/2019	SJC886B	CYCLE & CARRIAGE INDUSTRIES PTE LTD	188 PANDAN LOOP SINGAPORE 128378	GO CHEE HAN / 91817717	14:00-16:00	SKW7006L	05/07/19	
5	Eng Huey Huey	MT/1053676-002	23/7/2019	SFS3816Y	KAH MOTOR COMPANY SDN. BERHAD.	6A MANDAI ESTATE SINGAPORE 729903	ANNIKA LAI / 65145248	10:00-12:00	YM8463E	12/07/19	
6	-	MT/1052856-001	23/7/2019	JQR5773	LONG SHENG MOTOR SERVICE	BLK 6-399-G WOODLANDS ROAD YEW-TEE INDUSTRIAL ESTATE	MISS WOON / 67639733	-	-	-	PLS CANCEL THE SURVEY

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers




PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Denise Tay (LKKAUTO)

From: bpauto_wkshop <bpauto_wkshp@yahoo.com>
Sent: Tuesday, 27 August 2019 6:26 PM
To: Taufikh (LKKAUTO)
Subject: SLB6051K - Request for Finalization
Attachments: Question Mark (1).jpeg; Question Mark (2).jpeg; Question Mark (3).jpeg; Question Mark (4).jpeg; Question Mark (5).jpeg; Question Mark (6).jpeg; Question Mark (7).jpeg; Question Mark (8).jpeg; Question Mark (9).jpeg; Question Mark (10).jpeg; Question Mark (11).jpeg; Question Mark (12).jpeg; Question Mark (13).jpeg; Question Mark (14).jpeg; Question Mark (15).jpeg; Question Mark (16).jpeg; Question Mark (17).jpeg; Question Mark (18).jpeg; Question Mark (19).jpeg; Question Mark (20).jpeg; SLB6051K Wheel Alignment 22072019 140400.pdf; SLB6051K Wheel Alignment 29072019 162200.pdf; AFT (1).jpeg; AFT (2).jpeg; AFT (3).jpeg; AFT (4).jpeg; AFT (5).jpeg; AFT (6).jpeg; SLB6051K Estimate.pdf

Dear Taufikh

Kindly help to finalized below vehicle. The after photo attached.

TP NTUC	SLB6051K	Lumpsum	\$5,280.00
---------	----------	---------	------------

Repair days: 5 Days

Thanks & Regards,

Yvette Zhao

BP Auto
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: bpauto_wkshp@yahoo.com

Denise Tay (LKKAUTO)

From: bpauto_wkshop <bpauto_wkshp@yahoo.com>
Sent: Wednesday, 4 September 2019 5:46 PM
To: Taufikh (LKKAUTO); Denise Tay (LKKAUTO)
Subject: Re: SLB6051K - Request for Finalization

Dear Denise,

COR \$5,150.00 and 5 repair days confirmed

Thanks & Regards,

Yvette Zhao

BP Auto
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: bpauto_wkshp@yahoo.com

On Wednesday, 4 September 2019, 10:32:56 am SGT, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear Yvette,

Offer lump sum 5,150/- , 5 Days.

Please check and get back on confirmation

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Soon Huat Autoserv Pte Ltd

48 Toh Guan Road East #01-136

Enterprise Hub

Singapore 608586

Phone Number: 8402-5982, 9770-5782

Customer: BP AUTO			Date: 7/22/2019 2:04 PM			
Company:			VIN			
License No: SLB6051K			Technician: AL HONG			
Odometer:			Order No.:			
VEHICLE ALIGNMENT REPORT						
MERCEDES -BENZ, 117 (C / X) ECE, Standard Suspension, CODE 485(Custom), 2012-2014,						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°34'	6°40'	7°40'	6°46'
		Right	6°27'	6°40'	7°40'	6°43'
	Camber	Left	-1°06'	-1°20'	-0°40'	-1°09'
		Right	-0°49'	-1°20'	-0°40'	-0°47'
	Toe	Left	7.4	0.2mm	1.2mm	5.5
		Right	-7.7	0.2mm	1.2mm	-5.9
Total		-0.3	0.4	2.5	-0.4	
Rear	Camber	Left	-1°18'	-2°20'	-1°20'	-1°27'
		Right	-4°31'	-2°20'	-1°20'	-0°45'
	Toe	Left	-0.9	-0.1mm	1.4mm	0.0
		Right	15.9	-0.1mm	1.4mm	12.6
		Total	15.0	0.6	2.1	12.6
	Thrust Angle		1°23'	-0°08'	0°08'	1°02'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		10°55'	----	----	10°55'
	Right		10°41'	----	----	10°41'
Included Angle	Left		9°49'	----	----	9°46'
	Right		9°52'	----	----	9°54'
Toe Out On Turns	Left		----	0°24'	1°24'	----
	Right		----	0°24'	1°24'	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-1mm	----	----	3mm
	Rear		-11mm	----	----	-3mm
Track Width Diff.			16mm			3mm
Wheel Base Diff.			11mm			6mm
Front Ride Height	Left		0mm	0mm	22mm	0mm
	Right		0mm	0mm	22mm	0mm
Rear Ride Height	Left		0mm	10mm	32mm	0mm
	Right		0mm	10mm	32mm	0mm
Frame Angle						----

Thank You For Your Business

Soon Huat Autoserv Pte Ltd

48 Toh Guan Road East #01-136

Enterprise Hub

Singapore 608586

Phone Number: 8402-5982, 9770-5782

Customer:	SK AUTO	Date:	7/29/2019 4:22 PM
Company:		VIN	
License No:	SLB6051K	Technician:	AL HONG
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

MERCEDES -BENZ, 117 (C / X) ECE, Standard Suspension, CODE 485(Custom), 2012-2014,

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°29'	6°40'	7°40'	7°16'
		Right	6°18'	6°40'	7°40'	6°56'
	Camber	Left	-0°57'	-1°20'	-0°40'	-1°01'
		Right	-1°02'	-1°20'	-0°40'	-1°03'
	Toe	Left	-1.1	0.2mm	1.2mm	0.6
		Right	0.3	0.2mm	1.2mm	0.6
Total		-0.8	0.4	2.5	1.2	
Rear	Camber	Left	-1°04'	-2°20'	-1°20'	-1°01'
		Right	-2°05'	-2°20'	-1°20'	-1°38'
	Toe	Left	0.1	-0.1mm	1.4mm	0.7
		Right	-2.7	-0.1mm	1.4mm	0.6
		Total	-2.6	0.6	2.1	1.3
	Thrust Angle		-0°14'	-0°08'	0°08'	0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		10°44'	----	----	10°44'
	Right		10°50'	----	----	10°50'
Included Angle	Left		9°47'	----	----	9°43'
	Right		9°48'	----	----	9°47'
Toe Out On Turns	Left		----	0°24'	1°24'	----
	Right		----	0°24'	1°24'	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		4mm	----	----	2mm
	Rear		1mm	----	----	-2mm
Track Width Diff.			4mm			4mm
Wheel Base Diff.			3mm			5mm
Front Ride Height	Left		0mm	0mm	22mm	0mm
	Right		0mm	0mm	22mm	0mm
Rear Ride Height	Left		0mm	10mm	32mm	0mm
	Right		0mm	10mm	32mm	0mm
Frame Angle						----

Thank You For Your Business

TGBP19-0716

Surveyor: Taufikh

5 days Lumpsum

BP Auto

(UEN No. 53378133K)

48 Toh Guan Road Esat #01-121

Enterprise Hub S(608586)

Tel: 6266 0555 Fax : 6266 3155

TO	: NTUC	DATE	: 22-Jul-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SLB6051K
ADDRESS	:	MODEL / MAKE	: MERC BENZ A180
TEL. NO.	:	CHASSIS NO.	: WDD1760422J449917
OWNER INSURANCE	: SOMPO	ACCIDENT DETAIL	
POLICY NO.	: D19MTPV01005025	DATE	: 18-Jul-19
		TIME	: 18:20hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR BUMPER	1	\$ 1,165.50	\$ 1,165.50	dfe ✓
2	REAR BUMPER REVERSE SENSOR	2	\$ 195.80	\$ 391.60	dr ✓
3	REAR BUMPER REVERSE SENSOR HOLDER	4	\$ 35.70	\$ 142.80	ae ✓
4	REAR BUMPER REVERSE SENSOR RUBBER SEAL	4	\$ 10.90	\$ 43.60	ae ✓
5	REAR BUMPER REVERSE SENSOR WIRE HARNESS SET	1	\$ 213.70	\$ 213.70	X
6	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 35.40	\$ 70.80	LH X RH ✓
7	REAR BUMPER TOP RETAINER	1	\$ 137.50	\$ 137.50	X
8	REAR BUMPER LOWER DIFFUSER	1	\$ 289.10	\$ 289.10	dr ✓
9	REAR BUMPER TOW HOOK COVER	1	\$ 46.20	\$ 46.20	X
10	REAR FENDER RH	1	\$ 2,497.50	\$ 2,497.50	RY ✓
11	REAR FENDER INNER SHIELD RH	1	\$ 167.30	\$ 167.30	dr ✓
12	REAR FENDER INNER AIR VENT RH	1	\$ 33.90	\$ 33.90	X
13	REAR WINDSCREEN MOULDING	1	\$ 101.40	\$ 101.40	X
14	REAR TAILLAMP RH	1	\$ 576.10	\$ 576.10	dr ✓
15	REAR TAILLAMP LOWER BRACKET RH	1	\$ 231.30	\$ 231.30	dr ✓
16	REAR TAILLAMP INNER PANEL RH	1	\$ 411.80	\$ 411.80	X
17	REAR SUSPENSION SHOCK ABSORBER RH	1	\$ 289.30	\$ 289.30	X
18	REAR SUSPENSION KNUCKLE ARM RH	1	\$ 1,165.60	\$ 1,165.60	? ✓ PHOTO
19	REAR SUSPENSION KNUCKLE ARM BEARING RH	1	\$ 386.90	\$ 386.90	? ✓ PHOTO
20	REAR SUSPENSION UPPER ARM RH	1	\$ 152.30	\$ 152.30	? X
21	REAR SUSPENSION LOWER ARM RH	1	\$ 187.40	\$ 187.40	? ✓ PHOTO
22	REAR SUSPENSION THRU SRM RH	1	\$ 135.90	\$ 135.90	X ✓ PHOTO
23	REAR SUSPENSION TRAILING ARM RH	1	\$ 155.70	\$ 155.70	X
24	REAR 17" SPORT RIM ORIGINAL RH	1	\$ 899.10	\$ 899.10	dr ✓
TOTAL PRICE				\$ 9,892.30	5,817.60
LESS -10%				\$ (989.23)	581.76
SUB TOTAL PRICE				\$ 8,903.07	5,235.84

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00
2	REAR BUMPER RIVET SET	1	\$ 40.00	\$ 40.00
3	REAR FENDER SEALANT RH	1	\$ 80.00	\$ 80.00
4	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET RH	1	\$ 60.00	\$ 60.00
5	REAR FENDER INNER SHIELD CLIPS SET RH	1	\$ 50.00	\$ 50.00
6	REAR WINDSCREEN SEALANT WITH PRIMER SET	1	\$ 120.00	\$ 120.00
7	REAR TAILLAMP CLIPS SET RH	1	\$ 30.00	\$ 30.00
8	REAR TAILLAMP INNER ANEL SEALANT RH	1	\$ 60.00	\$ 60.00

TOTAL

\$ 520.00

60.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,500.00	500.	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,000.00	450.	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 100.00	30.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30.	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	30.	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 250.00	120	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 80.00	✓	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

Parts: 5,235.84

TOTAL

\$ 3,600.00

1,300.00

SY: 60.00

5,295.84

labour: 1,300.00

6,595.84

less 20%: 1,319.17

5,276.67

Lumpsum: \$ 5,280.00 x 5days.

Soon Huat Autoserv Pte Ltd

48 Toh Guan Road East #01-136

Enterprise Hub

Singapore 608586

Phone Number: 8402-5982, 9770-5782

Customer: BP AUTO			Date: 7/22/2019 2:04 PM			
Company:			VIN			
License No: SLB6051K			Technician: AL HONG			
Odometer:			Order No.:			
VEHICLE ALIGNMENT REPORT						
MERCEDES -BENZ, 117 (C / X) ECE, Standard Suspension, CODE 485(Custom), 2012-2014,						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°34'	6°40'	7°40'	6°46'
		Right	6°27'	6°40'	7°40'	6°43'
	Camber	Left	-1°06'	-1°20'	-0°40'	-1°09'
		Right	-0°49'	-1°20'	-0°40'	-0°47'
	Toe	Left	7.4	0.2mm	1.2mm	5.5
		Right	-7.7	0.2mm	1.2mm	-5.9
Total		-0.3	0.4	2.5	-0.4	
Rear	Camber	Left	-1°18'	-2°20'	-1°20'	-1°27'
		Right	-4°31'	-2°20'	-1°20'	-0°45'
	Toe	Left	-0.9	-0.1mm	1.4mm	0.0
		Right	15.9	-0.1mm	1.4mm	12.6
		Total	15.0	0.6	2.1	12.6
	Thrust Angle		1°23'	-0°08'	0°08'	1°02'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		10°55'	----	----	10°55'
	Right		10°41'	----	----	10°41'
Included Angle	Left		9°49'	----	----	9°46'
	Right		9°52'	----	----	9°54'
Toe Out On Turns	Left		----	0°24'	1°24'	----
	Right		----	0°24'	1°24'	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-1mm	----	----	3mm
	Rear		-11mm	----	----	-3mm
Track Width Diff.			16mm			3mm
Wheel Base Diff.			11mm			6mm
Front Ride Height	Left		0mm	0mm	22mm	0mm
	Right		0mm	0mm	22mm	0mm
Rear Ride Height	Left		0mm	10mm	32mm	0mm
	Right		0mm	10mm	32mm	0mm
Frame Angle						----

Thank You For Your Business

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2019 13:14
Date Of Accident	18/07/2019 18:20
Exact Location Of Accident	PIONEER ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB6051K
Insured/Policyholder	
Name Of Registered Owner	KHOR CHIN GUAN
NRIC No	S1344604J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81982417
Alternative Phone No	OFFICE-81982417

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A180-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01005025
Cover Note Number	

Driver

Name of Driver	CLAYTON KHOR JUN HAO
NRIC No	S9317635I
Date Of Birth	17/05/1993
Occupation	INDOOR
Date Of Driving Pass	27/01/2014
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81982417
Fax Number	
Contact Number	
Email Address	CLAYTONKJH@GMAIL.COM

Address	32 PAVILION GROVE
Postcode	658624
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer to sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT4209R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the above date and location

I stopped my vehicle at the traffic light junction conforming to red light traffic

I am in my own lane

Vehicle B from my right changed lane and hit onto the right hand rear portion of my vehicle

After the accident my RHF seat belt was jammed

DECLARATION

(We declare the foregoing particulars are true in every respect.)


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GEC1437C

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO : NTUC ATTENTION : MOTOR CLAIMS DEPARTMENT ESTIMATE REPORT : OWNER PARTICULAR NAME : ADDRESS : TEL. NO. : OWNER INSUANCE : SOMPO POLICY NO. : D19MTPV01005025 PERSON INCHARGE :	DATE : 22-Jul-19 JOB TYPE : T/P CLAIMS VEHICLE DETAILS VEHICLE NO. : SLB6051K MODEL / MAKE : MERC BENZ A180 CHASSIS NO. : WDD1760422J449917 ACCIDENT DETAIL DATE : 18-Jul-19 TIME : 18:20hrs
---	---

QUOTATION SUMMARY **PAGE 01**

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 1,165.50	\$ 1,165.50
2	REAR BUMPER REVERSE SENSOR	2	\$ 195.80	\$ 391.60
3	REAR BUMPER REVERSE SENSOR HOLDER	4	\$ 35.70	\$ 142.80
4	REAR BUMPER REVERSE SENSOR RUBBER SEAL	4	\$ 10.90	\$ 43.60
5	REAR BUMPER REVERSE SENSOR WIRE HARNESS SET	1	\$ 213.70	\$ 213.70
6	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 35.40	\$ 70.80
7	REAR BUMPER TOP RETAINER	1	\$ 137.50	\$ 137.50
8	REAR BUMPER LOWER DIFFUSER	1	\$ 289.10	\$ 289.10
9	REAR BUMPER TOW HOOK COVER	1	\$ 46.20	\$ 46.20
10	REAR FENDER RH	1	\$ 2,497.50	\$ 2,497.50
11	REAR FENDER INNER SHIELD RH	1	\$ 167.30	\$ 167.30
12	REAR FENDER INNER AIR VENT RH	1	\$ 33.90	\$ 33.90
13	REAR WINDSCREEN MOULDING	1	\$ 101.40	\$ 101.40
14	REAR TAILLAMP RH	1	\$ 576.10	\$ 576.10
15	REAR TAILLAMP LOWER BRACKET RH	1	\$ 231.30	\$ 231.30
16	REAR TAILLAMP INNER PANEL RH	1	\$ 411.80	\$ 411.80
17	REAR SUSPENSION SHOCK ABSORBER RH	1	\$ 289.30	\$ 289.30
18	REAR SUSPENSION KNUCKLE ARM RH	1	\$ 1,165.60	\$ 1,165.60
19	REAR SUSPENSION KNUCKLE ARM BEARING RH	1	\$ 386.90	\$ 386.90
20	REAR SUSPENSION UPPER ARM RH	1	\$ 152.30	\$ 152.30
21	REAR SUSPENSION LOWER ARM RH	1	\$ 187.40	\$ 187.40
22	REAR SUSPENSION THRU SRM RH	1	\$ 135.90	\$ 135.90
23	REAR SUSPENSION TRAILING ARM RH	1	\$ 155.70	\$ 155.70
24	REAR 17" SPORT RIM ORIGINAL RH	1	\$ 899.10	\$ 899.10

TOTAL PRICE	\$ 9,892.30
LESS -10%	\$ (989.23)
SUB TOTAL PRICE	\$ 8,903.07

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS SET	1	\$ 80.00	\$ 80.00
2	REAR BUMPER RIVET SET	1	\$ 40.00	\$ 40.00
3	REAR FENDER SEALANT RH	1	\$ 80.00	\$ 80.00
4	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET RH	1	\$ 60.00	\$ 60.00
5	REAR FENDER INNER SHIELD CLIPS SET RH	1	\$ 50.00	\$ 50.00
6	REAR WINDSCREEN SEALANT WITH PRIMER SET	1	\$ 120.00	\$ 120.00
7	REAR TAILLAMP CLIPS SET RH	1	\$ 30.00	\$ 30.00
8	REAR TALLAMP INNER ANEL SEALANT RH	1	\$ 60.00	\$ 60.00

TOTAL

\$ 520.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,500.00	500	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,000.00	450	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 100.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	X NH	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	30	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 250.00	120	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 80.00	✓	5
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X NH	

TOTAL

\$ 3,600.00

QUOTATION SUMMARY

PAGE 03

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	9,423.07
TOTAL LABOUR COST	:	\$	3,600.00
TOTAL REPAIR COST	:	\$	13,023.07

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

Tanphi 17495749
wp

24/7/19 @ 1pm

Resurvey after repair.

sur elkhanto.com

5 days

[Signature]
26/7/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012980/T1tf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 09-09-2019



ATTN : CHARLOTTE CHEW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 4209R	Veh. Inspected	SLB 6051K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1054291-002	Excess (\$)	0.00
Assign From	HAZALYSA	Assign Date	23/07/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ A180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD1760422J449917	Colour	GREY
Odometer	48384 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/07/2019	Inspect Date / Time	24/07/2019 (01:00 PM)
Survey held at	48 TOH GUAN RD EAST #01-121		
Repairer	BP AUTO		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 6051K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,165.50	1,165.50
2	REAR BUMPER REVERSE SENSOR @\$195.80	DISTORTED	391.60	391.60
4	REAR BUMPER REVERSE SENSOR HOLDER @\$35.70	NECESSARY	142.80	142.80
4	REAR BUMPER REVERSE SENSOR RUBBER SEAL @\$10.90	NECESSARY	43.60	43.60
1	SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	213.70	-
2	REAR BUMPER SIDE RETAINER LH / RH @\$35.40	N/S NOT NECESSARY / O/S NECESSARY	70.80	35.40
1	REAR BUMPER TOP RETAINER	NOT NECESSARY	137.50	-
1	REAR BUMPER LOWER DIFFUSER	TORN	289.10	289.10
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	46.20	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,497.50	-
1	REAR FENDER INNER SHIELD RH	TORN	167.30	167.30
1	REAR FENDER INNER AIR VENT RH	NOT NECESSARY	33.90	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	101.40	-
1	REAR TAILLAMP RH	CRACKED	576.10	576.10
1	REAR TAILLAMP LOWER BRACKET RH	CRACKED	231.30	231.30
1	REAR TAILLAMP INNER PANEL RH	NOT NECESSARY	411.80	-
1	REAR SUSPENSION SHOCK ABSORBER RH	NOT NECESSARY	289.30	-
1	REAR SUSPENSION KNUCKLE ARM RH	BENT	1,165.60	1,165.60
1	REAR SUSPENSION KNUCKLE ARM BEARING RH	BENT	386.90	386.90
1	REAR SUSPENSION UPPER ARM RH	NOT NECESSARY	152.30	-
1	REAR SUSPENSION LOWER ARM RH	BENT	187.40	187.40
1	REAR SUSPENSION THRUS SRM RH	NOT NECESSARY	135.90	-
1	REAR SUSPENSION TRAILING ARM RH	NOT NECESSARY	155.70	-
1	REAR 17" SPORT RIM ORIGINAL RH	CUT	899.10	899.10
	LESS 10% DISCOUNT		-989.23	-568.17
			8,903.07	5,113.53
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00

Report Ref No. CS/INC19012980/T1tf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER RIVET (SN)	NECESSARY	40.00	20.00
1	REAR FENDER SEALANT RH (SN)	NOT NECESSARY	80.00	-
1	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS RH (SN)	NOT NECESSARY	60.00	-
1	SET REAR FENDER INNER SHIELD CLIPS RH (SN)	NECESSARY	50.00	10.00
1	SET REAR WINDSCREEN SEALANT WITH PRIMER (SN)	NOT NECESSARY	120.00	-
1	SET REAR TAILLAMP CLIPS RH (SN)	NOT NECESSARY	30.00	-
1	REAR TAILLAMP INNER PANEL SEALANT RH (SN)	NOT NECESSARY	60.00	-
			520.00	60.00
	LABOUR			
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,500.00	500.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,000.00	450.00
	TO APPLY ANTI-RUST & TUFF KOTE.		100.00	30.00
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.		80.00	30.00
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS.		250.00	120.00
	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT.		80.00	80.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	60.00
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.	NOT NECESSARY	80.00	-
			-	-
			-	-
			-	-
			3,600.00	1,300.00
GRAND TOTAL			13,023.07	6,473.53

Report Ref No. CS/INC19012980/T1tf3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			5,150.00
---	--	--	----------

Report Ref No. CS/INC19012980/T1tf3e2



MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU CPT(RET)
BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE
REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.