

2007/2008

ASS. REC. BY:

REF: CS/CT119012989/kgf30

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): ONG Chin Kiatof CT1Date/Time: 23.7.19 1635p.m

Estimated Cost:

Bill to:

O.D. TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SN 9882 U

Insured:

SMD 4226P

at Workshop m/s

Cheng Hoe Motor

Tel:

67506142

of

BK 1019 # 01-374 / 382 Vishnu Industrial Park A

Policy No:

DMPCN 3115919000

Claim No:

SNM 911203420002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

20.7.2019

CA / REV / REP. / REV 24 HRS

mvp

H.O.D. Endorsement:

Date/Time: 23.7.19 4.41p.m

Person Contacted:

FidaVehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SN 9882 U - XSMD 4226P - X

19/12/19 @ 11.23am confirmed with speeds US \$6550, 18 days.
(Red @ 18/2.10, 22%).

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 824K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 18 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SYN9882U Yr Regn: 03, 09

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Aventura cc 1591

Colour: M. Black AG: Insured / Std / NI / NA

Sp. Reading: 57065 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH DU 41BR9U 707659

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: _____

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 20/7/19

Rear

R/Bal: 9 mm

L/Bal: 9 mm

D.O.I: 23/7/19

Survey held at _____

Des. of Damages: Frt X Rear / O/S / N/S / U/C / Rooftop or

& As N/S

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 19 DEC 2019

Date/Time, File Pass to?

☐

: Prell. Report

1) 10/12/19

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 6550

MCD-TP
6550

Days Of Repair: 18

Resurvey No. of Trip: 3

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

F.I.N.S

Others

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2019 Sendback Est	23 Jul 2019 11:42 S\$8,030.10	23 Jul 2019 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			
Insured:	WIB, Co. Reg. No.: 53377354K		
Main Claimant:	KHATIJAH BTE OSMAN, ID: 51450473G		
Vehicle Reg. No.:	SJN9882U	Date of Loss:	20/07/2019 17:00 - :59 [124 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203420C02	Policy/Cover Note No.:	DMPCSN30115919000
Vehicle Reg. No. (Insured):	SMD4226P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/08/2019]		
Driver/Custodian (Insured):	CHEAN YONG HONG (/ Male), NRIC: G7566994T, Tel: +6598475219 Email:		

ASSOCIATED MAIL RECEIVED	
View All	Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	473G
Vehicle Details	
Vehicle No.:	SJN9882U
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jul 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U615476
Chassis No.:	KMH DU41BR9U707659
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,888.00
Original Registration Date:	09 Mar 2009
First Registration Date:	09 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$1,363.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$11,812.00
Total Rebate Amount:	\$11,812.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/07/2019 13:41
Date Of Accident	20/07/2019 17:40
Exact Location Of Accident	BKE TWDS KJE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN9882U
Insured/Policyholder	
Name Of Registered Owner	KHATIJAH BTE OSMAN
NRIC No	S1450473G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98717282
Alternative Phone No	OFFICE-98717282

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z19VP05022435
Cover Note Number	EXP 08.03.2020

Driver

Name of Driver	MASUD BIN MOHAMED ALI
NRIC No	S1450811B
Date Of Birth	30/10/1960
Occupation	INDOOR
Date Of Driving Pass	03/03/2005
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98717282
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 927 YISHUN CENTRAL 1, 02-161
Postcode	760927
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KHATIJAH BTE OSMAN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT ATTACH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD4226P
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	FRONT
Vehicle Category	PRIVATE CAR
Name of Driver	CHEAN YONG HONG JACKIE
NRIC/Passport Number	G7566994T
Contact Number	98475219
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLD6281C
Vehicle Make/Model/Colour	
Details Of Properties	REAR RIGHT
Vehicle Category	PRIVATE CAR
Name of Driver	LEE HUI JIN JENNY
NRIC/Passport Number	S8227231C
Contact Number	98783434
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

A: SJN 98824
 B: SMD 4226P
 CHAN YONG HON JACKIE
 G75669947
 U/P: 98675719
 C: SLD 6281C
 LEE HUI JIN JENNY
 58227231C
 U/P: 98783634

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident occurred on 20/7/19 @ 5.40pm along BKE
 towards KJB at the extreme left lane. Out of
 sudden, motor car SLD 6281C in front of me brakes and
 slow down and I follow likewise. However motor
 car SMD 4226P behind ran onto the rear of my
 vehicle and it push my vehicle forward collide onto
 the rear of SLD 6281C.
 My vehicle sustain damages on front and rear.
 No one was injured

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim
 under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

YS 21/7/19

GIARMC Sketchplan form V3

() Claim Own Policy (X) Claim Third Party () Reporting Only
 () Claim OD/TP at other workshop ()

SKETCH PLAN

VEHICLE NO.: SIN 9882 U
INSURER : Longac
DATE & TIME: 20/7/19 @ 5.40pm


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: YS
NRIC/FIN No.:

SJN9882U
TP/china

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	TP/CHINA	Date of Incident:	20/07/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	GLS
Model Sheet Number:	30 22 51
Registration:	SJN9882U
VIN number:	
Odometer:	

Model Specs

AIR CONDITIONING	1.6 LTR 90 KW
------------------	---------------

Not Authorised
11/12/87
Paying After Repair
18 days

LKK Auto Consultants hence notify the Repairer of the following:

- To ensure the repairer's painting
- To ensure the repairer's painting
- Parts colour and finish specification
- To ensure the repairer's painting
- To ensure the repairer's painting
- To ensure the repairer's painting
- To ensure the repairer's painting
- To ensure the repairer's painting

Acknowledged by: _____
Signature: _____
Date: _____

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☒
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.		6.0	25.20
NO NUMBER	RENEW FR NUMBER PLATE (REMOVED)		1.0	4.20
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	12.60
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		6.0	25.20
79110R00)	R + R L/BONNET HINGE (BONNET REMOVED)		1.0	4.20
66300R0B	R + R BOTH FRONT WINGS		13.0	54.60
NO NUMBER	R + R LEFT FRONT WING BADGE		2.0	8.40

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Code	Description	WU	Price SGD
NO NUMBER	R + R FRONT PANEL	20.0	84.00
86150R00	R + R LOWER WINDSCREEN COVER	3.0	12.60
	INCLUDES: R + R BOTH WIPER ARMS		
86520R00	RENEW REAR BUMPER CPL	8.0	33.60
	INCLUDES: REAR BUMPER, REAR LAMPS,		
	REINFORCEMENT REAR BUMPER AND		
	REQUIRED TRIMS REMOVE AND REFIT		
	ATTACHED PARTS ASSEMBLE IF NECESS RENEW		
69200R00	RENEW BOOTLID	8.0	33.60
	INCLUDES: R + R BOOTLID,		
	CONVERT ATTACHED PARTS, RENEW IF		
	NECESSARY		
79210R00)	R + R L/BOOTLID HINGE	5.0	21.00
87321R00	R + R BOOTLID SEAL	2.0	8.40
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)	1.0	4.20
NO NUMBER	RENEW REAR END PANEL	63.0	264.60
NO NUMBER	RENEW LEFT TAILLAMP SUPPORT	15.0	63.00
NO NUMBER	RENEW BOOT FLOOR CPL	50.0	210.00
NO NUMBER	RENEW L/REAR S-MEMBER	41.0	172.20
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	42.00
85610R00	R + R REAR PARCEL SHELF TRIM	6.0	25.20
85731R00)	R + R LEFT BOOT TRIM	1.0	4.20
85731R0R)	R + R RIGHT BOOT TRIM	1.0	4.20
85710R00	R + R LUGGAGE COMP FLOOR CARPET	2.0	8.40
25300R00)	R + R RADIATOR	7.0	29.40
	INCLUDES: R + R COMPLETE RADIATOR SHROUD		
29140R00	R + R LOWER ENGINE COVER	2.0	8.40
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	21.00
8827	RR EXHAUST SILENCER REMOVE AND REFIT	10 15.0*	63.00
1005	CHECK UNDERCARRIAGE REMOVE&REFIT	20 30.0*	126.00
1117	L/F WHEELHOUSE REPAIR	35 45.0*	189.00
1201	L/F SIDE MEMBER REPAIR	20.0* ✓	84.00
3451	L/R SIDE PANEL CPL REPAIR	30 40.0*	168.00
3452	R/R SIDE PANEL CPL REPAIR	25 40.0*	168.00
3992	R/R SIDE MEMBER REPAIR	10.0* ✓	42.00
1004	WHEEL ALIGNMENT ALIGNMENT	15.0* ✓	63.00

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	48.50	485.0	2,037.00
Alignment			
Measuring Work	1.50	15.0	63.00
Total of Labour			2,100.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	BONNET NEW PART PAINTING	22.0
	L/F WING NEW PART PAINTING	9.0
	REAR BUMPER SUPPORT SURFACE PAINT	4.0
	REAR PANEL NEW PART PAINTING	20.0
	BOOTLID NEW PART PAINTING	15.0
	L/R LAMP PANEL SURFACE PAINT	4.0
	BOOTFLOOR CPL SURFACE PAINT	9.0
	L/R SIDE MEMBER SURFACE PAINT	4.0
	FRONT BUMPER NEW PART PAINT K1R	9.0
	REAR BUMPER NEW PART PAINT K1R	9.0
	R/F WING REPAIR PAINTING >50%	15.0
	LEFT FRONT DOOR REPAIR PAINTING >50%	23.0
	L/R DOOR REPAIR PAINTING >50%	20.0
	L/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0
	R/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0
	L/F WHEELHOUSE SURFACE PAINT	6.0
	L/F SIDE MEMBER SURFACE PAINT	4.0
	R/R SIDE MEMBER SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	2.99
0471	BONNET NEW PART PAINTING	61.26
0741	L/F WING NEW PART PAINTING	14.11
2640	REAR BUMPER SUPPORT SURFACE PAINT	2.99
2711	REAR PANEL NEW PART PAINTING	20.98
2931	BOOTLID NEW PART PAINTING	34.66
3571	L/R LAMP PANEL SURFACE PAINT	0.88
3900	BOOTFLOOR CPL SURFACE PAINT	22.70
3991	L/R SIDE MEMBER SURFACE PAINT	3.87
0283	FRONT BUMPER NEW PART PAINT K1R	33.50

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	33.50
0742	R/F WING REPAIR PAINTING >50%	11.24
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	26.00
1781	L/R DOOR REPAIR PAINTING >50%	21.19
3451	L/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
3452	R/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
1117	L/F WHEELHOUSE SURFACE PAINT	9.15
1201	L/F SIDE MEMBER SURFACE PAINT	2.29
3992	R/R SIDE MEMBER SURFACE PAINT	3.87

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			223.0	
Preparation Main Work Metal		1.70	17.0	71.40
Preparation Comp. Work Plastic		0.30	3.0	12.60
Total	10 WU/h	24.30	243.0	1,020.60

Material Cost - Paint

	Price SGD
New Part Painting	131.01
New Part Painting - Plastic K1R	67.00
Repair Painting	104.65
Surface-/Blend Paint	48.74
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	378.50

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		CM 35.00 ✓
0283	FRONT BUMPER	865112H000		Bu 190.00 ✓
0315	FRT BUMPER ABSORBER	865202H010		CM 65.00 ✓
0327	LEFT RETAINER	1491005000		CM 18.00 ✓
0340	FRT BUMPER SUPPORT	865302H010		D.I 110.00 ✓
0471	BONNET	664002H010		R 430.00 ✓
0475	LEFT BONNET HINGE	791102H000		D.I 32.00 ✓
0561	LEFT HEADLAMP ASSY	921012H090		CM 195.00 ✓
0741	L/F WING	663112H022		An 170.00 ✓

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Code	Description	Part Number	Supplier	Price SGD	
0811	L/F WING BADGE	863162H000		32.00	✓
0841	L/F WHEELHOUSE COVER	868112H010		18.00	✓
1009	INNER FRT PANEL CPL	641012H000		310.00	✓
2583	REAR BUMPER	866102H000		190.00	✓
2640	REAR BUMPER SUPPORT	866312H010		100.00	✓
2644	REAR BUMPER DAMPER	866202H010		58.00	✓
2702	REAR NUMBER PLATE	KNPL6		35.00	✓
2711	REAR PANEL	691002H010		185.00	✓
2931	BOOTLID	692002H071		320.00	✓
2944	BOOT/TAILGATE SEAL	873212H000		65.00	✓
2953	L/R HINGE	792102H000		60.00	✓
2977	BOOT/TAILGATE LOCK	812202H000		78.00	✓
3013	BADGE HYUNDAI	863212H000		18.00	✓
3015	REAR MANUFACT BADGE	863002H000		18.00	✓
3020	TYPE BADGE	863102H000		22.00	✓
3021	VERSION BADGE	863142H000		0.00	
3022	VERSION BADGE	863122H000		0.00	
3023	VERSION BADGE	863152H000		0.00	
3024	VERSION BADGE	863132H000		0.00	
3025	VERSION BADGE	863472H000		0.00	
3281	L/R OUTER LAMP	924012H010		125.00	✓
3282	R/R OUTER LAMP	924022H010		125.00	✓
3291	L/R INNER LAMP	924032H000		105.00	✓
3571	L/R LAMP PANEL	715752H100		58.00	✓
3900	BOOTFLOOR CPL	655132H010		420.00	✓
3991	L/R SIDE MEMBER	657102H010		305.00	✓
4985	LUGGAGE COMPART TRIM	857702H000MC		40.00	✓
4991	L/R WHEELARCH TRIM	857302H000MC		175.00	✓
1000	FRT BUMPER LWR GRILL PARTS			32.00	✓
1002	lh foglamp garnish parts			42.00	✓

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	4,181.00
Fixed Sundry Parts Price	100.00
Total	4,281.00

Extras

Code	Description	Price SGD
1001	1ser reverse sensor parts	200.00*

Cheng Hoe Motor Pte Ltd
#01-374/382,Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Code	Description	Price SGD
1003	a/con gas	50.00*
	Total Extras	250.00

Final Calculation

	SGD	SGD
Parts	4,181.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,281.00
Labour Time Base 10 WU/h		
Total 485.0 WU X 42.00 SGD/h	2,037.00	
Alignment		
Measuring Work	63.00	
Total of Labour		2,100.00
Total Of Extras		250.00
Paint Work Time Base 10 WU/h		
Labour Cost 243.0 WU X 42.00 SGD/h	1,020.60	
Material Cost	378.50	
Total Paint Including Material		1,399.10
Repair Cost Excludes GST		8,030.10
GST (+7.0%)		562.11
Repair Cost Included GST		8,592.21

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

SJN9882U
TP/china

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
Assessment number: A0032
Version: 1810
Date calculated: 23/07/2019 11:10 AM

Full Report
Registration: SJN9882U
Printed: 23/07/2019 11:11 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	TP/CHINA	Date of Incident:	20/07/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	GLS
Model Sheet Number:	30 22 51
Registration:	SJN9882U
VIN number:	
Odometer:	
Model Specs	
AIR CONDITIONING	1.6 LTR 90 KW

Not Authorised
11/12/87
Paying After Repair
18 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
Assessment number: A0032
Version: 1810
Date calculated: 23/07/2019 11:10 AM

Full Report
Registration: SJN9882U
Printed: 23/07/2019 11:11 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW	6.0	25.20	
NO NUMBER	RENEW FR NUMBER PLATE (REMOVED)	1.0	4.20	
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS	3.0	12.60	
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	6.0	25.20	
79110R00)	R + R L/BONNET HINGE (BONNET REMOVED)	1.0	4.20	
66300R0B	R + R BOTH FRONT WINGS	13.0	54.60	
NO NUMBER	R + R LEFT FRONT WING BADGE	2.0	8.40	

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
 Assessment number: A0032
 Version: 1810
 Date calculated: 23/07/2019 11:10 AM

Full Report
 Registration: SJN9882U
 Printed: 23/07/2019 11:11 AM

Code	Description	WU	Price SGD
NO NUMBER	R + R FRONT PANEL	20.0	84.00
86150R00	R + R LOWER WINDSCREEN COVER INCLUDES: R + R BOTH WIPER ARMS	3.0	12.60
86520R00	RENEW REAR BUMPER CPL INCLUDES: REAR BUMPER, REAR LAMPS, REINFORCEMENT REAR BUMPER AND REQUIRED TRIMS REMOVE AND REFIT ATTACHED PARTS ASSEMBLE IF NECESS RENEW	8.0	33.60
69200R00	RENEW BOOTLID INCLUDES: R + R BOOTLID, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	8.0	33.60
79210R00)	R + R L/BOOTLID HINGE	5.0	21.00
87321R00	R + R BOOTLID SEAL	2.0	8.40
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)	1.0	4.20
NO NUMBER	RENEW REAR END PANEL	63.0	264.60
NO NUMBER	RENEW LEFT TAILLAMP SUPPORT	15.0	63.00
NO NUMBER	RENEW BOOT FLOOR CPL	50.0	210.00
NO NUMBER	RENEW L/REAR S-MEMBER	41.0	172.20
97605R00	R + R AIR CONDITIONING CONDENSER	10.0	42.00
85610R00	R + R REAR PARCEL SHELF TRIM	6.0	25.20
85731R00)	R + R LEFT BOOT TRIM	1.0	4.20
85731R0R)	R + R RIGHT BOOT TRIM	1.0	4.20
85710R00	R + R LUGGAGE COMP FLOOR CARPET	2.0	8.40
25300R00)	R + R RADIATOR INCLUDES: R + R COMPLETE RADIATOR SHROUD	7.0	29.40
29140R00	R + R LOWER ENGINE COVER	2.0	8.40
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	21.00
8827	RR EXHAUST SILENCER REMOVE AND REFIT	10 15.0*	63.00
1005	CHECK UNDERCARRIAGE REMOVE&REFIT	20 30.0*	126.00
1117	L/F WHEELHOUSE REPAIR	35 45.0*	189.00
1201	L/F SIDE MEMBER REPAIR	20.0*	84.00
3451	L/R SIDE PANEL CPL REPAIR	30 40.0*	168.00
3452	R/R SIDE PANEL CPL REPAIR	25 40.0*	168.00
3992	R/R SIDE MEMBER REPAIR	10.0*	42.00
1004	WHEEL ALIGNMENT ALIGNMENT	15.0*	63.00

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	48.50	485.0	2,037.00
Alignment			
Measuring Work	1.50	15.0	63.00
Total of Labour			2,100.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	BONNET NEW PART PAINTING	22.0
	L/F WING NEW PART PAINTING	9.0
	REAR BUMPER SUPPORT SURFACE PAINT	4.0
	REAR PANEL NEW PART PAINTING	20.0
	BOOTLID NEW PART PAINTING	15.0
	L/R LAMP PANEL SURFACE PAINT	4.0
	BOOTFLOOR CPL SURFACE PAINT	9.0
	L/R SIDE MEMBER SURFACE PAINT	4.0
	FRONT BUMPER NEW PART PAINT K1R	9.0
	REAR BUMPER NEW PART PAINT K1R	9.0
	R/F WING REPAIR PAINTING >50%	15.0
	LEFT FRONT DOOR REPAIR PAINTING >50%	23.0
	L/R DOOR REPAIR PAINTING >50%	20.0
	L/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0
	R/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0
	L/F WHEELHOUSE SURFACE PAINT	6.0
	L/F SIDE MEMBER SURFACE PAINT	4.0
	R/R SIDE MEMBER SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	2.99
0471	BONNET NEW PART PAINTING	61.26
0741	L/F WING NEW PART PAINTING	14.11
2640	REAR BUMPER SUPPORT SURFACE PAINT	2.99
2711	REAR PANEL NEW PART PAINTING	20.98
2931	BOOTLID NEW PART PAINTING	34.66
3571	L/R LAMP PANEL SURFACE PAINT	0.88
3900	BOOTFLOOR CPL SURFACE PAINT	22.70
3991	L/R SIDE MEMBER SURFACE PAINT	3.87
0283	FRONT BUMPER NEW PART PAINT K1R	33.50

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	33.50
0742	R/F WING REPAIR PAINTING >50%	11.24
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	26.00
1781	L/R DOOR REPAIR PAINTING >50%	21.19
3451	L/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
3452	R/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
1117	L/F WHEELHOUSE SURFACE PAINT	9.15
1201	L/F SIDE MEMBER SURFACE PAINT	2.29
3992	R/R SIDE MEMBER SURFACE PAINT	3.87

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		223.0	
Preparation Main Work Metal	1.70	17.0	71.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	243.0	1,020.60

Material Cost - Paint

	Price SGD
New Part Painting	131.01
New Part Painting - Plastic K1R	67.00
Repair Painting	104.65
Surface-/Blend Paint	48.74
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	378.50

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		CM	35.00 ✓
0283	FRONT BUMPER	865112H000		R ₁	190.00 ✓
0315	FRT BUMPER ABSORBER	865202H010		CM	65.00 ✓
0327	LEFT RETAINER	1491005000		CM	18.00 ✓
0340	FRT BUMPER SUPPORT	865302H010		D ₁	110.00 ✓
0471	BONNET	664002H010		R ₁	430.00 ✓
0475	LEFT BONNET HINGE	791102H000		D ₁	32.00 ✓
0561	LEFT HEADLAMP ASSY	921012H090		CM	195.00 ✓
0741	L/F WING	663112H022		R ₁	170.00 ✓

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA

Assessment number: A0032

Version: 1810

Date calculated: 23/07/2019 11:10 AM

Full Report

Registration: SJN9882U

Printed: 23/07/2019 11:11 AM

Code	Description	Part Number	Supplier	Price SGD	
0811	L/F WING BADGE	863162H000		32.00	✓
0841	L/F WHEELHOUSE COVER	868112H010		18.00	✓
1009	INNER FRT PANEL CPL	641012H000		310.00	✓
2583	REAR BUMPER	866102H000		190.00	✓
2640	REAR BUMPER SUPPORT	866312H010		100.00	✓
2644	REAR BUMPER DAMPER	866202H010		58.00	✓
2702	REAR NUMBER PLATE	KNPL6		35.00	✓
2711	REAR PANEL	691002H010		185.00	✓
2931	BOOTLID	692002H071		320.00	✓
2944	BOOT/TAILGATE SEAL	873212H000		65.00	✓
2953	L/R HINGE	792102H000		60.00	✓
2977	BOOT/TAILGATE LOCK	812202H000		78.00	✓
3013	BADGE HYUNDAI	863212H000		18.00	✓
3015	REAR MANUFACT BADGE	863002H000		18.00	✓
3020	TYPE BADGE	863102H000		22.00	✓
3021	VERSION BADGE	863142H000		0.00	✓
3022	VERSION BADGE	863122H000		0.00	✓
3023	VERSION BADGE	863152H000		0.00	✓
3024	VERSION BADGE	863132H000		0.00	✓
3025	VERSION BADGE	863472H000		0.00	✓
3281	L/R OUTER LAMP	924012H010		125.00	✓
3282	R/R OUTER LAMP	924022H010		125.00	✓
3291	L/R INNER LAMP	924032H000		105.00	✓
3571	L/R LAMP PANEL	715752H100		58.00	✓
3900	BOOTFLOOR CPL	655132H010		420.00	✓
3991	L/R SIDE MEMBER	657102H010		305.00	✓
4985	LUGGAGE COMPART TRIM	857702H000MC		40.00	✓
8991	L/R WHEELARCH TRIM	857302H000MC		175.00	✓
1000	FRT BUMPER LWR GRILL PARTS			32.00	✓
1002	lh foglamp garnish parts			42.00	✓
f: OEM Parts				0.00	
n: Non-OEM Parts				4,181.00	
u: Used parts				100.00	
Savings					
Subtotal				4,181.00	
Fixed Sundry Parts Price				100.00	
Total				4,281.00	

Extras

Code	Description	Price SGD
1001	1ser reverse sensor parts	200.00*

Attn: MR. Kenneth

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference: TP/CHINA
 Assessment number: A0032
 Version: 1810

Full Report
 Registration: SJN9882U
 Printed: 23/07/2019 11:11 AM

Date calculated: 23/07/2019 11:10 AM

Code	Description	Price SGD
1003	a/con gas	50.00*
	Total Extras	250.00

Final Calculation

	SGD	SGD
Parts	4,181.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,281.00
Labour Time Base 10 WU/h		
Total 485.0 WU X 42.00 SGD/h	2,037.00	
Alignment		
Measuring Work	63.00	
Total of Labour		2,100.00
Total Of Extras		250.00
Paint Work Time Base 10 WU/h		
Labour Cost 243.0 WU X 42.00 SGD/h	1,020.60	
Material Cost	378.50	
Total Paint Including Material		1,399.10
Repair Cost Excludes GST		8,030.10
GST (+7.0%)		562.11
Repair Cost Included GST		8,592.21

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Supp

1 pc battery tray CM #32 ✓
 1 pc 1/4 head long lower beam #22 Br ✓
 1 pc 1/4 corner garnish CM #28 ✓
 #82

① To mount on CAR-O-LINER

\$250/ ✓

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: TP/CHINA
Repairer Reference: A0032
Date calculated: 24/08/2019 11:42 AM
Summary Information

Full Report
Registration: SJN9882U
Printed: 24/08/2019 11:42 AM

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	TP/CHINA	Date of Incident:	20/07/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	GLS
Model Sheet Number:	30 22 51
Registration:	SJN9882U
VIN number:	
Odometer:	

Model Specs

AIR CONDITIONING	1.6 LTR 90 KW
------------------	---------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: TP/CHINA

Repairer Reference: A0032

Date calculated: 24/08/2019 11:42 AM

Full Report

Registration: SJN9882U

Printed: 24/08/2019 11:42 AM

Code	Description	WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.	6.0	25.20
NO NUMBER	RENEW FR NUMBER PLATE (REMOVED)	1.0	4.20
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS	3.0	12.60
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	6.0	25.20
79110R00)	R + R L/BONNET HINGE (BONNET REMOVED)	1.0	4.20
66300R0B	R + R BOTH FRONT WINGS	13.0	54.60
NO NUMBER	R + R LEFT FRONT WING BADGE	2.0	8.40
NO NUMBER	R + R FRONT PANEL	20.0	84.00
86111R00	R + R WINDSCREEN INCLUDES: R + R INTERIOR MIRROR, WIPER ARMS, WINDSCREEN FRAME COVER, ROOF STORAGE CONSOLE, SUN VISORS AND A-PILLAR TRIMS	20.0	84.00
86520R00	RENEW REAR BUMPER CPL INCLUDES: REAR BUMPER, REAR LAMPS, REINFORCEMENT REAR BUMPER AND REQUIRED TRIMS REMOVE AND REFIT ATTACHED PARTS ASSEMBLE IF NECESS RENEW	8.0	33.60
69200R00	RENEW BOOTLID INCLUDES: R + R BOOTLID, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	8.0	33.60
79210R00)	R + R L/BOOTLID HINGE	5.0	21.00
87321R00	R + R BOOTLID SEAL	2.0	8.40
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)	1.0	4.20
NO NUMBER	RENEW REAR END PANEL	63.0	264.60
NO NUMBER	RENEW LEFT TAILLAMP SUPPORT	15.0	63.00
NO NUMBER	RENEW BOOT FLOOR CPL	50.0	210.00
NO NUMBER	RENEW L/REAR S-MEMBER	41.0	172.20
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	42.00
85610R00	R + R REAR PARCEL SHELF TRIM	6.0	25.20
85731R00)	R + R LEFT BOOT TRIM	1.0	4.20
85731R0R)	R + R RIGHT BOOT TRIM	1.0	4.20
85710R00	R + R LUGGAGE COMP FLOOR CARPET	2.0	8.40
25300R00)	R + R RADIATOR INCLUDES: R + R COMPLETE RADIATOR SHROUD	7.0	29.40
29140R00	R + R LOWER ENGINE COVER	2.0	8.40

Cheng Hoe Motor Pte Ltd
#01-374/382,Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: TP/CHINA

Repairer Reference: A0032

Date calculated: 24/08/2019 11:42 AM

Full Report

Registration: SJN9882U

Printed: 24/08/2019 11:42 AM

Code	Description	WU	Price SGD
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	21.00
8827	RR EXHAUST SILENCER REMOVE AND REFIT	10.0*	42.00
1005	CHECK UNDERCARRIAGE REMOVE&REFIT	20.0*	84.00
1117	L/F WHEELHOUSE REPAIR	35.0*	147.00
1201	L/F SIDE MEMBER REPAIR	20.0*	84.00
3451	L/R SIDE PANEL CPL REPAIR	30.0*	126.00
3452	R/R SIDE PANEL CPL REPAIR	25.0*	105.00
3992	R/R SIDE MEMBER REPAIR	10.0*	42.00
1007	MOUNT ON CAR-O-LINER REPAIR		250.00*
1004	WHEEL ALIGNMENT ALIGNMENT	15.0*	63.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		45.20	452.0
Fixed Rate			1,898.40
Alignment			250.00
Measuring Work		1.50	15.0
Total of Labour			2,211.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	BONNET NEW PART PAINTING	22.0
	L/F WING NEW PART PAINTING	9.0
	BATTERY CARRIER SURFACE PAINT	4.0
	REAR BUMPER SUPPORT SURFACE PAINT	4.0
	REAR PANEL NEW PART PAINTING	20.0
	BOOTLID NEW PART PAINTING	15.0
	L/R LAMP PANEL SURFACE PAINT	4.0
	BOOTFLOOR CPL SURFACE PAINT	9.0
	L/R SIDE MEMBER SURFACE PAINT	4.0
	FRONT BUMPER NEW PART PAINT K1R	9.0
	REAR BUMPER NEW PART PAINT K1R	9.0
	R/F WING REPAIR PAINTING >50%	15.0
	LEFT FRONT DOOR REPAIR PAINTING >50%	23.0
	L/R DOOR REPAIR PAINTING >50%	20.0
	L/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0
	R/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0
	L/F WHEELHOUSE SURFACE PAINT	6.0
	L/F SIDE MEMBER SURFACE PAINT	4.0
	R/R SIDE MEMBER SURFACE PAINT	4.0

Cheng Hoe Motor Pte Ltd
#01-374/382,Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: TP/CHINA

Repairer Reference: A0032

Date calculated: 24/08/2019 11:42 AM

Paint Material Per Part

Full Report

Registration: SJN9882U

Printed: 24/08/2019 11:42 AM

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	2.99
0471	BONNET NEW PART PAINTING	61.26
0741	L/F WING NEW PART PAINTING	14.11
1331	BATTERY CARRIER SURFACE PAINT	0.70
2640	REAR BUMPER SUPPORT SURFACE PAINT	2.99
2711	REAR PANEL NEW PART PAINTING	20.98
2931	BOOTLID NEW PART PAINTING	34.66
3571	L/R LAMP PANEL SURFACE PAINT	0.88
3900	BOOTFLOOR CPL SURFACE PAINT	22.70
3991	L/R SIDE MEMBER SURFACE PAINT	3.87
0283	FRONT BUMPER NEW PART PAINT K1R	33.50
2583	REAR BUMPER NEW PART PAINT K1R	33.50
0742	R/F WING REPAIR PAINTING >50%	11.24
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	26.00
1781	L/R DOOR REPAIR PAINTING >50%	21.19
3451	L/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
3452	R/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
1117	L/F WHEELHOUSE SURFACE PAINT	9.15
1201	L/F SIDE MEMBER SURFACE PAINT	2.29
3992	R/R SIDE MEMBER SURFACE PAINT	3.87

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		227.0	
Preparation Main Work Metal	1.70	17.0	71.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	247.0	1,037.40

Material Cost - Paint

	Price SGD
New Part Painting	131.01
New Part Painting - Plastic K1R	67.00
Repair Painting	104.65
Surface-/Blend Paint	49.44
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	379.20

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
------	-------------	-------------	----------	-------------------------	-----------

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: TP/CHINA

Repairer Reference: A0032

Date calculated: 24/08/2019 11:42 AM

Full Report

Registration: SJN9882U

Printed: 24/08/2019 11:42 AM

Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		35.00
0283	FRONT BUMPER	865112H000		190.00
0315	FRT BUMPER ABSORBER	865202H010		65.00
0327	LEFT RETAINER	1491005000		18.00
0340	FRT BUMPER SUPPORT	865302H010		110.00
0471	BONNET	664002H010		430.00
0475	LEFT BONNET HINGE	791102H000		32.00
0561	LEFT HEADLAMP ASSY	921012H090		195.00
0741	L/F WING	663112H022		170.00
0811	L/F WING BADGE	863162H000		32.00
0841	L/F WHEELHOUSE COVER	868112H010		18.00
1009	INNER FRT PANEL CPL	641012H000		310.00
1331	BATTERY CARRIER	371502H100		32.00
1423	L/COWL MOULDING	861502H910		28.00
2583	REAR BUMPER	866102H000		190.00
2640	REAR BUMPER SUPPORT	866312H010		100.00
2644	REAR BUMPER DAMPER	866202H010		58.00
2702	REAR NUMBER PLATE	KNPL6		35.00
2711	REAR PANEL	691002H010		185.00
2931	BOOTLID	692002H071		320.00
2944	BOOT/TAILGATE SEAL	873212H000		65.00
2953	L/R HINGE	792102H000		60.00
2977	BOOT/TAILGATE LOCK	812202H000		78.00
3013	BADGE HYUNDAI	863212H000		18.00
3015	REAR MANUFACT BADGE	863002H000		18.00
3020	TYPE BADGE	863102H000		22.00
3021	VERSION BADGE	863142H000		0.00
3022	VERSION BADGE	863122H000		0.00
3023	VERSION BADGE	863152H000		0.00
3024	VERSION BADGE	863132H000		0.00
3025	VERSION BADGE	863472H000		0.00
3281	L/R OUTER LAMP	924012H010		125.00
3282	R/R OUTER LAMP	924022H010		125.00
3291	L/R INNER LAMP	924032H000		105.00
3571	L/R LAMP PANEL	715752H100		58.00
3900	BOOTFLOOR CPL	655132H010		420.00
3991	L/R SIDE MEMBER	657102H010		305.00
4985	LUGGAGE COMPART TRIM	857702H000MC		40.00
4991	L/R WHEELARCH TRIM	857302H000MC		175.00
1002	lh foglamp garnish	parts		42.00
1006	LH H/LAMP LWR BEAM	parts		22.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Fixed Sundry Parts Price

0.00
4,231.00
100.00

Cheng Hoe Motor Pte Ltd
#01-374/382,Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: TP/CHINA
 Repairer Reference: A0032
 Date calculated: 24/08/2019 11:42 AM

Full Report
 Registration: SJN9882U
 Printed: 24/08/2019 11:42 AM

Total **4,331.00**

Extras

Code	Description	Price SGD
1001	1ser reverse sensor parts	200.00*
1003	a/con gas	50.00*
	Total Extras	250.00

Final Calculation


	SGD	SGD
Parts	4,231.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,331.00
Labour Time Base 10 WU/h		
Total 452.0 WU X 42.00 SGD/h	1,898.40	
Fixed Rate	250.00	
Alignment		
Measuring Work	63.00	
Total of Labour		2,211.40
Total Of Extras		250.00
Paint Work Time Base 10 WU/h		
Labour Cost 247.0 WU X 42.00 SGD/h	1,037.40	
Material Cost	379.20	
Total Paint Including Material		1,416.60
Repair Cost Excludes GST		8,209.00
GST (+7.0%)		574.63
Repair Cost Included GST		8,783.63

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chrmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**W18**

61 WOODLANDS IND PK E9

#03-07

Singapore 757047

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA
Policy No:		Date of Loss:	20/07/2019
Vehicle Reg. No.:	SJN9882U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MASUD BIN MOHAMED ALI	Driver (Insured):	CHEAN YONG HONG
Make/Model:	HYUNDAI AVANTE, 1.6 HD (A)	Vehicle Reg. Date:	09/03/2009
Vehicle Colour:	BLACK		
Engine No:	G4FC9U615476	Chassis No:	KMH DU41BR9U707659
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS	Amount
Parts	4,181.00
Miscellaneous Items	350.00
Labour	3,499.10
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	8,030.10
+ GST 7.00% (\$\$)	562.11
Nett Amount (\$\$)	8,592.21

This claim is handled by: EFEEDA BINTE MOHAMED OTHMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

8362.10

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jul 2019)

Parts: 143 HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SJN9882U/23/07/2019 11:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*parts	0.00	0.00	4,181.00 F
Total Parts (S\$)						4,181.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SJN9882U/23/07/2019 11:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items


No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	snett	250.00
2	1	sundry	100.00
Sub Total (S\$)			350.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	panel beating	New	2,100.00
2	spray painting	New	1,399.10
Gross Labour Cost (S\$)			3,499.10

Cheng Hoe Motor Pte Ltd/SJN9882U/23/07/2019 11:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

(SUPPLEMENTARY)

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

WI8

61 WOODLANDS IND PK E9

#03-07

Singapore 757047

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA
Policy No:	DMPCSN30115919000	Date of Loss:	20/07/2019
Vehicle Reg. No.:	SJN9882U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MASUD BIN MOHAMED ALI	Driver (Insured):	CHEAN YONG HONG
Make/Model:	HYUNDAI AVANTE, 1.6 HD (A)	Vehicle Reg. Date:	09/03/2009
Vehicle Colour:	BLACK	Chassis No:	KMH DU41BR9U707659
Engine No:	G4FC9U615476		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS

	Amount
Parts	82.00
Miscellaneous Items	0.00
Labour	250.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	332.00
+ GST 7.00% (\$)	23.24
Nett Amount (\$)	355.24
+ Previous Estimates (\$)	8,592.21
Claim Total (\$)	8,947.45

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2019)**Parts:** 143 HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SJN9882U/19/12/2019 11:32**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BATTERT TRAY	0.00	0.00	CLP *32.00 F ✓
2	1		*LH HEADLAMP LOWER BEAM	0.00	0.00	BT *22.00 F ✓
3	1		*BUMPER LH CORNER GARNISH	0.00	0.00	CPA *28.00 F ✓
Total Parts (S\$)						82.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SJN9882U/19/12/2019 11:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO MOUNT ON CAR-O-LINER	New	250.00
Gross Labour Cost (S\$)			250.00

Cheng Hoe Motor Pte Ltd/SJN9882U/19/12/2019 11:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: TP/CHINA
Repairer Reference: A0032
Date calculated: 12/12/2019 4:23 PM

Full Report
Registration: SJN9882U
Printed: 12/12/2019 4:23 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	TP/CHINA	Date of Incident:	20/07/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	GLS
Model Sheet Number:	30 22 51
Registration:	SJN9882U
VIN number:	
Odometer:	

Model Specs

AIR CONDITIONING	1.6 LTR 90 KW
------------------	---------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.	6.0	25.20	
NO NUMBER	RENEW FR NUMBER PLATE (REMOVED)	1.0	4.20	
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS	3.0	12.60	
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	6.0	25.20	
79110R00)	R + R L/BONNET HINGE (BONNET REMOVED)	1.0	4.20	
66300R0B	R + R BOTH FRONT WINGS	13.0	54.60	
NO NUMBER	R + R LEFT FRONT WING BADGE	2.0	8.40	
NO NUMBER	R + R FRONT PANEL	20.0	84.00	
86111R00	R + R WINDSCREEN INCLUDES: R + R INTERIOR MIRROR, WIPER ARMS, WINDSCREEN FRAME COVER, ROOF STORAGE CONSOLE, SUN VISORS AND A-PILLAR TRIMS	20.0	84.00	
86520R00	RENEW REAR BUMPER CPL INCLUDES: REAR BUMPER, REAR LAMPS, REINFORCEMENT REAR BUMPER AND REQUIRED TRIMS REMOVE AND REFIT ATTACHED PARTS ASSEMBLE IF NECESS RENEW	8.0	33.60	
69200R00	RENEW BOOTLID INCLUDES: R + R BOOTLID, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	8.0	33.60	
79210R00)	R + R L/BOOTLID HINGE	5.0	21.00	
87321R00	R + R BOOTLID SEAL	2.0	8.40	
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)	1.0	4.20	
NO NUMBER	RENEW REAR END PANEL	63.0	264.60	
NO NUMBER	RENEW LEFT TAILLAMP SUPPORT	15.0	63.00	
NO NUMBER	RENEW BOOT FLOOR CPL	50.0	210.00	
NO NUMBER	RENEW L/REAR S-MEMBER	41.0	172.20	
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	42.00	
85610R00	R + R REAR PARCEL SHELF TRIM	6.0	25.20	
85731R00)	R + R LEFT BOOT TRIM	1.0	4.20	
85731R0R)	R + R RIGHT BOOT TRIM	1.0	4.20	
85710R00	R + R LUGGAGE COMP FLOOR CARPET	2.0	8.40	
25300R00)	R + R RADIATOR INCLUDES: R + R COMPLETE RADIATOR SHROUD	7.0	29.40	
29140R00	R + R LOWER ENGINE COVER	2.0	8.40	
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60	
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	21.00	
8827	RR EXHAUST SILENCER REMOVE AND REFIT	10.0*	42.00	
1005	CHECK UNDERCARRIAGE REMOVE&REFIT	20.0*	84.00	
1117	L/F WHEELHOUSE REPAIR	35.0*	147.00	
1201	L/F SIDE MEMBER REPAIR	20.0*	84.00	

Code	Description	WU	Price SGD
3451	L/R SIDE PANEL CPL REPAIR	30.0*	126.00
3452	R/R SIDE PANEL CPL REPAIR	25.0*	105.00
3992	R/R SIDE MEMBER REPAIR	10.0*	42.00
1007	MOUNT ON CAR-O-LINER REPAIR		250.00*
1004	WHEEL ALIGNMENT ALIGNMENT	15.0*	63.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		45.20	452.0
Fixed Rate			1,898.40
Alignment			250.00
Measuring Work		1.50	15.0
Total of Labour			63.00
			2,211.40

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU	Price SGD
	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
	BONNET NEW PART PAINTING	22.0	
	L/F WING NEW PART PAINTING	9.0	
	BATTERY CARRIER SURFACE PAINT	4.0	
	REAR BUMPER SUPPORT SURFACE PAINT	4.0	
	REAR PANEL NEW PART PAINTING	20.0	
	BOOTLID NEW PART PAINTING	15.0	
	L/R LAMP PANEL SURFACE PAINT	4.0	
	BOOTFLOOR CPL SURFACE PAINT	9.0	
	L/R SIDE MEMBER SURFACE PAINT	4.0	
	FRONT BUMPER NEW PART PAINT K1R	9.0	
	REAR BUMPER NEW PART PAINT K1R	9.0	
	R/F WING REPAIR PAINTING >50%	15.0	
	LEFT FRONT DOOR REPAIR PAINTING >50%	23.0	
	L/R DOOR REPAIR PAINTING >50%	20.0	
	L/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0	
	R/R SIDE PANEL CPL REPAIR PAINTING >50%	21.0	
	L/F WHEELHOUSE SURFACE PAINT	6.0	
	L/F SIDE MEMBER SURFACE PAINT	4.0	
	R/R SIDE MEMBER SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0340	FRT BUMPER SUPPORT SURFACE PAINT	2.99
0471	BONNET NEW PART PAINTING	61.26
0741	L/F WING NEW PART PAINTING	14.11
1331	BATTERY CARRIER SURFACE PAINT	0.70
2640	REAR BUMPER SUPPORT SURFACE PAINT	2.99
2711	REAR PANEL NEW PART PAINTING	20.98
2931	BOOTLID NEW PART PAINTING	34.66
3571	L/R LAMP PANEL SURFACE PAINT	0.88
3900	BOOTFLOOR CPL SURFACE PAINT	22.70
3991	L/R SIDE MEMBER SURFACE PAINT	3.87
0283	FRONT BUMPER NEW PART PAINT K1R	33.50
2583	REAR BUMPER NEW PART PAINT K1R	33.50

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING REPAIR PAINTING >50%	11.24
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	26.00
1781	L/R DOOR REPAIR PAINTING >50%	21.19
3451	L/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
3452	R/R SIDE PANEL CPL REPAIR PAINTING >50%	23.11
1117	L/F WHEELHOUSE SURFACE PAINT	9.15
1201	L/F SIDE MEMBER SURFACE PAINT	2.29
3992	R/R SIDE MEMBER SURFACE PAINT	3.87

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		227.0	
Preparation Main Work Metal	1.70	17.0	71.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	24.70	247.0

Material Cost - Paint

	Price SGD
New Part Painting	131.01
New Part Painting - Plastic K1R	67.00
Repair Painting	104.65
Surface-/Blend Paint	49.44
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	379.20

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	KNPL3		35.00
0283	FRONT BUMPER	865112H000		190.00
0315	FRT BUMPER ABSORBER	865202H010		65.00
0327	LEFT RETAINER	1491005000		18.00
0340	FRT BUMPER SUPPORT	865302H010		110.00
0471	BONNET	664002H010		430.00
0475	LEFT BONNET HINGE	791102H000		32.00
0561	LEFT HEADLAMP ASSY	921012H090		195.00
0741	L/F WING	663112H022		170.00
0811	L/F WING BADGE	863162H000		32.00
0841	L/F WHEELHOUSE COVER	868112H010		18.00
1009	INNER FRT PANEL CPL	641012H000		310.00
1331	BATTERY CARRIER	371502H100		32.00
1423	L/COWL MOULDING	861502H910		28.00
2583	REAR BUMPER	866102H000		190.00
2640	REAR BUMPER SUPPORT	866312H010		100.00
2644	REAR BUMPER DAMPER	866202H010		58.00
2702	REAR NUMBER PLATE	KNPL6		35.00
2711	REAR PANEL	691002H010		185.00
2931	BOOTLID	692002H071		320.00

Code	Description	Part Number	Supplier	Price SGD
2944	BOOT/TAILGATE SEAL	873212H000		65.00
2953	L/R HINGE	792102H000		60.00
2977	BOOT/TAILGATE LOCK	812202H000		78.00
3013	BADGE HYUNDAI	863212H000		18.00
3015	REAR MANUFACT BADGE	863002H000		18.00
3020	TYPE BADGE	863102H000		22.00
3021	VERSION BADGE	863142H000		0.00
3022	VERSION BADGE	863122H000		0.00
3023	VERSION BADGE	863152H000		0.00
3024	VERSION BADGE	863132H000		0.00
3025	VERSION BADGE	863472H000		0.00
3281	L/R OUTER LAMP	924012H010		125.00
3282	R/R OUTER LAMP	924022H010		125.00
3291	L/R INNER LAMP	924032H000		105.00
3571	L/R LAMP PANEL	715752H100		58.00
3900	BOOTFLOOR CPL	655132H010		420.00
3991	L/R SIDE MEMBER	657102H010		305.00
4985	LUGGAGE COMPART TRIM	857702H000MC		40.00
4991	L/R WHEELARCH TRIM	857302H000MC		175.00
1002	lh foglamp garnish	parts		42.00
1006	LH H/LAMP LWR BEAM	parts		22.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 4,231.00
u: Used parts				Fixed Sundry Parts Price 100.00
Total				4,331.00

Extras

Code	Description	Price SGD
1001	1ser reverse sensor parts	200.00*
1003	a/con gas	50.00*
Total Extras		250.00

Final Calculation

	SGD	SGD
Parts	4,231.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,331.00
Labour Time Base 10 WU/h		
Total 452.0 WU X 42.00 SGD/h	1,898.40	
Fixed Rate	250.00	
Alignment		
Measuring Work	63.00	
Total of Labour		2,211.40
Total Of Extras		250.00
Paint Work Time Base 10 WU/h		
Labour Cost 247.0 WU X 42.00 SGD/h	1,037.40	
Material Cost	379.20	
Total Paint Including Material		1,416.60
Repair Cost Excludes GST		8,209.00
GST (+7.0%)		574.63
Repair Cost Included GST		8,783.63

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2019 Sendback Est	23 Jul 2019 11:42 S\$8,030.10	23 Jul 2019 16:35 Edit Adj Rpt	S\$6,550.00 Edit Estimates	S\$6,550.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	19 Dec 2019 11:30	19 Dec 2019 11:32 S\$332.00	19 Dec 2019 11:32			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	WIB, Co. Reg. No.: S3377354K								
Main Claimant:	KHATIJAH BTE OSMAN, ID: S1450473G								
Vehicle Reg. No.:	SJN9882U	Date of Loss:	20/07/2019 17:00 - :59 [124 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203420C02	Policy/Cover Note No.:	DMPCSN30115919000						
Vehicle Reg. No. (Insured):	SMD4226P	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/08/2019]								
Driver/Custodian (Insured):	CHEAN YONG HONG (/ Male), NRIC: G7566994T, Tel: +6598475219 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJN9882U (SNM19D203420C02)
[SMD4226P]

TP

KHATIJAH BTE OSMAN

Jul 20 2019 5:00PM

[W18]

Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	23/07/19 11:42	Repairer Estimates		Load HTM	
2	19/12/19 11:32	Repairer Estimates Suppl. #1		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
2	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
3	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
4	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
5	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
6	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
7	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
8	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
9	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
10	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
11	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
12	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
13	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
14	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
15	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
16	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
17	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
18	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
19	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
20	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
21	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
22	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
23	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
24	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
25	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
26	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
27	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
28	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
29	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
30	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
31	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
32	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
33	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
34	12/12/19 17:12	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
35	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
36	12/12/19 17:12	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
37	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
38	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>
39	12/12/19 17:12	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
40	12/12/19 17:12	General View		<input checked="" type="checkbox"/>
41	12/12/19 17:12	General View		<input checked="" type="checkbox"/>
42	12/12/19 17:12	General View		<input checked="" type="checkbox"/>
43	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
44	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
45	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
46	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
47	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
48	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
49	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
50	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
51	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
52	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
53	12/12/19 17:16	DISMANTLE PHOTOS		<input checked="" type="checkbox"/>
54	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
55	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
56	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
57	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
58	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
59	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
60	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
61	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
62	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
63	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
64	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
65	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
66	12/12/19 17:22	RESURVEY PHOTOS		<input checked="" type="checkbox"/>
67	12/12/19 17:23	AFTER PAINT PHOTOS		<input checked="" type="checkbox"/>
68	12/12/19 17:23	AFTER PAINT PHOTOS		<input checked="" type="checkbox"/>
69	12/12/19 17:23	AFTER PAINT PHOTOS		<input checked="" type="checkbox"/>
70	12/12/19 17:23	AFTER PAINT PHOTOS		<input checked="" type="checkbox"/>
71	12/12/19 17:23	AFTER PAINT PHOTOS		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	23/07/19 11:41	E-filed GIA report		<input checked="" type="checkbox"/>
2	23/07/19 11:42	Repair Estimates		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/12/19 10:04	Supplementary		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119012989/KQF3E2

Date: 31/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30115919000
Claimant Vehicle No :	SJN9882U	Insured Vehicle No :	SMD4226P
Date of Loss:	20/07/2019	Nature of Claim: TP	Claim No: SNM19D203420C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN9882U	Engine No:	G4FC9U615476
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)	Chassis No:	KMH DU41BR9U707659
Reg. Date:	09/03/2009 (Man. Year: 2009)	Odometer:	57065 km
Colour:	Metallic Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,263.00	4,231.00	32.00	0.75
Miscellaneous Items	350.00	350.00	0.00	0.00
Labour	3,749.10	3,628.00	121.10	3.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,362.10	8,209.00	153.10	1.83
Approved Total (Overridden) (S\$)		6,550.00		
(S\$)	8,362.10	6,550.00	1,812.10	21.67
+ GST 7.00/7.00% (S\$)	585.35	458.50	126.85	21.67
Nett Amount (S\$)	8,947.45	7,008.50	1,938.95	21.67

INSPECTION

Date of Assignment:	23/07/2019	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	23/07/2019	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	18.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Dec 2019)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN9882U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*parts		4,181.00 F	*4,149.00 F
Supplementary #1						
2	1		*BATTERT TRAY	Cracked	32.00 F	*32.00 F
3	1		*LH HEADLAMP LOWER BEAM	Bent	22.00 F	*22.00 F
4	1		*BUMPER LH CORNER GARNISH	Cracked	28.00 F	*28.00 F
Total Parts (S\$)					4,263.00	4,231.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	snett	250.00	250.00
2	1	sundry (NECESSARY)	100.00	100.00
Sub Total (S\$)			350.00	350.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	panel beating	New	2,100.00	1,961.40
2	spray painting	New	1,399.10	1,416.60
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	TO MOUNT ON CAR-O-LINER	New	250.00	250.00
Gross Labour Cost (S\$)			3,749.10	3,628.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >