

ASS. REC. BY:

REF:

CS/FCI 19012996/E+130

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): CWS Gilen Lee

of FET

Date/Time: 224pm @ 23/7/19

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 1900T

Insured:

SHC 858EH

at Workshop m/s:

Carz Auto Services

Tel:

83227418

of

No. 61 woodlands Ind. Park EA #04-04

Policy No:

Claim No:

D190047 S1MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:40pm @ 23/7/19

Person Contacted:

Jurylyn

Vehicle:

IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SLU 1900T	NA/AIG/8012674/14	DOA = 11/7/18
	S1TC 858EH	CC3/FCI/6013387/Kvbn2	DOA 18/7/16
	Finalize lump sum \$15,350 (Red: 15757.93/50%)		

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 at _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No


Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 1900T Yr Regn: 29/11/17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: NISSAN QASHQAI L.C. 1197
 Colour: SLV A/C: Insured / Std / NI / NA
 Sp. Reading: 42876 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SJNFEAJ114 2092959
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Castrol
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 19/7/19 D.O.I. 23/7/19
 Survey held at Carz Auto
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time: _____ Action / Instruction

MV- 83,000
 PV- 50,054
 NV- 32,946

RECEIVED 15 AUG 2019

Date/Time, File Pass to?

11 1470 Typist

Date/Time, File Return to?

3

Report Format :

Lump Sum / I.B.I. (\$) TP

15,350

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech Insp (\$) ☐ Workshop (\$)

Survey Fee:

Transportation

1 \$ + Rm 2

1 Parking

1 Lunch

1 ...

(Total)

21x15=315

170+315

50

50+50

225

860

MOTOR SURVEY ASSIGNMENT

Date	22-07-2019	Our Ref No. D19004759MFSH
Accident Date	19-07-2019	Claim Type. Third Party
Insured Vehicle	SHC8588H	Third Party Vehicle. SLU1900T
Survey Location	NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04, E9 PREMIUM, S(757047)	
Contact Person.	JESLYN CHUA	
Contact No.	83227418/ 83227418	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CARZ AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: jeslyn@carzauto.com.sg
Sent: Thursday, 8 August 2019 11:37 AM
To: Denise Tay (LKKAuto)
Cc: SUR
Subject: RE: After Repair photos for SLU1900T

Hi Denise Tay

Good Morning

We accept the lump sum amount \$15,350/- (before 7% gst) and 9 days repair days.
Please advise us the document need to mail out to who?

Thank You.

With Regards,
Jeslyn Chua
HP: 8322 7418

-----Original Message-----

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, 7 August 2019 10:10 AM
To: jeslyn@carzauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: After Repair photos for SLU1900T

Dear Jeslyn,

Offer at lump sum \$15,350/-, 9days

Please check and confirm

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi
Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: jeslyn@carzauto.com.sg [mailto:jeslyn@carzauto.com.sg]
Sent: Friday, August 02, 2019 12:13 PM
To: Steve Chen (LKK Auto)
Cc: 'alex'
Subject: After Repair photos for SLU1900T

Hi Mr Steve

Good Afternoon

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/07/2019 13:32
Date Of Accident	19/07/2019 22:00
Exact Location Of Accident	PIE TWDS JURONG EASY BELOW JURONG EAST FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU1900T
Insured/Policyholder	
Name Of Registered Owner	ANG LIAN GUAN
NRIC No	S1630254F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83996145
Alternative Phone No	OFFICE-83996145

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700082415-01
Cover Note Number	

Driver

Name of Driver	AARON ANG KIAN HAI
NRIC No	S9616156E
Date Of Birth	10/05/1996
Occupation	INDOOR
Date Of Driving Pass	09/01/2018
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83996145
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 CHOA CHU KANG STREET 64 #12-17
Postcode	689105
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - -
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : HO LEE CHENG GENDER: : FEMALE
Passenger 2	NAME: : ALICIA ANG KAI XIN GENDER: : FEMALE
Passenger 3	NAME: : ADRIAN ANG KIAN YANG GENDER: : MALE
Passenger 4	NAME: : ANGELINE ANG KAI QI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20190720/2002.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8588H
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMG4033M
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	AARON ANG KIAN HAI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLU1900T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	HO LEE CHENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLU1900T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	ALICIA ANG KAI XIN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLU1900T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 4

Name ADRIAN ANG KIAN YANG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLU1900T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 5

Name ANGELINE ANG KAI QI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLU1900T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/7/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

SKETCH PLAN

PIE TOWARD JUPONG EAST
BELOW FLYOVER

C
A
B

VEH A
SLU 1900 T

VEH B
SHG 8588 H

VEH C
SMG 4033 M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As Per Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/PIN No.: _____



**SINGAPORE
POLICE FORCE**



T/20190720/2002

1 of 4

Report No. T/20190720/2002

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/07/2019 00:24	Vide Report No.:	Station Diary No.: 13
--	------------------	--------------------------

Informant's Particulars

Name of Informant: AARON ANG KIAN KAI			Address: 44 CHOA CHU KANG STREET 64 #12-17 SINGAPORE 689105		
ID Type / ID No.: NRIC NO / S9616156E			Contact No.: Home/Office: Mobile: 83996145		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 23	Date of Birth: 10/05/1996	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: STUDENT AT NTU			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/07/2019 22:00	Type of Location:
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Jurong East, below Jurong East Flyover				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC8588H	TAXI				Seriously Damaged	4
SLU1900T	Car				Seriously Damaged	5
SMG4033M	Car					0



**SINGAPORE
POLICE FORCE**



T/20190720/2002

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689200
Tel No: 1800-7659999

2 of 4

Report No. T/20190720/2002

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	AARON ANG KIAN KAI	ID No.	S9616156E
Related Vehicle	SLU1900T (Car)	Contact No.	83996145
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/07/2019 at about 2200hrs at PIE towards Jurong East, below Jurong East Flyover. I was driving my vehicle (SLU1900T) on a 3 lane road, at the left lane (slowest), whereby, vehicle was slowing down to turn into Jurong Town Hall Road.

I was driving behind a white car (SMG4033M), as the vehicle had come to a stop, I had to apply emergency brake to prevent hitting the vehicle in front. I managed to brake in time and did not knock onto the white car.

While doing so, I felt an impact from the rear and I realised that one Taxi (SHC8588H) whom did not stop in time knocked onto the rear of my vehicle.

Due to the impact, my vehicle inched forward and my vehicle front knocked onto the rear of the white car, however, the driver did not stop and left after leaving his contact details. The white car suffered scratches at the rear bumper.

After which, both parties alighted and exchanged particulars, and we came to an agreement that we will leave it to our insurance company to settle the issue.

I also made a check with the Taxi driver and his passengers no one was injured. My passengers and I also not injured.

Subsequently, Traffic Police and Ambulance came to scene.

After the Traffic Police Officer spoken to me and informed me that I can leave the location, and both parties left.

Due to the accident, my vehicle rear bumper dented in, and the boot is unable to close.

My car has an in car camera and it is in working condition.

The Taxi driver details
Low Yew Seng



**SINGAPORE
POLICE FORCE**



T/20190720/2002

3 of 4

Report No. T/20190720/2002

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

CONTINUATION OF REPORT

S1732699F
98769891

The White car details
Bernard
98331182



**SINGAPORE
POLICE FORCE**



T/20190720/2002

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689288
Tel No: 1800-7659999

4 of 4

Report No. T/20190720/2002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report J / Sgt 3 YONG SENG HOCK	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 20/07/2019 00:24
Officer In Charge Of Case: TR / GIT / SI ONG CHEE HIEN Contact No.: 65476437	Classification Of Case:

Authentication Stamp
NP168

Accident Sketch Plan Pg. 1



Traffic Police
AMENDMENT

Traffic Police Department
Charge Office
10 Ubi Avenue 3
S408865

NP168 No:	T/20190720/2002	Name:	Aaron Ang Kian Kai
Accident Date/Time:	19/07/2019 @ 2200hrs	Address:	Block 44 Choa Chu Kang St 64
Vehicle(s) Involved:	SHC8588H		#12-17, Singapore 689105
	SLU1900T		
	SMG4033M	NRIC No:	S9616156E
		Telephone No:	83996145
		Date:	20/07/2019

Dear Sir/Madam

I wish to amend and add as follows:

To add in that the passengers in my car and myself were issued 3 days of MC respectively.
Aaron Ang Kian Kai- S9616156E. MC ref: #188419
Ang Kai Qi Angeline- T0736402J. MC ref: #188423
Ho Lee Cheng - S7032332Z. MC ref: #188420
Ang Kian Yang Adrian - T0517820C. MC ref: #188421
Ang Kai Xin Alicia - T0220704J. MC ref: #188415

Yours faithfully

BUKIT BATOK NPC
NO. 31 BUKIT BATOK EAST AVE 4
SINGAPORE 659340
TEL: 66657999



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9616156E



Name

AARON ANG KIAN KAI

洪健凱

Race

CHINESE

Date of birth

10-05-1995

Sex

M

Country of birth
SINGAPORE



478888

NRIC No. S9616156E



Date of issue

22-08-2011

Address

44 CHOA CHU KANG STREET #4
#12-17
SINGAPORE 689106



CERTIFICATE OF INSURANCE

NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Ang Lian Guan
 Period of Insurance : 24 Nov 2018 To 23 Nov 2019
 Engine No. : HRA2516705A
 Chassis No. : SJNFEAJ11U2092959

Vehicle No. : SLU1900T
 Policy No. : 1700082415-01
 Endorsement No. :
 Issued Date : 26 Oct 2018

ABOUT THE COVER

Make/Model : NISSAN Qashqai 1.2 DIG-Turbo
 Engine Capacity/Tonnage : 1,197.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$5,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations mentioned inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188) and Section 35 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 (Own Damage) - \$500 (Theft) - \$0 (Flood Cover) - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Ang Lian Guan - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC AutoCentre Add: No. 1, Sixth Loh Yang Road Singapore 629559 6292212
2. Automobile Industrial Add: 19 Cda Road 4 Singapore 409623 6496588
3. TC AutoCentre Add: 25 Leng Kee Road Singapore 150097 67038511 67038513 67038515
4. Tan Chong Motor Sales Add: 913 Bukit Timah Road Singapore 596023 64954281 64954282 64954283
5. Tan Chong Motor Sales Add: 17 Lorong 8 Tsa Payoh Singapore 316254 63670783 63670784

For other Approved Reporting Centres/AUG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6339 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG 3G Mobile App. Simply search and download "AIG 3G" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy in which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0000010315

TAN CHONG CREDIT PTE LTD-CPH
 911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE
 SINGAPORE 596022 ANSP-MOTOR
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

00PCAN

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	254F
Vehicle Details	
Vehicle No.:	SLU1900T
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	HRA2516705A
Chassis No.:	SJNFEAJ11U2092959
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$19,750.00
Original Registration Date:	24 Nov 2017
First Registration Date:	24 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$14,750.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2027
PARF Rebate Amount:	\$11,062.00
Intended COE Rebate Details	
COE Expiry Date:	23 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$38,992.00
Total Rebate Amount:	\$50,054.00

The information contained herein is correct as at 23 Jul 2019

OK



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Insurance Company:	MS FIRST CAPITAL INSURANCE LIMITED (SINGAPORE)		
Address:	36, ROBINSON ROAD, #16-01, CITY HOUSE SINGAPORE 068877		
Telephone:	6507 3848	Fax:	6507 3849
Email:			
Make/ Model :	NISSAN QASHQAI	Date:	23/7/2019
Chassis No :	SJNFEAJUU2092959	Vehicle No:	SLU 1900 T
Date/Time of Accident :	19/7/2019 22:00		

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	BONNET X R	1	\$ 981.80	10%	\$ 883.62
2	BONNET WEATHERSTRIP OUTER X NAI	1	\$ 89.80	10%	\$ 80.82
3	BONNET LOCK X NAI	1	\$ 88.60	10%	\$ 79.74
4	BONNET LOCK CATCH TOP X NAI	1	\$ 110.20	10%	\$ 99.18
5	BONNET HINGE X NAI	2	\$ 130.60	10%	\$ 117.54
6	FRONT BUMPER / BR	1	\$ 1,855.60	10%	\$ 1,670.04
7	FRONT BUMPER SIDE RETAINER / BR nn	2	\$ 64.80	10%	\$ 58.32
8	FRONT BUMPER FOG LAMP COVER X NAI	2	\$ 241.40	10%	\$ 217.26
9	FRONT BUMPER LED LAMP / (RH) BR	2	\$ 281.90	10%	\$ 507.42
10	FRONT BUMPER LOWER X NAI	1	\$ 453.70	10%	\$ 408.33
11	FRONT BUMPER PROTECTOR X NAI	1	\$ 203.40	10%	\$ 183.06
12	FRONT BUMPER TOW HOOD COVER / CRU	1	\$ 32.60	10%	\$ 29.34
13	FRONT BUMPER SPONGE FRONT / BR	1	\$ 97.90	10%	\$ 88.11
14	FRONT BUMPER SPONGE REAR / BR	1	\$ 195.70	10%	\$ 176.13
15	FRONT BUMPER REINFORCEMENT X R	1	\$ 675.40	10%	\$ 607.86
16	FRONT BUMPER TOP BEAM X NAI	1	\$ 337.70	10%	\$ 303.93
17	FRONT BUMPER BRACKET X NAI	2	\$ 370.20	10%	\$ 333.18
18	FRONT HEAD LAMP RH / BR LH / BR	2	\$ 5,922.00	10%	\$ 5,329.80
19	FRONT HEAD LAMP LOWER BRACKET X NAI	2	\$ 77.00	10%	\$ 69.30
20	FRONT HEAD LAMP TOP PANEL X NAI	2	\$ 221.80	10%	\$ 199.62
21	FRONT RADIATOR GRILLE ASSY / CRU	1	\$ 561.20	10%	\$ 505.08
22	FRONT RADIATOR GRILLE LOGO / CRU	1	\$ 109.20	10%	\$ 98.28
23	FRONT RADIATOR GRILLE INNER FRAME / CRU	1	\$ 215.20	10%	\$ 193.68
24	FRONT SUPPORT PANEL X NAI	1	\$ 588.70	10%	\$ 529.83
25	FRONT SUPPORT PANEL TOP GARNISH X NAI	1	\$ 92.30	10%	\$ 83.07
26	FRONT SUPPORT PANEL SIDE GARNISH X NAI	2	\$ 171.80	10%	\$ 154.62
27	TAIL GATE / CRU	1	\$ 2,936.80	10%	\$ 2,643.12
28	TAIL GATE TOP LOCK / CRU	1	\$ 185.80	10%	\$ 167.22
29	TAIL GATE WEATHERSTRIP / CRU	1	\$ 165.70	10%	\$ 149.13
30	TAIL GATE INNER TRIM / CRU	1	\$ 336.50	10%	\$ 302.85
31	TAIL GATE WINDSCREEN MOULDING / NAI	1	\$ 68.90	10%	\$ 62.01

18,346.70
-19%
15,484.49 ✓

32	TAIL GATE REFLECTOR X NAI	2	\$ 431.80	10%	\$ 388.62	X
33	TAIL GATE LOGO A / APC	1	\$ 60.00	10%	\$ 54.00	✓
34	TAIL GATE LOGO GARNISH 2 / DR	1	\$ 336.00	10%	\$ 302.40	✓
35	TAIL GATE EMBLEM QASHQAI / AK	1	\$ 87.00	10%	\$ 78.30	✓
36	TAIL GATE SHOCKABSOBER X NAI	2	\$ 433.60	10%	\$ 390.24	X
37	REAR BUMPER / DD	1	\$ 878.60	10%	\$ 790.74	717 ✓
38	REAR BUMPER SIDE RETAINER / BR	2	\$ 35.90 96.60	10%	\$ 86.94	7180 ✓
39	REAR BUMPER LOWER X NAI	1	\$ 545.20	10%	\$ 490.68	X
40	REAR BUMPER LOWER TOW COVER / MIS	1	\$ 38.50	10%	\$ 34.65	✓
41	REAR BUMPER REFLECTOR RH / DR	12	\$ 65.40 130.80	10%	\$ 117.72	6540 ✓
42	REAR BUMPER REINFORCEMENT 2 / DD	1	\$ 619.20	10%	\$ 557.28	✓
43	REAR TAIL LAMP / CUT	1	\$ 647.40	10%	\$ 582.66	✓
44	REAR END PANEL 2 / DD	1	\$ 436.60	10%	\$ 392.94	✓
45	REAR END PANEL TOP GARNISH 2 / CUT	1	\$ 110.80	10%	\$ 99.72	✓
46	REAR FLOOR PANEL TOP BOARD (CUSHION) X NAI	2	\$ 174.00	10%	\$ 156.60	X
47	REAR FLOOR PANEL TOP COVER X NAI	1	\$ 394.70	10%	\$ 355.23	X
48	REAR FENDER GARNISH LH * ✓ RH / DR	2 20	\$ 966.00	10%	\$ 869.40	✓
49	REAR SILENCER BOX / DD	1	\$ 693.60	10%	\$ 624.24	✓
50	REAR SILENCER MOUNTING / TN	2 2	\$ 10.70 32.10	10%	\$ 28.89	21.48 ✓
51	REAR SILENCER INSULATOR / DD	1	\$ 90.60	10%	\$ 81.54	✓
52	REAR CENTER SILENCER X 2 / DD	1	\$ 809.30	10%	\$ 728.37	✓
53	REAR ELECTRICAL KEY SENSOR 2 X NAI	1	\$ 385.60	10%	\$ 347.04	X


SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT NUMBER PLATE / DR	1	\$ 50.00	\$ 35 50.00
2	FRONT BUMPER CLIP / APC	10	\$ 45.00	\$ 70 45.00
3	FRONT RADIATOR GRILLE CLIP / APC	5	\$ 22.50	\$ 10 22.50
4	FRONT SUPPORT PANEL TOP GARNISH CLIP X NAI	7	\$ 31.50	\$ 31.50
5	FRONT SUPPORT PANEL SIDE GARNISH CLIP X NAI	6	\$ 27.00	\$ 27.00
6	TAIL GATE WINDSCREEN SEALANT / APC	1	\$ 50.00	\$ 40 50.00
7	TAIL GATE LOGO GARNISH CLIP X NAI	6	\$ 24.60	\$ 24.60
8	REAR NUMBER PLATE / CUT	1	\$ 50.00	\$ 35 50.00
9	REAR BUMPER CLIP / APC	10	\$ 45.00	\$ 30 45.00
10	REAR TAIL LAMP CLIP X NAI	4	\$ 18.00	\$ 18.00
11	REAR END PANEL TOP GARNISH CLIP / APC	5	\$ 22.50	\$ 10 22.50
12	REAR FENDER GARNISH CLIP / APC	12	\$ 68.40	\$ 30 68.40
13	REAR REVERSE SENSOR / DR	1 SET	\$ 350.00	\$ 200 350.00
Total Cost				\$ 24,694.19

410 ✓

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 400 900.00
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1000 1,800.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TOWING (separate bill)	\$ X 60.00
TO TUFFCOAT AFFECTED AREA	\$ 50 250.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$ 100 120.00
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS	\$ X 120.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ X 120.00
TO REMOVE/ REFIX WIRING CHECKS	\$ 30 60.00
TO REMOVE/ REPLACE REAR SILENCER BOX	\$ 50 250.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 20 100.00
TO REMOVE AND RENEW REAR DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS 800	\$ 600 1,200.00
TO REMOVE AND RE-INSTALL VIDEO CAMERA	\$ 20 100.00
TO REMOVE AND REPLACE TAIL GATE MECHANISM	\$ 50 120.00
Total Others Cost	\$ 2,500.00
GRAND TOTAL	\$ 29,894.19


 Steve CLKK)
 8322 8813
 Steve.chm@lkkauto.com

W/L Archie 23/7/19, 3.30pm
 9 days
 P/P 31107-43
 Ray before spray





CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chun
 Job Title: Motor Claim
 Mobile: 65 8322 7418
 Email: jeslyn@carzauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:



CARZ AUTO SERVICES PTE LTD

UEN/GST 201409457D

61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Make/ Model :	NISSAN QASHQAI	Date:	24/7/2019
Chassis No :	SJNFEAJUU2092959	Vehicle No:	SLU 1900 T
Date/Time of Accident :	19/7/2019 22:00		

SUPPLEMENTARY PARTS

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	REAR BUMPER BRACKET / 00	2	\$ 252.00	10%	\$ 226.80
2	REAR BUMPER SPONGE X BR (Replaced Item 14)	1	\$ 126.40	10%	\$ 113.76
3	FRONT A/C CONDENSER / 00	1	\$ 685.20	10%	\$ 616.68
4	FRONT ENGINE UNDER COVER / BR	1	\$ 285.00	10%	\$ 256.50
Total Cost					\$ 1,213.74

Steve (24/7/19)

1195.20
- 10%
1075.68

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9 repair days



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 Singapore 757047
Email: alex@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

Insurance Company: MS FIRST CAPITAL INSURANCE LIMITED (SINGAPORE)

Address: 36, ROBINSON ROAD, #16-01, CITY HOUSE SINGAPORE 068877

Telephone: 6507 3848 Fax: 6507 3849 Email:

Make/ Model: NISSAN QASHQAI

Date: 23/7/2019

Chassis No: SJNFEAJUJ2092959

Vehicle No: SLU 1900 T

Date/Time of Accident: 19/7/2019 22:00

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	BONNET X R	1	\$ 981.80	10%	\$ 883.62
2	BONNET WEATHERSTRIP OUTER X	1	\$ 89.80	10%	\$ 80.82
3	BONNET LOCK X	1	\$ 88.60	10%	\$ 79.74
4	BONNET LOCK CATCH TOP X	1	\$ 110.20	10%	\$ 99.18
5	BONNET HINGE X	2	\$ 130.60	10%	\$ 117.54
6	FRONT BUMPER / BR	1	\$ 1,855.60	10%	\$ 1,670.04
7	FRONT BUMPER SIDE RETAINER / BR	2	\$ 64.80	10%	\$ 58.32
8	FRONT BUMPER FOG LAMP COVER X	2	\$ 241.40	10%	\$ 217.26
9	FRONT BUMPER LED LAMP X RH / BR	1	\$ 563.80	10%	\$ 507.42
10	FRONT BUMPER LOWER X	1	\$ 453.70	10%	\$ 408.33
11	FRONT BUMPER PROTECTOR X	1	\$ 203.40	10%	\$ 183.06
12	FRONT BUMPER TOW HOOD COVER / CRU	1	\$ 32.60	10%	\$ 29.34
13	FRONT BUMPER SPONGE FRONT / BR	1	\$ 97.90	10%	\$ 88.11
14	FRONT BUMPER SPONGE REAR / BR	1	\$ 195.70	10%	\$ 176.13
15	FRONT BUMPER REINFORCEMENT ? X R	1	\$ 675.40	10%	\$ 607.86
16	FRONT BUMPER TOP BEAM ? X	1	\$ 337.70	10%	\$ 303.93
17	FRONT BUMPER BRACKET X	2	\$ 370.20	10%	\$ 333.18
18	FRONT HEAD LAMP RH / BR LH / BR	2	\$ 5,922.00	10%	\$ 5,329.80
19	FRONT HEAD LAMP LOWER BRACKET X RH / LH / BR	2	\$ 77.00	10%	\$ 69.30
20	FRONT HEAD LAMP TOP PANEL X	2	\$ 221.80	10%	\$ 199.62
21	FRONT RADIATOR GRILLE ASSY / CRU	1	\$ 561.20	10%	\$ 505.08
22	FRONT RADIATOR GRILLE LOGO / CRU	1	\$ 109.20	10%	\$ 98.28
23	FRONT RADIATOR GRILLE INNER FRAME / CRU	1	\$ 215.20	10%	\$ 193.68
24	FRONT SUPPORT PANEL X	1	\$ 588.70	10%	\$ 529.83
25	FRONT SUPPORT PANEL TOP GARNISH X	1	\$ 92.30	10%	\$ 83.07
26	FRONT SUPPORT PANEL SIDE GARNISH X	2	\$ 171.80	10%	\$ 154.62
27	TAIL GATE / CRU	1	\$ 2,936.80	10%	\$ 2,643.12
28	TAIL GATE TOP LOCK ? / CRU	1	\$ 185.80	10%	\$ 167.22
29	TAIL GATE WEATHERSTRIP ? / CRU	1	\$ 165.70	10%	\$ 149.13
30	TAIL GATE INNER TRIM ? / BR	1	\$ 336.50	10%	\$ 302.85
31	TAIL GATE WINDSCREEN MOULDING / CRU	1	\$ 68.90	10%	\$ 62.01

32	TAIL GATE REFLECTOR X	2	\$ 431.80	10%	\$ 388.62
33	TAIL GATE LOGO ? / APC	1	\$ 60.00	10%	\$ 54.00
34	TAIL GATE LOGO GARNISH ? / DR	1	\$ 336.00	10%	\$ 302.40
35	TAIL GATE EMBLEM QASHQAI / DR	1	\$ 87.00	10%	\$ 78.30
36	TAIL GATE SHOCKABSORBER X	2	\$ 433.60	10%	\$ 390.24
37	REAR BUMPER / DD	1	\$ 878.60	10%	\$ 790.74
38	REAR BUMPER SIDE RETAINER / BR	2	\$ 35.90 96.60	10%	\$ 86.94
39	REAR BUMPER LOWER X	1	\$ 545.20	10%	\$ 490.68
40	REAR BUMPER LOWER TOW COVER / MIS	1	\$ 38.50	10%	\$ 34.65
41	REAR BUMPER REFLECTOR RH / DR	12	\$ 65.40 130.80	10%	\$ 117.72
42	REAR BUMPER REINFORCEMENT ? / DD	1	\$ 619.20	10%	\$ 557.28
43	REAR TAIL LAMP LH X RH X / CUT	12	\$ 647.40	10%	\$ 582.66
44	REAR END PANEL ? / DD	1	\$ 436.60	10%	\$ 392.94
45	REAR END PANEL TOP GARNISH ? / CR4	1	\$ 110.80	10%	\$ 99.72
46	REAR FLOOR PANEL TOP BOARD (CUSHION) X	2	\$ 174.00	10%	\$ 156.60
47	REAR FLOOR PANEL TOP COVER X	1	\$ 394.70	10%	\$ 355.23
48	REAR FENDER GARNISH LH X RH / DR	122	\$ 966.00	10%	\$ 869.40
49	REAR SILENCER BOX / DD	1	\$ 693.60	10%	\$ 624.24
50	REAR SILENCER MOUNTING / TN	2	\$ 10.70 32.10	10%	\$ 28.89
51	REAR SILENCER INSULATOR / DD	1	\$ 90.60	10%	\$ 81.54
52	REAR CENTER SILENCER X ? / DD	1	\$ 809.30	10%	\$ 728.37
53	REAR ELECTRICAL KEY SENSOR ? X	1	\$ 385.60	10%	\$ 347.04

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT NUMBER PLATE / DR	1	\$ 50.00	\$ 35 50.00
2	FRONT BUMPER CLIP / APC	10	\$ 45.00	\$ 90 45.00
3	FRONT RADIATOR GRILLE CLIP / DR	5	\$ 22.50	\$ 10 22.50
4	FRONT SUPPORT PANEL TOP GARNISH CLIP X	7	\$ 31.50	\$ 31.50
5	FRONT SUPPORT PANEL SIDE GARNISH CLIP X	6	\$ 27.00	\$ 27.00
6	TAIL GATE WINDSCREEN SEALANT / APC	1	\$ 50.00	\$ 40 50.00
7	TAIL GATE LOGO GARNISH CLIP X	6	\$ 24.60	\$ 24.60
8	REAR NUMBER PLATE / CUT	1	\$ 50.00	\$ 35 50.00
9	REAR BUMPER CLIP / APC	10	\$ 45.00	\$ 50 45.00
10	REAR TAIL LAMP CLIP X	4	\$ 18.00	\$ 18.00
11	REAR END PANEL TOP GARNISH CLIP / APC	5	\$ 22.50	\$ 10 22.50
12	REAR FENDER GARNISH CLIP / DR	12	\$ 68.40	\$ 80 68.40
13	REAR REVERSE SENSOR / DR	1 SET	\$ 350.00	\$ 200 350.00
Total Cost				\$ 24,694.19

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 400 900.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1000 1,800.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TOWING (separate bill)	\$ X 60.00
TO TUFFCOAT AFFECTED AREA	\$ 50 250.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$ 100 120.00
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS	\$ X 120.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ X 120.00
TO REMOVE/ REFIX WIRING CHECKS	\$ 30 60.00
TO REMOVE/ REPLACE REAR SILENCER BOX	\$ 50 250.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 20 100.00
TO REMOVE AND RENEW REAR DAMAGED PARTS; REPLACE REALIGNED ALL AFFECTED PARTS 800	\$ 600 1,200.00
TO REMOVE AND RE-INSTALL VIDEO CAMERA	\$ 20 100.00
TO REMOVE AND REPLACE TAIL GATE MECHANISM	\$ 50 120.00
Total Others Cost	\$ 2,500.00
GRAND TOTAL	\$ 29,894.19




Steve CLKK
8322 8813
steve.chm@1kkauto.com

W/L Repaire 23/7/19, 3.30pm
9 days
P/P C/S
Ray before spy

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Job Title: Motor Claim
Mobile: 65 8322 7418
Email: jeslyn@carzauto.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19012996/Etd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8588H	Veh. Inspected	SLU 1900T
Policy No.		Coverage (\$)	0.00
Claim No.	D19004759MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	23/07/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFEAJ11U2092959	Colour	SILVER
Odometer	42876	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/07/2019	Inspection Date	23/07/2019
Survey held at	NO.61 WOODLAND IND PARK E9 #04-04		
Repairer	CARZ AUTO SERVICES PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 1900T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	981.80	-
1	BONNET WEATHERSTRIP OUTER	NOT NECESSARY	89.80	-
1	BONNET LOCK	NOT NECESSARY	88.60	-
1	BONNET LOCK CATCH TOP	NOT NECESSARY	110.20	-
2	BONNET HINGE	NOT NECESSARY	130.60	-
1	FRONT BUMPER	BROKEN	1,855.60	630.00
2	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	64.80	-
2	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	241.40	-
2	FRONT BUMPER LED LAMP	O/S BROKEN	563.80	281.90
1	FRONT BUMPER LOWER	NOT NECESSARY	453.70	-
1	FRONT BUMPER PROTECTOR	NOT NECESSARY	203.40	-
1	FRONT BUMPER TOW HOOD COVER	CRUSHED	32.60	32.60
1	FRONT BUMPER SPONGE FRONT	BROKEN	97.90	97.90
1	BUMPER SPONGE REAR	BROKEN	195.70	126.40
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	675.40	-
1	FRONT BUMPER TOP BEAM	NOT NECESSARY	337.70	-
2	FRONT BUMPER BRACKET	NOT NECESSARY	370.20	-
2	FRONT HEAD LAMP	BROKEN	5,922.00	5,500.00
2	FRONT HEAD LAMP LOWER BRACKET	NOT NECESSARY	77.00	-
2	FRONT HEAD LAMP TOP PANEL	NOT NECESSARY	221.80	-
1	FRONT RADIATOR GRILLE ASSY	CUT	561.20	461.00
1	FRONT RADIATOR GRILLE LOGO	CUT	109.20	73.60
1	FRONT RADIATOR GRILLE INNER FRAME	CRUSHED	215.20	215.20
1	FRONT SUPPORT PANEL	NOT NECESSARY	588.70	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	92.30	-
2	FRONT SUPPORT PANEL SIDE GARNISH	NOT NECESSARY	171.80	-
1	TAIL GATE	DENTED	2,936.80	2,936.80
1	TAIL GATE TOP LOCK	BENT	185.80	185.80
1	TAIL GATE WEATHERSTRIP	CRUSHED	165.70	165.70

Report Ref No. CS/FCI19012996/Etd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL GATE INNER TRIM	BROKEN	336.50	336.50
1	TAIL GATE WINDSCREEN MOULDING	NECESSARY	68.90	68.90
2	TAIL GATE REFLECTOR	NOT NECESSARY	431.80	-
1	TAIL GATE LOGO	NECESSARY	60.00	60.00
1	TAIL GATE LOGO GARNISH	BROKEN	336.00	336.00
1	TAIL GATE EMBLEM QASHQAI	NECESSARY	87.00	87.00
2	TAIL GATE SHOCK ABSORBER	NOT NECESSARY	433.60	-
1	REAR BUMPER	DENTED	878.60	717.00
2	REAR BUMPER SIDE RETAINER	BROKEN	96.60	71.80
1	REAR BUMPER LOWER	NOT NECESSARY	545.20	-
1	REAR BUMPER LOWER TOW COVER	MISSING	38.50	38.50
2	REAR BUMPER REFLECTOR	O/S BROKEN	130.80	65.40
1	REAR BUMPER REINFORCEMENT	DENTED	619.20	619.20
1	REAR TAIL LAMP	CUT	647.40	647.40
1	REAR END PANEL	DENTED	436.60	436.60
1	REAR END PANEL TOP GARNISH	CRUSHED	110.80	110.80
2	REAR FLOOR PANEL TOP BOARD (CUSHION)	NOT NECESSARY	174.00	-
1	REAR FLOOR PANEL TOP COVER	NOT NECESSARY	394.70	-
2	REAR FENDER GARNISH	BROKEN	966.00	966.00
1	REAR SILENCER BOX	DENTED	693.60	693.60
3	REAR SILENCER MOUNTING	TORN - 2PCS ONLY	32.10	21.40
1	REAR SILENCER INSULATOR	DENTED	90.60	90.60
1	REAR CENTER SILENCER	DENTED	809.30	809.30
1	REAR ELECTRICAL KEY SENSOR	NOT NECESSARY	385.60	-
2	REAR BUMPER BRACKET (ADDITIONAL)	DENTED	252.00	252.00
1	REAR BUMPER SPONGE (ADDITIONAL)	REPEATED	126.40	-
1	FRONT A/C CONDENSER (ADDITIONAL)	DENTED	685.20	658.20
1	FRONT ENGINE UNDER COVER (ADDITIONAL)	BROKEN	285.00	285.00
	LESS 10% DISCOUNT		-2,789.27	-1,807.81
			25,103.43	16,270.29
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BROKEN	50.00	35.00
10	FRONT BUMPER CLIP (SN)	NECESSARY	45.00	30.00

Report Ref No. CS/FCI19012996/Etd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
5	FRONT RADIATOR GRILLE CLIP (SN)	NECESSARY	22.50	10.00
7	FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	31.50	-
6	FRONT SUPPORT PANEL SIDE GARNISH CLIP (SN)	NOT NECESSARY	27.00	-
1	TAIL GATE WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
6	TAIL GATE LOGO GARNISH CLIP (SN)	NOT NECESSARY	24.60	-
1	REAR NUMBER PLATE (SN)	CUT	50.00	35.00
10	REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
4	REAR TAIL LAMP CLIP (SN)	NOT NECESSARY	18.00	-
5	REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	22.50	10.00
12	REAR FENDER GARNISH CLIP (SN)	NECESSARY	68.40	20.00
1	SET REAR REVERSE SENSOR (SN)	BROKEN	350.00	200.00
			804.50	410.00
	LABOUR			
	TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF BONNET AND FRONT BUMPER REINFORCEMENT.		900.00	400.00
	TO RESPRAY AFFECTED AREAS.		1,800.00	1,000.00
	TOWING.	NOT NECESSARY	60.00	-
	TO TUFFCOAT AFFECTED AREA.		250.00	50.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		120.00	100.00
	TO REMOVE / REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS.	NOT NECESSARY	120.00	-
	TO REMOVE / REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	120.00	-
	TO REMOVE / REFIX WIRING CHECKS.		60.00	30.00
	TO REMOVE / REPLACE REAR SILENCER BOX.		250.00	50.00
	TO REMOVE / REPLACE REVERSE SENSORS.		100.00	20.00
	TO REMOVE AND RENEW REAR DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED AREAS.		1,200.00	800.00
	TO REMOVE AND RE-INSTALL VIDEO CAMERA.		100.00	20.00
	TO REMOVE AND REPLACE TAIL GATE MECHANISM.		120.00	50.00
			5,200.00	2,520.00
GRAND TOTAL			31,107.93	19,200.29

Report Ref No. CS/FCI19012996/Etd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,350.00
---	--	--	--	-----------

Report Ref No. CS/FCI19012996/Etd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.