

22/07/2019

ASS. REC. BY:

REF:

CS3/119/19013007/Kcd3²

Special Instruction:

Supervisor:

Chin Lee Ying

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

MIG

Date/Time:

23/7/19 @ 4:54pm

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 571R

Insured:

SLC1084T

at Workshop in/s

Khek Joo Motor

Tel:

9616 6658

of

Blk 9004, Tampines St-93 #01-94

Policy No:

2100463856

Claim No:

986302205986

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/07/2019

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5:08pm 23/7/19

Person Contacted:

Mr. Ng

Vehicle:

IN OUT

Date/Time	Action/Instruction	Voluntary X
	SLC1084T - CS/FCI/19012001 / RIVF3	DOA 4/7/19
	SLB571R - NA/lpc 19006386 / 21	DOA 7/1/2019
	Dismantle: 25/7/2019	

PRS

ASSIGNMENT

From:

Date:

24/7/19

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SIC1084T

at Workshop m/s

KheK JOO Motor

of

B11c9004, tumpines st. 93 #01-94

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Mr. Ng @ 96166658

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12.8

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{cap}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLB571R

Yr Regn:

26 Mar 2016

Type: ☒ M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Qashqai

1.2

c.c

1197

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

76728

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SJNFEAJ114.1606590

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

215/60R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental (Rear ~~AT~~)

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24-07-19

Survey held at

w/s

11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~\$7000 - \$8000~~

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

12

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + PS: \$

Photo:

Other:

TOTAL

Report Format:

DAR

Lump Sum / L.B.C. /

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2019 Edit Reg		23 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by adjuster]	
Insured:	TERESA LIM LAY HONG, ID: S0508648E								
Main Claimant:	NG BOON PENG, ID: S0508648E								
Vehicle Reg. No.:	SLB571R			Date of Loss:	20/07/2019 22:00 - :59				
Claim Type:	TP / 9863022059SG			Policy/Cover Note No.:	2100463856 (Comprehensive)				
Vehicle Reg. No. (Insured):	SLC1084T			Policy No. (Claimant):					
				Excess:					
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/08/2019]								
Claimant's Solicitor:	TOMMY CHOO, MARK GO LLC - Tel: 65322455								
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
AIG_SG (24/07/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS								View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLC1084T AND SLB571R ON 20/07/2019

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: Tuesday, 23 July, 2019 4:54:40 PM
Attachments:  PRI - SLB 571 R - (AIG) - dtd 23.07.2019.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: thling@tcmg.com.sg

Our Ref: TCMG/SLB571R/0719/KJM

Your Ref: SLC 1084 T

23 July 2019

BY E-MAIL ONLY
(shengyang.lim@aig.com)

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way#07-16

AIG Building

Singapore 079120

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Ng Boon Peng**, the owner and/or driver of motor vehicle no. **SLB 571 R**, which was involved in an accident along Junction of Commonwealth Drive & Queensway on 20 July 2019 at 22:00 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SLC 1084 T** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Khek Joo Motor, (Block 9004, Tampines Street 93 #01-94, Singapore 528838 – Mr Ng Wee Khiang @ 9616 6658).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,


MR LING LEONG HUI

cc. M/s Khek Joo Motor
(Your ref: SLB 571 R)

BY E-MAIL ONLY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/07/2019 11:49
Date Of Accident	20/07/2019 22:00
Exact Location Of Accident	JUNCTION OF COMMONWEALTH DRIVE & QUEENSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB571R
Insured/Policyholder	
Name Of Registered Owner	NG BOON PENG
NRIC No	S0508648E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90259429
Alternative Phone No	OTHERS-97501136

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800023508
Cover Note Number	

Driver

Name of Driver	NG WEI JUN, IVAN
NRIC No	S8802451F
Date Of Birth	21/01/1988
Occupation	INDOOR
Date Of Driving Pass	02/08/2008
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97501136
Fax Number	
Contact Number	
Email Address	IVANNWJ@GMAIL.COM

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NG WEI JUN, IVAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLB571R
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name CAROL NG MUI KIM
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLB571R
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 3

Name JACOB YEO KANG WEN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLB571R
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report.

Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Reporting Centre Personnel's Signature
Name: *DEWEN*
NRIC/FIN No.:

22/2/19
11:29am



**SINGAPORE
POLICE FORCE**



T/20190721/2009

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3

Report No. T/20190721/2009

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NG WEI JUN, IVAN	ID No.	S8802451F
Related Vehicle	SLB571R (Car)	Contact No.	97501136
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	20/07/2019	Date Discharge	20/07/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Theresa Lim	ID No.	NIL
Related Vehicle	SLC1084T (Car)	Contact No.	97646343
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On the mentioned date and time, I was driving along Commonwealth Drive stopping at first lane before T-junction of Queensway. There was also vehicle on the second lane. When the traffic light turned green for our right of way, the drivers drove on turning left into Queensway. However, before I could complete the left turn, the car SLC1084T came from the adjacent (Queensway) collided to the right side of my car.

My nephew and I were having some pain and we were conveyed to NUH by ambulance. My nephew was Jacob Yeo Kang Wen (NRIC: T0427452G) HP: 87207525.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	648E
Vehicle No.:	SLB571R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	HRA2246395A
Chassis No.:	SJNFEAJ11U1606590
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,974.00
Original Registration Date:	26 Mar 2016
First Registration Date:	26 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$13,974.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2026
PARF Rebate Amount:	\$10,480.00
COE Expiry Date:	25 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$30,012.00
Total Rebate Amount:	\$40,492.00

The information contained herein is correct as at 24 Jul 2019

OK

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CRA	/	
1005	992341	Frt Bumper Clips	NGC	/	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	CRA	/	2
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA	/	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA	/	
1022	991328	Frt Grille Emblem	NGC	/	
1023	991799	Frt Grille Chrome Moulding	CRA	/	
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT	/	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn	CRA	/	
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA	/	
1030	991821	Frt RH Headlamp Assy	CRA	/	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BT	/	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator	NGC	/	
1037	990273	Bonnet Flange	BT	/	2
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	BT	/	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator Side Garnish	CRA	/	
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank	CRA	/	
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold	CRA	/	
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No:

SLB 571R

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	CRA	/	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover	CRA	/	
1085	991011	Engine Under Cover	BT	/	
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member	Repair	X	
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector	NGC	/	
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BT	/	
1106	991739	Frt RH Fender Inner Panel	NGC	/	
1107	991744	Frt RH Fender Lamp	CRA	/	
1108	991752	Frt RH Fender Protector	CRA	/	
1109	991740	Frt RH Fender Inner Shield	BT	/	
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim	CRA	/	
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor	Act	/	
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit	Act	/	
1132	990864	Frt Driver Seat	Act	/	
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		oil cooler	BT	/	
		Driver seat Airbag	Act	/	
		Rear RH Door window	Act	/	

29/7/19

Condition Legend:
 (1) Bent (2) Bent (3) Distorted (4) Cracked (5) Bent (6) Scratched
 (7) Deformed (8) Stuffed (9) Buckled (10) Broken (11) Necessary (12) Missing
 (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACTION TAG
 (1) Replace (✓) (2) Repair (X) (3) Check (✓)
 (4) Not Consistent (INC)

Vehicle No: **SLB571R**

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	Repair	X	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board	CRA		
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel Trim	Crump		
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag	Act		
1314	994084	Roof Top Air-bag Sensor	Act		
1315	994083	Roof Top Air-bag Control Unit	Act		
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

(01)Item (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Turn (14)Unconfirmed (15)Not Working

MOTOR CAR (UC)

(1)Repiece (✓) (2)Repair (A) (3)Check (✓)
(4)Not Consistent (NC)

Vehicle No: SB571R

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1410	990534	Centre Exhaust Pipe Assy			
1411	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			

No of Items: _____

Assessor: _____

Original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2019 Edit Reg		23 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TERESA LIM LAY HONG, ID: S0508648E, Tel: +6599999999		
Main Claimant:	NG BOON PENG, ID: S0508648E		
Vehicle Reg. No.:	SLB571R	Date of Loss:	20/07/2019 22:00 - :59 [39 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9863022059SG	Policy/Cover Note No.:	2100463856 (Comprehensive)
Vehicle Reg. No. (Insured):	SLC1084T	Policy No. (Claimant):	
		Excess:	
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/08/2019]		
Claimant's Solicitor:	TOMMY CHOO, MARK GO LLC - Tel: 65322455		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (24/07/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB571R (9863022059SG)**
[SLC1084T]
TP
NG BOON PENG
Jul 20 2019 10:00PM
[TERESA LIM LAY HONG]
Khek Joo Motor Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/07/19 15:55	General View	 Load JPG	☒
2	29/07/19 15:55	General View	 Load JPG	☒
3	29/07/19 15:55	General View	 Load JPG	☒
4	29/07/19 15:55	General View	 Load JPG	☒
5	29/07/19 15:55	General View	 Load JPG	☒
6	29/07/19 15:55	General View	 Load JPG	☒
7	29/07/19 15:55	General View	 Load JPG	☒
8	29/07/19 15:55	General View	 Load JPG	☒
9	29/07/19 15:55	General View	 Load JPG	☒
10	29/07/19 15:55	General View	 Load JPG	☒
11	29/07/19 15:55	General View	 Load JPG	☒
12	29/07/19 15:55	General View	 Load JPG	☒
13	29/07/19 15:55	General View	 Load JPG	☒
14	29/07/19 15:55	General View	 Load JPG	☒
15	29/07/19 15:55	General View	 Load JPG	☒
16	29/07/19 15:55	General View	 Load JPG	☒
17	29/07/19 15:55	General View	 Load JPG	☒
18	29/07/19 15:55	General View	 Load JPG	☒
19	29/07/19 15:55	General View	 Load JPG	☒
20	29/07/19 15:55	General View	 Load JPG	☒
21	29/07/19 15:55	General View	 Load JPG	☒
22	29/07/19 15:55	General View	 Load JPG	☒
23	29/07/19 15:55	General View	 Load JPG	☒
24	29/07/19 15:55	General View	 Load JPG	☒
25	29/07/19 15:55	General View	 Load JPG	☒
26	29/07/19 15:55	General View	 Load JPG	☒
27	29/07/19 15:55	General View	 Load JPG	☒
28	29/07/19 15:55	General View	 Load JPG	☒
29	29/07/19 15:55	General View	 Load JPG	☒
30	29/07/19 15:55	General View	 Load JPG	☒
31	29/07/19 15:55	General View	 Load JPG	☒
32	29/07/19 15:55	General View	 Load JPG	☒
33	29/07/19 15:55	General View	 Load JPG	☒
34	29/07/19 15:55	General View	 Load JPG	☒
35	29/07/19 15:55	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	29/07/19 15:55	General View	 Load JPG	☒
37	29/07/19 15:55	General View	 Load JPG	☒
38	29/07/19 15:55	General View	 Load JPG	☒
39	29/07/19 15:55	General View	 Load JPG	☒
40	29/07/19 15:55	General View	 Load JPG	☒
41	29/07/19 15:55	General View	 Load JPG	☒
42	29/07/19 15:55	General View	 Load JPG	☒
43	29/07/19 15:55	General View	 Load JPG	☒
44	29/07/19 15:55	General View	 Load JPG	☒
45	29/07/19 15:55	General View	 Load JPG	☒
46	29/07/19 15:55	General View	 Load JPG	☒
47	29/07/19 15:55	General View	 Load JPG	☒
48	29/07/19 15:55	General View	 Load JPG	☒
49	29/07/19 15:55	General View	 Load JPG	☒
50	29/07/19 15:55	General View	 Load JPG	☒
51	29/07/19 15:55	General View	 Load JPG	☒
52	29/07/19 15:55	General View	 Load JPG	☒
53	29/07/19 15:55	General View	 Load JPG	☒
54	29/07/19 15:55	General View	 Load JPG	☒
55	29/07/19 15:55	General View	 Load JPG	☒
56	29/07/19 15:55	General View	 Load JPG	☒
57	29/07/19 15:55	General View	 Load JPG	☒
58	29/07/19 15:55	General View	 Load JPG	☒
59	29/07/19 15:55	General View	 Load JPG	☒
60	29/07/19 15:55	General View	 Load JPG	☒
61	29/07/19 15:55	General View	 Load JPG	☒
62	29/07/19 15:55	General View	 Load JPG	☒
63	29/07/19 15:55	General View	 Load JPG	☒
64	29/07/19 15:55	General View	 Load JPG	☒
65	29/07/19 15:55	General View	 Load JPG	☒
66	29/07/19 15:55	General View	 Load JPG	☒
67	29/07/19 15:55	General View	 Load JPG	☒
68	29/07/19 15:55	General View	 Load JPG	☒
69	29/07/19 15:55	General View	 Load JPG	☒
70	29/07/19 15:55	General View	 Load JPG	☒
71	29/07/19 15:55	General View	 Load JPG	☒
72	29/07/19 15:55	General View	 Load JPG	☒
73	29/07/19 15:55	General View	 Load JPG	☒
74	29/07/19 15:55	General View	 Load JPG	☒
75	29/07/19 15:55	General View	 Load JPG	☒
76	29/07/19 15:55	General View	 Load JPG	☒
77	29/07/19 15:55	General View	 Load JPG	☒
78	29/07/19 15:55	General View	 Load JPG	☒
79	29/07/19 15:55	General View	 Load JPG	☒
80	29/07/19 15:55	General View	 Load JPG	☒
81	29/07/19 15:55	General View	 Load JPG	☒
82	29/07/19 15:55	General View	 Load JPG	☒
83	29/07/19 15:55	General View	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	29/07/19 15:55	General View	 Load JPG	☒
85	29/07/19 15:55	General View	 Load JPG	☒
86	29/07/19 15:55	General View	 Load JPG	☒
87	29/07/19 15:55	General View	 Load JPG	☒
88	29/07/19 15:55	General View	 Load JPG	☒
89	29/07/19 15:55	General View	 Load JPG	☒
90	29/07/19 15:55	General View	 Load JPG	☒
91	29/07/19 15:55	General View	 Load JPG	☒
92	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
93	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
94	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
95	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
96	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
97	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
98	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
99	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
100	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
101	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
102	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
103	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
104	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
105	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
106	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
107	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
108	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
109	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
110	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
111	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
112	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
113	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
114	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
115	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
116	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
117	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
118	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
119	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
120	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
121	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
122	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
123	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
124	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
125	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
126	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
127	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
128	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
129	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
130	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
131	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
132	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
133	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
134	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
135	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
136	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
137	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
138	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
139	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
140	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
141	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
142	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
143	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
144	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
145	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
146	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
147	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
148	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
149	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
150	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
151	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
152	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
153	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
154	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
155	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
156	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
157	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
158	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
159	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
160	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
161	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
162	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
163	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
164	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
165	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
166	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
167	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
168	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
169	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
170	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
171	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
172	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
173	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
174	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
175	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
176	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
177	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
178	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	☒
179	29/07/19 15:57	Photographs of Damaged Parts	Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
180	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
181	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
182	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
183	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
184	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
185	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
186	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
187	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
188	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
189	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
190	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
191	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
192	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
193	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
194	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
195	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
196	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
197	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
198	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
199	29/07/19 15:57	Photographs of Damaged Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/07/19 09:18	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19013007/GCD3S2
 Date: 01/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100463856
 Claimant Vehicle No: SLB571R Insured Vehicle No: SLC1084T
 Date of Loss: 20/07/2019 Nature of Claim: TP Claim No: 9863022059SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB571R
 Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: HRA2246395A
 Reg. Date: 26/03/2016 (Man. Year: 2016) Chassis No: SJNFEAJ11U1606590
 Colour: Blue Odometer: 76728 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/07/2019
 Date Inspected: 24/07/2019 Inspected At: Khok Joo Motor Workshop (HQ)
 BLK 9004 TAMPINES STREET 93 #01-94
 Singapore 528838
 Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*-F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	2		*FRT BUMPER SIDE RETAINER	Cut	0.00 F	*-F
4	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*-F
5	1		*FRT GRILLE	Cut	0.00 F	*-F
6	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*-F
7	1		*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*-F
8	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
9	1		*HORN	Cracked	0.00 F	*-F
10	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*-F
11	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*-F
12	1		*BONNET	Bent	0.00 F	*-F
13	1		*BONNET INSULATOR CLIPS	Necessary	0.00 F	*-F
14	2		*BONNET HINGE	Bent	0.00 F	*-F
15	1		*AIR CON CONDENSER	Bent	0.00 F	*-F
16	1		*RADIATOR SIDE GARNISH	Cracked	0.00 F	*-F
17	1		*RADIATOR EXPANSION TANK	Cracked	0.00 F	*-F
18	1		*FRT EXHAUST MANIFOLD	Cracked	0.00 F	*-F
19	1		*WIPER WASHER TANK	Cracked	0.00 F	*-F
20	1		*ENGINE OIL TANK	Cracked	0.00 F	*-F
21	1		*ENGINE UNDER COVER	Deformed	0.00 F	*-F
22	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*-F
23	1		*FRT LH FENDER PROTECTOR	Missing	0.00 F	*-F
24	1		*FRT RH FENDER	Buckled	0.00 F	*-F
25	1		*FRT RH FENDER INNER PANEL	Buckled	0.00 F	*-F
26	1		*FRT RH FENDER GARNISH	Cracked	0.00 F	*-F
27	1		*FRT RH FENDER PROTECTOR	Cut	0.00 F	*-F
28	1		*FRT RH FENDER INNER SHIELD	Torn	0.00 F	*-F
29	1		*FRT RH WHEEL RIM	Cut	0.00 F	*-F
30	1		*AIRBAG SENSOR	Activated	0.00 F	*-F
31	1		*AIRBAG CONTROL UNIT	Activated	0.00 F	*-F
32	1		*FRT DRIVER SEAT BELT	Activated	0.00 F	*-F
33	1		*OIL COOLER	Bent	0.00 F	*-F
34	1		*DRIVER SEAT AIRBAG	Activated	0.00 F	*-F
35	1		*FRT RH DOOR	Repair	0.00 F	*-F
36	1		*FRT RH DOOR INNER TRIM BOARD	Cracked	0.00 F	*-F
37	1		*ROOF TOP PANEL TRIM	Crumpled	0.00 F	*-F
38	1		*ROOF TOP AIR-BAG	Activated	0.00 F	*-F
39	1		*ROOF TOP AIR-BAG SENSOR	Activated	0.00 F	*-F
40	1		*ROOF TOP AIR-BAG CONTROL UNIT	Activated	0.00 F	*-F
41	1		*FRT ANTI ROLL BAR	*Check	0.00 F	*-F
42	1		*FRT ANTI ROLL BAR LINKAGE	*Check	0.00 F	*-F
43	1		*FRT RH SHOCK ABSORBER	*Check	0.00 F	*-F
44	1		*FRT RH KNUCKLE ARM	*Check	0.00 F	*-F
45	1		*FRT RH KNUCKLE ARM BEARING	Necessary	0.00 F	*-F
46	1		*FRT RH LOWER ARM	*Check	0.00 F	*-F
47	1		*FRT RH TIE ROD	*Check	0.00 F	*-F

F=Franchise part.

Total Parts (\$\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >