

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 22/07/2019

TP Veh Reg No: SLL3187U

Estimate No: ES1991780/YISHUN

Date: 23 Jul 2019

Policy No: 5035075476-10

Veh Reg No: SGU9641Y

Make/Model: HONDA FIT 1.3 (A)

Chassis No: GD12407754

Engine No: L13A2332599

Reg. Date: 30/05/2007

Estimate Repair Cost to Vehicle No :SGU9641Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	470.90	1 PC	470.90	✓
2 REAR BUMPER SIDE RETAINER	13.70	2 PC	27.40	✓
3 REAR BUMPER CLIP	3.90	5 PC	19.50	✓
4 REAR TAILGATE	849.50	1 PC	849.50	✓
5 TAILGATE INNER LOCK	119.40	1 PC	119.40	✓
6 TAILGATE INNER RUBBER	97.40	1 PC	97.40	5081a
7 TAILGATE EMBLEM 'FIT'	28.80	1 PC	28.80	✓
8 TAILGATE OUTER GARNISH	120.40	1 PC	120.40	?
9 TAILGATE WINDSCREEN GLASS MOULDING	46.50	1 SET	46.50	✓
10 TAILLAMP	243.10	2 PC	486.20	✓
11 REAR END PANEL	296.40	1 PC	296.40	✓
12 REAR END PANEL INNER TOP GARNISH	63.40	1 PC	63.40	✓
13 REAR END PANEL INNER TOP GARNISH CLIP	4.30	3 PC	12.90	✓
14 REAR FENDER	613.80	2 PC	1,227.60	4
15 REAR FENDER LOWER INNER GARNISH	158.60	2 PC	317.20	2+
16 REAR FENDER LOWER INNER GARNISH CLIPS	4.30	10 PC	43.00	?
17 REAR SPARE TYRE COMPARTMENT PANEL	737.40	1 PC	737.40	?
18 REAR SPARE TYRE TOP BOARD	195.40	1 PC	195.40	✓
19 REAR DOOR	896.50	2 PC	1,793.00	✓
20 REAR DOOR INNER RUBBER	82.60	2 PC	165.20	5081a
21 REAR DOOR INNER LOCK	230.60	2 PC	461.20	✓
22 REAR DOOR INNER TRIM BOARD	453.10	2 PC	906.20	✓
23 REAR DOOR FRAME STICKERS	30.70	2 SET	61.40	✓
24 REAR DOOR FRAME INNER RUBBERS	80.90	2 PC	161.80	?
			8,708.10	
		Less 20%	1,741.62	6,966.48
Special Net				
25 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
26 REVERSE SENSOR	200.00	1 SET	200.00	✓
27 REAR WINDSCREEN GLASS SEALANT	40.00	1 UNIT	40.00	✓
28 REAR FENDER GLASS SEALANT	60.00	2 UNITS	120.00	4 4081a
29 REAR SPARE TYRE PANEL TOP COAT	100.00	1 UNIT	100.00	✓
			495.00	495.00
Labour				
30 TOWING	50.00	1 LA	50.00	✓
31 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 22/07/2019
TP Veh Reg No: SLL3187U

Estimate No: ES1991780/YISHUN
Date: 23 Jul 2019
Policy No: 5035075476-10
Veh Reg No: SGU9641Y
Make/Model: HONDA FIT 1.3 (A)
Chassis No: GD12407754
Engine No: L13A2332599
Reg. Date: 30/05/2007

Estimate Repair Cost to Vehicle No :SGU9641Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
32 REMOVE & REFIX REAR BOTH FENDER QUARTER GLASSES	100.00	1 LA	100.00	80 ✓
33 REMOVE & REFIX REAR BUMPER, TAILGATE & SPOILER & ATTACHMENTS, TAIL LAMPS, REAR BOTH DOORS & ATTACHMENTS; TO CUT, WELD & RENEW REAR END PANEL, REAR SPARE TYRE PANEL, BOTH FENDERS; KNOCKING & REPAIR BOTH CHASSIS FRAMES & REALIGN THE SAME	1,800.00	1 LA	1,800.00	1600 ✓
34 PUTTY & RESPRAY REAR BUMPER, TAILGATE & SPOILER, ROOF PANEL, BOTH FENDERS, REAR END PANEL, REAR SPARE TYRE PANEL, BOTH REAR DOORS, FRT RH DOOR, BOTH CHASSIS FRAMES & ALL AFFECTED AREAS	1,800.00	1 LA	1,800.00	1600 ✓
35 REMOVE & REFIX BOTH REAR DOORS WINDOW GLASSES & RESET CENTRAL LOCKING	120.00	1 LA	120.00	✓
36 REMOVE & REFIX TOP ROOF LINING, CARPET, SEAT GARNISHES TO FACILITATE REPAIR	120.00	1 LA	120.00	✓
37 TO MOUNT ON CAR-O-LINER, JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
38 REMOVE & REFIX FUEL TANK ASSY TO FACILITATE REPAIR	80.00	1 LA	80.00	60 ✓
39 RUSTPROOFING	180.00	1 LA	180.00	✓
			4,620.00	4,620.00
Total				S\$ 12,081.48
Add GST @ 7%				845.70
Total Amount Payable				S\$ 12,927.18

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: