

**CHARN'S CUSTOMCRAFT**  
**1010 Bukit Merah Lane 3,**  
**159724**

**Claim Reference:**

**Assessment number: 011393**

**Version: 1810**

**Date calculated: 23/07/2019 5:00 PM**

**Full Report**

**Registration: SKP8578H**

**Printed: 23/07/2019 5:00 PM**

**Summary Information**

**Claim**

Location: Singapore (SG)

Printed by: Sharon Lee

Claim Reference:

Estimated Repair Time:

Actual Repair Days:

Work Provider:

Currency:

Date of Incident:

Hire Car Start:

Hire Car End:

AXA Insurance Pte Ltd

SGD

**Vehicle Details**

**Vehicle**

Manufacturer:

SUZUKI

Model:

SWIFT

Sub Model:

GLX

Model Sheet Number:

50 24 12

Registration:

SKP8578H

VIN number:

Odometer:

**Model Specs**

SINGAPORE VERSION

5-DOOR

PRODUCTION IN JAPAN

**LKK Auto Consultants hence notify**

**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**

Taufik 97495749  
- WP'

29/7/19 @ 230 pm

sure@lkkauto.com

taufik@lkkauto.com

6-7 days humpun

Resurvey after repair

**CHARN'S CUSTOMCRAFT**  
**1010 Bukit Merah Lane 3,**  
**159724**

Claim Reference:  
 Assessment number: 011393  
 Version: 1810  
 Date calculated: 23/07/2019 5:00 PM

Full Report  
 Registration: SKP8578H  
 Printed: 23/07/2019 5:00 PM


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All ☐  
 Underbody ☐



**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
OP 302	RENEW L/R DOOR		25.0	112.50
OP 500	RENEW L/R SIDE PANEL INCLUDES: REAR BUMPER, L/TAILLAMP, REAR SEATS AND NECESSARY TRIMS, REMOVE AND REFIT NOT INCLUDED: TAILGATE AND FUEL TANK REMOVE AND REFIT		77.0	346.50
NJ01R0)	R + R BOOTLID		3.0	13.50
NO NUMBER	R + R FUEL TANK		11.0	49.50
1001	RIM R/F		8.0*	36.00
2101	L/SILL PANEL CPL REPAIR		10.0*	45.00
2581	REAR BUMPER REPAIR		15.0*	67.50

**CHARN'S CUSTOMCRAFT**  
**1010 Bukit Merah Lane 3,**  
**159724**

Claim Reference:

Assessment number: 011393

Version: 1810

Date calculated: 23/07/2019 5:00 PM

Full Report

Registration: SKP8578H

Printed: 23/07/2019 5:00 PM

<b>Labour Cost</b>	<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>	<b>14.90</b>	<b>149.0</b>	<b>670.50</b>
<b>Total of Labour</b>			<b>670.50</b>

**Paint**

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	L/R SIDE PANEL NEW PART PAINTING		18.0	
	REAR BUMPER REPAIR PAINT PLASTIC		15.0	
	L/R DOOR REPAIR PAINTING >50%		21.0	
	L/SILL PANEL CPL REPAIR PAINTING >50%		14.0	

**Paint Material Per Part**

Code	Description	Price SGD
3481	L/R SIDE PANEL NEW PART PAINTING	17.92
2581	REAR BUMPER REPAIR PAINT PLASTIC	37.80
1781	L/R DOOR REPAIR PAINTING >50%	22.79
2101	L/SILL PANEL CPL REPAIR PAINTING >50%	10.27

<b>Labour Cost - Paint</b>	<b>Hrs</b>	<b>WU</b>	<b>Price SGD</b>
Factor	45.00 SGD/h		
Time Paint		68.0	
Preparation Main Work Metal	1.70	17.0	76.50
Preparation Comp. Work Plastic	0.60	6.0	27.00
<b>Total</b>	<b>10 WU/h</b>	<b>9.10</b>	<b>409.50</b>

<b>Material Cost - Paint</b>	<b>Price SGD</b>
New Part Painting	17.92
Repair Painting	33.06
Repair Painting Plastic	37.80
Material-constant Metal	18.10
Material-constant Plastic	12.70
<b>Total</b>	<b>119.58</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01
				Price SGD

**CHARN'S CUSTOMCRAFT**  
**1010 Bukit Merah Lane 3,**  
**159724**

Claim Reference:

Assessment number: 011393

Version: 1810

Date calculated: 23/07/2019 5:00 PM

Full Report

Registration: SKP8578H

Printed: 23/07/2019 5:00 PM

Code	Description	Part Number	Supplier	Price SGD
1781	L/R DOOR	6800471L00000		430.00
3481	L/R SIDE PANEL	6451171LV0P31		250.00
4201	L/R WHEELHOUSE COVER	7552171L00000		55.00
4207	L/FASTENING CLIP	0940907340000		18.00
1000	FRAME STICKER	R/L DOOR		35.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 788.00
u: Used parts				Addition(+15.00%) 118.20
<b>Total</b>				<b>906.20</b>

**Final Calculation**

	SGD	SGD
<b>Parts</b>	788.00	
Addition(+15.00%)	118.20	
<b>Total Parts</b>		<b>906.20</b>
<b>Labour Time Base 10 WU/h</b>		
Total 149.0 WU X 45.00 SGD/h	670.50	
<b>Total of Labour</b>		<b>670.50</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 91.0 WU X 45.00 SGD/h	409.50	
Material Cost	119.58	
<b>Total Paint Including Material</b>		<b>529.08</b>
<b>Repair Cost Excludes GST</b>		<b>2,105.78</b>
GST (+7.0%)		147.40
<b>Repair Cost Included GST</b>		<b>2,253.18</b>

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS