

ASS. REC. BY:

REF: CS/CT119013029/RIVf3^{SV} Special Instruction:

Surveyor: Rusul

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTE

Date/Time: 24/7/19 @ 8.42am

Estimated Cost:

Bill to:

OD/FP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDQ 9928C

Insured: WC 6593C

at Workshop m/s

Cycle & Carriage Industries

Tel: 91817717

of

188 pendan loop

Policy No:

Claim No: SNM19D203078

Sum Insured:

Excess:

D.O.A. 28/6/2019.

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 10.19am @ 24/7/19

Person Contacted:

Chee Han

Vehicle IN/OUT

Date/Time

Action/Instruction

Completed ✓

SDQ 9928C NA/INC17010593/5 DOA = 30/5/17
WC 6593C X.

26/8/19

@ 256pm Chee Han said vehicle did not repair at CDC

ASS. FILED BY:

Rasm

REF: CTE

8556

LOG RPT 14/12/2022/PKS

ASSIGNMENT

From: Date: 30/07/19

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDQ 9928C
at Workshop m/s Cycle & Carriage Industries
of 188 pendon loop

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: 3pm (waiting)
Chee Hun @ 9181 7717

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 49K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDQ 9928C Yr Regn: 2012 / PKS

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ C180 Komp c.c 1597

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 20 2274 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 204 045 2 A 6 728 29

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R:

BS / DUN / EXNOVA / G / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/06/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 30/07/19

CYCLE & CARRIAGE (PL)

Date / Time

Action / Instruction

refer to email for repair limit

RECEIVED 26 AUG 2019

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) 16/8 - typist

Report Format: merimen

Lump Sum / H.R.:

Days Of Repair: 8

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ West end (\$)

Survey Fee:

Transportation:

S + PS: \$

Folio:

Other:

TOTAL

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 24 July 2019 8:42 AM
To: Go Chee Han
Cc: Irene Tay; LKK Auto Appraisers (assignments@lkkauto.com)
Subject: RE: accident involving motor vehicle sdq9928c and wc6593c / our ref: snm19d203078

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Go Chee Han [mailto:cheehan.go@cyclecarriage.com.sg]
Sent: Tuesday, 23 July, 2019 7:55 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: accident involving motor vehicle sdq9928c and wc6593c / our ref: snm19d203078

Dear Boon Sen,

We may assign anyone of the surveyor for us to conduct pre-repair survey on the vehicle.

Vehicle survey date & time to be confirm with our client's and get back to you.

Thanks

Your Sincerely,

GO CHEE HAN
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 9181 7717 | DID: 6771 4336 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Monday, 22 July, 2019 11:06 AM
To: Go Chee Han
Cc: Irene Tay
Subject: RE: accident involving motor vehicle sdq9928c and wc6593c / our ref: snm19d203078

This email was sent from outside of your organisation

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Wednesday, 31 July, 2019 9:08 AM
To: 'Go Chee Han'
Subject: SDQ 9928C DOA : 28/06/19

Hi Chee Han,

Kindly take note this vehicle repair limit is 17K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/07/2019 13:56
Date Of Accident	28/06/2019 18:05
Exact Location Of Accident	ALONG SIMS WAY TOWARDS PIE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDQ9928C
Insured/Policyholder	
Name Of Registered Owner	TSANG BIH CHEE @ PETER
NRIC No	S2576895G
Email Address	PTSANG@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-93699326
Alternative Phone No	OTHERS-93699326

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107051851
Cover Note Number	

Driver

Name of Driver	TSANG BIH CHEE @ PETER
NRIC No	S2576895G
Date Of Birth	09/08/1964
Occupation	INDOOR
Date Of Driving Pass	02/04/1987
Driving Experience	32 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93699326
Fax Number	
Contact Number	OTHERS-93699326
Email Address	PTSANG@SINGNET.COM.SG

Address	55 HUME AVENUE #03-07
Postcode	598752
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC6593C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	C. MANOHARAN
NRIC/Passport Number	031540836
Contact Number	84517872
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Kallang Road/Sing Avenue where I then turned left to go to Sims Way. When there was no traffic, I filtered to the right successfully and then drive straight. A lorry, WC 6593C in the middle lane filtered to the left and hit my right-rear part of my car. The driver of WC 6593C is a foreign worker (Indian) and don't speak English properly.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	895G
Vehicle Details	
Vehicle No.:	SDQ9928C
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 KOMPRESSOR
Primary Colour:	Brown
Manufacturing Year:	2011
Engine No.:	27191031352091
Chassis No.:	WDD2040452A672829
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,076.00
Original Registration Date:	29 Feb 2012
First Registration Date:	29 Feb 2012
Transfer Count:	0
Actual ARF Paid:	\$31,076.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2022
PARF Rebate Amount:	\$18,645.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$48,112.00
COE Rebate Amount:	\$12,428.00
Total Rebate Amount:	\$31,073.00

The information contained herein is correct as at 31 Jul 2019

OK

49,000
 31,073

 17,927

 17k



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDQ9928C

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 34756
Reg No/Reg Date SDQ9928C / 29/02/2012
Date In/Mileage / 0
Chassis No WDD2040452A672829
Engine No 27191031352091
Make/Model MB/C 180K (BlueEFFICIENCY) S
Colour/Trim 024 497 Cuprite Bro/ 042 224 Leather Cas

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	02/07/2019/ 14:42	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 5107051851 // 28-6-2019								
DRIVE IN/TP VEH NUMBER : 2-7-2019 // WC6593C - CHINA TAIPING								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.								
A BPIRES								
RESPRAY RH/REAR FENDER & REAR BUMPER & END PANEL								
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT							0.10	380.00
A BPILAB								120.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								480
A BPILAB								960
REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR. NETT								960
A BPILAB								2400.00
REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.								420.00
A BPILAB								560.00
TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS. NETT							0.07	300.00
A BPILAB								560.00
REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL. NETT								300.00
S BPNSUB								300.00
SUPPLY & INSTALL 1 PC REAR WINDSCREEN SOLAR HUPER OPTIK FILM. NETT								2102.57
M RIGHT REAR FENDER					1.00	2102.57	00.00	2102.57
M REAR FENDER INSULATION					1.00	20.83	00.00	20.83
M FUEL TANK RECESS					1.00	165.27	00.00	165.27
M REAR WINDOW					1.00	952.27	00.00	952.27

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDQ9928C

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **34756**
Reg No/Reg Date **SDQ9928C / 29/02/2012**
Date In/Mileage **/ 0**
Chassis No **WDD2040452A672829**
Engine No **27191031352091**
Make/Model **MB/C 180K (BlueEFFICIENCY) S**
Colour/Trim **024 497 Cuprite Bro/ 042 224 Leather Cas**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	02/07/2019/ 14:42	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR WINDSHIELD BOTTOM PAD <i>see</i>	1.00	13.79	00.00	13.79
M WINDSHIELD SUPPORT <i>see</i>	2.00	6.09	00.00	12.18
M REAR TOP INTERMEDIATE LAYER <i>see</i>	2.00	18.91	00.00	37.82
M REAR BUMPER <i>repair</i>	1.00	1400.31	00.00	1400.31
M LEFT REAR BUMPER CHROME MOULDING <i>see</i>	1.00	138.28	00.00	138.28
M RIGHT REAR BUMPER CHROME MOULDING <i>see</i>	1.00	138.28	00.00	138.28
M CENTER REAR BUMPER CHROME MOULDING <i>see</i>	1.00	194.45	00.00	194.45
M RIGHT REAR LAMP COMBINATION <i>see</i>	1.00	687.24	00.00	687.24

Rashid

Hp 90010068

8 days

30/07/19 @ 1450

Resy before part

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirmed & accepted by

Acknowledged by Repairer

Signature:

Nett **17,963.29**
7% GST on **17963.29** **1257.43**
Total Payable **19,220.72**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Sep 2019 15:40		31 Jul 2019 11:57 Edit Adj Rpt	S\$13,322.98 Edit Estimates	S\$13,322.98 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	TSANG BIH CHEE @ PETER , ID: S2576895G								
Vehicle Reg. No.:	SDQ9928C	Date of Loss:	28/06/2019 18:00 - :59 [87 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	WC6593C	Policy No. (Claimant):	5107051851						
		Excess:	S\$0.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDQ9928C
[WC6593C]

TP

TSANG BIH CHEE @ PETER
Jun 28 2019 6:00PM
















[-]

Cycle & Carriage Industries Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	01/07/19 14:01	Video - Accident [Linked Accident Report Documents]	Load MP4	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	01/07/19 14:01	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/19 14:59	General View	Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	01/07/19 14:00	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	01/07/19 14:00	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	01/07/19 14:01	Video - Accident	Load MP4	

Video			1 per page ▼	✓
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
Photos/Images			3 per page ▼	✓
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	01/07/19 14:01	Accident Photo	 Load JPG	✓
2	01/07/19 14:01	Accident Photo	 Load JPG	✓
3	01/07/19 14:01	Accident Photo	 Load JPG	✓
4	01/07/19 14:01	Accident Photo	 Load JPG	✓
5	01/07/19 14:01	Accident Photo	 Load JPG	✓
6	01/07/19 14:01	Accident Photo	 Load JPG	✓
7	01/07/19 14:01	Accident Photo	 Load JPG	✓
8	01/07/19 14:01	Accident Photo	 Load JPG	✓
9	01/07/19 14:01	Accident Photo	 Load JPG	✓
10	01/07/19 14:01	Accident Photo	 Load JPG	✓
11	01/07/19 14:01	Accident Photo	 Load JPG	✓
12	01/07/19 14:01	Accident Photo	 Load JPG	✓
13	01/07/19 14:01	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	01/07/19 14:00	Sketch Plan	 Load TIF	
2	01/07/19 14:00	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013029/R1VF3S2

Date: 02/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No: SDQ9928C

Insured Vehicle No: WC6593C

Date of Loss: 28/06/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDQ9928C

Make & Model: MERCEDES-BENZ C180, 1.6 Kompressor (A)

Engine No: 27191031352091

Reg. Date: 29/02/2012 (Man. Year: 2011)

Chassis No: WDD2040452A672829

Colour: Brown

Odometer: 202274 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,163.29	4,762.98	1,400.31	22.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,800.00	8,560.00	3,240.00	27.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,963.29	13,322.98	4,640.31	25.83
+ GST 7.00/7.00% (S\$)	1,257.43	932.61	324.82	25.83
Nett Amount (S\$)	19,220.72	14,255.59	4,965.13	25.83

INSPECTION

Date of Assignment: 31/07/2019

Date Inspected: 30/07/2019 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)

188 Pandan Loop

Singapore 128378

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Sep 2019)

Parts: 143 MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDQ9928C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT REAR FENDER	Bent	2,102.57 FS	*2,102.57 FS
2	1		*REAR FENDER INSULATION	Necessary	20.83 FS	*20.83 FS
3	1		*FUEL TANK RECESS	Necessary	165.27 FS	*165.27 FS
4	1		*REAR WINDOW	Necessary	952.27 FS	*952.27 FS
5	1		*REAR WINDSCREEN SOLAR HUPER OPTIK FILM	Necessary	300.00 FS	*300.00 FS
6	1		*REAR WINDSHIELD BOTTOM PAD	Necessary	13.79 FS	*13.79 FS
7	2		*WINDSHIELD SUPPORT	Necessary	12.18 FS	*12.18 FS
8	2		*REAR TOP INTERMEDIATE LAYER	Necessary	37.82 FS	*37.82 FS
9	1		*REAR BUMPER	Repair	1,400.31 FS	*- FS
10	1		*LEFT REAR BUMPER CHROME MOULDING	Necessary	138.28 FS	*138.28 FS
11	1		*RIGHT REAR BUMPER CHROME MOULDING	Necessary	138.28 FS	*138.28 FS
12	1		*CENTER REAR BUMPER CHROME MOULDING	Necessary	194.45 FS	*194.45 FS
13	1		*RIGHT REAR LAMP COMBINATION	Scratched	687.24 FS	*687.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,163.29** **4,762.98**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.	New	4,800.00	3,840.00
2	RESPRAY RH/REAR FENDER & REAR BUMPER & END PANEL.	New	2,160.00	1,800.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.	New	120.00	120.00
5	REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR.	New	960.00	480.00
6	REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UPHOLSTERY ETC FOR NECESSARY REPAIR.	New	2,400.00	960.00
7	TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS.	New	420.00	420.00
8	REMOVE & REPLACE REAR WINDSCREEN WITH INSATLL.	New	560.00	560.00
Gross Labour Cost (\$\$)			11,800.00	8,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >