

P.P. CASE OWNER:

LEE HING YAO | 003 / AIG 190 / 3036 / Kha3

AK
ITAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

23/7/19

Date / Time:

23/7/19

Registered in Merimen:

24/7/19

Pre-assign / CCU/FTE:



Insured Vehicle No. : SMG 9984 Y

Claim No. : 357771610466

Name of Insured : Seah Yang Ling

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II :SS D.O.A: 21/7/19

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

IF NO, Driver Name / Age :

OI GIA REPORT YES / NO ; TP GIA REPORT: YES NO

Driver Tel No. : (V/L YES / NO)

Insured Liability : % Final? Yes / No

SMG 9984 Y → SHF602L → SH8891A →



INSRS:
WSP:
Tel:
Liability:
RMKS: (01)



INSRS:
WSP: Trans-Cab
Tel:
Liability:
RMKS: (TP)



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
30/08/19	Call OI:	
	After call ltr to OI:	30/08/19 - JIC
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
16/09/19	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
11/11/19	Towing Invoice:	<input checked="" type="checkbox"/>
04/12/19	LIA / GIA :	<input checked="" type="checkbox"/>
07/12/19	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	LG	SS 21,650.50	14 days)	Reduction: 81 %
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email:	Call:
Final Liability:	%	100 (Agreed / Assessed)	BOLA S/N No.:	28
Repair Cost:	(w/gov)	SS 23,165.50	IF NO or B 28, Ass. Lia: 100% (3 Veh. C.C., 01 Unit)	
Loss of Rental (LOR):	SS	1,520.64	(16 days) x 95.04	
Loss of Use (LOU):	SS	-	(5 x days)	
Loss of Income (LOI):	SS	-	(5 x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search	SS	7.49		
Medical:	SS	-	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	SS	-	(e.g. Tow/ Independent)	
Legal Cost	SS	-	2) Report Format:	
Total:	SS	24,693.63	Globe' Sum SS:	-
FINAL PAYMENT	Date/Time:	Confirm with:	Email:	Call:
Payee 1:	SS	24,693.63	Name 1:	TRANS-CAB AUTO SERVICES PTE LTD
Payee 2: (Strike if N.A.)	SS	-	Name 2:	-
Payee 3: (Strike if N.A.)	SS	-	Name 3:	-

COPY SENT 16/12/19

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

AAD1907-192

Not Authorised
U/Smp B

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model: *23 JUL 2019*
Date of Accident :
Third Party Insurer :
Date of Registration :

SHF 602L
VF1ABL15AUC278441
RENAULT
LATITUDE
21.7.19
AIG
27/6/2014

PART		LIST	
1	1 BUMPER COVER REAR	\$ <i>Ry</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$ <i>B110.1</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>D17</i> 113.47	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$ <i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$ <i>R</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$ <i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$ <i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$ <i>Ry</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>D17</i> 225.95	✓
13	1 BOOT REAR	\$ <i>Ry</i> 2,872.68	✓
14	1 BOOT FINISHER	\$ <i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$ <i>SL</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$ <i>R</i> 225.36	✓
19	1 BOOT BADGE	\$ <i>R</i> 225.36	✓
20	1 BOOT STRUT LH	\$ <i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$ <i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$ <i>R</i> 367.84	
23	1 BOOT HINGE RH	\$ <i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$ <i>SL</i> 586.45	
25	1 BOOT SWITCH	\$ <i>SL</i> 168.13	
26	1 BOOT LOCK	\$ <i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$ <i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$ <i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

30	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	}
31	1	FENDER PANEL REAR LH	\$	R	3,299.13	
32	1	WHEELARCH REAR LH	\$	Sm	543.47	
33	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	
34	1	FENDER PANEL REAR RH	\$	R	3,299.13	
35	1	WHEELARCH REAR RH	\$	Sm	543.47	
36	1	TAILLAMP RH	\$	Sm	552.55	
37	1	TAILLAMP PANEL RH	\$	R	986.70	
38	1	TAILLAMP LH	\$	Sm	552.55	
39	1	TAILLAMP PANEL LH	\$	R	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	Bg	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	rd	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bt/Bu	2,189.88	✓
43	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X
46	1	FUEL FLAP L70Y	\$	Sm	343.57	X
47	1	BUMPER COVER FRT	\$	Bu	1,259.42	✓
48	1	BUMPER SPOILER FRT	\$	Sm	181.75	X
49	1	BUMPER ABSORBER FRT	\$	CM	394.68	✓
50	1	BUMPER RETAINER FRT LH	\$	Dr	151.41	✓
51	1	BUMPER SUPPORT FRT	\$	Sm	123.88	X
52	1	BUMPER RETAINER FRT RH	\$	Dr	150.77	✓
53	1	BUMPER SUPPORT FRT	\$	Sm	123.88	X
54	1	BUMPER UNDERTRAY FRT	\$	Sm	472.83	X
55	1	BUMPER GRILLE LOWER FRT	\$	Sm	266.80	X
56	1	BUMPER FOG LAMP GRILLE LH	\$	Sm	207.21	X
57	1	BUMPER FOG LAMP GRILLE RH	\$	Sm	207.21	X
58	1	BUMPER BEAM FRT	\$	Bt	914.08	✓
59	1	TOW COVER FRT	\$	Sm	28.61	X
60	1	RADIATOR GRILLE	\$	CM	1,707.78	✓
61	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R	225.36	✓
62	1	RADIATOR GRILLE FRAME	\$	CM	1,353.75	✓
63	1	FRAME FULL SUPPORT PANEL	\$	CM	615.90	✓
64	1	FRAME FULL SUPPORT BRACKET	\$	Bt	89.79	✓
65	1	FRONT BRACE PANEL	\$	Bt	177.22	✓
66	1	HORN	\$	Sm	314.17	X
67	1	HORN BRACKET	\$	R	40.45	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

AAD1907-192

68	1	HEADLAMP LH	\$	<i>m/cmt</i>	1,184.43	✓
69	1	HEADLAMP RH	\$	<i>cm</i>	1,184.43	✓
70	1	HEADLAMP PANEL FRT LH	\$	<i>n</i>	152.15	X
71	1	HEADLAMP PANEL FRT RH	\$	<i>n</i>	152.15	X
72	1	BONNET	\$	<i>As</i>	1,941.63	✓
73	1	BONNET INSULATOR	\$	<i>su</i>	405.73	X
74	1	BONNET STRUT LH	\$	<i>su</i>	88.61	X
75	1	BONNET STRUT RH	\$	<i>su</i>	88.61	X
76	1	BONNET HINGE LH	\$	<i>n</i>	348.31	X
77	1	BONNET HINGE RH	\$	<i>n</i>	348.31	X
78	1	BONNET LOCK	\$	<i>As</i>	305.48	✓
79	1	BONNET CABLE	\$	<i>su</i>	119.19	X
80	1	BONNET CABLE COVER	\$	<i>su</i>	161.03	} X
81	1	BONNET SEAL OUTER	\$	<i>su</i>	92.36	
82	1	BONNET SEAL INNER	\$	<i>su</i>	157.28	
83	1	FENDER PANEL FRT LH	\$	<i>n</i>	783.83	
84	1	WHEELARCH FRT LH	\$	<i>su</i>	278.84	
85	1	FENDER BRACKET LOWER LH	\$	<i>su</i>	15.79	
86	1	FENDER INSULATOR LH	\$	<i>su</i>	130.84	
87	1	FENDER INSULATOR RH	\$	<i>su</i>	130.84	
88	1	FENDER PANEL FRT RH	\$	<i>n</i>	783.83	
89	1	WHEELARCH FRT RH	\$	<i>su</i>	278.84	
90	1	FENDER BRACKET LOWER RH	\$	<i>su</i>	15.79	
91	1	WIPER RESERVOIR	\$	<i>su</i>	348.25	
92	1	WIPER RESERVOIR NECK	\$	<i>su</i>	136.11	
93	1	WIPER RESERVOIR MOTOR	\$	<i>su</i>	270.06	
94	1	AIR CLEANER LOWER	\$	<i>su</i>	271.26	
95	1	AIR CLEANER HOSE	\$	<i>su</i>	76.14	
96	1	BASE BATTERY TRAY	\$	<i>su</i>	363.40	
97	1	AIR CLEANER BOX	\$	<i>su</i>	464.20	
98	1	TURBO DUCT	\$	<i>su</i>	1,027.80	
99	1	A/C HEATER VALVE	\$	<i>su</i>	484.50	
100	1	SUBFRAME OUTER FRT	\$	<i>su</i>	2,652.45	
101	1	SUBFRAME BRACKET OUTER LH	\$	<i>su</i>	92.36	
102	1	SUBFRAME BRACKET OUTER RH	\$	<i>su</i>	92.36	
103	1	ENGINE UNDERTRAY	\$	<i>su</i>	564.98	
104	1	A/C CONDENSER	\$	<i>As</i>	2,020.37	✓
105	1	A/C CONDENSER GARNISH LH UPPER	\$	<i>su</i>	39.67	X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

106	1	A/C CONDENSER GARNISH RH UPPER	\$	Sm	39.67	X
107	1	A/C CONDENSER GARNISH LH	\$	Sm	58.81	X
108	1	A/C CONDENSER GARNISH RH	\$	Sm	59.60	X
109	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sm	208.39	X
110	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sm	658.72	X
111	1	A/C PIPE COMPRESSOR	\$	Sm	334.29	X
112	1	A/C PIPE	\$	Sm	658.72	X
113	1	A/C COMRPRESSOR	\$	Sm	2,684.61	X
114	1	AIR COOLER	\$	Sm	792.60	X
115	1	AIR INTERCOOLER HOSE (LONG)	\$	Sm	1,014.13	X
116	1	AIR INTERCOOLER HOSE (Short)	\$	Sm	375.14	X
117	1	TRANSMISSION COOLER	\$	Sm	1,219.30	X
118	1	TRANSMISSION COOLER PAD	\$	Sm	17.96	X
119	1	RADIATOR	\$	Sm	1,202.20	?
120	2	RADIATOR STUD UPPER	\$	Sm	14.41	X
121	2	RADIATOR BUSH UPPER	\$	Sm	50.12	X
122	2	RADIATOR MTG LOWER	\$	Sm	55.85	X
123	1	RADIATOR FAN COWLING	\$	onc	820.54	X
124	1	RADIATOR FAN MOTOR LH	\$	onc	967.36	X
125	1	RADIATOR FAN MOTOR RH	\$	onc	1,479.46	X
127	1	RADIATOR TANK	\$	Sm	324.62	} X
128	1	RADIATOR HOSE UPPER	\$	Sm	240.56	
129	1	RADIATOR HOSE LOWER	\$	Sm	491.18	
130	1	RADIATOR TANK HOSE	\$	Sm	61.18	
131	1	AUTO COMPUTER	\$	Sm	5,032.17	
132	1	INJECTION COMPUTER	\$	Sm	4,706.30	
133	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sm	5,154.52	
134	1	STEERING PUMP ELECTRIC L70Y	\$	Sm	2,306.90	
135	1	STEERING PINION RACK L70Y	\$	Sm	4,413.11	
TOTAL			\$		98,714.07	
10%			\$		9,871.41	
			\$		88,842.67	

Special Nett

1	1SET PARKING AID	\$	Shan	700.00	400sn
2	1SET REAR BUMPER CLIP	\$	nc	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	nc	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nc	10.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

AAD1907-192

5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	sh	17.82	} X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT INNER TRIM CLIP	\$	na	45.00	
13	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
14	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
15	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
16	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
17	1 TAILLAMP CLIP RH	\$	na	5.00	
18	1 TAILLAMP CLIP LH	\$	na	5.00	
19	2 REAR WINDSCREEN SEALANT	\$	na	80.00	
20	1 WINDSCREEN MOULDING	\$	na	100.00	
21	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
22	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sh	385.00	
23	1 SPARE TYRE	\$	sh	330.00	
24	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	—
25	1SET BUMPER CLIP FRT	\$	na	66.00	✓
26	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
27	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	X
28	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	X
29	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	X
30	1SET RADIATOR GRILLE SCREW	\$	na	16.00	X
31	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	✓
32	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
33	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
34	2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
35	1 Windscreen moulding	\$	na	100.00	X
36	1 FRONT WINDSCREEN SEALANT	\$	na	253.80	X
37	1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
38	1SET Front licence plate with holder	\$	Bj	80.00	451m
39	1 WHEELARCH CLIP FRT LH	\$	na	30.50	X
40	1 WHEELARCH CLIP FRT RH	\$	na	30.50	X
41	2 BONNET STRUT L70Y	\$	na	88.61	X
42	6 BONNET INSULATOR CLIP L70Y	\$	na	7.30	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

AAD1907-192

43	2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85	X
44	2	BONNET CABLE CLIP L70Y	\$	na	6.31	X
45	1	REAR RIGHT TYRE	\$	sin	300.00	X
46	1	REAR RIGHT TYRE RIM	\$	sin	380.00	X
47	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
48	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
49	1	FRONT LEFT TYRE	\$	sin	300.00	X
50	1	FRONT LEFT TYRE RIM	\$	sin	380.00	X
TOTAL			\$		4,660.90	
TOTAL PARTS			\$		93,503.56	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	17601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	18001
To Rust-Proofing Of The Affected Areas.	\$	170.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	801
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	801
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

To Check Electrical Lighting Concerned.	\$	~ 170.00	401
Towing Fees	\$	150.00	501
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	1001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2501
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
To repair and realign rear exhaust pipe.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To replace, refix and top up coolant for radiator.	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 340.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	~ 180.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L**AAD1907-192**

To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i>	180.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i>	180.00	X
To transfer of front windscreen glass to facilitate bodywork repair.	\$	<i>na</i>	170.00	X
To Transfer Of Rear Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i>	340.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i>	170.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>na</i>	440.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	<i>na</i>	480.00	X
TOTAL	\$		22,380.00	
Over All Total	\$		115,883.56	

Repair Days (LUMP SUM)**25 DAYS***14 days*

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 878K

Vehicle Details

Vehicle No.: SHF602L
Vehicle to be Exported: Yes
Intended Deregistration Date: 22 Jul 2019
Vehicle Make: RENAULT
Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour: Red
Manufacturing Year: 2014
Engine No.: M9R8839C001708
Chassis No.: VF1ABL15AUC278441
Maximum Power Output: 127.0 kW (170 bhp)
Open Market Value: \$19,998.00
Original Registration Date: 27 Jun 2014
First Registration Date: 27 Jun 2014
Transfer Count: 0
Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Jun 2022
PARF Rebate Amount: \$8,748.00

Intended COE Rebate Details

COE Expiry Date: 26 Jun 2022
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$57,338.00
COE Rebate Amount: \$20,984.00
Total Rebate Amount: \$29,732.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Jul 2019

OK

Print Received Message

This mail is associated with :

***SHF602L (3377716104SG)**

[SMG9954Y]

TP

TRANS-CAB SERVICES PTE LTD

Jul 21 2019 12:00PM

[SEAH YANG LING]

Trans-Cab Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 04/12/2019 17:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$24693.63) - SHF602L - Claim Handler: Lee, Ming-Yao

Approved:24693.63.

Vic (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 6 November, 2019 10:15 AM
To: Vic (LKKAuto)
Cc: Admin A; claims@transcab.com.sg
Subject: RE: TCS REF: AAD1907-192--Accident involving SMG9954Y (AIG) & SHF602L on 21.07.19 - LKK REF CC3/AIG19013036/Kha3
Attachments: REG 27.06.14 SHF602L.PDF

WITHOUT PREJUDICE

Dear Vic

Please see the attachment for the purchase invoice.

Net Book Value : \$ 43,204.94

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]
Sent: Friday, 1 November, 2019 9:44 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; claims@transcab.com.sg
Subject: TCS REF: AAD1907-192--Accident involving SMG9954Y (AIG) & SHF602L on 21.07.19 - LKK REF CC3/AIG19013036/Kha3

Without Prejudice

Dear Wai Yin,

We refer to your below email.

We would like to request for the Book Value and Purchase Invoice of the vehicle SHF 602L.

Thank you.



DRIVE THE CHANGE

Wearnes Automotive Pte. Ltd.
Renault Showroom & Service Centre
38 Lang Kie Road Singapore 159105

Renault Commercial Centre
2 Jalan Pasawaf Singapore 619358

Telephone: +65 6471 3313
Facsimile: +65 6471 3393

Telephone: +65 6676 5550
Facsimile: +65 6676 5051

GST Reg No. : M2-8920828X
Tax Invoice No. : R 1016200- 1018241
Date : 27-06-2014
ST: R

Invoice to:
r05498
TRANS-CAB SERVICES PTE LTD
58 DEFU LANE 1
DEFU INDUSTRIAL ESTATE
SINGAPORE 539498

Deliver To:
r05498
TRANS-CAB SERVICES PTE LTD
58 DEFU LANE 1
DEFU INDUSTRIAL ESTATE
SINGAPORE 539498

Model Latitude 2.0A Diesel	Colour NXD/ / ORIENTAL RED	VSB Refer to Attached	Order No r05498
Engine No Refer To Attached	Chassis No. Refer To Attached	Sales Consultant Jay Tan	Reg No. Refer To Attached

Description	Value/ Unit	Unit	GST (7%) @ 42 unit	Amount (S\$)
Vehicle Price	38,953.40	42	77,778.96	1,713,821.76
Road Tax	3,055.00	42	-	128,310.00
Registration Fee	140.00	42	-	5,880.00
COE Quota Premium	57,338.00	42	-	2,408,196.00
Custom Duty	3,999.60	42	11,758.74	179,741.94
Insurance	1,926.00	42	-	80,892.00
Equipment- Taximeter	600.00	42	1,764.00	26,964.00

Vehicle Total Price incl GST

	4,543,805.70
DOWNPAYMENT	4,089,425.13
Amount payable by Trans-Cab Services Pte Ltd	<u>454,380.57</u>

This is a computer-generated invoice. No signature is required.

E. & O. E.

	Supply	GST
TRANS-CAB SERVICES PTE LTD DBS BANK LIMITED	1,304,310.00	91,301.70
Taxable	1,304,310.00	91,301.70
Non-taxable	3,148,194.00	-
	<u>4,452,504.00</u>	<u>91,301.70</u>

Please quote this invoice number when making payment.
Please remit payment to:
Oversea-Chinese Banking Corporation Limited
OCBC Centre Branch
85 Chulia Street, Singapore 049513
Bank Code: 7199
Branch Code: 101
Bank Account Name: Wearnes Automotive Pte Ltd
Bank Account: 296127101
SWIFT CODE: OCCB3300
Cheques should be crossed and made payable to "Wearnes Automotive Pte Ltd"

TP Veh	
Date of Reg	
DOA	

\$

<u>(I) Estimated Book Value</u>	
Unit Cost	38,953.40
Import Duty	3,999.60
Registration Fee	140.00
PQP Paid	57,338.00
ARF Paid	12,498.00
Estimated Per Taxi Purchase Price	<u>112,929.00</u>
Estimated Per Taxi Purchase Price	112,929.00
Less 60% of ARF Paid	<u>7,498.80</u>
Estimated Full Lifespan Depreciation	<u>105,430.20</u>
Estimated Full Lifespan Depreciation	105,430.20
Times Balance Life (49/96 months)	<u>53,813.33</u>
Add 60% of ARF Paid	<u>53,813.33</u>
Estimated Book Value	<u>53,813.33</u>
<u>(II) Adjusted LTA Rebate</u>	
PARF Rebate	
PQP Paid	
Times Balance Life (40/96 months)	<u> </u>
Adjusted COE Rebate	<u> </u>
PARF Rebate	
Add Adjusted COE Rebate	<u> </u>
Adjusted LTA Rebate	<u>20,984.00</u>
<u>(Summary) Estimated Nett Value</u>	
Estimated Book Value	53,813.33
Less Adjusted LTA Rebate	<u>20,984.00</u>
Estimated Net Value	<u>32,829.33</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jul 2019 Edit Reg		23 Jul 2019 00:00 Edit Adj Rpt	S\$21,650.00 Edit Estimates	S\$21,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SEAH YANG LING , ID: S9032683Z								
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHF602L	Date of Loss:	21/07/2019 12:00 - :59 [60 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3377716104SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 08/01/2019 - 07/01/2020						
Vehicle Reg. No. (Insured):	SMG9954Y	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (04/12/2019): Alert - Adj Mandate Approved (S\$24693.63) - SHF602L - Claim Handler: Lee, Ming-Y...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHF602L (33777161045G)
[SMG9954Y]
TP
TRANS-CAB SERVICES PTE LTD
Jul 21 2019 12:00PM
[SEAH YANG LING]
Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View	View in Browser
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit			
Photos/Images															3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	30/08/19 13:44	Odometer Reading											Load JPG <input checked="" type="checkbox"/>			
2	30/08/19 13:44	Chassis Number											Load JPG <input checked="" type="checkbox"/>			
3	30/08/19 13:44	General View											Load JPG <input checked="" type="checkbox"/>			
4	30/08/19 13:44	General View											Load JPG <input checked="" type="checkbox"/>			
5	30/08/19 13:44	General View											Load JPG <input checked="" type="checkbox"/>			
6	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
7	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
8	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
9	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
10	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
11	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
12	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
13	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
14	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
15	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
16	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
17	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
18	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
19	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
20	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
21	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
22	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
23	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
24	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
25	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
26	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
27	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
28	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
29	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
30	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
31	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
32	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
33	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
34	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
35	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
36	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
37	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
38	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
39	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			
40	30/08/19 13:45	General View											Load JPG <input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	30/08/19 13:45	General View		Load JPG <input checked="" type="checkbox"/>
42	30/08/19 13:45	General View		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/19 17:06	TP ESTIMATE - MARKED		Load PDF
2	24/07/19 17:06	TP GIA REPORT		Load PDF
3	30/08/19 13:42	EMAIL TO OI		Load PDF
4	30/08/19 13:42	LETTER TO OI		Load PDF
5	31/10/19 15:57	RENTAL RECEIPT		Load PDF
6	31/10/19 15:57	RENTAL MILEAGE		Load PDF
7	31/10/19 15:57	LTA SEARCH		Load PDF
8	31/10/19 15:57	LOD		Load PDF
9	18/12/19 08:55	AUTHORISATION TO ACT FORM		Load PDF
10	18/12/19 08:55	Release Voucher		Load PDF
11	18/12/19 08:56	WORKSHOP INVOICE		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/07/19 10:34	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SMG9954Y (Insd veh)	Model:	RENAULT LATITUDE 2.0 L (A)
	SHF602L (TP veh)		
Date of Accident:	21/07/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	: \$		123,995.40
Final Repair Cost	: \$		23,165.50
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		1,520.64 16 days
LTA / GIA Search Fee	: \$		7.49
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		24,693.63
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): ____ 100 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	: \$	24,693.63
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

18 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19013038/KHA3Q2

Date: 18/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant SHF602L **Insured Vehicle No :** SMG9954Y
Vehicle No : SHF602L **Nature of Claim:** TP **Claim No:** 3377716104SG
Date of Loss: 21/07/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF602L**
 Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C001708
 Reg. Date: 27/06/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278441
 Colour: Metallic White/Red Odometer: 368555 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Giti 8 mm Rear Left Side: Giti 8 mm
 Front Right Side: Giti 8 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	93,503.55	22,550.56	70,952.99	75.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,380.00	4,510.00	17,870.00	79.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	115,883.55	27,060.56	88,822.99	76.65
Approved Total (Overridden) (S\$)		21,650.00		
(S\$)	115,883.55	21,650.00	94,233.55	81.32
+ GST 7.00/7.00% (S\$)	8,111.85	1,515.50	6,596.35	81.32
Nett Amount (S\$)	123,995.40	23,165.50	100,829.90	81.32
+ Car Rental (16.0 x S\$95.04/day) (S\$)		1,520.64		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		24,693.63		

INSPECTION

Date of Assignment: 23/07/2019
 Date Inspected: 23/07/2019 Inspected At: Trans-Cab Services Pte Ltd (HQ)
 2 Ang Mo Kio Street 63
 Singapore 569111

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Bent / Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Distorted	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
31	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
32	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
33	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
34	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
35	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
36	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
39	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
40	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
41	1		*OUTER PANEL REAR (END PANEL)TRIM	Dented	404.56 FL	*404.56 FL
42	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Bent / Buckled	2,189.88 FL	*2,189.88 FL
43	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
44	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
45	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
46	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
47	1		*BUMPER COVER FRT	Buckled	1,259.42 FL	*1,259.42 FL
48	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
49	1		*BUMPER ABSORBER FRT	Cracked	394.68 FL	*394.68 FL
50	1		*BUMPER RETAINER FRT LH	Distorted	151.41 FL	*151.41 FL
51	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
52	1		*BUMPER RETAINER FRT RH	Distorted	150.77 FL	*150.77 FL
53	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	1	*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
55	1	*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
56	1	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
57	1	*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
58	1	*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
59	1	*TOW COVER FRT	Serviceable	28.61 FL	*- FL
60	1	*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
61	1	*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
62	1	*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
63	1	*FRAME SUPPORT SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
64	1	*FRAME SUPPORT SUPPORT BRACKET	Bent	89.79 FL	*89.79 FL
65	1	*FRONT BRACE PANEL	Bent	177.22 FL	*177.22 FL
66	1	*HORN	Serviceable	314.17 FL	*- FL
67	1	*HORN BRACKET	Repair	40.45 FL	*- FL
68	1	*HEADLAMP LH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
69	1	*HEADLAMP RH	Cracked	1,184.43 FL	*1,184.43 FL
70	1	*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
71	1	*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
72	1	*BONNET	Bent	1,941.63 FL	*1,941.63 FL
73	1	*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
74	1	*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
75	1	*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
76	1	*BONNET HINGE LH	Repair	348.31 FL	*- FL
77	1	*BONNET HINGE RH	Repair	348.31 FL	*- FL
78	1	*BONNET LOCK	Bent	305.48 FL	*305.48 FL
79	1	*BONNET CABLE	Serviceable	119.19 FL	*- FL
80	1	*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
81	1	*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
82	1	*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
83	1	*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
84	1	*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
85	1	*FENDER BRACKER LOWER LH	Serviceable	15.79 FL	*- FL
86	1	*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
87	1	*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
88	1	*FENDER PANEL FRT RH	Repair	783.83 FL	*- FL
89	1	*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
90	1	*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
91	1	*WIPER RESERVOIR	Serviceable	348.25 FL	*- FL
92	1	*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*- FL
93	1	*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*- FL
94	1	*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
95	1	*AIR CLEANER HOSE	Serviceable	76.14 FL	*- FL
96	1	*BASE BATTERY TRAY	Serviceable	363.40 FL	*- FL
97	1	*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
98	1	*TURBO DUCT	Serviceable	1,027.80 FL	*- FL
99	1	*A/C HEATER VALVE	Serviceable	484.50 FL	*- FL
100	1	*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*- FL
101	1	*SUBFRAME BRACKET OUTER LH	Serviceable	92.36 FL	*- FL
102	1	*SUBFRAME BRACKET OUTER RH	Serviceable	92.36 FL	*- FL
103	1	*ENGINE UNDERTRAY	Serviceable	564.98 FL	*- FL
104	1	*A/C CONDENSER	Bent	2,020.37 FL	*2,020.37 FL
105	1	*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*- FL
106	1	*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*- FL
107	1	*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*- FL
108	1	*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*- FL
109	1	*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
110	1	*A/C PIPE CONDENSER TO EXPENSION VALVE	Serviceable	658.72 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
111	1	*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
112	1	*A/C PIPE	Serviceable	658.72 FL	*- FL
113	1	*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
114	1	*AIR COOLER	Serviceable	792.60 FL	*- FL
115	1	*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
116	1	*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
117	1	*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
118	1	*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*- FL
119	1	*RADIATOR	Serviceable	1,202.20 FL	*- FL
120	2	*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
121	2	*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
122	2	*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
123	1	*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
124	1	*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
125	1	*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
126	1	*RADIATOR TANK	Serviceable	324.62 FL	*- FL
127	1	*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*- FL
128	1	*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*- FL
129	1	*RADIATOR TANK HOSE	Serviceable	61.18 FL	*- FL
130	1	*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
131	1	*INJECTION COMPUTER	Serviceable	4,706.30 FL	*- FL
132	1	*RHD HYDRAULIC POWER (ROCK & PINION)	Serviceable	5,154.52 FL	*- FL
133	1	*STEERING PUMP ELECTRIC L70Y	Serviceable	2,306.90 FL	*- FL
134	1	*STEERING PINION RACK L70Y	Serviceable	4,413.11 FL	*- FL
135	1	*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
136	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
137	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
138	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
139	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
140	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
141	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
142	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
143	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
144	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
145	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
146	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
147	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
148	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
149	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
150	1	*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
151	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
152	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
153	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
154	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
155	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
156	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
157	1	*SPARE TYRE	Serviceable	330.00 FS	*- FS
158	1	*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
159	1	*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
160	1	*BUMPR BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
161	1	*BUMPER SUPPOT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
162	1	*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
163	1	*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
164	1	*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
165	1	*SET BUMPER GRILLE LOWER CLIP	Necessary	69.00 FS	*69.00 FS
166	1	*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
167	2	*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
168	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
169	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
170	1		*FRONT WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
171	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
172	1		*SET FRONT LICENCE PLATE WITH HOLDER	Bent	80.00 FS	*45.00 FS
173	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
174	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
175	2		*BONNET STRUT L70Y	Not Necessary	88.61 FS	*- FS
176	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
177	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
178	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
179	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
180	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
181	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
182	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
183	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
184	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	103,374.96	24,960.96
- List Item Discount on L Items 10.00/10.00% (\$\$)	9,871.41	2,410.40
Total Parts (\$\$)	93,503.55	22,550.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	7,500.00	1,760.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	7,500.00	1,800.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	120.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	80.00
6	TO DROP DIESEL TANK ,PIPES ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING	New	380.00	80.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	40.00
11	TOWING FEES	New	150.00	50.00
12	TO TRANSFER OF REAR WINDSCREEN FITTING AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
14	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR CONDENSER	New	380.00	100.00
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	250.00
16	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE -IN- GAS	New	380.00	0.00
17	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	60.00
18	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
19	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
20	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
21	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	50.00
22	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	340.00	0.00
23	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	180.00	0.00
24	TO TRANSFER OF FRONT BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	180.00	0.00
25	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
26		New	180.00	0.00
Report was unsubmitted during this print-out.				

No	Particulars	Lab.Type	Repairer's	Amount
	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.			
27	TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
28	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	340.00	0.00
29	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
30	TO REMOVE AND RENEW POWER STEERING PUMP OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
31	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS	New	480.00	0.00
Gross Labour Cost (S\$)			22,380.00	4,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >