

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

AAD1907-192

Not Authorised

1/1 Imp B

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model: **23 JUL 2019**
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHF 602L
 VF1ABL15AUC278441
 RENAULT
 LATITUDE
 21.7.19
AIG
 27/6/2014

PART		LIST	
1	1 BUMPER COVER REAR	\$ <i>Ry</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$ <i>B11011</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>DIT</i> 113.47	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$ <i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$ <i>SL</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$ <i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$ <i>CPH</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$ <i>Ry</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>DIT</i> 225.95	✓
13	1 BOOT REAR	\$ <i>Ry</i> 2,872.68	✓
14	1 BOOT FINISHER	\$ <i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$ <i>SL</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$ <i>Na</i> 225.36	—
19	1 BOOT BADGE	\$ <i>Na</i> 225.36	—
20	1 BOOT STRUT LH	\$ <i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$ <i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$ <i>R</i> 367.84	
23	1 BOOT HINGE RH	\$ <i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$ <i>SL</i> 586.45	
25	1 BOOT SWITCH	\$ <i>SL</i> 168.13	
26	1 BOOT LOCK	\$ <i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$ <i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$ <i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

30	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	}
31	1	FENDER PANEL REAR LH	\$	R	3,299.13	
32	1	WHEELARCH REAR LH	\$	Sm	543.47	
33	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	
34	1	FENDER PANEL REAR RH	\$	R	3,299.13	
35	1	WHEELARCH REAR RH	\$	Sm	543.47	
36	1	TAILLAMP RH	\$	Sm	552.55	
37	1	TAILLAMP PANEL RH	\$	R	986.70	
38	1	TAILLAMP LH	\$	Sm	552.55	
39	1	TAILLAMP PANEL LH	\$	R	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	B ₁	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	R ₁	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	B ₁ /B ₂	2,189.88	✓
43	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X
46	1	FUEL FLAP L70Y	\$	Sm	343.57	X
47	1	BUMPER COVER FRT	\$	B ₂	1,259.42	✓
48	1	BUMPER SPOILER FRT	\$	Sm	181.75	X
49	1	BUMPER ABSORBER FRT	\$	CMA	394.68	✓
50	1	BUMPER RETAINER FRT LH	\$	D ₁	151.41	✓
51	1	BUMPER SUPPORT FRT	\$	Sm	123.88	X
52	1	BUMPER RETAINER FRT RH	\$	D ₁	150.77	✓
53	1	BUMPER SUPPORT FRT	\$	Sm	123.88	X
54	1	BUMPER UNDERTRAY FRT	\$	Sm	472.83	X
55	1	BUMPER GRILLE LOWER FRT	\$	Sm	266.80	X
56	1	BUMPER FOG LAMP GRILLE LH	\$	Sm	207.21	X
57	1	BUMPER FOG LAMP GRILLE RH	\$	Sm	207.21	X
58	1	BUMPER BEAM FRT	\$	B ₁	914.08	✓
59	1	TOW COVER FRT	\$	Sm	28.61	X
60	1	RADIATOR GRILLE	\$	CMA	1,707.78	✓
61	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R ₂	225.36	✓
62	1	RADIATOR GRILLE FRAME	\$	CMA	1,353.75	✓
63	1	FRAME FULL SUPPORT PANEL	\$	CMA	615.90	✓
64	1	FRAME FULL SUPPORT BRACKET	\$	B ₁	89.79	✓
65	1	FRONT BRACE PANEL	\$	B ₁	177.22	✓
66	1	HORN	\$	Sm	314.17	X
67	1	HORN BRACKET	\$	R	40.45	X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

68	1	HEADLAMP LH	\$	<i>mgcm</i> 1,184.43	✓
69	1	HEADLAMP RH	\$	<i>cm</i> 1,184.43	✓
70	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
71	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
72	1	BONNET	\$	<i>B</i> 1,941.63	✓
73	1	BONNET INSULATOR	\$	<i>su</i> 405.73	X
74	1	BONNET STRUT LH	\$	<i>su</i> 88.61	X
75	1	BONNET STRUT RH	\$	<i>su</i> 88.61	X
76	1	BONNET HINGE LH	\$	<i>R</i> 348.31	X
77	1	BONNET HINGE RH	\$	<i>R</i> 348.31	X
78	1	BONNET LOCK	\$	<i>B</i> 305.48	✓
79	1	BONNET CABLE	\$	<i>su</i> 119.19	X
80	1	BONNET CABLE COVER	\$	<i>su</i> 161.03	} X
81	1	BONNET SEAL OUTER	\$	<i>su</i> 92.36	
82	1	BONNET SEAL INNER	\$	<i>su</i> 157.28	
83	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83	
84	1	WHEELARCH FRT LH	\$	<i>su</i> 278.84	
85	1	FENDER BRACKET LOWER LH	\$	<i>su</i> 15.79	
86	1	FENDER INSULATOR LH	\$	<i>su</i> 130.84	
87	1	FENDER INSULATOR RH	\$	<i>su</i> 130.84	
88	1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83	
89	1	WHEELARCH FRT RH	\$	<i>su</i> 278.84	
90	1	FENDER BRACKET LOWER RH	\$	<i>su</i> 15.79	
91	1	WIPER RESERVOIR	\$	<i>su</i> 348.25	
92	1	WIPER RESERVOIR NECK	\$	<i>su</i> 136.11	
93	1	WIPER RESERVOIR MOTOR	\$	<i>su</i> 270.06	
94	1	AIR CLEANER LOWER	\$	<i>su</i> 271.26	
95	1	AIR CLEANER HOSE	\$	<i>su</i> 76.14	
96	1	BASE BATTERY TRAY	\$	<i>su</i> 363.40	
97	1	AIR CLEANER BOX	\$	<i>su</i> 464.20	
98	1	TURBO DUCT	\$	<i>su</i> 1,027.80	
99	1	A/C HEATER VALVE	\$	<i>su</i> 484.50	
100	1	SUBFRAME OUTER FRT	\$	<i>su</i> 2,652.45	
101	1	SUBFRAME BRACKET OUTER LH	\$	<i>su</i> 92.36	
102	1	SUBFRAME BRACKET OUTER RH	\$	<i>su</i> 92.36	
103	1	ENGINE UNDERTRAY	\$	<i>su</i> 564.98	
104	1	A/C CONDENSER	\$	<i>B</i> 2,020.37	✓
105	1	A/C CONDENSER GARNISH LH UPPER	\$	<i>su</i> 39.67	X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

106	1	A/C CONDENSER GARNISH RH UPPER	\$	Sm	39.67	X
107	1	A/C CONDENSER GARNISH LH	\$	Sm	58.81	L
108	1	A/C CONDENSER GARNISH RH	\$	Sm	59.60	X
109	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sm	208.39	X
110	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sm	658.72	X
111	1	A/C PIPE COMPRESSOR	\$	Sm	334.29	X
112	1	A/C PIPE	\$	Sm	658.72	L
113	1	A/C COMPRESSOR	\$	Sm	2,684.61	X
114	1	AIR COOLER	\$	Sm	792.60	X
115	1	AIR INTERCOOLER HOSE (LONG)	\$	Sm	1,014.13	X
116	1	AIR INTERCOOLER HOSE (Short)	\$	Sm	375.14	X
117	1	TRANSMISSION COOLER	\$	Sm	1,219.30	X
118	1	TRANSMISSION COOLER PAD	\$	Sm	17.96	X
119	1	RADIATOR	\$		1,202.20	?
120	2	RADIATOR STUD UPPER	\$	Sm	14.41	X
121	2	RADIATOR BUSH UPPER	\$	Sm	50.12	X
122	2	RADIATOR MTG LOWER	\$	Sm	55.85	X
123	1	RADIATOR FAN COWLING	\$		820.54	?
124	1	RADIATOR FAN MOTOR LH	\$		967.36	?
125	1	RADIATOR FAN MOTOR RH	\$		1,479.46	?
127	1	RADIATOR TANK	\$	Sm	324.62	} X
128	1	RADIATOR HOSE UPPER	\$	Sm	240.56	
129	1	RADIATOR HOSE LOWER	\$	Sm	491.18	
130	1	RADIATOR TANK HOSE	\$	Sm	61.18	
131	1	AUTO COMPUTER	\$	Sm	5,032.17	
132	1	INJECTION COMPUTER	\$	Sm	4,706.30	
133	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sm	5,154.52	
134	1	STEERING PUMP ELECTRIC L70Y	\$	Sm	2,306.90	
135	1	STEERING PINION RACK L70Y	\$	Sm	4,413.11	
TOTAL			\$		98,714.07	
			10%	\$	9,871.41	
				\$	88,842.67	

Special Nett

1	1SET	PARKING AID	\$	Shan	700.00	400sn
2	1SET	REAR BUMPER CLIP	\$	Sm	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	Sm	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	Sm	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	si	17.82	} X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT INNER TRIM CLIP	\$	na	45.00	
13	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
14	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
15	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
16	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
17	1 TAILLAMP CLIP RH	\$	na	5.00	
18	1 TAILLAMP CLIP LH	\$	na	5.00	
19	2 REAR WINDSCREEN SEALANT	\$	na	80.00	
20	1 WINDSCREEN MOULDING	\$	na	100.00	
21	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
22	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	si	385.00	
23	1 SPARE TYRE	\$	si	330.00	
24	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	✓
25	1SET BUMPER CLIP FRT	\$	na	66.00	✓
26	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	X
27	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	X
28	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	X
29	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	X
30	1SET RADIATOR GRILLE SCREW	\$	na	16.00	X
31	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	✓
32	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
33	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
34	2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
35	1 Windscreen moulding	\$	na	100.00	X
36	1 FRONT WINDSCREEN SEALANT	\$	na	253.80	X
37	1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
38	1SET Front licence plate with holder	\$	By	80.00	45.00
39	1 WHEELARCH CLIP FRT LH	\$	na	30.50	X
40	1 WHEELARCH CLIP FRT RH	\$	na	30.50	X
41	2 BONNET STRUT L70Y	\$	na	88.61	X
42	6 BONNET INSULATOR CLIP L70Y	\$	na	7.30	X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

43	2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	X
44	2	BONNET CABLE CLIP L70Y	\$	nn	6.31	X
45	1	REAR RIGHT TYRE	\$	sn	300.00	X
46	1	REAR RIGHT TYRE RIM	\$	sn	380.00	X
47	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	✓
48	1	BOOT STICKER "6555-3333"	\$	nn	30.00	✓
49	1	FRONT LEFT TYRE	\$	sn	300.00	X
50	1	FRONT LEFT TYRE RIM	\$	sn	380.00	X
TOTAL			\$		4,660.90	

TOTAL PARTS	\$	93,503.56
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	1760
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	1800
To Rust-Proofing Of The Affected Areas.	\$	170.00	120
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	80
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	80
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

To Check Electrical Lighting Concerned.	\$	<i>nn</i>	170.00	40 40
Towing Fees	\$		150.00	50
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i>	380.00	X
To vacuum, replace, refix and recharge air condenser	\$		380.00	100
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$		380.00	250
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>Adjusted</i>	380.00	X
To repair and realign rear exhaust pipe.	\$		170.00	60
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
To replace, refix and top up coolant for radiator.	\$		170.00	50
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i>	340.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	180.00	X

Trans-cab Auto Services Pte Ltd

AAD1907-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 602L

To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i>	180.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i>	180.00	X
To transfer of front windscreen glass to facilitate bodywork repair.	\$	<i>na</i>	170.00	X
To Transfer Of Rear Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i>	340.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i>	170.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>na</i>	440.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	<i>na</i>	480.00	X

TOTAL \$ 22,380.00

Over All Total \$ 115,883.56

Repair Days (LUMP SUM)

~~25 DAYS~~

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: