

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 460P

AAD1907-204

Not Notified
Return by paint

Vehicle No.:	SHD 460P
Chassis No.:	VF1ABL15AUC283205
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	21.7.19
Third Party Insurer :	AIG
Date of Registration :	31/7/2017

23 JUL 2019

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>Bur Com</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>SL</i> 768.84	X
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	777.52	?
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95	X
13	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i> 1,471.77	} X
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56	
15	1	TAILLAMP RH	\$	<i>SL</i> 552.55	
16	1	TAILLAMP PANEL RH	\$	<i>N</i> 986.70	
17	1	TAILLAMP LH	\$	<i>SL</i> 552.55	
18	1	TAILLAMP PANEL LH	\$	<i>N</i> 986.70	
19	1	BOOT REAR	\$	<i>N</i> 2,872.68	
20	1	BOOT FINISHER	\$	<i>SL</i> 470.06	
21	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	
24	1	BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36	
25	1	BOOT BADGE	\$	<i>SL</i> 225.36	
26	1	BOOT STRUT LH	\$	<i>SL</i> 276.08	
27	1	BOOT STRUT RH	\$	<i>SL</i> 276.08	
28	1	BOOT HINGE LH	\$	<i>N</i> 367.84	
29	1	BOOT HINGE RH	\$	<i>N</i> 367.84	

Trans-cab Auto Services Pte Ltd

AAD1907-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 460P

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	<i>200</i>
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	<i>220</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>↪</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>↪</i>	220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>↪</i>	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>↪</i>	380.00	X
TOTAL	\$		11,550.00	

Over All Total \$ 27,376.21

LKK Auto Consultants hereby notify the Repairer of the following:
• To resurvey before/after spray painting
• **PART BY PART (REPAIR DAY)**
• Part prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*15 DAYS
2 days*

Trans-cab Auto Services Pte Ltd

AAD1907-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 460P

30	1	BOOT INNER TRIM	\$	na	586.45	X
31	1	BOOT SWITCH	\$	na	168.13	X
32	1	BOOT LOCK	\$	na	202.67	X
33	1	BOOT LOCK CATCH	\$	na	74.40	X
TOTAL			\$		16,046.87	
10%			\$		1,604.69	
			\$		14,442.19	

Special Nett

1	1SET	PARKING AID	\$	na	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	} X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	1	EXHAUST MOUNTING REAR	\$	na	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
14	1	WINDSCREEN MOULDING	\$	na	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
16	1	BOOT INNER TRIM CLIP	\$	na	45.00	
17	1SET	BOOT FINISHER CLIP	\$	na	24.20	
18	1	TAILLAMP CLIP LH	\$	na	5.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 15,826.21**LABOUR**

To Check Electrical Lighting Concerned.	\$	na	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00	X