

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9973C****AAD1907-190***Not Notified**Rev 1/1/13*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHB 9973C**

VF1ABL15AUC273487

RENAULT

LATITUDE

20.7.19

**AXA**

30/9/2013

| PART |                                 |
|------|---------------------------------|
| 1    | BUMPER COVER FRT                |
| 1    | BUMPER SPOILER FRT              |
| 1    | BUMPER ABSORBER FRT             |
| 1    | BUMPER RETAINER FRT LH          |
| 1    | BUMPER SUPPORT FRT              |
| 1    | BUMPER UNDERTRAY FRT            |
| 1    | BUMPER GRILLE LOWER FRT         |
| 1    | BUMPER FOG LAMP GRILLE LH       |
| 1    | BUMPER BEAM FRT                 |
| 1    | HEADLAMP LH                     |
| 1    | HEADLAMP PANEL FRT LH           |
| 1    | FENDER PANEL FRT LH             |
| 1    | WHEELARCH FRT LH                |
| 1    | FENDER BRACKET LOWER LH         |
| 1    | FENDER INSULATOR LH             |
| 1    | TOW COVER FRT                   |
| 1    | FRONT BRACE PANEL               |
| 1    | RADIATOR GRILLE                 |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' |
| 1    | RADIATOR GRILLE FRAME           |
| 1    | FRAME FULL SUPPORT PANEL        |
| 1    | FRAME FULL SUPPORT BRACKET      |
| 1    | BONNET                          |
| 1    | BONNET INSULATOR                |
| 1    | BONNET STRUT LH                 |
| 1    | BONNET STRUT RH                 |
| 1    | BONNET HINGE LH                 |

| LIST |            |
|------|------------|
| \$   | 1,259.42 X |
| \$   | 181.75 X   |
| \$   | 394.68 X   |
| \$   | 151.41 ✓   |
| \$   | 123.88 X   |
| \$   | 472.83 X   |
| \$   | 266.80 X   |
| \$   | 207.21 X   |
| \$   | 914.08 X   |
| \$   | 1,184.43 X |
| \$   | 152.15 X   |
| \$   | 783.83 ✓   |
| \$   | 278.84     |
| \$   | 15.79      |
| \$   | 130.84     |
| \$   | 28.61      |
| \$   | 177.22     |
| \$   | 1,707.78   |
| \$   | 225.36     |
| \$   | 1,353.75   |
| \$   | 615.90     |
| \$   | 89.79      |
| \$   | 1,941.63   |
| \$   | 405.73     |
| \$   | 88.61      |
| \$   | 88.61      |
| \$   | 348.31     |

**Trans-cab Auto Services Pte Ltd**

AAD1907-190

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9973C

|              |                                  |    |           |                  |   |          |
|--------------|----------------------------------|----|-----------|------------------|---|----------|
| 1            | BONNET HINGE RH                  | \$ | <i>R</i>  | 348.31           | } | <i>X</i> |
| 1            | BONNET LOCK                      | \$ | <i>n</i>  | 305.48           |   |          |
| 1            | BONNET CABLE                     | \$ | <i>in</i> | 119.19           |   |          |
| 1            | BONNET CABLE COVER               | \$ |           | 161.03           |   |          |
| 1            | BONNET SEAL OUTER                | \$ |           | 92.36            |   |          |
| 1            | BONNET SEAL INNER                | \$ |           | 157.28           |   |          |
| 1            | LOWER ARM LH L70Y                | \$ |           | 685.76           |   |          |
| 1            | KNUCKLE ARM LH L70Y              | \$ |           | 846.98           |   |          |
| 1            | ABSORBER FRT LH L70Y             | \$ |           | 360.54           |   |          |
| 1            | DRIVESHAFT LH                    | \$ |           | 1,747.45         |   |          |
| 1            | STABILIZER BAR FRT               | \$ |           | 604.65           |   |          |
| 1            | AIR CLEANER BOX                  | \$ |           | 464.20           |   |          |
| 1            | AIR CLEANER HOSE                 | \$ |           | 175.85           |   |          |
| 1            | AIR CLEANER LOWER                | \$ |           | 271.26           |   |          |
| 1            | LOWER ARM RH L70Y                | \$ |           | 685.76           |   |          |
| 1            | KNUCKLE ARM RH L70Y              | \$ |           | 846.98           |   |          |
| 1            | ABSORBER FRT RH L70Y             | \$ |           | 360.54           |   |          |
| 1            | DRIVESHAFT RH                    | \$ |           | 1,747.45         |   |          |
| 1            | AUTO COMPUTER                    | \$ |           | 5,032.17         |   |          |
| 1            | INJECTION COMPUTER               | \$ |           | 4,706.30         |   |          |
| 1            | RHD HYDRAULIC POWER(ROCK&PINION) | \$ |           | 5,154.52         |   |          |
| 1            | STEERING PUMP ELECTRIC L70Y      | \$ |           | 2,306.90         |   |          |
| 1            | STEERING PINION RACK L70Y        | \$ | <i>in</i> | 4,413.11         |   |          |
| <b>TOTAL</b> |                                  | \$ |           | <b>45,183.29</b> |   |          |
| <b>10%</b>   |                                  | \$ |           | <b>4,518.33</b>  |   |          |
|              |                                  | \$ |           | <b>40,664.96</b> |   |          |

**Special Nett**

|      |                                |    |           |       |   |          |
|------|--------------------------------|----|-----------|-------|---|----------|
| 1    | FRONT DOOR STICKER 'Trans-cab' | \$ | <i>na</i> | 80.00 | } | <i>X</i> |
| 1    | FRONT DOOR STICKER 'Classic'   | \$ | <i>na</i> | 80.00 |   |          |
| 1    | BUMPER CLIP FRT                | \$ | <i>na</i> | 66.00 |   |          |
| 1    | BUMPER BRACKET CLIP FRT RH     | \$ | <i>na</i> | 12.00 |   |          |
| 1    | BUMPER SUPPORT CLIP FRT RH     | \$ | <i>na</i> | 10.50 |   |          |
| 1    | BUMPER GRILLE LOWER CLIP       | \$ | <i>na</i> | 69.00 |   |          |
| 1SET | FRAME FULL SUPPORT PANEL CLIP  | \$ | <i>na</i> | 70.00 |   |          |

**Trans-cab Auto Services Pte Ltd**

AAD1907-190

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9973C**

|              |                                    |           |                 |
|--------------|------------------------------------|-----------|-----------------|
| 2            | FRAME FULL SUPPORT PANEL NUT       | \$        | 20.00           |
| 2            | FRAME FULL SUPPORT PANEL STUD      | \$        | 30.00           |
| 1            | WHEELARCH CLIP FRT RH              | \$        | 30.50           |
| 1            | FRONT RIGHT TYRE                   | \$        | 300.00          |
| 1            | FRONT RIGHT TYRE RIM               | \$        | 380.00          |
| 1SET         | Front licence plate with holder    | \$        | 80.00           |
| 1SET         | RADIATOR GRILLE SCREW              | \$        | 16.00           |
| 1SET         | RADIATOR GRILLE FRAME CLIP         | \$        | 52.00           |
| 1            | WINDSCREEN SEALANT                 | \$        | 253.80          |
| 1            | FRONT WINDSCREEN MOULDING          | \$        | 120.00          |
| 1            | FRONT WINDSCREEN INNER SPONGE SEAL | \$        | 100.00          |
| 6            | BONNET INSULATOR CLIP L70Y         | \$        | 7.30            |
| 2            | BONNET STRUT L70Y                  | \$        | 88.61           |
| 2            | BONNET CABLE CLIP L70Y             | \$        | 6.31            |
| 2            | BONNET CABLE COVER SCREW L70Y      | \$        | 10.85           |
| 1            | FRONT LEFT TYRE                    | \$        | 300.00          |
| 1            | FRONT LEFT TYRE RIM                | \$        | 380.00          |
| <b>TOTAL</b> |                                    | <b>\$</b> | <b>2,562.88</b> |

*X Br***TOTAL PARTS \$ 43,227.84****LABOUR**

|                                                                                                                           |    |                  |             |
|---------------------------------------------------------------------------------------------------------------------------|----|------------------|-------------|
| Putty and spray painting of the affected portion.                                                                         | \$ | 6,000.00         | <i>4401</i> |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 6,000.00         | <i>3001</i> |
| To dismantle and refit front end suspension, undercarriage parts, final checking and testing.                             | \$ | <i>na</i> 380.00 | <i>X</i>    |
| To transfer of front windscreen glass to facilitate bodywork repair.                                                      | \$ | <i>7</i> 170.00  | <i>X</i>    |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | <i>7</i> 380.00  | <i>X</i>    |

**Trans-cab Auto Services Pte Ltd****AAD1907-190**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9973C**

|                                                                                                 |           |                  |     |
|-------------------------------------------------------------------------------------------------|-----------|------------------|-----|
| To check steering geometry and computer wheel alignment                                         | \$        | 220.00           | X   |
| To rust-proofing of the affected areas.                                                         | \$        | 170.00           | 30  |
| To transfer of front bumper fittings, attachment and perform water seepage test.                | \$        | 380.00           | X   |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$        | 380.00           | X   |
| To transfer of front door fittings, attachment and perform water seepage test.                  | \$        | 380.00           | X   |
| To transfer of tire, rim and on wheel balancing.                                                | \$        | 170.00           | X   |
| To transfer of bonnet fittings, attachment and perform water seepage test.                      | \$        | 380.00           | X   |
| To Check Electrical Lighting Concerned.                                                         | \$        | 170.00           | 101 |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                 | \$        | 380.00           | X   |
| To apply paint protection system (PPS) maintain and enhancement                                 | \$        | 380.00           | X   |
| <b>TOTAL</b>                                                                                    | <b>\$</b> | <b>15,940.00</b> |     |
| <b>Over All Total</b>                                                                           | <b>\$</b> | <b>59,167.84</b> |     |

**LUMP SUM (REPAIR DAY)**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**20 DAYS**

2 days