

ASS. REC. BY:

Assigner: Steve
CWS

REF:

CS/FCI19013046/E+130

Final Instruction:

ASSIGNMENT (Office)

FROM (Person):

Henry Kao

of

FCI

Date/Time:

12:14pm @ 21/7/19

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SKU 1150C

Insured:

SHC 7049D

at Workshop m/s

Yew Tee Automobile

Tel:

62562281

of

Blk 6 Woodlands Road 399F Yew Tee Ind. Estate

Policy No:

Claim No:

D19004766MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:20pm @ 21/7/19

Person Contacted:

Yimei

Vehicle IN OUT

Date/Time	Action/Instruction
	Estimate <input checked="" type="checkbox"/> Ins:p: 39 woodlands close # 01-12
	SKU 1150C X
	SHC 7049D CS/FCI19005409/Gvd3n2 DOA = 21/3/19

ASS. REC'D. BY: Steve

REF: FCI

ASSIGNMENT

From: _____ Date: 25/7/19

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 1150C

at Workshop in/s: Yew Tee Automobile

of: Blk G Woodlands Rd 399F,

Insured: Yew Tee Ind. Estate.

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SKU 1150C Yr Regn: 5/2/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 525I c.c. 2497

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 177466 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA NU52059C 2 28981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 245/40R18
R: 6

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Achilles

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>19/7/19</u>	D.O.I. <u>25/7/19</u>

Survey held at: Yew Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GI/A / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV- 32,000
	PV- 26,494
	NV- 5596
	6/8/19 Finalize confirm \$5500, 5 days (Yee Meng)
	Cred: 13,528.92 : 71%

RECEIVED 06 AUG 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Survey Fee:	9x15=135
Transportation:	170+135
S+RS SI	50
Flotos	50+50
Others	72
TOTAL	527

Report Format: TP

Lump Sum / LBJ: 5500+

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Insp (\$) : Weekend (\$)

058
8/8/19

MOTOR SURVEY ASSIGNMENT

Date	22-07-2019	Our Ref No. D19004766MFSH
Accident Date	19-07-2019	Claim Type. Third Party
Insured Vehicle	SHC7049D	Third Party Vehicle. SKU1150C
Survey Location	BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE	
Contact Person.	MS LAI YEE MENG	
Contact No.	62562281/ 0	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 948J

Vehicle Details

Vehicle No.: SKU1150C
 Vehicle to be Exported: No
 Intended Deregistration Date: 22 Jul 2019
 Vehicle Make: B.M.W.
 Vehicle Model: 525I XL
 Primary Colour: White
 Manufacturing Year: 2009
 Engine No.: 08617198N52B25AF
 Chassis No.: WBANU52050C228981
 Maximum Power Output: 160.0 kW (214 bhp)
 Open Market Value: \$50,410.00
 Original Registration Date: 05 Feb 2010
 First Registration Date: 05 Feb 2010
 Transfer Count: 1
 Actual ARF Paid: \$50,410.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 04 Feb 2020
 PARF Rebate Amount: \$25,205.00 ✓

Intended COE Rebate Details

COE Expiry Date: 04 Feb 2020
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 10
 QP Paid: \$22,400.00
 COE Rebate Amount: \$1,199.00
Total Rebate Amount: \$26,404.00

The information contained herein is correct as at 22 Jul 2019

OK

b. Smith

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2019 15:53
Date Of Accident	19/07/2019 23:15
Exact Location Of Accident	ALONG ROAD 1 PIE > JURONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU1150C
Insured/Policyholder	
Name Of Registered Owner	SIM EE PING SUBRINA (SHEN YIPING)
NRIC No	S7734948J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96330203
Alternative Phone No	OFFICE-96330203

Vehicle Particulars

Manufacturer	BMW
Model	525I-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA158466/1
Cover Note Number	

Driver

Name of Driver	TNG SHI YING
NRIC No	S9340208A
Date Of Birth	24/10/1993
Occupation	INDOOR
Date Of Driving Pass	19/12/2016
Driving Experience	2 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98417750
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 442A BUKIT BATOK WEST AVENUE 8 #09-875
 Postcode 651442
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - DAUGHTER IN LAW
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 5
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : LESLIE GOH
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC7049D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver LAI WENG KAY
 NRIC/Passport Number S1306740F
 Contact Number 91199693
 Address

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLL6251Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver MOHAMED FARHAN BIN MOHAMED NORDIN
NRIC/Passport Number S8703881E
Contact Number 91704750
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SML3846P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLL475H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LEE JUNJIE
NRIC/Passport Number S9526281C
Contact Number 84844328
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

- (B) SHC 7094D
- (C) SLL 6251Y
- (D) SML 3816P
- (E) SLL 475H
- (A) SKU 1150C

PIE > Turning.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190720/2008

Police Station Of Origin.
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

1 of 4

Report No. T/20190720/2008

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/07/2019 01:21	Video Report No.: D/20190719/0132	Station Diary No.: 20
--	--------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: TNG SHI YING		Address: APT BLK 825 WOODLANDS STREET 81 #08-30 SINGAPORE 730825	
ID Type / ID No.: NRIC NO / S9340208A		Contact No.:	Mobile: 98417750
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 25	Date of Birth: 24/10/1993	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Coordinator		Driving Licence Information: Class: 3A	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/07/2019 23:15	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Tuas, 30.2km				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Chain Collision			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC7049D	Taxi			Yellow		0
SKU1150C	Car	BMW		White	Seriously Damaged	1
SLL475H	Car					0
SLL6251Y	Car	MAZDA		White		0
SML3846P	Car					0

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190720/2008

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

2 of 4

Report No. T/20190720/2008

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LAI WENG KAY	ID No	S1306740F
Related Vehicle	SHC7049D (Taxi)	Contact No.	91199693
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TNG SHI YING	ID No	S9340208A
Related Vehicle	SKU1150C (Car)	Contact No.	98417750
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE JUNJIE	ID No	S9526281C
Related Vehicle	SLL475H (Car)	Contact No.	84844328
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190720/2008

Police Station Of Origin:
Bukit Batok N P C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 4

Report No. T/20190720/2008

CONTINUATION OF REPORT

Driver			
Name	MOHAMED FARHAN BIN MOHAMED NORDIN	ID No.	S8703881E
Related Vehicle	SLL6251Y (Car)	Contact No.	91704750
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/07/2019 at 2316hrs, I was driving my vehicle, SKU1150C, along PIE towards Tuas. Then at 30.2km mark, I kept to the extreme left lane as I wanted to exit the expressway at the next exit. The cars in front of me started to slow down. At one point the vehicle in front of me stopped and I also stopped my vehicle. Within few seconds a taxi (SHC7049D) had collided onto the rear portion of my vehicle. At this point the vehicle in front of me had moved off. I alighted from the vehicle and spotted that it was chain collision. Another vehicle, SLL6251Y, which was the third vehicle had hit onto the rear portion of the taxi. The fourth vehicle, SML3846P did not collide into the third vehicle. The fifth vehicle, SLL475H had collided onto the fourth vehicle.

Traffic Police and Ambulance were at scene. Few of them were conveyed by ambulance.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190720/2008

4 of 4

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No. 1800-6659999

Report No T/20190720/2008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
J/
Sr Staff Sgt MOHAMED NASRUDIN BIN
SHAHUL HAMEED

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
20/07/2019 01:21

Officer In Charge Of Case:
TP / GIT /
SI ONG CHEE HIEN
Contact No.: 65476437

Classification Of Case:

Authentication Stamp
Signature:

Singapore Police Force



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

New leather seats, new 2k paintwork, new tyres.



\$0 drive away, \$700/Month, free 1 year warranty.
San Hup Bee (S) StarAd

■ Free VICOM evaluation
 ■ Free grooming and 6 months maintenance
 ■ In-house workshop ensures quality service
 ■ Member of SVTA and hire purchase association
 ■ 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

bmw 525

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 525	Any	Any	2010	Any	Any	Any	Availabl
	BMW 5 Series 525i XL	\$32,888	\$13,790 /yr	27-Jan-2010	2,497 cc	132,888 km	Luxury	Availabl
2 Owner, Car Is In Immaculate Condition!. All Wear And Tear Parts Replaced As Per Workshop Advise. Loan/Trade In Available. Please Call/SMS Now! Thanks. Posted: 10-Jun-2019 Tags: 2010 BMW 525i, 2010 bmw 525i, BMW 525i, bmw 525i, BMW, 525i, Used BMW								
	BMW 5 Series 525i XL	\$29,800	\$8,650 /yr	05-Feb-2010	2,497 cc	-	Luxury	Availabl
Depreciation Only \$8K+ For This BMW 525i XL Model. High Paper Value(\$26,386). Guaranteed Lowest Price In The Market. Only Asking Slightly Above Paper & Car Body Price. No Repairs Needed. 100% In Go Od Working Cond Itions. No Oil Leakage. No Funny Sounds. Exc... Posted: 25-Jul-2019 Tags: 2010 BMW 525i, 2010 bmw 525i, BMW 525i, bmw 525i, BMW, 525i, Used BMW								
	BMW 5 Series 525i XL	\$33,500	\$14,270 /yr	05-Feb-2010	2,497 cc	142,000 km	Luxury	Availabl
Consignment Code: A177. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us. Posted: 02-Jul-2019 Tags: 2010 BMW 525i, 2010 bmw 525i, BMW 525i, bmw 525i, BMW, 525i, Used BMW								
	BMW 5 Series 525i XL	\$39,988	\$27,230 /yr	09-Feb-2010	2,497 cc	85,000 km	Luxury	Availabl
Low Mileage Car Bought From Public Listed Cycle And Carriage Subsidiary. Car Is Still Used Daily So It Is A Functional Unit With The Odometer Photographed One Week Apart. Hence No Malfunction. Just Serviced With Receipt And Workshop Advise, Car Is Problem Free. Posted: 14-Jun-2019 Tags: 2010 BMW 525i, 2010 bmw 525i, BMW 525i, bmw 525i, BMW, 525i, Used BMW								
	BMW 5 Series 525i XL	\$34,488	\$12,910 /yr	24-Mar-2010	2,497 cc	151,000 km	Luxury	Availabl
Extended Wheelbase XL Version! Spacious Boot Space! Recently Serviced, Wear And Tear Parts Replaced As Advised By Reputable Workshop. Parked Mostly In Shelter Area! Owner Selling Due To Job Changes! Posted: 16-Jul-2019 Tags: 2010 BMW 525i, 2010 bmw 525i, BMW 525i, bmw 525i, BMW, 525i, Used BMW								

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

Save this search criteria, to get email alerts whenever a match is found.

Compare Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1907/020
Policy No:	GA158466/1	Date of Loss:	19/07/2019
Vehicle Reg. No.:	SKU1150C	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHC7049D
Any Injuries?	no	Contact No:	96330203
Insured/Claimant:	SIM EE PING SUBRINA (SHEN YIPING)	Driver:	TNG SHI YING

Make/Model:	BMW, 525i XL - WBANU52020CZ88639	Vehicle Reg. Date:	05/02/2010
Vehicle Colour:	WHITE	Engine Number:	08617198N52B25AF
Chassis No:	WBANU52050C228981	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: CHAIN COLLISION
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	13,141.92
Miscellaneous Items	710.00
Labour	2,690.00
Paintwork Labour	1,385.00
Towing	0.00
Gross Total(\$\$):	17,926.92
GST 7.00%(\$\$):	1,254.88
Nett Amount(\$\$):	19,181.80

This claim is handled by: Sky Toh T C

190 78 92

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER / <i>DD</i>	1,609.30	-5.00	1,528.84 <i>1502 ✓</i>
2	1	REAR BUMPER SIDE RETAINER LH / <i>DR</i>	115.50	-5.00	109.73 ✓
3	1	REAR BUMPER SIDE RETAINER RH / <i>DR</i>	115.50	-5.00	109.73 ✓
4	1	REAR BUMPER BRACKET LH / <i>CRV</i>	105.00	-5.00	99.75 ✓
5	1	REAR BUMPER BRACKET RH / <i>CRV</i>	105.00	-5.00	99.75 ✓
6	1	REAR BUMPER STAY LH / <i>DD</i>	110.00	-5.00	104.50 ✓
7	1	REAR BUMPER STAY RH / <i>X NAI</i>	110.00	-5.00	104.50 X
8	1	REAR BUMPER REINFORCEMENT / <i>X NAI</i>	572.10	-5.00	543.50 X
9	1	REAR BUMPER TOWING COVER / <i>MIS</i>	55.40	-5.00	52.63 ✓
10	1	REAR BUMPER CENTRE GUIDE / <i>X NAI</i>	171.20	-5.00	162.64 X
11	1	REAR BUMPER LOWER DIFFUSER / <i>GE</i>	170.30	-5.00	161.79 ✓
12	1	BOOT LID X <i>R</i>	2,127.40	-5.00	2,021.03 X
13	1	BOOT LID HINGES LH / <i>X NAI</i>	118.80	-5.00	112.86 X
14	1	BOOT LID HINGES RH / <i>X NAI</i>	118.80	-5.00	112.86 X
15	1	BOOT LID LOGO / <i>IPC</i>	71.25	-5.00	67.69 ✓
16	1	BOOT LID INNER TRIM BOARD X <i>NAI</i>	119.85	-5.00	113.86 X
17	1	BOOT LID LOCK / <i>ST</i>	154.50	-5.00	146.78 ✓
18	1	BOOT LID LOCK CATCH X <i>NAI</i>	145.00	-5.00	137.75 X
19	1	BOOT LID RUBBER / <i>IN</i>	194.20	-5.00	184.49 ✓
20	1	REAR TAILLAMP LH / <i>CH</i>	509.50	-5.00	484.03 ✓
21	1	REAR TAILLAMP RH X <i>NAI</i>	509.50	-5.00	484.03 X
22	1	REAR TAILLAMP PANEL LH X <i>NAI</i>	283.00	-5.00	268.85 X
23	1	REAR TAILLAMP PANEL RH X <i>NAI</i>	283.00	-5.00	268.85 X
24	1	REAR TAILLAMP GARNISH LH X <i>NAI</i>	83.80	-5.00	79.61 X
25	1	REAR FENDER LH X <i>NAI</i>	1,651.10	-5.00	1,568.55 X
26	1	REAR FENDER RH X <i>NAI</i>	0.00	0.00	0.00 X
27	1	REAR FENDER INNER TRIM BOARD LH X <i>NAI</i>	313.55	-5.00	297.87 X
28	1	REAR FENDER INNER TRIM BOARD RH X <i>NAI</i>	0.00	0.00	0.00 X
29	1	REAR END PANEL / <i>DD</i>	800.95	-5.00	760.90 ✓
30	1	REAR END PANEL INNER GARNISH / <i>CRV</i>	111.00	-5.00	105.45 ✓
31	1	REAR SPARE TYRE COMPARTMENT X / <i>DD</i>	1,213.55	-5.00	1,152.87 ✓
32	1	REAR EXHAUST PIPE / <i>X R</i>	1,785.55	-5.00	1,696.27 X

Total Parts (\$\$) 13,141.92 *5333.65*

-10%
4800.78

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	45.00	0.00	45.00 <i>30 nec</i>
2	1	REAR BUMPER SENSORS (1 SET)	360.00	0.00	360.00 <i>200 Short</i>
3	1	REAR NUMBER PLATE	45.00	0.00	45.00 X
4	1	BOOT LID TOP SPOILER	130.00	0.00	130.00 X
5	1	BOOT LID INNER TRIM BOARD CLIPS	40.00	0.00	40.00 X
6	1	REAR EXHAUST PIPE MOUNTING	30.00	0.00	30.00 X
7	1	REAR WINDSCREEN SEALANT	60.00	0.00	60.00 X <i>nn</i>

Sub Total (\$\$) 710.00 *230*

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical	30.00	0.00	30.00 ✓

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		wiring Harness Wire, Sockets, Replace Damaged Parts.			
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 20
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 X
4	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 30
5	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00 60
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,200.00	0.00	2,200.00 600
Gross Labour Cost (S\$)					2,690.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00 30
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	0.00	80.00 30
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,200.00	0.00	1,200.00 600
Gross Labour Cost (S\$)					1,385.00 1400

Signature
26/7/19

< END OF ESTIMATES >

Steve (LKK) mit April 25/7/19, 11.30am

5 days

L/S

Re AL my

P- 4800.28

M- 230

L- 1400

Supp - 958.50

7388.78

L/S - 5911.99

= 5900

limit repair \$5500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1907/020
Policy No:	GA158466/1	Date of Loss:	19/07/2019
Vehicle Reg. No.:	SKU1150C	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHC7049D
Any Injuries?	no	Contact No:	96330203
Insured/Claimant:	SIM EE PING SUBRINA (SHEN YIPING)	Driver:	TNG SHI YING

Make/Model:	BMW, 525i XL - WBANU52020CZ88639	Vehicle Reg. Date:	05/02/2010
Vehicle Colour:	WHITE	Engine Number:	08617198N52B25AF
Chassis No:	WBANU52050C228981	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss CHAIN COLLISION
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	1,102.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total(S\$):	1,102.00
GST 7.00%(S\$):	77.14
Nett Amount(S\$):	1,179.14

This claim is handled by: Lai Yee Meng

(Supp)

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR UNDER COVER / RR	280.00	280.00	-5.00	266.00 /
2	1	SPARE TYRE TOOL SPONGE TOP / CR4	220.00	220.00	-5.00	209.00 /
3	1	SPARE TYRE TOOL SPONGE BOTTOM / CR4	230.00	230.00	-5.00	218.50 /
4	1	REAR BUMPER INNER BRACKET CENTER / RR	430.00	430.00	-5.00	408.50 / 375

Total Parts (S\$) 1,102.00 1065
-106

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		stave 26/7/19				958.50
Sub Total (S\$)						<u>0.00</u>

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Gross Labour Cost (S\$)						<u>0.00</u>

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Gross Labour Cost (S\$)						<u>0.00</u>

< END OF ESTIMATES >

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
 Singapore 737856
 Tel: 62562281 Fax: Email: YTMG

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1907/020
Policy No:	GA158466/1	Date of Loss:	19/07/2019
Vehicle Reg. No.:	SKU1150C	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SHC7049D
Any Injuries?	no	Contact No:	96330203
Insured/Claimant:	SIM EE PING SUBRINA (SHEN YIPING)	Driver:	TNG SHI YING

Make/Model:	BMW, 525i XL - WBANU52020CZ88639	Vehicle Reg. Date:	05/02/2010
Vehicle Colour:	WHITE	Engine Number:	08617198N52B25AF
Chassis No:	WBANU52050C228981	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: CHAIN COLLISION
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	13,141.92
Miscellaneous Items	710.00
Labour	2,690.00
Paintwork Labour	1,385.00
Towing	0.00
Gross Total(\$\$):	17,926.92
GST 7.00%(\$\$):	1,254.88
Nett Amount(\$\$):	19,181.80

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER / <i>DD</i>	1,609.30	-5.00	1,528.84
2	1	REAR BUMPER SIDE RETAINER LH / <i>DR</i>	115.50	-5.00	109.73
3	1	REAR BUMPER SIDE RETAINER RH / <i>CRW</i>	115.50	-5.00	109.73
4	1	REAR BUMPER BRACKET LH / <i>CRW</i>	105.00	-5.00	99.75
5	1	REAR BUMPER BRACKET RH / <i>DD</i>	105.00	-5.00	99.75
6	1	REAR BUMPER STAY LH / <i>DD</i>	110.00	-5.00	104.50
7	1	REAR BUMPER STAY RH / <i>X</i>	110.00	-5.00	104.50
8	1	REAR BUMPER REINFORCEMENT / <i>X</i>	572.10	-5.00	543.50
9	1	REAR BUMPER TOWING COVER / <i>MJS</i>	55.40	-5.00	52.63
10	1	REAR BUMPER CENTRE GUIDE / <i>X</i>	171.20	-5.00	162.64
11	1	REAR BUMPER LOWER DIFFUSER / <i>DR</i>	170.30	-5.00	161.79
12	1	BOOT LID / <i>X R</i>	2,127.40	-5.00	2,021.03
13	1	BOOT LID HINGES LH / <i>X</i>	118.80	-5.00	112.86
14	1	BOOT LID HINGES RH / <i>X</i>	118.80	-5.00	112.86
15	1	BOOT LID LOGO / <i>MPC</i>	71.25	-5.00	67.69
16	1	BOOT LID INNER TRIM BOARD / <i>X</i>	119.85	-5.00	113.86
17	1	BOOT LID LOCK / <i>BT</i>	154.50	-5.00	146.78
18	1	BOOT LID LOCK CATCH / <i>X</i>	145.00	-5.00	137.75
19	1	BOOT LID RUBBER / <i>TH</i>	194.20	-5.00	184.49
20	1	REAR TAILLAMP LH / <i>CM</i>	509.50	-5.00	484.03
21	1	REAR TAILLAMP RH / <i>X</i>	509.50	-5.00	484.03
22	1	REAR TAILLAMP PANEL LH / <i>X</i>	283.00	-5.00	268.85
23	1	REAR TAILLAMP PANEL RH / <i>X</i>	283.00	-5.00	268.85
24	1	REAR TAILLAMP GARNISH LH / <i>X</i>	83.80	-5.00	79.61
25	1	REAR FENDER LH / <i>X</i>	1,651.10	-5.00	1,568.55
26	1	REAR FENDER RH / <i>X</i>	0.00	0.00	0.00
27	1	REAR FENDER INNER TRIM BOARD LH / <i>X</i>	313.55	-5.00	297.87
28	1	REAR FENDER INNER TRIM BOARD RH / <i>X</i>	0.00	0.00	0.00
29	1	REAR END PANEL / <i>DD</i>	800.95	-5.00	760.90
30	1	REAR END PANEL INNER GARNISH / <i>CRW</i>	111.00	-5.00	105.45
31	1	REAR SPARE TYRE COMPARTMENT / <i>DR</i>	213.55	-5.00	1,152.87
32	1	REAR EXHAUST PIPE / <i>X</i>	1,785.55	-5.00	1,696.27

26/7/19, limit ppv \$5500 Total Parts (S\$) 13,141.92

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	45.00	0.00	45.00 <i>30</i>
2	1	REAR BUMPER SENSORS (1 SET)	360.00	0.00	360.00 <i>250</i>
3	1	REAR NUMBER PLATE	45.00	0.00	45.00 <i>X</i>
4	1	BOOT LID TOP SPOILER	130.00	0.00	130.00 <i>X</i>
5	1	BOOT LID INNER TRIM BOARD CLIPS	40.00	0.00	40.00 <i>X</i>
6	1	REAR EXHAUST PIPE MOUNTING	30.00	0.00	30.00 <i>X</i>
7	1	REAR WINDSCREEN SEALANT	60.00	0.00	60.00 <i>X</i>
Sub Total (S\$)					<u>710.00</u>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical	30.00	0.00	30.00 <i>/</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		wiring Harness Wire, Sockets, Replace Damaged Parts.			
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 20
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 X
4	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 30
5	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	0.00	180.00 60
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	2,200.00	0.00	2,200.00 600
Gross Labour Cost (S\$)					2,690.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00 30
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	0.00	80.00 30
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,200.00	0.00	1,200.00 600
Gross Labour Cost (S\$)					1,385.00

< END OF ESTIMATES >

Steve (LKK) wil April 25/7/19, 11.30am
 5 days
 L/S
 Re AL say



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013046/Etf3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7049D	Veh. Inspected	SKU 1150C
Policy No.		Coverage (\$)	0.00
Claim No.	D19004766MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	24/07/2019
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 525I	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBANU52050C228981	Colour	WHITE
Odometer	177466	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	ACHILLES	6 mm
L/H Front Tyre	245/40 R18	ACHILLES	6 mm
R/H Rear Tyre	245/40 R18	ACHILLES	6 mm
L/H Rear Tyre	245/40 R18	ACHILLES	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/07/2019	Inspection Date	25/07/2019
Survey held at	39 WOODLANDS CLOSE #01-12		
Repairer	YEW TEE AUTOMOBILE TECH PL (HQ)		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 1150C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED	1,609.30	1,502.00
1	REAR BUMPER SIDE RETAINER LH	BROKEN	115.50	115.50
1	REAR BUMPER SIDE RETAINER RH	BROKEN	115.50	115.50
1	REAR BUMPER BRACKET LH	CRUSHED	105.00	105.00
1	REAR BUMPER BRACKET RH	CRUSHED	105.00	105.00
1	REAR BUMPER STAY LH	DENTED	110.00	110.00
1	REAR BUMPER STAY RH	NOT NECESSARY	110.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	572.10	-
1	REAR BUMPER TOWING COVER	MISSING	55.40	55.40
1	REAR BUMPER CENTRE GUIDE	NOT NECESSARY	171.20	-
1	REAR BUMPER LOWER DIFFUSER	BROKEN	170.30	170.30
1	BOOT LID	TO REPAIR SEE LABOUR	2,127.40	-
1	BOOT LID HINGES LH	NOT NECESSARY	118.80	-
1	BOOT LID HINGES RH	NOT NECESSARY	118.80	-
1	BOOT LID LOGO	NECESSARY	71.25	71.25
1	BOOT LID INNER TRIM BOARD	NOT NECESSARY	119.85	-
1	BOOT LID LOCK	BENT	154.50	154.50
1	BOOT LID LOCK CATCH	NOT NECESSARY	145.00	-
1	BOOT LID RUBBER	TORN	194.20	194.20
1	REAR TAILLAMP LH	CUT	509.50	509.50
1	REAR TAILLAMP RH	NOT NECESSARY	509.50	-
1	REAR TAILLAMP PANEL LH	NOT NECESSARY	283.00	-
1	REAR TAILLAMP PANEL RH	NOT NECESSARY	283.00	-
1	REAR TAILLAMP GARNISH LH	NOT NECESSARY	83.80	-
1	REAR FENDER LH	NOT NECESSARY	1,651.10	-
1	REAR FENDER RH (NPA)	NOT NECESSARY	-	-
1	REAR FENDER INNER TRIM BOARD LH	NOT NECESSARY	313.55	-
1	REAR FENDER INNER TRIM BOARD RH (NPA)	NOT NECESSARY	-	-
1	REAR END PANEL	DENTED	800.95	800.95
1	REAR END PANEL INNER GARNISH	CRUSHED	111.00	111.00

Report Ref No. CS/FCI19013046/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE COMPARTMENT	DENTED	1,213.55	1,213.55
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	1,785.55	-
1	REAR UNDER COVER (ADDITIONAL)	BROKEN	280.00	280.00
1	SPARE TYRE TOOL SPONGE TOP (ADDITIONAL)	CRUSHED	220.00	220.00
1	SPARE TYRE TOOL SPONGE BOTTOM (ADDITIONAL)	CRUSHED	230.00	230.00
1	REAR BUMPER INNER BRACKET CENTER (ADDITIONAL)	BROKEN	430.00	335.00
	LESS 5% DISCOUNT		-749.68	-
	LESS 10% DISCOUNT		-	-639.87
			14,243.92	5,758.78
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
1	SET REAR BUMPER SENSORS (SN)	SHORTED	360.00	200.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	BOOT LID TOP SPOILER (SN)	NOT NECESSARY	130.00	-
1	BOOT LID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	40.00	-
1	REAR EXHAUST PIPE MOUNTING (SN)	NOT NECESSARY	30.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			710.00	230.00
	<u>LABOUR</u>			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	30.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	20.00
	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		100.00	30.00
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS.		180.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF BOOT LID AND REAR EXHAUST PIPE.		2,200.00	600.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		60.00	30.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	NOT NECESSARY	45.00	-
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		80.00	30.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,200.00	600.00
			4,075.00	1,400.00
GRAND TOTAL			19,028.92	7,388.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CS/FCI19013046/Etf3e2

MARKET VALUE: \$32,000.00(EST)-LTA REIMBURSEMENT VALUE: \$26,404.00=NETT VALUE: \$5,596.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.