

Trans-cab Auto Services Pte Ltd

AAD1907-210

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 9765B

Not Authorised
1/1/2019

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

23 JUL 2019

SHD 9765B
 VF1ABL15AUC277236
 RENAULT
 LATITUDE
 22.7.19
AXA
 31/3/2014

	PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>BALCON</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>NO</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>DI</i> 113.47	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	X
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>DI/NO</i> 323.05	<i>502 SL @ 16.15/3</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>NO</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>NO</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1907-210

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9765B

30	1	FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	X
31	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
32	1	WHEELARCH REAR RH	\$	SL	543.47	X
33	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
34	1	FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45	X
35	1	WHEELARCH REAR LH	\$	SL R	543.47	X
36	1	TAILLAMP RH	\$	CM	552.55	✓
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	CM	552.55	✓
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	nd	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X
46	1	FUEL FLAP	\$	SL	343.57	X
TOTAL			\$		36,212.51	
10%			\$		3,621.25	
			\$		32,591.26	

Special Nett

1	1SET	PARKING AID	\$	Shan	700.00	4000IN
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	nn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	nn	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	nn	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	nn	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	SL	385.00	X

Trans-cab Auto Services Pte Ltd

AAD1907-210

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9765B

17	1	SPARE TYRE	\$	Sm	330.00	X
18	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
19	1	TAILLAMP CLIP RH	\$	nka	5.00	✓
20	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	X
21	1	WINDSCREEN MOULDING	\$	nn	100.00	X
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
23	1	TAILLAMP CLIP LH	\$	nn	5.00	✓
24	1	FENDER INNER TRIM CLIP LH	\$	nn	28.00	} X
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
26	1	Rear left tyre	\$	Sm	330.00	
27	1	Rear left tyre rim	\$	Sm	380.00	} X
28	1	Rear right tyre	\$	Sm	330.00	
29	1	Rear right tyre rim	\$	Sm	380.00	
TOTAL			\$		3,645.02	
TOTAL PARTS			\$		36,236.28	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	660
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	600
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 60
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	

Trans-cab Auto Services Pte Ltd

AAD1907-210

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9765B

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>h</i> 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>h</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>h</i> 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>h</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i> 380.00	X

TOTAL \$ 19,200.00

Over All Total \$ 55,436.28

(LUMP SUM) Repair Days

25 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To of state of repair (not to during resurvey)
- Part of the repair work to be carried out
- To be carried out on a "Without Prejudice" basis
- No other work to be carried out
- Surveys to be carried out by resurveyed and
- To be carried out by resurveyed and

Acknowledged by Repairer

Signature

Date