

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 898K**AAD1907-191***Not Authored
Permy B4paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

23 JUL 2019**SHD 898K**

JTDKB3FU603078991

TOYOTA

PRIUS

20.7.19

III

11/1/2019

		PART		LIST	
1	1	REAR BUMPER	\$	<i>Bu</i> 458.60	<i>✓</i>
2	1	REAR BUMPER RE-INFORCEMENT	\$	318.80	<i>7</i>
3	1	REAR BUMPER TOWING COVER	\$	<i>SL</i> 14.70	<i>X</i>
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>SL</i> 552.60	<i>X</i>
5	1	ANTENNA, ELECTRICAL KEY	\$	<i>SL</i> 61.40	<i>X</i>
6	1	REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i> 112.70	<i>X</i>
7	1	REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i> 112.70	<i>✓</i>
8	1	REAR TAILGATE	\$	<i>N</i> 1,547.27	<i>X</i>
9	1	REAR TAILGATE OUTER GARNISH	\$	<i>SL</i> 910.40	
10	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i> 54.70	
11	1	COVER, REAR COMBINATION LAMP, LH	\$	<i>SL</i> 54.70	
12	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>SL</i> 93.60	
13	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>SL</i> 93.60	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>SL</i> 55.40	
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>SL</i> 55.40	
16	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i> 254.40	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>SL</i> 51.20	
18	1	REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i> 365.20	
19	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	<i>N</i> 641.50	
20	1	TAILLAMP LOWER RH	\$	<i>CM</i> 548.40	<i>✓</i>
21	1	TAILLAMP UPPER RH	\$	<i>SL</i> 557.90	<i>X</i>
22	1	REAR BUMPER SIDE RH	\$	<i>my M</i> 232.00	<i>✓</i>
23	1	REAR BUMPER SIDE LH	\$	<i>SL</i> 232.00	<i>X</i>
24	1	TAILLAMP LOWER LH	\$	<i>SL</i> 548.40	<i>X</i>
25	1	TAILLAMP UPPER LH	\$	<i>SL</i> 557.90	<i>X</i>
26	1	REAR RH FENDER PANEL	\$	<i>N</i> 836.70	<i>X</i>
27	1	REAR LH FENDER PANEL	\$	<i>N</i> 836.70	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1907-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 898K

28	1	LINER, REAR WHEEL HOUSE, LH	\$	138.10	}	X
29	1	LINER, REAR WHEEL HOUSE, RH	\$	138.10		
30	1	BOARD, BACK DOOR TRIM	\$	220.70		
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	351.10		
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	351.10		
33	1	COVER, FLOOR UNDER, NO.1	\$	172.60		
34	1	COVER, FLOOR UNDER, NO.2	\$	238.70		
35	1	COVER, REAR FLOOR	\$	226.80		
TOTAL			\$	11,996.07		
25%			\$	2,999.02		
			\$	8,997.05		

Special Nett

Special Net						
1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	22.00	✓
3	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	X
4	1	WINDSCREEN MOULDING	\$	nn	100.00	X
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
6	1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	—
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	—
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	✓
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	3000
10	1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	3000
11	1	REAR BUMPER PROTECTOR	\$	nn	100.00	} X
12	1	REAR WHEEL RIM	\$	Sn	1,570.55	
13	1	REAR WHEEL RIM COVER	\$	Sn	175.80	
14	1	SPARE WHEEL RIM	\$	Sn	1,570.55	
15	1	SPARE WHEEL RIM COVER	\$	Sn	175.80	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	}
17	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	
TOTAL			\$	4,978.10		
TOTAL PARTS			\$	13,975.15		

LABOUR

Trans-cab Auto Services Pte Ltd**AAD1907-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 898K

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	2001
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	7 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	7 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	7 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	7 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 898K

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

	\$	<i>an</i> 380.00	X
TOTAL	\$	12,100.00	

Over All Total	\$	26,075.15
-----------------------	----	------------------

(PART-BY-PART) Repair Days~~15 Days~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: