

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019
 VEHICLE NO: SLB4324L
 MODEL: AXIO
 YEAR: 2016
 ACCIDENT DATE: 24/07/2019
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR WINDSCREEN	1	\$ 1,064.20 <i>Cna</i>
REAR WINDSCREEN MOULDING	1	\$ 198.70 <i>ng</i>
REAR FENDER UPPER INNER TRIM	2	\$ 698.60 <i>r</i>
BOOTLID	1	\$ 986.30 <i>bt</i>
BOOTLID HINGE	2	\$ 299.40 <i>bt</i>
BOOTLID STOPPER	2	\$ 44.60 <i>na</i>
BOOTLID OUTER CHROME GARNISH	1	\$ 218.30 <i>Cna</i>
REAR NUMBER PLATE LAMP	2	\$ 398.60 <i>?</i>
BOOTLID LOCK	1	\$ 368.30 <i>? photo</i>
REAR EMBLEM	1	\$ 55.30 <i>na</i>
REAR LOGO - COROLLA	1	\$ 52.30 <i>na</i>
REAR LOGO - AXIO	1	\$ 54.20 <i>na</i>
REAR BUMPER	1	\$ 789.50 <i>dis</i>
REAR BUMPER CLIPS	10	\$ 30.00 <i>na</i>
REAR BUMPER RETAINER - LONG	2	\$ 84.80 <i>LH-?, RH-dis</i>
REAR BUMPER RETAINER - SHORT	2	\$ 68.40 <i>LH-? RH-dis</i>
REAR BUMPER REFLECTOR	2	\$ 488.60 <i>LH-r, RH-ant</i>
TAILLAMP	2	\$ 882.60 <i>Cna</i>
TAILLAMP SEAL	2	\$ 66.80 <i>na</i>
TAILLAMP CLIPS	2	\$ 24.60 <i>na</i>
TAILLAMP PANEL	2	\$ 488.60 <i>LH-RY, RH-bt</i>
END PANEL	1	\$ 596.30 <i>bt</i>
SPARE TYRE PANEL	1	\$ 782.30 <i>RY</i>
SPARE TYRE BOARD	1	\$ 399.70 <i>?</i>
END PANEL TOP GARNISH	1	\$ 255.60 <i>?</i>
REAR WEATHER STRIP	1	\$ 249.70 <i>? photo</i>

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019
VEHICLE NO: SLB4324L
MODEL: AXIO
YEAR: 2016
ACCIDENT DATE: 24/07/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

RH REAR FENDER	1	\$	976.90 <i>buc</i>
RH REAR FENDER INNER PANEL	1		REPAIR
RH REAR FENDER INNER SHIELD	1	\$	196.50 ?
RH REAR FENDER INNER SHIELD CLIPS	10	\$	30.00 ?
RH REAR DOOR	1		REPAIR
RH REAR CHASSIS	1		REPAIR
LH REAR FENDER	1		REPAIR
REAR FENDER INNER TRIM	2	\$	682.80 <i>LH-Y, RH-?</i>
REAR SPEAKER BOARD TRIM	1	\$	458.30 ?
EXHAUST PIPE	1	\$	986.40 <i>Rx</i>
EXHAUST PIPE GASKET	1	\$	45.30 ?
EXHAUST PIPE MOUNTING	2	\$	188.60 ?
ROOF PANEL TRIM	1	\$	1,023.30 X
TOTAL: \$			14,234.40
DISCOUNT 25%: \$			3,558.60
			<u>\$ 10,675.80</u>

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019

VEHICLE NO: SLB4324L

MODEL: AXIO

YEAR: 2016

ACCIDENT DATE: 24/07/2019

TYPE OF CLAIM: TP

CLAIM ADVISOR: LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATION

S/NET		PRICE	
REVERSE SENSOR	1	\$	250.00 <i>200 new</i>
REAR NUMBER PLATE	1	\$	50.00 <i>45 bt</i>
END PANEL SEALANT	1	\$	100.00 <i>40 new</i>
SPARE TYRE PANEL BLACK STICKER	1	\$	150.00 <i>X</i>
PANEL SEALANT	1	\$	100.00 <i>X</i>
REAR WINDSCREEN SEALANT	1	\$	100.00 <i>60 new</i>
		\$	750.00

LABOUR		PRICE	
LABOUR FOR FACILITATE REPAIR		\$	1,800.00 <i>1400</i>
TO RESPRAY AFFECTED AREAS - REAR BUMPER		\$	300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - END PANEL		\$	300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - LH REAR FENDER		\$	300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - RH REAR FENDER AND INNER PANEL		\$	300.00 <i>250</i>
TO RESPRAY AFFECTED AREAS - RH REAR DOOR		\$	300.00 <i>X</i>
TO RESPRAY AFFECTED AREAS - RH REAR CHASSIS		\$	300.00 <i>X</i>
TO STRAIGHTEN AND ALIGN RH REAR CHASSIS		\$	300.00 <i>200? plus 60</i>
TO REMOVE AND REFIT REAR WINDSCREEN		\$	150.00 <i>120</i>
RUST PROOFING		\$	80.00 <i>40</i>
SUNDARIES		\$	50.00 <i>20</i>
TO REMOVE AND REFIT REAR SEAT, SPEAKER BOAR, ROOF LINING, FLOOR BOAR		\$	250.00 <i>100</i>

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019
VEHICLE NO: SLB4324L
MODEL: AXIO
YEAR: 2016
ACCIDENT DATE: 24/07/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REAR EXHAUST
TO REMOVE AND REFIT REVERSE SENSOR
TO VACUUM AND CLEAN UP FRAGMENT GLASS
TO CHECK AND RECONNECT ALL NECESSARY WIRING

\$	250.00	60
\$	150.00	60.
\$	100.00	30
\$	80.00	40.
\$	100.00	30
TOTAL: \$	5,110.00	

TOTAL: \$	16,535.80
7% GST: \$	1,157.51
\$	17,693.31

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749

WP

humpun

Resurvey after repair

taufik@lkkauto.com

9-10 days

25/7/19 @ 245pm