

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019

VEHICLE NO: SLB4324L

MODEL: AXIO

YEAR: 2016

ACCIDENT DATE: 24/07/2019

TYPE OF CLAIM: TP

CLAIM ADVISOR: LOUIS ONG (91928963)

EMAIL: louisongautowheels@yahoo.com

NRE 16100

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR WINDSCREEN	1	\$ 1,064.20 <i>CR9</i>
REAR WINDSCREEN MOULDING	1	\$ 198.70 <i>net</i>
REAR FENDER UPPER INNER TRIM	2	\$ 698.60 <i>x</i>
BOOTLID	1	\$ 986.30 <i>bt</i>
BOOTLID HINGE	2	\$ 299.40 <i>bt</i>
BOOTLID STOPPER	2	\$ 44.60 <i>net</i>
BOOTLID OUTER CHROME GARNISH	1	\$ 218.30 <i>net</i>
REAR NUMBER PLATE LAMP	2	\$ 398.60 <i>x SVC</i>
BOOTLID LOCK	1	* \$ <i>dis</i> 368.30 <i>? photo Distorted</i>
REAR EMBLEM	1	\$ 55.30 <i>net</i>
REAR LOGO - COROLLA	1	\$ 52.30 <i>net</i>
REAR LOGO - AXIO	1	\$ 54.20 <i>net</i>
REAR BUMPER	1	\$ 789.50 <i>dis</i>
REAR BUMPER CLIPS	10	\$ 30.00 <i>net</i>
REAR BUMPER RETAINER - LONG	2	✓ \$ 42.40 <i>80.80 LH-RH-dis</i>
REAR BUMPER RETAINER - SHORT	2	✓ \$ 34.20 <i>68.40 LH-RH-dis</i>
REAR BUMPER REFLECTOR	2	✓ \$ 244.30 <i>488.60 LH-RH-dis</i>
TAILLAMP	2	\$ 882.60 <i>CR9</i>
TAILLAMP SEAL	2	\$ 66.80 <i>net</i>
TAILLAMP CLIPS	2	\$ 24.60 <i>net</i>
TAILLAMP PANEL	2	✓ \$ 244.30 <i>488.60 LH-RH-dis</i>
END PANEL	1	\$ 596.30 <i>bt</i>
SPARE TYRE PANEL	1	\$ 782.30 <i>RY</i>
SPARE TYRE BOARD	1	\$ 399.70 <i>x net</i>
END PANEL TOP GARNISH	1	* \$ 255.60 <i>? Deform de</i>
REAR WEATHER STRIP	1	* \$ 249.70 <i>? photo Deform</i>

6,801.90

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019
 VEHICLE NO: SLB4324L
 MODEL: AXIO
 YEAR: 2016
 ACCIDENT DATE: 24/07/2019
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: loulisongautowheels@yahoo.com

ESTIMATION

RH REAR FENDER	1	\$	976.90	huc
RH REAR FENDER INNER PANEL	1		REPAIR	
RH REAR FENDER INNER SHIELD	1	\$	196.50	X SVC
RH REAR FENDER INNER SHIELD CLIPS	10	\$	30.00	X N/N
RH REAR DOOR	1		REPAIR	1,318.30
RH REAR CHASSIS	1		REPAIR	
LH REAR FENDER	1		REPAIR	
REAR FENDER INNER TRIM	2	* \$	341.40	682.80 LH-X, RH-? de
REAR SPEAKER BOARD TRIM	1	\$	458.30	? X SVC
EXHAUST PIPE	1	\$	986.40	Rx
EXHAUST PIPE GASKET	1	\$	45.30	? X SVC
EXHAUST PIPE MOUNTING	2	\$	188.60	? X SVC
ROOF PANEL TRIM	1	\$	1,023.30	X SVC
TOTAL:		\$	14,234.40	8,120.2
DISCOUNT 25%:		\$	3,558.60	25%
		\$	10,675.80	6,090.15

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#07-10 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019
 VEHICLE NO: SLB43241
 MODEL: AXIO
 YEAR: 2016
 ACCIDENT DATE: 24/07/2019
 TYPE OF CLAIM: TP
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

S/NET		PRICE	
REVERSE SENSOR	1	\$ 250.00	200nw
REAR NUMBER PLATE	1	\$ 50.00	45 fl
END PANEL SEALANT	1	\$ 100.00	40nw
SPARE TYRE PANEL BLACK STICKER	1	\$ 150.00	x nn
PANEL SEALANT	1	\$ 100.00	x nn
REAR WINDSCREEN SEALANT	1	\$ 100.00	60nw
		\$ 750.00	345

LABOUR	PRICE	
LABOUR FOR FACILITATE REPAIR	\$ 1,800.00	1400
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$ 300.00	200
TO RESPRAY AFFECTED AREAS - END PANEL	\$ 300.00	200
TO RESPRAY AFFECTED AREAS - LH REAR FENDER	\$ 300.00	200
TO RESPRAY AFFECTED AREAS - RH REAR FENDER AND INNER PANEL	\$ 300.00	250
TO RESPRAY AFFECTED AREAS - RH REAR DOOR	\$ 300.00	x nn
TO RESPRAY AFFECTED AREAS - RH REAR CHASSIS	\$ 300.00	x nn
TO STRAIGHTEN AND ALIGN RH REAR CHASSIS	\$ 300.00	200? photo
TO REMOVE AND REFIT REAR WINDSCREEN	\$ 150.00	120
RUST PROOFING	\$ 80.00	40
SUNDARIES	\$ 50.00	20
TO REMOVE AND REFIT REAR SEAT, SPEAKER BOAR, ROOF LINING, FLOOR BOAR	\$ 250.00	100
		2530

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 24/07/2019
VEHICLE NO: SLB4324L
MODEL: AXIO
YEAR: 2016
ACCIDENT DATE: 24/07/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS ONG (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REAR EXHAUST
TO REMOVE AND REFIT REVERSE SENSOR
TO VACUUM AND CLEAN UP FRAGMENT GLASS
TO CHECK AND RECONNECT ALL NECESSARY WIRING

\$	250.00	60	220
\$	150.00	60	
\$	100.00	30	
\$	80.00	40	
\$	100.00	30	27.50
TOTAL: \$	5,110.00		

TOTAL: \$	16,535.80	9,185.15
7% GST: \$	1,157.51	7,350
\$	17,693.31	9

Tanglim 97495749

WP

1 humpsum

Resum after repair

Tanglim @ Khanta. w.m.

9-10 days

25/7/19 @ 245pm.

3/10 Email Louis