



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34490

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 20/07/2019
CLAIM NO. : 11394
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBF5919L
MAKE/MODEL : YAM / XVS950A

*not Afford
1/5
3 day
24/7/19
The photo Afford*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	FOOTREST FRONT LH ASSY	REPLACE	1.00	\$454.00	454.00 X
2	FOOTREST FRONT RH ASSY	REPLACE	1.00	\$454.00	454.00 X
3	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS		1.00	\$175.00	175.00
4	LEVER BRAKE ASSY	REPLACE	1.00	\$52.00	52.00
5	LEVER CLUTCH	REPLACE	1.00	\$58.00	58.00 X
6	MIRROR LH ASSY	REPLACE	1.00	\$149.00	149.00 X
7	MIRROR RH ASSY	REPLACE	1.00	\$149.00	149.00
8	MUFFLER ASSY 1	REPLACE	1.00	\$3,353.00	3,353.00
9	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$16.00	16.00 10
10	SEAT BASE	REPLACE	1.00	\$7.00	7.00 ?
11	TAIL LIGHT ASSY <i>1/issue plate</i>	REPLACE	1.00	\$158.00	158.00
12	TRANSPORT CHARGES P/N: 07169	Supply/Install	1.00	\$35.00	35.00 X

SUB TOTAL
GST @ 7 %

\$5,060.00
\$354.20



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 20021-0383
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL					\$5,414.20

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0363
ISO 9001:2015