



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34487

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
MOTOR CLAIMS DEPT

DATE : 17/07/2019
CLAIM NO. : 11393
POLICY NO. : AVFMSB0000591904

FROM : RAYMOND

VEHICLE NO. : FBL9039T
MAKE/MODEL : YAM / YBR125

*Not Actual
hike
Take photo through
Sh.
24/7/19*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062	REPLACE	1.00	\$69.00	69.00
2	BRACKET MUDGUARD FRONT P/N: 46221	REPLACE	1.00	\$24.00	24.00
3	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180.00 ?
4	CAP, RESERVOIR	REPLACE	1.00	\$42.00	42.00 ?
5	COVER TANK SIDE LH (BLACK) P/N: 54458	REPLACE	1.00	\$98.00	98.00
6	COWLING FRONT (BLACK) P/N: 50000	REPLACE	1.00	\$283.00	283.00
7	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
8	FORK FRONT ASSY LH P/N: 56248	REPLACE	1.00	\$624.00	624.00 ?
9	FORK FRONT ASSY RH P/N: 53204	REPLACE	1.00	\$625.00	625.00 ?
10	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	\$14.00	14.00
11	GUIDE AIR LH P/N: 48403	REPLACE	1.00	\$23.00	23.00
12	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$490.00	490.00
13	LABOUR P/N: 06766	Supply/Install	8.00	\$35.00	280.00
- LABOUR FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED					



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LAMP SIGNAL FRONT RH P/N: 42003	REPLACE	1.00	\$54.00	54.00
15	LEVER BRAKE P/N: 50001	REPLACE	1.00	\$23.00	23.00
16	METER ASSY P/N: 50954	REPLACE	1.00	\$328.00	328.00
17	MIRROR RH P/N: 54029	REPLACE	1.00	\$80.00	80.00
18	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$98.00	98.00
19	PEDAL GEAR P/N: 50002	REPLACE	1.00	\$20.00	20.00
20	PIPE EXHAUST ASSY P/N: 50025	REPLACE	1.00	\$1,665.00	1,665.00?
21	PLATE FRONT COWLING P/N: 46220	REPLACE	1.00	\$26.00	26.00?
22	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
23	SPRAY PAINT COVER TANK SIDE LH	Spray	1.00	\$28.00	28.00
24	SPRAY PAINT COWLING FRONT	Spray	1.00	\$63.00	63.00 ⁵⁰
25	SPRAY PAINT FRONT MUDGUARD	Spray	1.00	\$45.00	45.00 ³⁰
26	STAY HEADLAMP P/N: 45750	REPLACE	1.00	\$68.00	68.00?
27	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	66.00?
28	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	2.00	\$16.00	32.00
29	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00 ¹⁰
30	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO OUTLET ONCE REPAIR DONE .		1.00	\$35.00	35.00
31	WELDING WORK P/N: 18037 - WELDING FOR CRASHBAR BRACKET	Knocking	1.00	\$60.00	60.00

SUB TOTAL

\$5,664.00

GST @ 7 %

\$396.48

GRAND TOTAL

\$6,060.48

50% deposit required before ordering of parts.

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
Validity: 30 days					

For & on Behalf of

BAN HOCK HIN CO PTE LTD**RAYMOND**

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**bizSAFE₃**