

Trans-cab Auto Services Pte Ltd

AAD1907-195

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5888G

Not Authored
Recovery By Paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

23 JUL 2019

SHD 5888G

JTDKB3FU203077062

TOYOTA

PRIUS

20.7.19

AXA

4/12/2018

		PART		LIST	
1	1	REAR BUMPER	\$	Bul/Re 458.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	BT 318.80	✓
3	1	REAR BUMPER TOWING COVER	\$	Re 14.70	✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	Re/Re 552.60	✓
5	1	ANTENNA, ELECTRICAL KEY	\$	Re 61.40	X
6	1	REAR BUMPER SIDE RETAINER LH	\$	Re 112.70	X
7	1	REAR BUMPER SIDE RETAINER RH	\$	Re 112.70	X
8	1	REAR BUMPER SIDE RH	\$	Cra 232.00	✓
9	1	REAR BUMPER SIDE LH	\$	Re 232.00	X
10	1	REAR TAILGATE	\$	Re 1,547.27	X
11	1	REAR TAILGATE OUTER GARNISH	\$	Re 905.10	X
12	1	COVER, REAR COMBINATION LAMP, RH	\$	Re 54.70	} X
13	1	COVER, REAR COMBINATION LAMP, LH	\$	Re 54.70	
14	1	GARNISH, BACK DOOR SIDE, LH	\$	Re 93.60	
15	1	GARNISH, BACK DOOR SIDE, RH	\$	Re 93.60	
16	1	BOARD ASSY, BACK DOOR TRIM	\$	Re 254.40	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	Re 51.20	
18	1	REAR TAILGATE WEATHERSTRIP	\$	Re 365.20	
19	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	Re 55.40	
20	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	Re 55.40	
21	1	BOARD, BACK DOOR TRIM	\$	Re 220.70	
22	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	Re 641.50	
23	1	TAILLAMP LOWER RH	\$	Re 548.40	
24	1	TAILLAMP UPPER RH	\$	Re 557.90	
25	1	TAILLAMP LOWER LH	\$	Re 548.40	
26	1	TAILLAMP UPPER LH	\$	Re 557.90	
27	1	PANEL SUB-ASSY, QUARTER, LH	\$	Re 836.70	
28	1	PANEL SUB-ASSY, QUARTER, RH	\$	Re 836.70	
29	1	LINER, REAR WHEEL HOUSE, LH	\$	Re 138.10	

Trans-cab Auto Services Pte Ltd**AAD1907-195**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5888G

30	1	LINER, REAR WHEEL HOUSE, RH	\$	138.10	X
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	351.10	X
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	351.10	X
33	1	COVER, FLOOR UNDER, NO.1	\$	172.60	X
34	1	COVER, FLOOR UNDER, NO.2	\$	238.70	X
35	1	COVER, REAR FLOOR	\$	226.80	X
36	1	FRONT BUMPER	\$	499.90	✓
37	1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	101.20	X
38	1	REINFORCEMENT, FRONT BUMPER	\$	BT 696.40	✓
39	1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	svc 242.80	X
40	1	ABSORBER, FRONT BUMPER, LOWER	\$	svc 130.20	X
41	1	ABSORBER, FRONT BUMPER ENERGY	\$	svc 78.10	X
42	1	FRONT BUMPER SIDE RETAINER RH	\$	112.70	X
43	1	FRONT BUMPER SUPPORT	\$	81.70	X
44	1	FRONT BUMPER SIDE RETAINER LH	\$	112.70	}
45	1	COVER SUB-ASSY, ENGINE, NO.1	\$	466.00	
46	1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	238.70	
47	1	EXTENSION, FRONT BUMPER, RH	\$	118.50	
48	1	EXTENSION, FRONT BUMPER, LH	\$	118.50	
49	1	FRONT LED LAMP (LOWER) LH	\$	907.75	
50	1	FRONT HEADLAMP LH	\$	2,909.04	
51	1	FRONT LED LAMP (LOWER) RH	\$	907.75	
52	1	FRONT HEADLAMP RH	\$	2,909.04	
53	1	FRONT FENDER RH	\$	945.30	
54	1	EXTENSION, FRONT FENDER, RH	\$	48.80	
55	1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	98.30	
56	1	LINER, FRONT FENDER, RH	\$	200.70	
57	1	FRONT FENDER EMBLEM	\$	86.50	
58	1	FRONT FENDER LH	\$	945.30	
59	1	EXTENSION, FRONT FENDER, LH	\$	48.80	
60	1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	98.30	
61	1	LINER, FRONT FENDER, LH	\$	200.70	
62	1	FRONT FENDER EMBLEM	\$	86.50	
63	1	GRILLE SUB-ASSY, RADIATOR	\$	341.60	}
64	1	GRILLE, RADIATOR, LOWER NO.1	\$	167.90	
65	1	FRONT BONNET	\$	969.00	
TOTAL			\$	26,859.45	
25%			\$	6,714.86	

Trans-cab Auto Services Pte Ltd

AAD1907-195

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5888G

\$	20,144.59
----	------------------

Special Nett

1	1SET PARKING AID	\$	Pl 700.00	X
2	1SET REAR BUMPER CLIP	\$	nn 66.00	✓
3	2 REAR WINDSCREEN SEALANT	\$	nn 80.00	X
4	1 WINDSCREEN MOULDING	\$	nn 100.00	X
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	X
6	1 REAR TAILGATE TOYOTA LOGO	\$	nn 47.00	—
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	nn 52.90	—
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	nn 53.50	✓
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn 80.00	3000
10	1 REAR TAILGATE STICKER '6555-3333'	\$	nn 80.00	3000
11	1 REAR BUMPER PROTECTOR	\$	nn 100.00	4000
12	1 FRONT WHEEL RIM	\$	Pl 1,570.55	X
13	1 FRONT WHEEL RIM COVER	\$	Pl 175.80	X
14	1 CLIP, FRONT FENDER LINER	\$	Pl 22.00	X
15	1 REAR WHEEL RIM	\$	Pl 1,570.55	X
16	1 REAR WHEEL RIM COVER	\$	Pl 175.80	X
17	1SET BUMPER CLIP FRT	\$	nn 66.00	✓
18	1 FRONT NUMBER PLATE WITH MOULDING	\$	Pl 200.00	X

TOTAL	\$	5,240.10
--------------	----	-----------------

TOTAL PARTS	\$	25,384.69
--------------------	----	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	8000
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6000
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	500
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-195**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5888G

To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
Towing Fees.	\$	nn	150.00	X
To Check Electrical Lighting Concerned.	\$		170.00	faq
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	nn	480.00	X

Trans-cab Auto Services Pte Ltd**AAD1907-195**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5888G

To transfer of Bonnet fittings, attachments and perform
water seepage test.

\$ ~~170.00~~ 170.00 X

To transfer of Front Fender fittings, attachments and
perform water seepage test.

\$ ~~170.00~~ 170.00 X**TOTAL \$ 16,040.00****Over All Total \$ 41,424.69****(PART-BY-PART) Repair Days**~~20 DAYS~~

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: