

**Trans-cab Auto Services Pte Ltd**

AAD1907-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5404A

*Not Whorw**L1 Sy 8*

Vehicle No.:

Chassis No.:

Vehicle Make:

23 JUL 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5404A

VF1ABL15AUC279603

RENAULT

LATITUDE

21.7.19

AXA

4/11/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>n</i> 2,844.66 X
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Ln</i> 466.51 X
1	ROCKER PANEL INNER RH	\$	<i>Ln</i> 1,024.79 X
1	ROCKER PANEL OUTER RH	\$	<i>n</i> 1,184.99 X
1	ROCKER PANEL CENTER RH	\$	<i>n</i> 990.25 X
1	BOOT REFLECTOR LAMP RH	\$	<i>n</i> 493.35 X
1	FENDER PANEL REAR RH	\$	<i>Bu</i> 3,299.13 ✓
1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Ln</i> 671.45 X
1	WHEELARCH REAR RH	\$	<i>Ln</i> 543.47 ✓
1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
1	BUMPER LOWER REAR	\$	<i>Ln</i> 768.84
1	BUMPER BRACKET CTR REAR	\$	<i>Ln</i> 113.47
1	BUMPER BRACKET SIDE RH REAR	\$	<i>Ln</i> 135.97
1	BUMPER RETAINER RH REAR	\$	<i>Ln</i> 44.99
1	BUMPER REFLECTOR RH	\$	<i>Ln</i> 43.61
1	BUMPER BEAM REAR	\$	<i>n</i> 777.52
1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95
1	TAILLAMP RH	\$	<i>Ln</i> 552.55
1	TAILLAMP PANEL RH	\$	<i>n</i> 986.70
TOTAL		\$	16,276.66
10%		\$	1,627.67
		\$	14,649.00

**Special Nett**

1	REAR DOOR STICKER '6555-3333'	\$	<i>nn</i> 80.00 X
1	FENDER INNER TRIM CLIP RH	\$	<i>nn</i> 28.00 X
1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00 X
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i> 80.00 <i>40sn</i>

**Trans-cab Auto Services Pte Ltd**

AAD1907-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5404A

1	WINDSCREEN MOULDING	\$	nn	100.00	✓
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn
1	REAR RIGHT TYRE	\$	sn	300.00	X
1	REAR RIGHT TYRE RIM	\$	sn	380.00	X
1SET	PARKING AID	\$	sn	700.00	X
1SET	REAR BUMPER CLIP	\$	nn	66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	✓
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
1SET	BUMPER RETAINER CLIP RH RR	\$	nn	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	X
1	EXHAUST MOUNTING REAR	\$	nn	17.82	X
<b>TOTAL</b>		<b>\$</b>		<b>2,042.82</b>	
<b>TOTAL PARTS</b>		<b>\$</b>		<b>16,691.82</b>	

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	600
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To rust-proofing of the affected areas.	\$	170.00	30
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1907-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5404A

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
Putty and spray painting of the affected portion.	\$	4,500.00	4401
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To apply paint protection system (PPS) maintain and enhancement	\$	~ 380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>12,350.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>29,041.82</b>	

**LUMP SUM (REPAIR DAY)**~~15 DAYS~~

4 days

<p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by Repairer Signature: Date:</p>
---