

Meriden

1CC3/ALG19013064/Asf3m2

ASSIGNMENT

From: _____ Date: **24/7/19**

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SMJ9503A**

at Workshop mis: **Premium**

of: **55 ubi Road**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: **\$800/-**

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **120K.**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **11 / 8/9** days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SMJ9503A.** Regn: **2019 March**

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Audi Q2** CC: **999.**

Colour: **Yellow.** A/C: Insured / Std / NI / NA

Sp. Reading: **66/3.** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WAUZZ2GAKA022456**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size: F: **225/45 R18.**
R: **225/45 R18.**

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear
R/Bal. 96 mm		R/Bal. 96 mm
L/Bal. 96 mm		L/Bal. 96 mm
D.O.A. _____		D.O.I. 24/07/19.

Survey held at: **Premium.**

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD ALG.
25/07/19 @ 10:10 am	received IA to AZG via meriden.
25/07/19 @ 10:11 am	mandate request authorize repair to AZG via meriden
29/07/19 @ 16:19 pm	mandate approved by Victor Koh.
29/07/19 @ 17:02 pm	inform clg to Troy via email.
2/8/19	Pending Supplementary approval
23/10/19	Combined P/P \$19,768.48 @ 11 days

Days Of Repair: **11**

Resurvey No. of Trip: **1**

Survey Fee: _____

Transportation: **200**

Phone: **11**

Other: _____

Grand Total: **211**

Cost/Time. File Pass to? **16/11/20**

1) Typist ☒ : Final Report

Cost/Time. File Return to? _____

3

Report Format: _____

Lump Sum **19,768.48 P/P**

Add Fee: ☐ : Site Insp 15
☐ : Interview 15
☐ : Tech Insp 15
☐ : (New) eng 15

RECEIVED 10 JAN 2020

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 16 Aug 2019

Preliminary Advice

Vehicle No	: SMJ9503A	Accident Date	: 21/07/2019
Make	: AUDI Q2	Policy No.	: 1900079887
Assignment Date	: 24/07/2019	Excess	: S\$800.00
Date of Inspection	: 24/07/2019	Est. Duration of Repair	: 9 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,266.00 (incl.supplementary \$681.00)
Revised Amount	:S\$	20,917.50 (incl check items and supplemenata
Check Items (Estimated)	:S\$	3,585.00
Total	:S\$	24,502.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	44,632.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,368.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Supplementary \$ 681.00, check items given \$ 2,044.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 02 Aug 2019

Preliminary Advice

Vehicle No	: SMJ9503A	Accident Date	: 21/07/2019
Make	: AUDI Q2	Policy No.	: 1900079887
Assignment Date	: 24/07/2019	Excess	: S\$800.00
Date of Inspection	: 24/7/2019	Est. Duration of Repair	: 9
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,266.00 (incl.supplementary \$681.00)
Revised Amount	:S\$	18,364.50 (incl.supplementary \$681.00)
Check Items (Estimated)	:S\$	5,629.00
Total	:S\$	23,993.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	44,632.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,368.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Jul 2019

Preliminary Advice

Vehicle No	: SMJ9503A	Accident Date	: 20/07/2019
Make	: AUDI Q2	Policy No.	: 1900079887
Assignment Date	: 24/07/2019	Excess	: S\$0.00
Date of Inspection	: 24/07/2019	Est. Duration of Repair	: 9 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,585.00
Revised Amount	:S\$	17,683.50
Check Items (Estimated)	:S\$	5,629.00
Total	:S\$	23,312.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	44,632.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,368.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 29 July 2019 5:08 PM
To: 'Claims'
Cc: Admin-D (LKKAuto); Admin A; SUR; assignments
Subject: RE: OD CLAIM FOR YOUR INSURED SMJ 9503 A DOA: 21/07/2019 VEHICLE IN

Dear Troy,

Please refer to the below email from AIG.

From: Chan, Yoke Shi [mailto:yokeshi.chan@aig.com]
Sent: Monday, 29 July 2019 5:04 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: Lim, Sheng Yang <ShengYang.Lim@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>
Subject: OD claim # SMJ9503A

Dear Shirley,

As spoken, please inform Premium Automobiles to assist insured to activate the LOU for insured.

Thank you

Regards,

Yoke Shi
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 29 July 2019 5:02 PM
To: 'Claims' <claims@premiumauto.com.sg>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: OD CLAIM FOR YOUR INSURED SMJ 9503 A DOA: 21/07/2019 VEHICLE IN

Dear Troy,

As instructed by our client, please proceed to repair the insured vehicle **SMJ 9503A (Excess S 800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Monday, 29 July 2019 3:12 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: 'Claims Dept' <claims@premiumauto.com.sg>

Subject: RE: OD CLAIM FOR YOUR INSURED SMJ 9503 A DOA: 21/07/2019 VEHICLE IN

Dear all,

Kindly assist to advise for this case mentioned and for approval.

Thanks

Best Regards,

TRoy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 19990221W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Thursday, 25 July 2019 8:52 AM

To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'; 'assignments'

View Received Message

This mail is associated with :

***SMJ9503A (6653322787SG)**

OD

Jul 21 2019 3:00PM

[TOH LAY LING]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 02/12/2019 10:42 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$19768.48) - SMJ9503A - Claim Handler: Chan, Yoke Shi

Approved:19768.48.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SMJ9503A (6653322787SG)**

OD

Jul 21 2019 3:00PM

[TOH LAY LING]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/08/2019 15:16 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$20917.50) - SMJ9503A - Claim Handler: Chan, Yoke Shi

Approved:20917.50:

DOCUMENTS SUMMARY

There are no documents.

View Sent Message

This mail is associated with :

***SMJ9503A (66533227875G)**

OD

Jul 21 2019 3:00PM

[TOH LAY LING]

Premium Automobiles Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 16/08/2019 11:30 AM.

To Victor-CK.Koh@aig.com

CC yokeshi.chan@aig.com; sur@lkkauto.com

Subject Fw: Re: Alert - Adj Mandate Maintained - SMJ9503A - Claim Handler: Chan, Yoke Shi

RE-SEND

Hi Victor,

We refer to your below email above matter.

Check items no. given is items no. 11, 12, 13, 29, 37, 39, 43, 53, 61, 63.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 05/08/2019 09:42 AM

Subject: Alert - Adj Mandate Maintained - SMJ9503A - Claim Handler: Chan, Yoke Shi

Maintained:What are the check items given?

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SMJ9503A (6653322787SG)**

OD

Jul 21 2019 3:00PM

[TOH LAY LING]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 05/08/2019 09:42 AM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SMJ9503A - Claim Handler: Chan, Yoke Shi

Maintained:What are the check items given?

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SMJ9503A (6653322787SG)**

OD

Jul 21 2019 3:00PM

[TOH LAY LING]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 29/07/2019 16:19 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$17683.50) - SMJ9503A - Claim Handler: Chan, Yoke Shi

Approved:17683.50:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 4 December 2019 11:13 am
To: Boo seng yak
Cc: Adrian Ling (LKKAuto); SUR; Carrine Leong; Chang Chee Sing; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SMJ9503A - OD AIG - SURVEYED 24 JUL 19

Dear Mr. Boo,

Confirmed final fig \$19,768.48 @ 11 days of repairs before excess \$ 800/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, 17 October 2019 2:17 pm
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SMJ9503A - OD AIG - SURVEYED 24 JUL 19

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$19,768.48 @ 11 days of repairs exclude 2 Sundays.

Your early closure is well appreciated.

Best regards - jb

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 748A

Vehicle Details

Vehicle No.: SMJ9503A
Vehicle to be Exported: No
Intended Deregistration Date: 25 Jul 2019
Vehicle Make: AUDI
Vehicle Model: Q2 1.0 TFSI S TRONIC
Primary Colour: Yellow
Manufacturing Year: 2018
Engine No.: CHZC26341
Chassis No.: WAUZZZGA5KA022456
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$23,678.00
Original Registration Date: 26 Mar 2019
First Registration Date: 26 Mar 2019
Transfer Count: 0
Actual ARF Paid: \$25,150.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Mar 2029
PARF Rebate Amount: \$18,862.00

Intended COE Rebate Details

COE Expiry Date: 25 Mar 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$26,659.00
COE Rebate Amount: \$25,770.00
Total Rebate Amount: \$44,632.00

The information contained herein is correct as at 25 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/07/2019 18:52
Date Of Accident	21/07/2019 15:45
Exact Location Of Accident	ALONG PIE AT THE ENTRANCE TO CLEMENTI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ9503A
Insured/Policyholder	
Name Of Registered Owner	TOH LAY LING
NRIC No	SXXXX748A
Email Address	TOH.LAYLING@CHANGIAIRPORT.COM
Mobile Phone No	(LOCAL) +65-96844409
Alternative Phone No	OTHERS-96844409

Vehicle Particulars

Manufacturer	AUDI
Model	Q2 1.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900079887
Cover Note Number	

Driver

Name of Driver	SIM YEW KEONG
NRIC No	SXXXX494H
Date Of Birth	04/02/1977
Occupation	INDOOR
Date Of Driving Pass	13/11/2007
Driving Experience	11 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91144070
Fax Number	
Contact Number	OTHERS-91144070

Address	APT BLK 272 TOH GUAN ROAD #09-79
Postcode	600272
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : TAN LAY LING GENDER: : FEMALE
Passenger 2	NAME: : OLIVER SIM GENDER: : MALE
Passenger 3	NAME: : OSCAR SIM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS I WAS SIGNALLING TO SWITCH LANE FROM 1ST TO 2ND LANE, A BIKE APPEARED AT THE 2ND LANE NO TIME AND SPACE TO STOP, SO MY CAR HIT THE CAR IN FRONT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD9010Z
Vehicle Make/Model/Colour	MAZDA 5 BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PUNG HEE LEONG, MALCOM

NRIC/Passport Number

S8013280H

Contact Number

98799614

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature

Date & Time: 22 Jul 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Chan SG Heo, Tony

NRIC/ID No.: S687494V

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I was signaling to switch lane from 1st to 2nd lane, a bike appeared, a I cut back into the 1st lane, but there was ^{at the 2nd lane} no time and space to stop, so my ~~the~~ car hit the car in front.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

22 Jul 2019

maximus Sun

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre (Punjab)'s Signature
Name: Chhvi Shri Ravi
NRC/CTN No: 15 08052019

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA 119095968 Vehicle Registration No : SMJ 9503A
Name (as shown in NRIC) : Teh Lay Ling NRIC/FIN/Passport No : S78127484
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : Apt Bk 272 Teh Guan Road # 09-79 600272 Singapore ()
Contact (Tel) : 9684409 Mobile No. : _____
Email Address : teh.layling@chang-airport.com
Date of Accident : 21/7/2019 Time of Accident : 15:45pm
Place of Accident : Along IE at the entrance to Changi Road.
Insurance Company : AI

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Correction the date of accident from 20/7/2019 to 21/7/2019

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: Chia Shi Hoo, Tracy
NRIC/FIN No.: C65877926
Date: 26/7/2019

Accident Photo





Name of Policyholder : TOH LAY LING (ZHUO LILING)
Period of Insurance : 26 Mar 2019 To 25 Mar 2021
Engine No. : CHZC26341
Chassis No. : WAUZZZGA5KA022456

Vehicle No. : SMJ9503A
Policy No. : 1900079887
Endorsement No. :
Issued Date : 27 Mar 2019

Make/Model	AUDI Q2/ Q2 Sport 1.0 TFSI S tronic				
Engine Capacity/Tonnage	999.00 CC	Sum Insured	Market Value	First Year of Registration	2019
Driver Restriction	NA	Off Peak Car	No	Insuring with COE/PARF	Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as 'Inexperienced Driver Excess' (IDR) if you are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Limitation as to use*

Use only for social, domestic, and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 106) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreens : \$100

Named Driver and Excess (where applicable)

TOH LAY LING (ZHUO LI LING) - \$800 (Owen Darmstad)

1. Audi Customer Service Center Add: 35 Ubi Road 1 Singapore 408698 63662323

For other Approved Reporting Centres/AIG Authorised Repairs, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125263

PREMIUM LEASING - NO

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159838

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Cheng Cheng Chen

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte, Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0890/2019/TG
Date : 23-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Toh Lay Ling
Address : Apt Blk 272 Toh Guan Road
#09-79
Singapore 600272
Telephone : (HP) +65 96844409
Type of Claim : Own Damage Claims
Policy No. : 1900079887
Vehicle No : **SMJ 9503 A**
Model Code : Audi Q2 1.0 TFSI S Tronic
Model / Year : 26/3/2019
Engine No : CHZ C26341
Chassis No : WAUZZZGA5KA022456
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jul-19
Place of Accident : Along PIE at the entrance to clementi road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMJ 9503 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and renew aircond condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,400.00 ✓	R.S.
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00 X.	
4	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align console to position. Re-install all parts removed.	\$ 7,200.00	3000 (with Lock Carrier) 1750 (without Lock Carrier)
5	To respray front bumper, both front fenders, bonnet and lhs front door.	\$ 5,300.00	2200
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 14,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMJ 9503 A**

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	S	1,705.00	✓ 1364.00
2	FRONT BUMPER FIXING PARTS <i>new</i>	S	314.00	+
3	FRONT BUMPER GRILLE - CENTER <i>Cracked</i>	S	179.00	✓ 143.20
4	FRONT BUMPER AIR GRILLE - LH / RH <i>RH Distorted</i>	2 S	307.00	153.50 122.80
5	FRONT BUMPER AIR GRILLE REAR COVER - LH / RH <i>Not New</i>	2 S	61.00	° X
6	FRONT BUMPER SPOILER <i>Distorted</i>	S	273.00	✓ 218.00
7	FRONT BUMPER CLOSING ELEMENT <i>Not Nec</i>	S	142.00	? X
8	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2 S	62.00	+
9	ADAPTER - LH / RH <i>Not Nec</i>	2 S	70.00	? X
10	RADIATOR GRILLE <i>Cracked</i>	S	1,301.00	✓ 1040.80
11	RADIATOR STRIKER PLATE <i>Cracked</i>	S	114.00	? ✓ 91.20
12	FRONT BUMPER CARRIER <i>Best</i>	S	625.00	? ✓ 499.60
13	FRONT BUMPER FOAM FILLER PIECE <i>Cracked</i>	S	71.00	? ✓ 56.08
14	FRONT BUMPER TOP COVER <i>Distorted</i>	S	91.00	✓ 72.56
15	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 S	64.00	+
16	CAUTION STICKER <i>3</i>	S	13.00	✓ 9.76
17	AC STICKER <i>new</i>	S	7.00	✓ 5.12
18	SIGNAL HORN - LOW TONE LH <i>Not Nec</i>	S	262.00	? X
19	SIGNAL HORN - HIGHT TONE RH <i>Not Nec</i>	S	180.00	? X
20	SPRING SHACKLE - LH / RH <i>new</i>	2 S	57.00	+
SUB TOTAL SPARE PARTS		:	\$ 5,898.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMJ 9503 A**

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remark
21	FRONT FENDER - LH / RH <i>LH Bucleled, RH Repair</i>	2	S	2,094.00	<i>1048. 837.60</i>
22	FRONT FENDER ATTACHEMENT PARTS <i>Not New</i>	2	S	72.00	<i>? X</i>
23	POP RIVET <i>Not</i>	12	S	36.00	<i>x ✓ 28 80</i>
24	FRONT FENDER BRACE - RH <i>new</i>		S	29.00	<i>x</i>
25	WHEEL HOUSING LINER - RH <i>new</i>		S	183.00	<i>x</i>
26	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		S	52.00	<i>x</i>
27	BONNET <i>Distorted</i>		S	2,549.00	<i>✓ 2039.20</i>
28	BONNET ATTACHMENT PARTS <i>new</i>		S	149.00	<i>? X</i>
29	BONNET LID HINGE - LH / RH <i>Dist. Bent.</i>	2	S	111.00	<i>x ? ✓ 88.48</i>
30	GAS FILLED STRUT <i>new</i>		S	93.00	<i>x</i>
31	SOUND ABS FOR ENGINE BONNET <i>new</i>		S	201.00	<i>x</i>
32	IMPACT PROTECTION - CENTER		S	27.00	<i>✓ 21.20</i>
33	IMPACT PROTECTION - LH		S	28.00	<i>✓ 22.00</i>
34	IMPACT PROTECTION - RH		S	27.00	<i>✓ 21.20</i>
35	FRONT FENDER COVER - RH <i>new</i>		S	37.00	<i>x</i>
36	DEFLECTOR COVER - LH / RH <i>new</i>	2	S	28.00	<i>x</i>
37	BOWDEN CABLE - CENTER <i>Damaged</i>		S	53.00	<i>? ✓ 41.68</i>
38	LID LOCK CABLE <i>Not new</i>		S	67.00	<i>? X</i>
39	LID LOCK COVER <i>Damaged</i>		S	9.00	<i>? ✓ 7.12</i>
40	RELEASE ELEMENT FOR LID LOCK <i>Not New</i>		S	53.00	<i>? X</i>
SUB TOTAL SPARE PARTS			:	\$ 5,898.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 9503 A

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remark
41	BOWDEN CABLE - LH / RH <i>Not New</i>	2	S	105.00	? X
42	RELEASE LEVER <i>Not New</i>		S	12.00	? X
43	HEADLIGHT MOUNTING - LH / RH <i>RH crushed.</i>	2	S	214.00	? ✓ 85.60
44	HEADLIGHT - LH / RH <i>RH Cut.</i>	2	S	8,982.00	4491 3592.80
45	HEADLIGHT POWER MODULE		S	693.00	+
46	HEADLIGHT CONTROL UNIT		S	508.00	+
47	HEADLIGHT HEAT SINK - RH <i>He m</i>		S	666.00	+
48	HEADLIGHT HOSE - RH		S	26.00	+
49	HEADLIGHT LIFT CYLINDER - LH / RH	2	S	155.00	+
50	HEADLIGHT WASHER HOSE		S	170.00	+
51	HEADLIGHT WASHER T FITTING		S	27.00	+
52	HEADLIGHT WASHER ELBOW FITTING	3	S	81.00	+
53	FRONT RADIATOR LOCK CARRIER <i>Delivered.</i>		S	907.00	? ✓ 725.60
54	AC CONDENSER <i>Not New Dented</i>		S	503.00	✓ 402.00
55	AC O RING		S	3.00	✓ 2.40
56	AC O RING <i>Not New</i>		S	4.00	✓ 3.20
57	COOLER FOR COOLANT <i>He m</i>		S	878.00	+
58	ADDITIONAL COOLER FOR COOLANT <i>He m</i>		S	837.00	+
59	COOLANT <i>Not New</i>	4	S	165.00	? X
60	COOLING FAN <i>He m</i>		S	1,046.00	+
SUB TOTAL SPARE PARTS			:	\$ 15,982.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMJ 9503 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	RADIATOR AIR GUIDE - LH / RH <i>Rt Deland.</i>	2 \$ 56.00	? ✓ 21.36
62	RADIATOR SEAL - OUTER RH <i>new Not New</i>	\$ 6.00	+ ✓ 14.48
63	RADIATOR AIR GUIDE - UPPER CENTRE <i>Deland</i>	\$ 19.00	? ✓ 15.20
64	FRONT PANEL AIR DUCT <i>Not New</i>	\$ 53.00	? X
65	AIR HOSE FOR ENGINE <i>New</i>	\$ 62.00	+ X
66	AIR FILTER <i>Not New</i>	\$ 259.00	? X
67	INTAKE MANIFOLD <i>New</i>	\$ 129.00	+
68	WATER DRAINAGE HOSE <i>New</i>	\$ 31.00	+
69	FRONT NO. PLATE <i>Bent</i>	\$ 40.00	✓
70	SUNDRIES <i>New.</i>	\$ 400.00	? ✓ 15.04
TOTAL SPARE PARTS		\$ 28,833.00	
TOTAL LABOUR CHARGES		\$ 14,752.00	
GRAND TOTAL		\$ 43,585.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

44606.4

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian King

Surveyed Date

:

24/07/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 6 Days (Without Lock Carrier)
9 Days (With Lock Carrier)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0890/2019/TG

31-Jul-19

Glory Tan

1 of 1

SMJ 9503 A

Audi Q2 1.0 TFSI S Tronic

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

- | | | | |
|---|---------------------------------|-----------|---------------|
| 1 | Lid lock with micro switch | \$ 367.00 | Part / 293.60 |
| 2 | Bonnet striker LHS | \$ 100.00 | bt / 79.52 |
| 3 | Bonnet striker RHS | \$ 100.00 | bt / 79.52 |
| 4 | Front fender outer bracket RHS | \$ 43.00 | repair |
| 5 | Front fender outer bracket LHS | \$ 43.00 | bt / 34.08 |
| 6 | Front fender middle bracket LHS | \$ 14.00 | bt / 11.04 |
| 7 | Front fender inner bracket LHS | \$ 14.00 | bt / 11.04 |

\$ 681.00

TOTAL

\$ 681.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 9503 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 1,705.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 314.00	+
3	FRONT BUMPER GRILLE - CENTER <i>Cracked</i>	\$ 179.00	✓
4	FRONT BUMPER AIR GRILLE - LH / RH <i>RH Damaged</i>	2 \$ 302.00	153.50
5	FRONT BUMPER AIR GRILLE REAR COVER - LH / RH ?	2 \$ 61.00	0
6	FRONT BUMPER SPOILER <i>Distorted</i>	\$ 273.00	✓
7	FRONT BUMPER CLOSING ELEMENT	\$ 142.00	?
8	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2 \$ 62.00	+
9	ADAPTER - LH / RH ?	2 \$ 70.00	?
10	RADIATOR GRILLE <i>Cracked</i>	\$ 1,301.00	✓
11	RADIATOR STRIKER PLATE ? <i>OK</i>	\$ 114.00	?
12	FRONT BUMPER CARRIER ? <i>OK</i>	\$ 625.00	?
13	FRONT BUMPER FOAM FILLER PIECE <i>OK</i>	\$ 71.00	?
14	FRONT BUMPER TOP COVER <i>Cracked</i>	\$ 91.00	✓
15	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$ 64.00	+
16	CAUTION STICKER ?	\$ 13.00	✓
17	AC STICKER ?	\$ 7.00	✓
18	SIGNAL HORN - LOW TONE LH ?	\$ 262.00	?
19	SIGNAL HORN - HIGHT TONE RH ?	\$ 180.00	?
20	SPRING SHACKLE - LH / RH <i>new</i>	2 \$ 57.00	?
SUB TOTAL SPARE PARTS		\$ 5,898.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

[Signature]

01/08/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 9503 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER - LH / RH <i>LH Buckled, RH Repair</i>	2 \$	2,094.00 <i>1048</i>
22	FRONT FENDER ATTACHEMENT PARTS ?	2 \$	72.00 ?
23	POP RIVET <i>new</i>	12 \$	36.00 x
24	FRONT FENDER BRACE - RH <i>new</i>	\$	29.00 x
25	WHEEL HOUSING LINER - RH <i>new</i>	\$	183.00 +
26	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	52.00 +
27	BONNET <i>Distorted</i>	\$	2,549.00 ✓
28	BONNET ATTACHMENT PARTS ?	\$	149.00 ?
29	BONNET LID HINGE - LH / RH <i>Dist ? 31</i>	2 \$	111.00 <i>new</i> ?
30	GAS FILLED STRUT <i>new</i>	\$	93.00 +
31	SOUND ABS FOR ENGINE BONNET <i>new</i>	\$	201.00 +
32	IMPACT PROTECTION - CENTER	\$	27.00 ✓
33	IMPACT PROTECTION - LH	\$	28.00 ✓
34	IMPACT PROTECTION - RH	\$	27.00 ✓
35	FRONT FENDER COVER - RH <i>new</i>	\$	37.00 x
36	DEFLECTOR COVER - LH / RH <i>new</i>	2 \$	28.00 +
37	BOWDEN CABLE - CENTER <i>? 31</i>	\$	53.00 ?
38	LID LOCK CABLE ?	\$	67.00 ?
39	LID LOCK COVER ? <i>mis</i>	\$	9.00 ?
40	RELEASE ELEMENT FOR LID LOCK ?	\$	53.00 ?
SUB TOTAL SPARE PARTS		\$	5,898.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

[Signature]
01/08/17

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMI 9503 A

S/N	Parts Description		Damaged Parts & Prices S/Nett	Remark
41	BOWDEN CABLE - LH / RH ?	2 S	105.00 ?	
42	RELEASE LEVER ?	S	12.00 ?	
43	HEADLIGHT MOUNTING - LH / RH ?	2 S	214.00 ?	107
44	HEADLIGHT - LH / RH RH cut	2 S	8,982.00	4491
45	HEADLIGHT POWER MODULE	S	693.00 +	
46	HEADLIGHT CONTROL UNIT	S	508.00 +	
47	HEADLIGHT HEAT SINK - RH	S	666.00 +	
48	HEADLIGHT HOSE - RH	S	26.00 +	
49	HEADLIGHT LIFT CYLINDER - LH / RH	2 S	155.00 +	
50	HEADLIGHT WASHER HOSE	S	170.00 +	
51	HEADLIGHT WASHER T FITTING	S	27.00 +	
52	HEADLIGHT WASHER ELBOW FITTING	3 S	81.00 +	
53	FRONT RADIATOR LOCK CARRIER ?	S	907.00 ?	
54	AC CONDENSER	S	503.00 +	
55	AC O RING	S	3.00 +	
56	AC O RING	S	4.00 +	
57	COOLER FOR COOLANT	S	878.00 +	
58	ADDITIONAL COOLER FOR COOLANT	S	837.00 +	
59	COOLANT	4 S	165.00 ?	
60	COOLING FAN	S	1,046.00 +	
SUB TOTAL SPARE PARTS		:	\$ 15,982.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMJ 9503 A

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
2/7-61	RADIATOR AIR GUIDE (LH) RH ?	2	\$ 56.00	? 28
2/7-62	RADIATOR SEAL - OUTER RH new con	\$	6.00	+
3/7-63	RADIATOR AIR GUIDE - UPPER CENTRE ? con	\$	19.00	?
64	FRONT PANEL AIR DUCT ?	\$	53.00	?
65	AIR HOSE FOR ENGINE new	\$	62.00	+
66	AIR FILTER ?	\$	259.00	?
67	INTAKE MANIFOLD new	\$	129.00	+
68	WATER DRAINAGE HOSE new	\$	31.00	+
69	FRONT NO. PLATE Bent	\$	40.00	✓
70	SUNDRIES ?	\$	400.00	?
TOTAL SPARE PARTS		:	\$ 28,833.00	
TOTAL LABOUR CHARGES			\$ 14,752.00	
GRAND TOTAL			\$ 43,585.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

2278

2209

2044

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *24/07/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 6 Days (Without Lock Carrier)
9 Days (With Lock Carrier)*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0890/2019/TG
Date : 23-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

We took 11 days exclude 12 Sundays
Checked items, and added repairs

jb 17 Oct 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Toh Lay Ling
Address : Apt Blk 272 Toh Guan Road
#09-79
Singapore 600272
Telephone : (HP) +65 96844409
Type of Claim : Own Damage Claims
Policy No. : 1900079887
Vehicle No : **SMJ 9503 A**
Model Code : Audi Q2 1.0 TFSI S Tronic
Model / Year : 26/3/2019
Engine No : CHZ C26341
Chassis No : WAUZZZGA5KA022456
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jul-19
Place of Accident : Along PIE at the entrance to Clementi road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMJ 9503 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Reccomendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and renew aircond condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N	\$ 1,400.00	\$ 1,400.00
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N	\$ 300.00	
4	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To renew front lock carrier and align console to position. Re-install all parts removed.		\$ 7,200.00	\$ 3,000.00
5	To respray front bumper, both front fenders, bonnet and lhs front door.		\$ 5,300.00	\$ 2,200.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 14,752.00</u>	<u>\$ 7,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMJ 9503 A**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,705.00	\$ 1,364.00
2	FRONT BUMPER FIXING PARTS	\$ 314.00	
3	FRONT BUMPER GRILLE - CENTER	\$ 179.00	\$ 143.20
4	FRONT BUMPER AIR GRILLE - LH / RH	2 \$ 307.00	\$ 122.80
5	FRONT BUMPER AIR GRILLE REAR COVER - LH / RH	2 \$ 61.00	
6	FRONT BUMPER SPOILER	\$ 273.00	\$ 218.00
7	FRONT BUMPER CLOSING ELEMENT	\$ 142.00	
8	FRONT WHEEL SPOILER - LH / RH	2 \$ 62.00	
9	ADAPTER - LH / RH	2 \$ 70.00	
10	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
11	RADIATOR STRIKER PLATE	\$ 114.00	\$ 91.20
12	FRONT BUMPER CARRIER	\$ 625.00	\$ 499.60
13	FRONT BUMPER FOAM FILLER PIECE	\$ 71.00	\$ 56.08
14	FRONT BUMPER TOP COVER	\$ 91.00	\$ 72.56
15	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$ 64.00	
16	CAUTION STICKER	\$ 13.00	\$ 9.76
17	AC STICKER	\$ 7.00	\$ 5.12
18	SIGNAL HORN - LOW TONE LH	\$ 262.00	
19	SIGNAL HORN - HIGHT TONE RH	\$ 180.00	
20	SPRING SHACKLE - LH / RH	2 \$ 57.00	
SUB TOTAL SPARE PARTS		\$ 5,898.00	\$ 3,623.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMJ 9503 A**

S/N	Parts Description	c/f	Damaged Parts & Prices		Remark
			S/Nett		
				\$	3,623.12
21	FRONT FENDER - LH / RH	2	\$ 2,094.00	\$	837.60
22	FRONT FENDER ATTACHEMENT PARTS	2	\$ 72.00		
23	POP RIVET	12	\$ 36.00	\$	28.80
24	FRONT FENDER BRACE - RH		\$ 29.00		
25	WHEEL HOUSING LINER - RH		\$ 183.00		
26	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 52.00		
27	BONNET		\$ 2,549.00	\$	2,039.20
28	BONNET ATTACHMENT PARTS		\$ 149.00		
29	BONNET LID HINGE - LH / RH	2	\$ 111.00	\$	88.48
30	GAS FILLED STRUT		\$ 93.00		
31	SOUND ABS FOR ENGINE BONNET		\$ 201.00		
32	IMPACT PROTECTION - CENTER		\$ 27.00	\$	21.20
33	IMPACT PROTECTION - LH		\$ 28.00	\$	22.00
34	IMPACT PROTECTION - RH		\$ 27.00	\$	21.20
35	FRONT FENDER COVER - RH		\$ 37.00		
36	DEFLECTOR COVER - LH / RH	2	\$ 28.00		
37	BOWDEN CABLE - CENTER		\$ 53.00	\$	41.68
38	LID LOCK CABLE		\$ 67.00		
39	LID LOCK COVER		\$ 9.00	\$	7.12
40	RELEASE ELEMENT FOR LID LOCK		\$ 53.00		
SUB TOTAL SPARE PARTS			\$ 5,898.00	\$	6,730.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMJ 9503 A**

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>	
			S/Nett	Remark
				\$ 6,730.40
41	BOWDEN CABLE - LH / RH	2	\$ 105.00	
42	RELEASE LEVER		\$ 12.00	
43	HEADLIGHT MOUNTING - LH / RH	2	\$ 214.00	\$ 85.60
44	HEADLIGHT - LH / RH	2	\$ 8,982.00	\$ 3,592.80
45	HEADLIGHT POWER MODULE		\$ 693.00	
46	HEADLIGHT CONTROL UNIT		\$ 508.00	
47	HEADLIGHT HEAT SINK - RH		\$ 666.00	
48	HEADLIGHT HOSE - RH		\$ 26.00	
49	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 155.00	
50	HEADLIGHT WASHER HOSE		\$ 170.00	
51	HEADLIGHT WASHER T FITTING		\$ 27.00	
52	HEADLIGHT WASHER ELBOW FITTING	3	\$ 81.00	
53	FRONT RADIATOR LOCK CARRIER		\$ 907.00	\$ 725.60
54	AC CONDENSER		\$ 503.00	\$ 402.00
55	AC O RING		\$ 3.00	\$ 2.40
56	AC O RING		\$ 4.00	\$ 3.20
57	COOLER FOR COOLANT		\$ 878.00	
58	ADDITIONAL COOLER FOR COOLANT		\$ 837.00	
59	COOLANT	4	\$ 165.00	
60	COOLING FAN		\$ 1,046.00	
SUB TOTAL SPARE PARTS		:	\$ 15,982.00	\$ 11,542.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMJ 9503 A**

S/N	Parts Description	c/l	<u>Damaged Parts & Prices</u>	
			S/Nett	Remark
				\$ 11,542.00
61	RADIATOR AIR GUIDE - LH / RH	2	\$ 56.00	\$ 21.36
62	RADIATOR SEAL - OUTER RH		\$ 6.00	\$ 4.48
63	RADIATOR AIR GUIDE - UPPER CENTRE		\$ 19.00	\$ 15.20
64	FRONT PANEL AIR DUCT		\$ 53.00	
65	AIR HOSE FOR ENGINE		\$ 62.00	
66	AIR FILTER		\$ 259.00	
67	INTAKE MANIFOLD		\$ 129.00	
68	WATER DRAINAGE HOSE		\$ 31.00	
69	FRONT NO. PLATE		\$ 40.00	\$ 40.00
70	Added parts - see attached		\$ 588.00	\$ 469.60
71	Added parts - see attached		\$ 681.00	\$ 508.80
72	SUNDRIES		\$ 400.00	\$ 15.04
TOTAL SPARE PARTS			\$ 30,102.00	\$ 12,616.48
TOTAL LABOUR CHARGES			\$ 14,752.00	\$ 7,152.00
GRAND TOTAL			\$ 44,854.00	\$ 19,768.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0690/2019/TG 13-Aug-19 Glory Tan 1 OF 1 SMJ 9503 A Audi Q2 1.0 TFSI S Tronic
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Wheel arch cover RHS front } <i>NEC.</i>	\$ 294.00	\$ 234.80
2	Wheel arch cover LHS front }	\$ 294.00	\$ 234.80
		\$ 588.00	\$ 469.60
TOTAL		\$ 588.00	\$ 939.20

For Premium Automobiles Pte Ltd

Adrian Ling
AS

Authorised Signature

- Auto Consultants hence notify
- Repairer of the following
- Survey before/after spray painting
- Display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications allowed
- Supplementary items made to be surveyed and is subject to final approval from Insurance Company

Acknowledged by Requester

Signature:

Date:

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0890/2019/TG 31-Jul-19 Glory Tan 1 of 1 SMJ 9503 A Audi Q2 1.0 TFSI S Tronic
Quantity	Description	Unit Price	Amount
Parts			
1	Lid lock with micro switch	\$ 367.00	\$ 293.60 Jam
2	Bonnet striker LHS	\$ 100.00	\$ 79.52 BT
3	Bonnet striker RHS	\$ 100.00	\$ 79.52 BT
4	Front fender outer bracket RHS	\$ 43.00	\$ R
5	Front fender outer bracket LHS	\$ 43.00	\$ 34.08 BT
6	Front fender middle bracket LHS	\$ 14.00	\$ 11.04 BT
7	Front fender inner bracket LHS	\$ 14.00	\$ 11.04 BT
		\$ 681.00	\$ 508.80
	TOTAL	\$ 681.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMJ 9503 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0890/2019/NH

14TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SMJ 9503 A, Audi Q2 1.0 TFSI S-TRONIC.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SMJ 9503 A**, claimant, **Ms. Toh Lay Ling**, please find the related document per attached.

1. A copy of the Original invoice no. 85014722 – S\$ 20,296.27.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SMJ 9503 A

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159936
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159936
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 8841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:43

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120			Invoice No: 85014722	Account: A0006 (T 0)	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
			Date : 10/01/2020				
			Order : SMJ9503A				
			Term : 30				
Regn No: SMJ9503A (V 40880)			Regn Date: 26/03/2019	Mileage: 6612	WIP No.: 61409		
Model: Q2 1.0 TFSI S tronic GABANG			Chassis: WAUZZZGA5KA022456	Engine: CHZ C26341	Dept: U		
You have been assisted by :- UB-Tony Foong (33)							
		Details			Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE			40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability			-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY			360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM			1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND RHS HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED			3000.00	1.00	3,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER AND BONNET			2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK			192.00	1.00	192.00
X	AB1A807107 GRU	COVER (LAST)	Less 020%	1.00	785.50		628.40
X	AB1A807108 GRU	COVER (LAST)	Less 020%	1.00	785.50		628.40
X	AB1A807663 GRU	CONN PIECE	Less 020%	1.00	134.00		107.20
X	AB1A807647 4W3	GRILLE	Less 020%	1.00	179.00		143.20
X	AB1A807672 4W3	GRILL (LAST)	Less 020%	1.00	153.50		122.80
X	AB1A807110 4W3	SPOILER	Less 020%	1.00	272.50		218.00
X	AB1A853651 MX3	(GER) GRILLE (LAST)	Less 020%	1.00	1301.00		1,040.80
X	AB1A853037	(A) (SK) PLATE 25/7/19	Less 020%	1.00	114.00		91.20
X	AB1A807109C	(SK) BRACKET (LAST)	Less 020%	1.00	624.50		499.60
X	AB1A807550	FOAM INSER (LAST)	Less 020%	1.00	70.10		56.08

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Teletax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Teletax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Teletax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:43

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014722 Date: 10/01/2020 Order: SMJ9503A Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SMJ9503A (V 40880)	Regn Date: 26/03/2019	Mileage: 6612	WIP No.: 61409
Model: Q2 1.0 TFSI S tronic GABANG	Chassis: WAUZZZGA5KA022456	Engine: CHZ C26341	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
X	A81A807081	(SK) COVER (LAST)	Less 020%	1.00	90.70
X	ABK0010520A	PLATE	Less 020%	1.00	12.20
X	ABV0010515A	STICKER	Less 020%	1.00	6.40
X	A81A821105	FENDER (LAST)	Less 020%	1.00	1047.00
X	AN 0161857	POP-RIVET	Less 020%	12.00	3.00
X	A81A823029	(SK) HOOD (LAST)	Less 020%	1.00	2549.00
X	A81A823301D	(A) (SK) HINGE 1/8/19	Less 020%	1.00	55.30
X	A81A823302D	(A) (SK) HINGE 1/8/19	Less 020%	1.00	55.30
X	A81A823124	PROTECTION	Less 020%	1.00	26.50
X	A81A823125	PROTECTION	Less 020%	1.00	27.50
X	A81A823126	PROTECTION	Less 020%	1.00	26.50
X	A81A823531	007358 / (V) (GER) BOWD	Less 020%	1.00	52.10
X	A4H0823543	COVER	Less 020%	1.00	8.90
X	A81A805608C	MOUNTING (LAST)	Less 020%	1.00	107.00
X	A81A941774A	007352 / (V) (GER) HEADL	Less 020%	1.00	4491.00
X	A81A805594A	(SK) CARRIER	Less 020%	1.00	907.00
X	A5Q0816411AS	(SK) CONDENSER	Less 020%	1.00	502.50
X	A81A121284K	(A) (SK) AIR DUCT 1/8/	Less 020%	1.00	26.70
X	A81A121230	(A) (SK) SEAL 1/8/19	Less 020%	1.00	5.60
X	A81A121285	(SK) AIR DUCT	Less 020%	1.00	19.00
X	A81A823509A	(A) (SK) LOCK 1/8/19	Less 020%	2.00	183.50
X	A81A823185A	(A) (SK) CATCH 1/8/19	Less 020%	1.00	99.40
X	A81A823186A	(A) (SK) CATCH 1/8/19	Less 020%	1.00	99.40
X	AWHT001308	NUT	Less 020%	4.00	1.30
X	AN 90798808	NUT	Less 020%	4.00	1.10
X	AN 91154701	BOLT	Less 020%	4.00	2.30
X	A81A821467	(A) (SK) BRACKET 1/8/1	Less 020%	1.00	42.60
X	A81A821469	(A) (SK) BRACKET 1/8/1	Less 020%	1.00	13.80
X	A81A821471	BRACKET	Less 020%	1.00	13.80
X	A3D0260749C	WASHER	Less 020%	1.00	4.00
X	A4D0260749B	WASHER	Less 020%	1.00	3.00
X	A81A853717 4W3	COVER	Less 020%	1.00	293.50
X	A81A853718 4W3	COVER	Less 020%	1.00	293.50

Parts 12,576.48
Labour 0.00
Sublet 7,192.00
Menus 0.00
Lubricant 0.00

Sub-Total 18,968.48

7% GST 1,327.79

Grand Total 20,296.27



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMJ 9503 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0890/2019/KS
13 Aug 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q2 1.0 TFSI S Tronic
Vehicle Chassis No. : WAUZZZGA5KA022456
Vehicle Regn No. : SMJ 9503 A
Vehicle Mileage : 6612 Km
Vehicle Owner : Ms. Toh Lay Ling
Certificate No : 1900079887
Own Damage Excess : \$856.00 (Including 7% GST)
Accident Date : 21/7/2019
Place : Along PIE at the Entrance to Clementi Road
Repair Cost : \$ 20,296.27
WIP No. : 61409
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


15 8:00pm
13 Aug 2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jul 2019		24 Jul 2019 16:29 Edit Adj Rpt	S\$19,768.48 Edit Estimates	S\$19,768.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	TOH LAY LING, ID: S7812748A			
Vehicle Reg. No.:	SMJ9503A	Date of Loss:	21/07/2019 15:00 - :59 [3 Months and 25 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 6653322787SG	Policy/Cover Note No.:	1900079887 (Comprehensive)	
		Excess:	S\$800.00	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/08/2019]			
Driver/Custodian:	SIM YEW KEONG (42 / Male) , NRIC: S7702494H, Tel: +6591144070 Email: MAX.MARU@ME.COM			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (02/12/2019): Alert - Adj Mandate Approved (S\$19768.48) - SMJ9503A - Claim Handler: Chan, Yoke...
- AIG_SG (28/08/2019): Alert - Adj Mandate Approved (S\$20917.50) - SMJ9503A - Claim Handler: Chan, Yoke...
- AIG_SG (05/08/2019): Alert - Adj Mandate Maintained - SMJ9503A - Claim Handler: Chan, Yoke Shi
- AIG_SG (29/07/2019): Alert - Adj Mandate Approved (S\$17683.50) - SMJ9503A - Claim Handler: Chan, Yoke...
- AIG_SG (29/07/2019): SMJ9503A / OD / 21/07/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMJ9503A (6653322787SG)**

OD

Jul 21 2019 3:00PM

[TOH LAY LING]

Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser ▼](#)

Assessment Reports					1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	25/07/19 10:10	Adjuster Immediate Advice		Load HTM		
2	02/08/19 12:28	Adjuster Immediate Advice		Load HTM		
3	16/08/19 10:58	Adjuster Immediate Advice		Load HTM		
4	16/08/19 11:09	Adjuster Immediate Advice		Load HTM		

Photos/Images					3 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	25/07/19 09:19	General View		Load JPG		
2	25/07/19 09:19	General View		Load JPG		
3	25/07/19 09:19	General View		Load JPG		
4	25/07/19 09:19	General View		Load JPG		
5	25/07/19 09:19	General View		Load JPG		
6	25/07/19 09:19	General View		Load JPG		
7	25/07/19 09:19	General View		Load JPG		
8	25/07/19 09:19	General View		Load JPG		
9	25/07/19 09:19	General View		Load JPG		
10	25/07/19 09:19	General View		Load JPG		
11	25/07/19 09:19	General View		Load JPG		
12	25/07/19 09:19	General View		Load JPG		
13	25/07/19 09:19	General View		Load JPG		
14	25/07/19 09:19	General View		Load JPG		
15	25/07/19 09:19	General View		Load JPG		
16	25/07/19 09:19	General View		Load JPG		
17	25/07/19 09:19	General View		Load JPG		
18	25/07/19 09:19	General View		Load JPG		
19	25/07/19 09:19	General View		Load JPG		
20	25/07/19 09:19	General View		Load JPG		
21	25/07/19 09:19	General View		Load JPG		
22	25/07/19 09:19	General View		Load JPG		
23	25/07/19 09:19	General View		Load JPG		
24	25/07/19 09:19	General View		Load JPG		
25	25/07/19 09:19	General View		Load JPG		
26	25/07/19 09:19	General View		Load JPG		
27	25/07/19 09:19	General View		Load JPG		
28	25/07/19 09:19	General View		Load JPG		
29	25/07/19 09:19	General View		Load JPG		
30	25/07/19 09:19	General View		Load JPG		
31	25/07/19 09:19	General View		Load JPG		
32	25/07/19 09:19	General View		Load JPG		
33	25/07/19 09:19	General View		Load JPG		
34	25/07/19 09:19	General View		Load JPG		
35	25/07/19 09:19	General View		Load JPG		
36	25/07/19 09:19	General View		Load JPG		

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
38	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
39	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
40	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
41	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
42	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
43	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
44	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
45	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
46	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
47	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
48	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
49	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
50	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
51	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
52	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
53	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
54	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
55	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
56	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
57	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
58	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
59	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
60	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
61	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
62	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
63	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
64	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
65	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
66	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
67	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
68	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
69	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
70	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
71	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
72	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
73	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
74	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
75	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
76	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
77	02/08/19 12:14	Reinspection Photo	 Load JPG	☒
78	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
79	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
80	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
81	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
82	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
83	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
84	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
85	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
86	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
87	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
88	24/10/19 14:08	Reinspection Photo	 Load JPG	☒
89	24/10/19 14:08	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
90	24/10/19 14:08	Reinspection Photo	Load JPG	
91	24/10/19 14:08	Reinspection Photo	Load JPG	
Documentation			1 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 09:17	SMJ 9503A GIA.pdf	Load PDF	
2	25/07/19 09:17	DRIVING & CI.pdf	Load PDF	
3	25/07/19 09:17	ESTIMATE.pdf	Load PDF	
4	02/08/19 12:29	SUPPLEMENTARY	Load PDF	
5	16/08/19 10:31	ESTIMATE 1.pdf	Load PDF	
6	24/10/19 14:09	ESTIMATE & SUPP 1 & 2 MARKED.pdf	Load PDF	
7	16/01/20 14:37	WORKSHOP INVOICE	Load PDF	
8	16/01/20 14:37	DISCHARGE VOUCHER	Load PDF	
9	16/01/20 14:38	Supplementary	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/07/19 18:48	Addendum Sheet	Load JPG	
2	04/09/19 01:54	Accident Statement	Load HTM	
3	04/09/19 02:03	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/07/19 19:21	Accident Photo	Load JPG	
2	22/07/19 19:21	Accident Photo	Load JPG	
3	22/07/19 19:21	Accident Photo	Load JPG	
4	22/07/19 19:21	Accident Photo	Load JPG	
5	22/07/19 19:21	Accident Photo	Load JPG	
6	22/07/19 19:21	Accident Photo	Load JPG	
7	22/07/19 19:21	Accident Photo	Load JPG	
8	22/07/19 19:21	Accident Photo	Load JPG	
9	22/07/19 19:21	Accident Photo	Load JPG	
10	22/07/19 19:21	Accident Photo	Load JPG	
11	22/07/19 19:21	Accident Photo	Load JPG	
12	22/07/19 19:21	Accident Photo	Load JPG	
13	22/07/19 19:21	Accident Photo	Load JPG	
14	22/07/19 19:21	Accident Photo	Load JPG	
15	22/07/19 19:21	Accident Photo	Load JPG	
16	22/07/19 19:21	Accident Photo	Load JPG	
17	22/07/19 19:21	Accident Photo	Load JPG	
18	22/07/19 19:21	Accident Photo	Load JPG	
19	22/07/19 19:21	Accident Photo	Load JPG	
20	22/07/19 19:21	Accident Photo	Load JPG	
21	22/07/19 19:21	Accident Photo	Load JPG	
22	22/07/19 19:21	Accident Photo	Load JPG	
23	22/07/19 19:21	Accident Photo	Load JPG	
24	22/07/19 19:21	Accident Photo	Load JPG	
25	22/07/19 19:21	Accident Photo	Load JPG	
26	22/07/19 19:21	Accident Photo	Load JPG	
27	22/07/19 19:21	Accident Photo	Load JPG	
28	22/07/19 19:21	Accident Photo	Load JPG	
29	22/07/19 19:21	Accident Photo	Load JPG	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19013064/ASF3N2

Date: 16/01/2020

REFERENCE

Insured/Claimant:	TOH LAY LING	Policy No:	1900079887	
Date of Loss:	21/07/2019	Nature of Claim:	OD	Claim No: 6653322787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9503A		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZC26341
Reg. Date:	26/03/2019 (Man. Year: 2018)	Chassis No:	WAUZZZGA5KA022456
Colour:	Yellow	Odometer:	6613 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,854.40	12,616.48	17,237.92	57.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,752.00	7,152.00	7,600.00	51.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,606.40	19,768.48	24,837.92	55.68
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	43,806.40	18,968.48	24,837.92	56.70
+ GST 7.00/7.00% (S\$)	3,066.45	1,327.79	1,738.66	56.70
Nett Amount (S\$)	46,872.85	20,296.27	26,576.58	56.70

INSPECTION

Date of Assignment:	24/07/2019		
Date Inspected:	24/07/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	11.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,705.00 FS	*1,364.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE-CENTER	Cracked	179.00 FS	*143.20 FS
4	1	*FRONT BUMPER AIR GRILLE-LH/RH	O/s Deformed	307.00 FS	*122.80 FS
5	2	*FRONT BUMPER AIR GRILLE REAR COVER-LH/RH	Not Necessary	61.00 FS	*- FS
6	1	*FRONT BUMPER SPOILER	Distorted	273.00 FS	*218.00 FS
7	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	142.00 FS	*- FS
8	2	*FRONT WHEEL SPOILER-LH/RH	Not Necessary	62.00 FS	*- FS
9	2	*ADAPTER-LH/RH	Not Necessary	70.00 FS	*- FS
10	1	*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
11	1	*RADIATOR STRIKER PLATE	Cracked	114.00 FS	*91.20 FS
12	1	*FRONT BUMPER CARRIER	Bent	625.00 FS	*499.60 FS
13	1	*FRONT BUMPER FOAM FILLER PIECE	Cracked	71.00 FS	*56.08 FS
14	1	*FRONT BUMPER TOP COVER	Deformed	91.00 FS	*72.56 FS
15	2	*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	64.00 FS	*- FS
16	1	*CAUTION STICKER	Necessary	13.00 FS	*9.76 FS
17	1	*AC STICKER	Necessary	7.00 FS	*5.12 FS
18	1	*SIGNAL HORN-LOW TONE LH	Not Necessary	262.00 FS	*- FS
19	1	*SIGNAL HORN-HIGH TONE LH	Not Necessary	180.00 FS	*- FS
20	2	*SPRING SHACKLE-LH/RH	Not Necessary	57.00 FS	*- FS
21	1	*FRONT FENDER-LH/RH	N/s Buckled/O/s Repair	2,094.00 FS	*837.60 FS
22	2	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
23	12	*POP RIVET	Necessary	36.00 FS	*28.80 FS
24	1	*FRONT FENDER BRACE-RH	Not Necessary	29.00 FS	*- FS
25	1	*WHEEL HOUSING LINER-RH	Not Necessary	183.00 FS	*- FS
26	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	52.00 FS	*- FS
27	1	*BONNET	Distorted	2,549.00 FS	*2,039.20 FS
28	1	*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
29	2	*BONNET LID HINGE-LH/RH	Bent	111.00 FS	*88.48 FS
30	1	*GAS FILLED STRUT	Not Necessary	93.00 FS	*- FS
31	1	*SOUND ABS FOR ENGINE BONNET	Not Necessary	201.00 FS	*- FS
32	1	*IMPACT PROTECTION-CENTER	Necessary	27.00 FS	*21.20 FS
33	1	*IMPACT PROTECTION-LH	Necessary	28.00 FS	*22.00 FS
34	1	*IMPACT PROTECTION-RH	Necessary	27.00 FS	*21.20 FS
35	1	*FRONT FENDER COVER-RH	Not Necessary	37.00 FS	*- FS
36	2	*DEFLECTOR COVER-LH/RH	Not Necessary	28.00 FS	*- FS
37	1	*BOWDEN CABLE-CENTER	Damaged	53.00 FS	*41.68 FS
38	1	*LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
39	1	*LID LOCK COVER	Damaged	9.00 FS	*7.12 FS
40	1	*RELEASE ELEMENT FOR LID LOCK	Not Necessary	53.00 FS	*- FS
41	2	*BOWDEN CABLE-LH/RH	Not Necessary	105.00 FS	*- FS
42	1	*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
43	1	*HEADLIGHT MOUNTING-LH/RH	O/s Cracked	214.00 FS	*85.60 FS
44	1	*HEADLIGHT -LH/RH	O/s Cut	8,982.00 FS	*3,592.80 FS
45	1	*HEADLIGHT POWER MODULE	Not Necessary	693.00 FS	*- FS
46	1	*HEADLIGHT CONTROL UNIT	Not Necessary	508.00 FS	*- FS
47	1	*HEADLIGHT HEAT SINK-RH	Not Necessary	666.00 FS	*- FS
48	1	*HEADLIGHT HOSE-RH	Not Necessary	26.00 FS	*- FS
49	2	*HEADLIGHT LIFT CYLINDER-LH/RH	Not Necessary	155.00 FS	*- FS
50	1	*HEADLIGHT WASHER HOSE	Not Necessary	170.00 FS	*- FS
51	1	*HEADLIGHT WASHER T FITTING	Not Necessary	27.00 FS	*- FS
52	3	*HEADLIGHT WASHER ELBOW FITTING	Not Necessary	81.00 FS	*- FS
53	1	*FRONT RADIATOR LOCK CARRIER	Deformed	907.00 FS	*725.60 FS
54	1	*AC CONDENSER	Dented	503.00 FS	*402.00 FS
55	1	*AC O RING	Necessary	3.00 FS	*2.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*AC O RING	Necessary	4.00 FS	*3.20 FS
57	1		*COOLER FOR COOLANT	Not Necessary	878.00 FS	*- FS
58	1		*ADDITIONAL COOLER FOR COOLANT	Not Necessary	837.00 FS	*- FS
59	4		*COOLANT	Not Necessary	165.00 FS	*- FS
60	1		*COOLANT FAN	Not Necessary	1,046.00 FS	*- FS
61	1		*RADIATOR AIR GUIDE-LH/RH	O/s Deformed	56.00 FS	*21.36 FS
62	1		*RADIATOR SEAL-OUTER RH	Necessary	6.00 FS	*4.48 FS
63	1		*RADIATOR AIR GUIDE-UPPER CENTRE	Deformed	19.00 FS	*15.20 FS
64	1		*FRONT PANEL AIR DUCT	Not Necessary	53.00 FS	*- FS
65	1		*AIR HOSE FOR ENGINE	Not Necessary	62.00 FS	*- FS
66	1		*AIR FILTER	Not Necessary	259.00 FS	*- FS
67	1		*INTAKE MANIFOLD	Not Necessary	129.00 FS	*- FS
68	1		*WATER DRAINAGE HOSE	Not Necessary	31.00 FS	*- FS
69	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
70	1		*SUNDRIES	Necessary	400.00 FS	*15.04 FS
71	1		*LID LOCK WITH MICRO SWITCH	Jammed	293.60 FS	*293.60 FS
72	1		*BONNET STRIKER LHS	Bent	79.52 FS	*79.52 FS
73	1		*BONNET STRIKER RHS	Bent	79.52 FS	*79.52 FS
74	1		*FRONT FENDER OUTER BRACKET RHS	Repair	43.00 FS	*- FS
75	1		*FRONT FENDER OUTER BRACKET LHS	Bent	34.08 FS	*34.08 FS
76	1		*FRONT FENDER MIDDLE BRACKET LHS	Bent	11.04 FS	*11.04 FS
77	1		*FRONT FENDER INNER BRACKET LHS	Bent	11.04 FS	*11.04 FS
78	1		*WHEEL ARCH COVER RHS FRONT	Necessary	234.80 FS	*234.80 FS
79	1		*WHEEL ARCH COVER LHS FRONT	Necessary	234.80 FS	*234.80 FS

F=Franchise part, S=SpcNett.

Total Parts (S\$) 29,854.40 12,616.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER,RADIATOR,ADDITIONAL RADIATOR,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	300.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BOTH FRONT FENDERS,BONNET AND BOTH HEADLIGHTS.TO RENEW FRONT LOCK CARRIER AND ALIGN CONSOLE TO POSITION.RE-INSTALL ALL PARTS REMOVED	New	7,200.00	3,000.00
5	TO RESPRAY FRONT BUMPER,BOTH FRONT FENDERS,BONNET AND LHS FRONT DOOR	New	5,300.00	2,200.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			14,752.00	7,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >