Mrissen	From (Person): Gnoh Pau Loong of Smo		Date/Time: 24.7.1	9 15.50 p.h
70	Estimated Cost:	Bill to:		
	To Inspect Vehicle No. SMG 6533 Z		Insured: SLH 1266 Tel: 647 15111	1
	at Workshop m/s Carrinus Autolution of 160 sin ming Drive #02-04		Tel: 647 15111	
	Policy No: DIG MTPVOID 7898	Claim No:	(MTD1903536	
	Sum Insured:	Excess:		
	Make of Veh:		D.O.A. 22.7. 20	19
	CA / REV / REP. / REV 24 HRS  Date/Time: 24.1.19 4.1.19  Person Contacted:	Yuki	H.O.D. Endorsement: Vehicle IN OUT	
	Date/Time Action/Instruction ( v ) Estimate		24	
	SMG 6533Z - X S2H 1266J- X			
	26/07/19 @ 15:26 pm revised	PA 7	to anoh Pau Loo	<del>y</del>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

**GNOH PAU LOONG** 

Date: 26 Jul 2019

## Preliminary Advice

Insured Vehicle No : SLH1266J

TP Vehicle No

Inspection At

: SMG6533Z

Accident Date

: 22/07/2019

Make

: HONDA FIT

Assignment Date

: 24/07/2019

Est. Duration of Repair

: 4 days

Date of Inspection : 25/07/2019

: Cartimes Autolution (HQ)

160 Sin Ming Drive #02-04 Autocity

Singapore 575722

Point of Impact / General Description of Damages The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,713.00
Revised Amount	:S\$	2,394.00
Check Items (Estimated)	:S\$	464.00
Total	:S\$	2,858.00

Lump Sum Repair

:S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy cove Kindly let us have your authorisation.	rage
(	)	Kindly let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : TP : WP

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitter	Ad1 Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	23 Jul 2019	Lat Date in the	24 Jul 2019 15:50 Assign				New Assignr Cancel Case	0.00
	Main		teference		laim Details	Docum	ents	Show All
CLAIM S Insured: Main Clair Vehicle Re		SIM RAY SM	CHING LEONG, DA MOND WOO YUAN G6533Z	HONG, I	0: S82006241 Date of Loss:	598321984, Ema 22/0 D18	eated by insural; danz_sim@ya 07/2019 19:00 - 8MTPV01017898	hoo.com.sg
Claim Typ Vehicle R	ee: eg. No. (Insured		CMTD1903536	n v v (g -		(Co	(Comprehensive)	
Repairer: Cartimes Autolution (HQ) 160 Sin Ming Drive #02-04 Autocity, 575722 Sin Ming - Tel:  Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 [Handled by GNOH PAU LC]  63295217]								
Adjuster: Driver/Cu	ustodian (Insured	SIM	Auto Consultants CHING LEONG, DAI _sim@yahoo.com.s	VIEL (35 / Ma	2) - Tel: 6256-3561 ile) , NRIC: S841774	[ <b>Final Rpt</b> due 8B, Tel: +65983	02/08/2019 21984 Email:	l
Adj Asg.	Remarks:	YUK	LIM at 6471 5111					
ASSOCI	ATED MAIL RE	CEIVED				View	All Compo	ose Case Mail
There are	e no mail for this	case.						
ALL AS:			k Group Subje	ect Handl	1000	completed 0	reate New Task In Created	Complete

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Mobile Number Fax Number

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	23/07/2019 16:28
Date Of Accident	22/07/2019 19:20
Exact Location Of Accident	UPPER BUKIT TIMAH RD (BESIDE SHELL)
Country/State of Loss	SINGAPORE
	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SMG6533Z
Insured/Policyholder	
Name Of Registered Owner	RAYMOND WOO YUAN HONG
NRIC No	S8200624I
Email Address	WOO0501@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97691291
Alternative Phone No	OFFICE-97691291
Vehicle Particulars	
Manufacturer	HONDA
Model	FIT-1.3 GF CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO .
Policy Number	SD19V00327/VPC/R00
Cover Note Number	
Driver	
Name of Driver	RAYMOND WOO YUAN HONG
NRIC No	S8200624I
Date Of Birth	05/01/1982
Occupation	INDOOR
Date Of Driving Pass	11/10/2007
	11 YEARS AND 9 MONTHS
Driving Experience	TI TEARS AND S MONTHS

(LOCAL) +65-97691291

WOO0501@GMAIL.COM

OFFICE-97691291

Address

118 CORPORATION DRIVE #06-452

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

3

involved in the accident
Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SLH1266J

Vehicle Make/Model/Colour

HONDA VEZEL

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SCM9545G

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

AUDI

PRIVATE CAR

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8. Consent under the Personal Data Protection Act (POPA)

Funderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all incurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes"
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection. investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
  - [i] to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(iii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature Date & Time

Driver's Signature (If driver is not the policyholder) Date & Time


ym Er

Name:

Reporting Centre Person

NRIC/FIN NO 381242050

#### SKETCH PLAN



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22July 2019 1920h Itwas heary and Si	rs, Iwa	s driving lic. Ista	along upp	er bukil til Le yellow t	nah roas
It was heavy and si I was about to rear of my uchic	move,	sudden	by vehicle	B h# 2	on the

DECLARATION

1/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: YWK: PLCL NRIC/FIN NO.: 38124205D



VELUCIE NO CNACCE 227

MODEL:HONDA FIT

autolution

QTY	DESCRIPTION			PAIRER'S MATE(S\$)	SURVEYORS ADJUSTMENT
1 1 1 1 1 1 1 1 1 1 1 1 1	Rear tailgate 859.30 Rear tailgate inner trim Rear tailgate weatherstrip Rear bumper Rear bumper side retainer LH Rear bumper side retainer RH Rear RHS taillamp Rear LHS taillamp Rear key entenna Rear tailgate windscreen moulding "Fit" SMART BUZZER "Honda" logo Rear end panel top garnish		By Shan Sala Sa Sha Marina Sha	\$ 525.00 \$ 45.00 \$ 45.00 \$ 580.00 \$ 580.00 \$ 95.00 \$ 85.00 \$ 60.00	) x x ) x x x x x ) ) x x x
1 Set 1	SPECIAL NETT ITEMS  Rear bumper clips  Rear windscreen sealant  Rear number plate w/holder  Rear reverse sensor  Rear reverse camera	Total	5~	\$ 60.00 \$ 35.00 \$ 80.00 \$ 280.00 \$ 450.00 \$ 905.00	
			PARTS	\$ 4,013.00	

Not Ashorsed Rehnry B&paint 4 day

\$ 2353.44

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- \* No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company.



## VEHICLE NO:SMG6533Z MODEL:HONDA FIT

s/N	DESCRIPTION	PAIRER'S MATE (S\$)	SURVEYORS ADJUSTMEN	
1	LABOUR To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 800.00	4001	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 600.00	8401	
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 60.00	151	
4	To provide anti-rust treatment on affected areas	\$ 80.00	301	
5	To remove and replace reverse sensor & reverse camera & check for proper function.	\$ 60.00	501	
6	To remove and refit rear windscreen	\$ 100.00	_	
	Labour Total :	\$ 1,700.00		
	TOTAL (PARTS & LABOUR):	\$ 5,713.00		

## LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D18MTPV01017898

CS/SMO19013065/KSF3N2

Date:

26/08/2019

REFERENCE

Handling Insurer:

Sompo Insurance Singapore Pte.

Claimant Vehicle No: Date of Loss:

SMG6533Z

22/07/2019

Policy No:

Insured Vehicle No:

SLH1266J

Nature of Claim: TP Claim No:

CMTD1903536

L13B1441763

GK31334695

12062 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SMG6533Z

Make & Model: Reg. Date:

HONDA FIT, 1.3 GF CVT (A) 27/12/2018 (Man. Year: 2018)

Colour:

Metallic Black 1317 cc

N/A

Engine Capacity:

Market Value/New Car Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

**Engine No:** Chassis No:

Odometer:

Yes

Handbrake (Serviceable): **CONDITION OF TYRES** 

Front Tyre Size:

175/70R14

Rear Tyre Size: Rear Left Side:

175/70R14

Front Left Side: Front Right Side: Yokohama 9 mm Yokohama 9 mm

Rear Right Side:

Yokohama 9 mm Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	<b>Repairer's</b> 4,013.00 0.00	Adjuster's 1,318.44 0.00	2,694.56 0.00	<b>Diff %</b> 67.15
Labour Paintwork Labour	1,700.00 0.00	1,035.00 0.00	665.00 0.00	39.12
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,713.00	2,353.44	3,359.56	58.81
+ GST 7.00/7.00% (S\$)	399.91	164.74	235.17	58.81
Nett Amount (S\$)	6,112.91	2,518.18	3,594.73	58.81

INSPECTION

Date of Assignment:

24/07/2019

Date Inspected:

25/07/2019 Inspected At:

Cartimes Autolution (HQ)

160 Sin Ming Drive #02-04 Autocity

Singapore 575722

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2019)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for SMG6533Z)
Validity:	These estimate	tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Recommended Parts Repairer's Amount Condition No. Qty Part No. Particulars 910.00 FL \*859.30 FL Bent \*REAR TAILGATE 1 1 \*-FL 285.00 FL Serviceable \*REAR TAILGATE INNER TRIM 2 1 \*-FL 235.00 FL Serviceable \*REAR TAILGATE WEATHERSTRIP 3 1 525.00 FL \*525.00 FL Buckled \*REAR BUMPER 4 1 \*-FL Serviceable 45.00 FL \*REAR BUMPER SIDE RETAINER LH 5 \*-FL 45.00 FL Serviceable \*REAR BUMPER SIDE RETAINER RH 6 1 \*-FL 580.00 FL Serviceable \*REAR RHS TAILLAMP 7 1 \*-FL Serviceable 580.00 FL \*REAR LHS TAILLAMP 8 1 \*-FL Serviceable 95.00 FL \*REAR KEY ANTENNA 9 1 85.00 FL \*85.00 FL \*REAR TAILGATE WINDSCREEN MOULDING Necessary 10 1 \*60.00 FL 60.00 FL Necessary 1 11 \*- FI 135.00 FL Serviceable \*SMART BUZZER 12 1 \*-FL Not Necessary 60.00 FL \*HONDA LOGO 13 1 \*-FL Serviceable 245.00 FL \*REAR END PANEL TOP GARNISH 14 1 60.00 FS \*60.00 FS Necessary \*SET REAR BUMPER CLIPS 15 \*35.00 FS 35.00 FS Necessary \*SET REAR WINDSCREEN SEALANT 16 \*-FS 80.00 FS Serviceable \*REAR NUMBER PLATE W/HOLDER 17 1 \*-FS 280.00 FS Serviceable \*SET REAR REVERSE SENSOR 18 1 \*-FS Serviceable 450.00 FS \*REAR REVERSE CAMERA 19 F=Franchise part. S=SpcNett. L=ListItemDisc. 1,624.30 4,790.00 Sub Total (S\$) 305.86 777.00 - List Item Discount on L Items 20.00/20.00% (S\$) 4,013.00 1,318.44 Total Parts (S\$)

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

No	commended Labour Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	800.00	400.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	600.00	440.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	60.00	15.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	80.00	30.00
5	TO REMOVE AND REPLACE REVERSE SENSOR & REVERSE CAMERA & CHECK FOR PROPER FUNCTION	New	60.00	50.00
6	TO REMOVE AND REFIT REAR WINDSCREEN	New	100.00	100.00
	Gross Labou	r Cost (S\$)	1,700.00	1,035.00
	Report was unsubmitted during	ng this print-out.		

< END OF ESTIMATES >