

ASS. REC. BY:

REF:

CS/INC19013076/Kgd3n2

Special Instruction:

Surveyor: Kenneth

## ASSIGNMENT (Office)

From (Person): Cynthia Ang of INC Date/Time: 24/7/19 9.47am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SME 7036X Insured: GW 3781Eat Workshop m/s Leong Auto Tel: 9692 4113of 160 Sin Ming Drive # 02-13Policy No: \_\_\_\_\_ Claim No: M7/1054532-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 13/07/19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9.53am @ 24/7/19 Person Contacted: Daniel Vehicle: IN/OUT

Date/Time	Action/Instruction
	Estimate ✓
18/10	11 Lms @ 7650 7650L Confirm (Red @ 10649.81, 58%)

ASS. REC. BY:

REF:

INC/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 7036X

Yr Regn:

10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Puma G

c.c

1496

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

62364

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

M14F 22814 37.000 57900

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Dayton

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/7/19

D.O.A.

24/7/19

Survey held at

11.06am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to  
GIA not ready

RECEIVED 13 OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

1) 16/10 14:15

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

10

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

P. 125

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.A. (\$

7P

7650

250

## Nivitha (LKK Auto)

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Wednesday, 24 July 2019 11:38 AM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Cynthia Ang  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 24/07/2019

Dear LKK,

Resend with following details.

Thank you.

With Regards

Cynthia Ang  
Admin Assistant  
Motor Insurance  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**From:** Cynthia Ang  
**Sent:** Wednesday, 24 July 2019 9:47 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Subject:** TP CASES FARMED OUT TO LKK ON 24/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI Veh	DOA	Additional Remarks
1	Eric Tang	MT/1054041-002	SKP40U	AUBURN AUTO PTE LTD	176 SING MING DRIVE #04-18 SING MING AUTOCARE SINGAPORE 575721	SAM NG /		SJX5746D	18/07/2019	
2		*Pending advise*	SLD8749H	COMFORTDELGRO ENGINEERING PTE LTD	205 BRADDELL ROAD EAST WING 3RD FLR SINGAPORE 579701	ANDREW / 63837656				
3	Fiona Shen	MT/1054783-001	SLK1780A	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	carmen / 87990066	10:00-12:00	GBD9099L	12/07/2019	
4	Eng Huey Huey	MT/1053378-002	SLG3325P	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	CARM / 87990066	10:30-12:30	SMC4602S	13/07/2019	

5	Fiona Shen	MT/1054563-002	SLQ2069H	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	SERENE CHEE / 87990066		SLK9926U	22/07/2019
6	Jeff Lin	MT/1051997-002	SKF8917R	LAI HUAT MENG KEE MOTOR PTE LTD	160 SIN MING DRIVE #04-01 SIN MING AUTOCITY SINGAPORE 575722	DEBORAH LAI / 64538110		SJS5571S	05/07/2019
7		<b>*Pending advise*</b>	SME7036X	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SIN MING AUTOCITY	DANIEL TAN/CADY LEE / 9692 4113			
8	Eng Huey Huey	MT/1052391-002	SMC660A	MOTOR IMAGE ENTERPRISES PTE LTD	19 LORONG 8 TOA PAYOH SINGAPORE 319255	DANIEL A JUDE / 86113195	10:00-12:00	SLT8341R	07/07/2019
9	Jared Liu	MT/1054437-002	SMH6433Z	SKS AUTOMOBILE SOLUTION	176 SIN MING DRIVE #01-17 SIN MING AUTOCARE SINGAPORE 575721	MS YIWEN / 64550747		SME7134X	20/07/2019
10		<b>*Pending advise*</b>	SMC7382G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	STEVEN / 82636295			
11	Jeff Lin	MT/1054330-002	SLG586Y	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722	RAYMOND TEO / 64532121		SLQ6072X	20/07/2019

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Motor Insurance

T +65 6430 7900

[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at [income.com.sg/careers](http://income.com.sg/careers)

**in** with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

## Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

**From:** Cynthia Ang

**Sent:** Wednesday, 24 July 2019 9:47 AM

**To:** 'assignments@lkkauto.com' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** Teng Ken Leong <[kenleong.teng@income.com.sg](mailto:kenleong.teng@income.com.sg)>; Thio Tse Kiat <[tsekiat.thio@income.com.sg](mailto:tsekiat.thio@income.com.sg)>; Cynthia Ang <[Cynthia.Ang@income.com.sg](mailto:Cynthia.Ang@income.com.sg)>

**Subject:** TP CASES FARMED OUT TO LKK ON 24/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI Veh	DOA	Additional Remarks
1	Eric Tang	MT/1054041-002	SKP40U	AUBURN AUTO PTE LTD	176 SING MING DRIVE #04-18 SING MING AUTOCARE SINGAPORE 575721	SAM NG /		SJX5746D	18/07/2019	
2	Helena Tan	MT/1054892-001	SLD8749H	COMFORTDELGRO ENGINEERING PTE LTD	205 BRADDELL ROAD EAST WING 3RD FLR SINGAPORE 579701	ANDREW / 63837656		SDQ6966L	21/07/2019	
3	Fiona Shen	MT/1054783-001	SLK1780A	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	carmen / 87990066	10:00-12:00	GBD9099L	12/07/2019	
4	Eng Huey Huey	MT/1053378-002	SLG3325P	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	CARM / 87990066	10:30-12:30	SMC4602S	13/07/2019	
5	Fiona Shen	MT/1054563-002	SLQ2069H	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	SERENE CHEE / 87990066		SLK9926U	22/07/2019	
6	Jeff Lin	MT/1051997-002	SKF8917R	LAI HUAT MENG KEE MOTOR PTE LTD	160 SIN MING DRIVE #04-01 SING MING AUTOCITY SINGAPORE 575722	DEBORAH LAI / 64538110		SJS5571S	05/07/2019	
7	Helena Tan	MT/1054532-002	SME7036X	LEONG AUTO PTE LTD	160 SIN MING DRIVE #02-13 SING MING AUTOCITY	DANIEL TAN/CADY LEE / 9692 4113		GW3781E	23/07/2019	
8	Eng Huey Huey	MT/1052391-002	SMC660A	MOTOR IMAGE ENTERPRISES PTE LTD	19 LORONG 8 TOA PAYOH SINGAPORE 319255	DANIEL A JUDE / 86113195	10:00-12:00	SLT8341R	07/07/2019	
9	Jared Liu	MT/1054437-002	SMH6433Z	SKS AUTOMOBILE SOLUTION	176 SIN MING DRIVE #01-17 SING MING AUTOCARE SINGAPORE 575721	MS YIWEN / 64550747		SME7134X	20/07/2019	
10	Eric Tang	MT/1054600-002	SMC7382G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SING MING AUTOCARE	STEVEN / 82636295		FBE9525T	17/07/2019	
11	Jeff Lin	MT/1054330-002	SLG586Y	VIN'S AUTOMOTIVE GROUP	160 SIN MING DRIVE #08-09 SING MING DRIVE SINGAPORE 575722	RAYMOND TEO / 64532121		SLQ6072X	20/07/2019	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/07/2019 15:40
Date Of Accident	23/07/2019 07:55
Exact Location Of Accident	JURONG EAST CENTRAL TOWARDS JURONG EAST AVENUE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME7036X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIN KIN HONG
NRIC No	S7937529B
Email Address	HONG_LIN2002@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-94579997
Alternative Phone No	OFFICE-94579997

### Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104421619
Cover Note Number	

### Driver

Name of Driver	LIN KIN HONG
NRIC No	S7937529B
Date Of Birth	05/12/1979
Occupation	OUTDOOR
Date Of Driving Pass	26/12/2000
Driving Experience	18 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94579997
Fax Number	
Contact Number	OFFICE-94579997
Email Address	HONG_LIN2002@YAHOO.COM.SG



Address	BLK 659 #14-71 CHOA CHU KANG CRESCENT
Postcode	680659
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PASSENGER1 GENDER: : MALE
Passenger 2	NAME: : PASSENGER 2 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW3781E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBG9895P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)




SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

23 JUL 2019

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature

Name: **NG WING KIN JAMES**  
NRIC No. **admin.vac@vicom.com.sg**

# LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722  
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg  
Business Registration No. 201312846W  
GST Registration No. 201312846W

*Not Authorised* ESTIMATE  
*115m @ 7650h*  
*Running After Pain* 40 days

Owner IC: 7529B  
Date: 23/7/2019  
DOA: 23/7/2019

Vehicle No: SME7036X  
Make & Model: Toyota Sienta

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Tail Gate <i>1486.30</i>	\$ 1,760.60	✓
2	1	Rear Tail Gate Windscreen Moulding	\$ 224.90	✓
3	1	Rear Tail Gate Centre Logo	\$ 85.00	✓
4	1	Rear Tail Gate "G" Emblem	\$ 58.00	✓
5	1	Rear Tail Gate Outer Moulding	\$ 216.30	✓
6	2	Rear Tail Gate Outer Moulding No. Plate Lamp	\$ 147.70	x
7	1	Rear Tail Gate Outer Moulding Reverse Camera <i>Pri</i>	\$ 744.70	✓ <i>4505n</i>
8	1	Rear Tail Gate Wiper Motor	\$ 597.20	✓
9	1	Rear Tail Gate Wiper Arm	\$ 114.20	✓
10	1	Rear Tail Gate Lock Mechanism <i>305.10</i>	\$ 544.70	✓
11	1	Rear Tail Gate Lock Catch	\$ 46.20	x
12	1	Rear Tail Gate WeatherStrip <i>195.60</i>	\$ 320.00	✓
13	1	Rear Tail Gate Inner Trim Board	\$ 648.80	x
14	1	Rear Tail Gate Inner Handle	\$ 217.40	✓
15	2	Rear Tail Gate Reflector Lamp <i>0380.60</i> <i>n/s</i> <i>my</i> <i>cm</i>	\$ 857.50	✓
16	1	Rear End Panel <i>658.30</i>	\$ 748.00	✓
17	1	Rear End Panel Vertical Bracket	\$ 242.50	✓
18	1	Rear End Panel Top Garnish <i>195</i>	\$ 352.60	✓
19	1	Rear R/H Chassis Bar	\$ 461.20	x
20	1	Rear Spare Tyre Panel	\$ 852.40	✓
21	1	Rear Spare Tyre Panel Top Tray	\$ 322.80	✓
22	1	Rear Spare Tyre Panel Insulator Pad	\$ 264.50	✓ <i>7005n</i>
23	2	Rear Fender Inner Shield	\$ 147.90	x
24	2	Rear Fender Inner Trim Board <i>n/s</i> <i>my</i> <i>cm</i>	\$ 1,303.50	✓ <i>651.75</i>
25	1	Rear Bumper <i>566.10</i>	\$ 899.90	✓
26	2	Rear Bumper Side Retainer	\$ 236.20	x
27	1	Rear Bumper Centre Reflector Lamp <i>218</i>	\$ 384.00	✓
28	2	Rear Bumper Parking Sensor <i>Pri</i>	\$ 642.20	✓ <i>2005n</i>
29	1	Rear Bumper Protector <i>183</i>	\$ 315.80	✓
30	2	Rear Bumper Side Protector <i>e124</i> <i>n/s</i> <i>Ad</i>	\$ 426.70	✓ <i>124</i>
31	2	Rear Bumper Side Protector Reflector <i>n/s</i> <i>cm</i>	\$ 236.20	✓ <i>118.10</i>
32	1	Rear Exhaust Assy	\$ 898.20	x
33	2	Rear Exhaust Mounting	\$ 241.20	x
34	1	Rear Sound Beep	\$ 168.70	✓
			\$ 15,727.70	
		Less 25%	\$ 3,931.93	
			\$ 11,795.78	
		Special Nett Items		
1		Sundries	\$ 50.00	x
2	1	Rear Tail Gate Windscreen Moulding Sealant	\$ 120.00	✓ <i>405n</i>
3	1	Rear Tail Gate Windscreen Moulding Damping Seal	\$ 120.00	✓ <i>305n</i>
4	2 set	Rear Tail Gate Reflector Lamp Clips	\$ 80.00	✓ <i>124</i>
5	1 set	Rear Tail Gate Outer Moulding Clips	\$ 80.00	✓ <i>118.10</i>
6	1 set	Rear Tail Gate Inner Trim Board Clips	\$ 80.00	x

7	1	Rear End Panel Sealant	nu	\$	120.00	301n
8	1 set	Rear End Panel Top Garnish Clips	nu	\$	50.00	✓
9	2 set	Rear Fender Inner Trim Board Clips	nu	\$	120.00	x
10	2 set	Rear Fender Inner Shield Clips	nu	\$	80.00	✓
11	1 set	Rear Bumper Clips	nu	\$	50.00	✓
12	1 set	Rear Bumper Protector Clips	nu	\$	50.00	x
13	2 set	Rear Bumper Side Protector Clips	nu	\$	50.00	x
14	1 set	Rear No. Plate with Garnish	nu	\$	80.00	451n
				\$	1,130.00	
		Total Parts		\$	12,925.78	
S/N		Labour Description			Amount	Amount
		Labour for panel beating, cut, weld, straighten and replace rear				
	1	damaged parts.		\$	1,800.00	1200
	2	To putty and spray painting rear portion.		\$	1,600.00	900
	3	To check rear lighting and wiring.		\$	80.00	20
	4	To remove and install rear tail gate lock mechanism.		\$	120.00	60
	5	To remove and install inner garnish and trim to facilitate the		\$	380.00	80
	6	repair.		\$	250.00	90
	7	To apply anti rust proofing to rear affected area.		\$	150.00	50
	8	To remove and install rear reverse camera.		\$	150.00	50
	9	To remove and install rear reverse sensor.		\$	150.00	120
	10	To remove and install rear windscreen.		\$	150.00	120
		To adjust chassis alignment.	nu	\$	380.00	x
		To remove & refit tail gate component to replace tail gate, check				
	11	& re-adjust the close gap and alignment and water seepage		\$	120.00	x
		Total labour :		\$	5,180.00	
		Total parts :		\$	12,925.78	
		Total labour :		\$	5,180.00	
		Total repair cost :(Before GST)		\$	18,105.78	

18299.81

Use Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722  
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg  
Business Registration No. 201312846W  
GST Registration No. 201312846W

### ESTIMATE

Owner IC: 7529B

Date: 23/7/2019

DOA: 23/7/2019

Vehicle No: SME7036X

Make & Model: Toyota Sienta

S/N	Qty	Item Description	Parts Price	Surveyor
		<b>Supplementary Items</b>		
1	1	Rear Spare Tyre Windnut <i>CMA</i>	\$ 94.20	—
2	1	Rear Bumper Centre Reflector Lamp Inner Garnish <i>mgcm</i>	\$ 164.50	—
			\$ 258.70	
		Less 25%	\$ 64.68	
			\$ 194.03	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19013076/Kqd3n2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 16-10-2019



ATTN: HELENA TAN

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	GW 3781E	Veh. Inspected	SME 7036X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1054532-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	24/07/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA SIENTA G (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MHFZ28H3700057900	Colour	METALLIC GREY
Odometer	62364 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	185/60 R15	DAYTON	5 mm
L/H Front Tyre	185/60 R15	DAYTON	5 mm
R/H Rear Tyre	185/60 R15	DAYTON	5 mm
L/H Rear Tyre	185/60 R15	DAYTON	5 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	23/07/2019	Inspect Date / Time	24/07/2019 ( 11:06 AM )
Survey held at	LEONG AUTO PTE LTD 160 SIN MING DRIVE #02-13 SIN MING AUTOCITY SINGAPORE 575722		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 7036X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR TAIL GATE	BENT	1,760.60	1,486.30
1	REAR TAIL GATE WINDSCREEN MOULDING	NECESSARY	224.90	224.90
1	REAR TAIL GATE CENTRE LOGO	NECESSARY	85.00	85.00
1	REAR TAIL GATE "G" EMBLEM	NECESSARY	58.00	58.00
1	REAR TAIL GATE OUTER MOULDING	MTG CRACKED	216.30	216.30
2	REAR TAIL GATE OUTER MOULDING NO PLATE LAMP	SERVICEABLE	147.70	-
1	REAR TAIL GATE WIPER MOTOR	JAMMED	597.20	597.20
1	REAR TAIL GATE WIPER ARM	SERVICEABLE	114.20	-
1	REAR TAIL GATE LOCK MECHANISM	DENTED	544.70	305.10
1	REAR TAIL GATE LOCK CATCH	TO REPAIR SEE LABOUR	46.20	-
1	REAR TAIL GATE WEATHERSTRIP	DENTED / DISTORTED	320.00	195.60
1	REAR TAIL GATE INNER TRIM BOARD	SERVICEABLE	648.80	-
1	REAR TAIL GATE INNER HANDLE	DENTED	217.40	217.40
2	REAR TAIL GATE REFLECTOR LAMP	N/S MTG CRACKED / O/S SERVICEABLE	857.50	380.60
1	REAR END PANEL	BENT	748.00	658.30
1	REAR END PANEL VERTICAL BRACKET	TO REPAIR SEE LABOUR	242.50	-
1	REAR END PANEL TOP GARNISH	DENTED	352.60	195.00
1	REAR R/H CHASSIS BAR	TO REPAIR SEE LABOUR	461.20	-
1	REAR SPARE TYRE PANEL	BENT / BUCKLED	852.40	852.40
1	REAR SPARE TYRE PANEL TOP TRAY	MTG DISTORTED	322.80	322.80
2	REAR FENDER INNER SHIELD	SERVICEABLE	147.90	-
2	REAR FENDER INNER TRIM BOARD	N/S MTG CRACKED / O/S SERVICEABLE	1,303.50	651.75
1	REAR BUMPER	BENT	899.90	566.10
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	236.20	-
1	REAR BUMPER CENTRE REFLECTOR LAMP	CRACKED	384.00	218.00

Report Ref No. CS/INC19013076/Kqd3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER PROTECTOR	BENT	315.80	183.00
2	REAR BUMPER SIDE PROTECTOR	N/S DENTED	426.70	124.00
2	REAR BUMPER SIDE PROTECTOR REFLECTOR	N/S CRACKED	236.20	118.10
1	REAR EXHAUST ASSY	TO REPAIR SEE LABOUR	898.20	-
2	REAR EXHAUST MOUNTING	SERVICEABLE	241.20	-
1	REAR SOUND BEEP	SERVICEABLE	168.70	-
1	REAR SPARE TYRE WINDNUT (ADDITIONAL)	CRACKED	94.20	94.20
1	REAR BUMPER CENTRE REFLECTOR LAMP INNER GARNISH (ADDITIONAL)	MTG CRACKED	164.50	164.50
	LESS 25% DISCOUNT		-3,583.75	-1,978.64
			10,751.25	5,935.91
1	REAR TAIL GATE OUTER MOULDING REVERSE CAMERA (SN)	SCRATCHED	744.70	450.00
1	REAR SPARE TYRE PANEL INSULATOR PAD (SN)	NECESSARY	264.50	100.00
2	REAR BUMPER PARKING SENSOR (SN)	CRACKED	642.20	200.00
	LESS 25% DISCOUNT		-412.85	-
			1,238.55	750.00
	<b>SPECIAL NETT ITEMS</b>			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	REAR TAIL GATE WINDSCREEN MOULDING SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR TAIL GATE WINDSCREEN MOULDING DAMPING SEAL (SN)	NECESSARY	120.00	30.00
2	SET REAR TAIL GATE REFLECTOR LAMP CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET REAR TAIL GATE OUTER MOULDING CLIPS (SN)	NECESSARY	80.00	50.00
1	SET REAR TAIL GATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	120.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	50.00
2	SET REAR FENDER INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	120.00	-
2	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER PROTECTOR CLIPS (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/INC19013076/Kqd3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR BUMPER SIDE PROTECTOR CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR NO PLATE WITH GARNISH (SN)	MISSING	80.00	45.00
			1,130.00	295.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN AND REPLACE REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR TAIL GATE LOCK CATCH,REAR END PANEL VERTICAL BRACKET,REAR R/H CHASSIS BAR AND REAR EXHAUST ASSY.		1,800.00	1,200.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,600.00	900.00
	TO CHECK REAR LIGHTING AND WIRING.		80.00	20.00
	TO REMOVE AND INSTALL REAR TAIL GATE LOCK MECHANISM.		120.00	60.00
	TO REMOVE AND INSTALL INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		380.00	80.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		250.00	90.00
	TO REMOVE AND INSTALL REAR REVERSE CAMERA.		150.00	50.00
	TO REMOVE AND INSTALL REAR REVERSE SENSOR.		150.00	50.00
	TO REMOVE AND INSTALL REAR WINDSCREEN.		150.00	120.00
	TO ADJUST CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT TAIL GATE COMPONENT TO REPLACE TAIL GATE,CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.	NOT NECESSARY	120.00	-
			5,180.00	2,570.00
<b>GRAND TOTAL</b>			<b>18,299.80</b>	<b>9,550.91</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>7,650.00</b>

Report Ref No. CS/INC19013076/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.