

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 9965B - III**ROEL***Not Attached*
11 Sep 8 2600h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9965B - ROEL

VF1ABL15AUC273441

RENAULT

LATITUDE

07.10.16

III

PART			LIST		
1	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95	<i>X</i>
2	1	FENDER WHEELARCH FRT RH (Linner)	\$	<i>Sm</i> 107.33	<i>X</i>
3	1	DOOR FRT RH	\$	<i>R</i> 2,188.20	<i>X</i>
4	1	DOOR HANDLE OUTER FRT RH	\$	<i>R</i> 198.55	<i>X</i>
5	1	DOOR MOULDING FRT RH	\$	<i>Sm</i> 136.01	<i>X</i>
6	1	DOOR MIRROR RH	\$	<i>Sm</i> 1,141.08	<i>X</i>
7	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 759.61	<i>X</i>
8	1	DOOR REAR RH	\$	<i>R</i> 2,188.20	<i>✓</i>
9	1	DOOR HANDLE OUTER REAR RH	\$	<i>Sm</i> 97.31	<i>X</i>
10	1	FENDER PANEL REAR RH	\$	<i>R</i> 2,537.80	<i>X</i>
11	1	FENDER WHEELARCH REAR RH (Linner)	\$	<i>Sm</i> 418.06	<i>X</i>
12	1	BUMPER COVER REAR	\$	<i>Sm</i> 852.66	<i>X</i>
13	1	BUMEPR BRACKET SIDE RH REAR(Taillamp lo	\$	<i>Sm</i> 104.59	<i>X</i>
14	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 34.61	<i>X</i>

TOTAL	\$	11,366.96
10%	\$	1,136.70
	\$	10,230.26

Specical Nett

1	1	DOOR STICKER "Trans-cab"	\$	<i>R</i> 80.00	<i>60sm</i>
2	1	DOOR STICKER "Classic"	\$	<i>R</i> 30.00	<i>15sm</i>
3	1	DOOR STICKER "6555-3333"	\$	<i>WCC</i> 80.00	<i>60sm</i>
4	2	Rear Windscreen Sealant	\$	<i>R</i> 100.00	<i>X</i>
5	1	Rear Windscreen Inner Sponge Seal	\$	<i>R</i> 150.00	<i>X</i>
6	1	RIM RH RR (spare change)	\$	<i>Sm</i> 385.00	<i>X</i>
7	1	TYRE RH RR (spare change)	\$	<i>Sm</i> 330.00	<i>X</i>
8	1SET	WHEELARCH CLIP RR RH	\$	<i>R</i> 66.00	<i>X</i>
9	1SET	REAR BUMPER CLIP	\$	<i>R</i> 66.00	<i>X</i>
10	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>R</i> 20.00	<i>X</i>

TOTAL	\$	1,307.00
TOTAL PARTS	\$	11,537.26

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 9965B - III**ROEL**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	400
To Check Electrical Lighting Concerned.	\$	170.00	20
Putty and spray painting of the affected portion.	\$	3,000.00	600
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	60
To rust-proofing of the affected areas.	\$	170.00	30

TOTAL	\$	6,910.00
Over All Total	\$	18,447.26

(PARTS BY PARTS) Repair Days~~10-Days~~

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: