
























PAR Automotive Consultancy

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0146-19-N51

18 March 2019

ACCIDENT VEHICLE SURVEY REPORT

Chew Business Services
Blk 59 Tampines Central 7 #12-16
Singapore 528594

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SKW1216L	<i>Odometer:</i>	117888km
<i>Make & Model:</i>	Toyota Harrier 2.0A	<i>Colour:</i>	Black
<i>Chassis number:</i>	ZSU600059549	<i>Date of accident:</i>	03/01/2018
<i>Year of Regn.:</i>	27/11/2016	<i>Date inspected:</i>	09/01/2018
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	16/01/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

