

ASS. REC. BY:

REF: CS/FCI 19013099/Ut3

12

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

CWS

From (Person): Joanne Yong

of FCI

Date/Time: 5.48pm @ 21/7/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 1167K

Insured:

SH 6187M

at Workshop in/s

Polymath Garage

Tel:

82259818

of

10 Kaki Bukit Rd 2 # 01-21

Policy No:

Claim No:

D19004820MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22/7/2019

(Client's Record)

30/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.33am @ 25/7/19

Person Contacted:

Sebastian

Vehicle - IN / OUT

Date/Time	Action/Instruction	Remarks
	SH 1167K	NA/INC19012984/24 DDA = 22/7/19
	SH 6187M	"
21/7/19 @ 10.10am	Informed Joanne Yong, we are pending estimate from repairer.	
21/7/19 @ 10.16am	revised to Joanne Yong by email.	

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

Ref

ASSIGNMENT

From:
Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

OAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:



Veh No: SM/1167K Yr Regn: 7 08
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S / Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

c.c 1595

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

JHMFD462085201957

225/45 R17

64

Rear

R/Bal.

L/Bal.

D.O.I.

30/7/19

Reef 2 (S)

Date / Time Action / Instruction

5/8/19 25-7-2028
1/5 #1350 confid with Sebastian URed: 6168.26: 82901
MV: 45,000
LTA-33.383
NV: 11612
RECEIVED 13 AUG 2019

Date/Time, File Pass to?

1) B/z Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS SI

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 1350/-)

150

50

50

29

279



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004820MFSH

Date: 31 July 2019

Our Ref: CS/FCI19013099/Utf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJH 1167K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/07/2019 at the premises of M/s POLYMATH GARAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,518.26</u> .
Revised Estimate Amount	: S\$ <u>1,688.04</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-07-2019	Our Ref No. D19004820MFSH
Accident Date	22-07-2019	Claim Type. Third Party
Insured Vehicle	SH6187M	Third Party Vehicle. SJH1167K
Survey Location	10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE	
Contact Person.	MR SEBASTIAN HUANG	
Contact No.	0/ 82289818	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	POLYMATH GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	HIN TAT AUGUSTINE & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 31 July 2019 10:16 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004820MFSH/1
Attachments: CSFCI19013099Utf3.pdf

Dear Joanne,

Please ignore previously email.

Enclosed herewith preliminary advice of SJH 1167K.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, 31 July 2019 10:10 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004820MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SJH 1167K on 30/07/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 25 July 2019 9:35 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004820MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 31 July 2019 10:10 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004820MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SJH 1167K on 30/07/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 25 July 2019 9:35 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004820MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 July 2019 5:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004820MFSH/1

Need Items for Your Car?

We have thousands of car parts & accessories to explore.

The best online platform to sell and buy car parts & accessories - Marketplace

Civic Price Range Depreciation > 10 year Vehicle Type Submit

Advanced Search

Home » Used Cars » 360 VR Cars » Honda Civic 1.8A VTi-S (COE till 07/2028)

Honda Civic 1.8A VTi-S (COE till 07/2028)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

360° VR Cars

Price	\$49,000		
Depreciation	\$5,490 /yr	Reg Date	03-Jul-2008 (8yrs 11mths 2days COE left)
Mileage	163,000 km (14.7k /yr)	Manufactured	2008
Road Tax	\$1,076 /yr	Transmission	Auto
Dereg Value	\$32,947 as of today (change)	OMV	\$21,302
COE	\$36,888	ARF	\$21,302
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight	1,219 kg	No. of Owners	2

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Honda Civic (2006-2012)

Accessories

Sports Rims, Retractable Side Mirrors, Reverse Sensors. New Paint Work. Road Tax Renew At Early July 2019.

Description

Flexible And Attractive Loan Available To Choose. High Loan Available Too. Trade Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Compare



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

360 VR Cars



» dealer's pricelist

» 141 vehs sold | 114 vehs available

Address

26 Sin Ming Lane #07-111

Search cars nearby this location

Location

Midview City

Office No

69310005

Contact Person(s)

Alvin

96475408

James Tan

90700005

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 077Z

Vehicle Details

Vehicle No.: SJH1167K

Vehicle to be Exported: No

Intended Deregistration Date: 30 Jul 2019

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6L VTI AUTO

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: R16A13006000

Chassis No.: JHMFD46208S201957

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$18,655.00

Original Registration Date: 26 Jul 2008

First Registration Date: 26 Jul 2008

Transfer Count: 2

Actual ARF Paid: \$18,655.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Jul 2028

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

PQP Paid: \$37,165.00

COE Rebate Amount: \$33,388.00

Total Rebate Amount: \$33,388.00

The information contained herein is correct as at 30 Jul 2019

OK



Polymath garage

Polymath Garage Pte Ltd
10 Kaki Bukit Road 2 #01-21
First East Centre, Singapore 417868
24 Hour: +65 8228 9818
Phone: +65 6871 8861 | Fax: +65 6871 8814
Email: enquiry@polymathgarage.com.sg
UEN: 201605123Z

Estimated repair checklist

Vehicle Registration No.: SJH1167K
Vehicle Make/Model: Honda Civic

QTY Parts

- 1 Bootlid
1 Bootlid "Type R" emblem
1 Bootlid lock
1 Bootlid weatherstrip
1set Rear bumper clips 35.80
1 Rear bumper RH side retainer
1 Rear bumper LH side retainer
1 End panel
1 End panel inner garnish
1 RH taillamp assy 237.55
1 RH taillamp lower bracket
1 LH taillamp assy
1 LH taillamp lower bracket

not added
L/S 1350/-
24/7/19
thp to the car

Prices \$	
\$ 17	610.75 X
\$ 17	65.80 X
\$ 17	190.45 X
\$ 17	97.65 X
\$ new	50.00 ✓
\$ 17	32.40 X
\$ 17	32.40 X
\$ 17	342.55 X
\$ 17	80.43 X
\$ 512	348.75 ✓
\$ 17	23.95 X
\$ 17	348.75 X
\$ 17	23.95 X
Subtotal	\$ 2,247.83
Less: -20%	\$ 449.57
Total Parts	\$ 1,798.26

Special Nett items

- 1 Bootlid LH emblem
1 Bootlid centre red emblem
1 Rear bumper Sport type
1 Rear bumper lower diffuser
1set Exhaust silencer
1set Rear bumper reverse sensor

\$ 17	50.00 X
\$ 17	70.00 X
\$ 17	1,000.00 ✓
\$ 17	900.00 X
\$ 17	1,000.00 X
\$ 17	280.00 X
Total Special Nett	\$ 3,300.00

Labour charges

- Remove and replacing above parts
Putty and respray on affected areas
Check wiring and lighting system
Apply rust proofing on affected areas
Remove and replace rear inner trim
Remove and replace rear reverse sensor
Remove and replace exhaust silencer

\$	900.00 200
\$	1,000.00 200
\$	60.00 20
\$ 17	70.00 X
\$ 17	200.00 X
\$	70.00 50
\$ 17	120.00 X
Total Labour	\$ 2,420.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

\$ 7,518.26

LKK Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Page 1 of 1

P-272.55
202
P-218.04
S.N 1000.00
10hr - 470.00
1688.04
1700.43



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013099/Utf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6187M	Veh. Inspected	SJH 1167K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004820MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	24/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (M)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMFD46208S201957	Colour	SILVER	
Odometer	150074	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/07/2019	Inspection Date	30/07/2019	
Survey held at	10 KAKI BUKIT ROAD 2 #01-21			
Repairer	POLYMATH GARAGE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 1167K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	NOT NECESSARY	610.75	-
1	BOOTLID "TYPE R" EMBLEM	NOT NECESSARY	65.80	-
1	BOOTLID LOCK	NOT NECESSARY	190.45	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	97.65	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	35.00
1	REAR BUMPER RH SIDE RETAINER	NOT NECESSARY	32.40	-
1	REAR BUMPER LH SIDE RETAINER	NOT NECESSARY	32.40	-
1	END PANEL	NOT NECESSARY	342.55	-
1	END PANEL INNER GARNISH	NOT NECESSARY	80.43	-
1	RH TAILLAMP ASSY	SCRATCHED	348.75	237.55
1	RH TAILLAMP LOWER BRACKET	NOT NECESSARY	23.95	-
1	LH TAILLAMP ASSY	NOT NECESSARY	348.75	-
1	LH TAILLAMP LOWER BRACKET	NOT NECESSARY	23.95	-
	LESS 20% DISCOUNT		-449.57	-54.51
			1,798.26	218.04
SPECIAL NETT ITEMS				
1	BOOTLID LH EMBLEM (SN)	NOT NECESSARY	50.00	-
1	BOOTLID CENTRE RED EMBLEM (SN)	NOT NECESSARY	70.00	-
1	REAR BUMPER SPORT TYPE (SN)	DEFORMED / CRACKED	1,000.00	1,000.00
1	REAR BUMPER LOWER DIFFUSER (SN)	NOT NECESSARY	900.00	-
1	SET EXHAUST SILENCER (SN)	NOT NECESSARY	1,000.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
			3,300.00	1,000.00
LABOUR				
	REMOVE AND REPLACING ABOVE PARTS.		900.00	200.00
	PUTTY AND RESPRAY ON AFFECTED AREAS.		1,000.00	200.00
	CHECK WIRING AND LIGHTING SYSTEM.		60.00	20.00
	APPLY RUST PROOFING ON AFFECTED AREAS.	NOT NECESSARY	70.00	-
	REMOVE AND REPLACE REAR INNER TRIM.	NOT NECESSARY	200.00	-

Report Ref No. CS/FCI19013099/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REPLACE REAR REVERSE SENSOR.	NOT NECESSARY	70.00	50.00
	REMOVE AND REPLACE EXHAUST SILENCER.		120.00	-
			2,420.00	470.00
GRAND TOTAL			7,518.26	1,688.04

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00
---	--	--	--	----------

Report Ref No. CS/FCI19013099/Utf3n2

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$33,388.00=NETT VALUE: \$11,612.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.