

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67464422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Kharchan

Quotation

DATE : 14.08.2019
 VEH NO : SKW8665C
 MODEL : Lexus RX270
 D O A : 24.07.2019
 YR REF : SGP8838E

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKW8665C (LEXUS RX270)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Defaced</i>	1	969.50 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	211.00 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	363.20 ✓
5	Rear Bumper Sponge <i>crushed</i>	1	163.80 ✓
6	Rear Bumper Reinforcement <i>new</i>	1	681.60 ✓
7	Rear Bumper Undercover <i>Defaced</i>	1	289.40 ✓
8	Rear Bumper Undercover Clips <i>new</i>	1 set	30.00 ✓
9	Reverse Sensor <i>2 pieces damaged</i>	4	1,040.00 <i>520</i>
			3,778.50
			(377.85)
			\$ 3,400.65
	Total Parts		\$ 3,400.65

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 400.00 <i>250</i>
2	To putty & spray up paint works <i>560</i>	\$ 400.00 <i>250</i>
5	To remove reverse sensor	\$ 100.00 <i>60</i>
	Total Labour	\$ 900.00

Grand Total

\$ 4,300.65

total 2552.33.

4/s : 2K.

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: