

22000000

ASS. REC. BY:

REF: CS/FCI 19013109/TIV43ⁿ² Special Instruction:

Assigner: Taufik

ASSIGNMENT (Office)

From (Person): Senene for

of FCI

Date/Time: 44pm 24/7/19

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 1948R

Insured: SHC 21692

at Workshop m/s

Hitachi Capital

Tel: 68336282

of

8 fourth fork yong Road

Policy No:

Claim No: D19004736MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 17/07/2019

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 9:42am 25/7/19

Person Contacted: Jiong Hou

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Estimated ✓</u>
	<u>SLE 1948R X</u>
	<u>SHC 21692 CS/FCI 19004047/RI+d3n2 DOA=4/2/19</u>
<u>26/7/19</u>	<u>Email preli revised to FCI</u>
<u>21/8/19</u>	<u>Taufik said part price - OK</u>
<u>21/8/19</u>	<u>Final fig \$ 4269. confirmed by email (Red 2836.50, 4090) (No LS)</u>

ASS. REQ. BY:

Tayfer

REF:

FCL

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE 1948R

Yr Regn:

246, July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A/Lis

c.c.

1598

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

287 847

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

UK053 REH 104 554832

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

25/7/19 230km

Survey held at

Nitechi Capital

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 22 AUG 2019

21/8/2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

22/8 - typst

Report Format:

CWS

Lump Sum / L.B. / P.

4269/2

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Inve (\$)

☐

Week end (\$)

Survey Fee:

150

Transportation:

50

3 + P.S. SI

50

Photos:

31

Others:

TOTAL

281



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004736MFSH

Our ref: CS/FCI19013109/T1vf3

Date: 26/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 1948R


We thank you for your instruction on 24/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/7/2019 at the premises of M/s HITACHI CAPITAL ASIA PACIFIC PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,060.50
Revised Estimate Amount	: S\$4,162.50
"Check" Items Amount	: S\$365.25
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-07-2019	Our Ref No. D19004736MFSH
Accident Date	17-07-2019	Claim Type. Third Party
Insured Vehicle	SHC2169Z	Third Party Vehicle. SLE1948R
Survey Location	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG ROAD	
Contact Person.	NG JIONG HOW	
Contact No.	68336282/ 0	Fax No. 0
Survey Type	DIRECT SETTLEMENT: EST. COR - \$7554.74	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 26 July 2019 11:15 AM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004736MFSH/1-SLE 1948R
Attachments: SLE 1948R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLE 1948R
Date of survey: 25/7/2019
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 25 July 2019 11:04 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004736MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 July 2019 4:45 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004736MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 21 August 2019 11:16 AM
To: JiongHow, Ng
Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim; SUR
Subject: RE: SLE 1948R-DOA: 17/7/2019v

Dear Jiong How,

WITHOUT PREJUDICE

Confirm COR @ \$4269.00 Before GST @ 5 working days

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Sent: Tuesday, 20 August 2019 3:17 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>
Subject: RE: SLE 1948R-DOA: 17/7/2019v

Dear Veron,

Please confirm COR @ \$4269.00 Before GST

Thank you

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6282
e: jionghow.ng@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.
This email is intended solely for the attention and use of the name addressee(s).
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.
If you have received this email in error, please notify the sender immediately by email and delete it from your system.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, August 19, 2019 2:55 PM
To: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: RE: SLE 1948R-DOA: 17/7/2019

Dear Jiong How,

Can finalise?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Sent: Tuesday, 6 August 2019 3:23 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SLE 1948R-DOA: 17/7/2019

Hi Veron,

Vehicle repaired. Will finalise later on

Thank you

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6282
e: jionghow.ng@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.
This email is intended solely for the attention and use of the name addressee(s).
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.
If you have received this email in error, please notify the sender immediately by email and delete it from your system.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, August 6, 2019 3:12 PM
To: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: SLE 1948R-DOA: 17/7/2019

Dear Jiong How,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

FCIL

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 17/07/2019@1920HRS
 VRN : SLE1948R
 MODEL : Toyota Altis
 TP VRN : SHC2169Z

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Front Bumper	1	\$ 458.00	\$ 458.00 Rx	
2 Front Bumper Clips	10	\$ 5.50	\$ 55.00 x nn. der	
3 Front Bumper Outer Bracket LH/RH	2	\$ 82.00	\$ 164.00 LH-?, RH x nn.	
4 Headlamp LH	1	\$ 850.00	\$ 850.00 out -	
5 Headlamp Chrome LH	1	\$ 181.00	\$ 181.00 out -	
6 Front Fender LH	1	\$ 781.00	\$ 781.00 st -	
7 Front Fender Clips LH	10	\$ 17.00	\$ 170.00 x nn.	
8 Front Fender Shield LH	1	\$ 200.00	\$ 200.00 x nn	
9 Front Fender Shield Clips LH	10	\$ 5.50	\$ 55.00 x nn	
10 Bonnet	1	\$ 1,037.00	\$ 1,037.00 RP	
11 Bonnet Hinge LH/RH	2	\$ 75.00	\$ 150.00 x nn	
12 Bonnet Lock	1	\$ 130.00	\$ 130.00 x nn	
13 VVT-I Logo	1	\$ 50.00	\$ 50.00 n	
14 Side Mirror LH	1	\$ 1,250.00	\$ 1,250.00 bus	
15 Side Mirror Cover LH	1	\$ 78.00	\$ 78.00 n	
16 Front Door LH	Repair	\$ -	\$ -	
17 Front Door Stickers LH	1	\$ 45.00	\$ 45.00 x nn.	
Discount 25%			\$ (1,413.50)	
TOTAL			\$ 4,240.50	

Discount 25%

Front Door LH chrome moulding cut ✓ 60

2. Labor Charges

1 Remove, repair and replace parts for the affected areas	\$ 1,250.00
2 Spray paint on affected areas	\$ 1,250.00 700
3 Check wiring, re-align headlamps and ensure proper functioning	\$ 80.00 30
4 Remove & reinstall 2 pieces of bumper sensors	\$ 120.00 x nn.
5 Conduct water seepage test	\$ 120.00 40
Sub Total	\$ 2,820.00

Grand Total : \$ 7,060.50 7105.50
 Add 7% GST : \$ 494.24
 Nett Total : \$ 7,554.74

No. of repair days: 7

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)


26/7/19

Tanjil 9749549
'WP'

25/7/19 @ 330 pm

sur@lkkauto.com

05 days

Resurvey before paint.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

FCIL
Total - \$4219.00
ATTN: MOTOR CLAIMS DEPT

QUOTE NO
ACCIDENT DATE 17/07/2019@1920HRS
VRN SLE1948R
MODEL Toyota Altis
TP VRN SHC2169Z

PARTS REPLACEMENT

1. Body Repair

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
1 Front Bumper	1	\$ 458.00	\$ 458.00 Rx	
2 Front Bumper Clips	10	\$ 5.50	\$ 55.00 x	
3 Front Bumper Outer Bracket LH/RH	2	\$ 82.00	\$ 164.00 LH-?, RH x	
4 Headlamp LH	1	\$ 850.00	\$ 850.00 out -	
5 Headlamp Chrome LH	1	\$ 181.00	\$ 181.00 out -	
6 Front Fender LH	1	\$ 781.00	\$ 781.00 bt -	
7 Front Fender Clips LH	10	\$ 17.00	\$ 170.00 2 suspected.	
8 Front Fender Shield LH	1	\$ 200.00	\$ 200.00 ?	
9 Front Fender Shield Clips LH	10	\$ 5.50	\$ 55.00 ?	
10 Bonnet	1	\$ 1,037.00	\$ 1,037.00 Rx	
11 Bonnet Hinge LH/RH	2	\$ 75.00	\$ 150.00 9?	
12 Bonnet Lock	1	\$ 130.00	\$ 130.00 x	
13 VVT-I Logo	1	\$ 50.00	\$ 50.00 rx ✓	
14 Side Mirror LH	1	\$ 1,250.00	\$ 1,250.00 bno ✓	
15 Side Mirror Cover LH	1	\$ 78.00	\$ 78.00 m/s ✓	
16 Front Door LH	Repair	\$ -	\$ -	
17 Front Door Stickers LH	1	\$ 45.00	\$ 45.00 x	

Discount 25%

For Door LH chrome mounting out ✓ \$60.00

\$ (1,413.50)

TOTAL

\$ 4,240.50

2. Labor Charges

1 Remove, repair and replace parts for the affected areas	\$ 1,250.00 800
2 Spray paint on affected areas	\$ 1,250.00 900
3 Check wiring, re-align headlamps and ensure proper functioning	\$ 80.00 30
4 Remove & reinstall 2 pieces of bumper sensors	\$ 120.00 x
5 Conduct water seepage test	\$ 120.00 40

Sub Total : \$ 2,820.00

Grand Total : \$ 7,060.50
Add 7% GST : \$ 494.24
Nett Total : \$ 7,554.74

No. of repair days: 7



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013109/T1vf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2169Z	Veh. Inspected	SLE 1948R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004736MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	24/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104554832	Colour	SILVER	
Odometer	287849	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	6 mm	
L/H Front Tyre	205/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/07/2019	Inspection Date	25/07/2019	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1948R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	458.00	-
10	FRONT BUMPER CLIPS @\$5.50	NOT NECESSARY	55.00	-
2	FRONT BUMPER OUTER BRACKET LH/RH @\$82.00	N/S DEFORMED O/S NOT NECESSARY	164.00	82.00
1	HEADLAMP LH	CUT	850.00	850.00
1	HEADLAMP CHROME LH	CUT	181.00	181.00
1	FRONT FENDER LH	BENT	781.00	781.00
10	FRONT FENDER CLIPS LH @\$17.00	NOT NECESSARY	170.00	-
1	FRONT FENDER SHIELD LH	NOT NECESSARY	200.00	-
10	FRONT FENDER SHIELD CLIPS LH @\$5.50	NOT NECESSARY	55.00	-
1	BONNET	TO REPAIR SEE LABOUR	1,037.00	-
2	BONNET HINGE LH/RH @\$75.00	NOT NECESSARY	150.00	-
1	BONNET LOCK	NOT NECESSARY	130.00	-
1	VVT-I LOGO	NECESSARY	50.00	50.00
1	SIDE MIRROR LH	BROKEN	1,250.00	1,250.00
1	SIDE MIRROR COVER LH	MISSING	78.00	78.00
1	FRONT DOOR LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR STICKERS LH	NOT NECESSARY	45.00	-
1	FRT DOOR LH CHROME MOULDING	CUT	60.00	60.00
	LESS 25% DISCOUNT		-1,428.50	-833.00
			4,285.50	2,499.00
LABOUR				
	REMOVE,REPAIR AND REPLACE PARTS FOR THE AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,BONNET AND FRONT DOOR LH.		1,250.00	800.00
	SPRAY PAINT ON AFFECTED AREAS.		1,250.00	900.00
	CHECK WIRING,RE-ALIGN HEADLAMPS AND ENSURE PROPER FUNCTIONING.		80.00	30.00
	REMOVE & REINSTALL 2 PIECES OF BUMPER SENSORS.	NOT NECESSARY	120.00	-

Report Ref No. CS/FCI19013109/T1vf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CONDUCT WATER SEEPAGE TEST.		120.00	40.00
			2,820.00	1,770.00
GRAND TOTAL			7,105.50	4,269.00
RECOMMENDED COST OF REPAIRS				4,269.00

Report Ref No. CS/FCI19013109/T1vf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.