

# AUTO BOLT BODY AND PAINT PTE LTD

8 Kaki Bukit Avenue 4 #03-01 Premier @ Kaki Bukit Singapore 415875

Email : autoboltsvc@singnet.com.sg

Tel : 6384 1066 Fax : 6384 1067

Reg No.: SKU 3272 X  
Model: LAND ROVER DISCOVERY

TP111

24 July 2019

Cecilia

| QTY               | DESCRIPTION                                    | AMT S\$                   |
|-------------------|------------------------------------------------|---------------------------|
| <u>List Items</u> |                                                |                           |
| 1                 | Rear taillamp -R/H <i>new</i>                  | \$ 975.00 <i>+</i>        |
| 1                 | Rear end panel <i>new</i>                      | \$ 1,170.00 <i>+</i>      |
| 1                 | Rear end panel inner garnish <i>new</i>        | \$ 295.00 <i>+</i>        |
| 1                 | Rear bumper <i>2nd</i>                         | \$ 2,845.30 <i>✓</i>      |
| 2                 | Rear bumper centre side brackets <i>new</i>    | \$ 256.00 <i>+</i>        |
| 1                 | Rear bumper reflector <i>can't d</i>           | \$ 80.00 <i>✓</i>         |
| 1                 | Rear bumper reinforcement <i>Best</i>          | \$ 990.00 <i>✓</i>        |
| 2                 | Rear bumper side retainers <i>new</i>          | \$ 176.00 <i>✓</i>        |
| 1                 | Rear bumper top step garnish <i>2nd</i>        | \$ 232.00 <i>✓</i>        |
| 2                 | Rear bumper PDC sensors <i>1 piece damaged</i> | \$ <del>476.00</del> 238. |
|                   |                                                | \$ 7,495.30               |
|                   |                                                | \$ 749.53                 |
|                   |                                                | \$ 6,745.77               |

Less 10%

4561.30

4105.17

| S/N. | Labour Charges                                                         |                             |
|------|------------------------------------------------------------------------|-----------------------------|
| 1    | To remove, replaced damaged lamps and check up rear electrical wiring. | \$ 80.00 30.                |
| 2    | To remove and refit inner garnishes.                                   | \$ <del>150.00</del> 40     |
| 3    | To remove and refit rear reverse sensor.                               | \$ <del>150.00</del> 60.    |
| 4    | To apply undercoating.                                                 | \$ 100.00 <i>+</i>          |
| 5    | Panel beating.                                                         | \$ <del>1,200.00</del> 40.  |
| 6    | To respray painting on the affected areas.                             | \$ <del>1,200.00</del> 250. |
|      |                                                                        | \$ 2,880.00                 |

Grand Total : \$ 9,625.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj  
1/s. 24/07/19.  
03 Rys

total 4885.17

h/s : 3.9K.