



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

pare Parts

ehicle No. : **SLM 8458 A**
lake & Model : **TOYOTA PRIUS**
hassis No : **JTDKB3FUX03555180**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
①	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$129.00		✓
3	Bonnet	1	\$812.40		✓
4	Bonnet lock	1	\$130.00		✓
5	Bonnet hinge LH	1	\$57.80		✓
6	Bonnet hinge RH	1	\$57.80		✓
7	Bonnet heat insulator	1	\$440.12		X
8	Bonnet heat insulator clip	10	\$35.00		X
9	Front support panel centre	1	\$338.50		✓
10	Front support panel LH	1	\$213.50		✓
11	Front support panel RH	1	\$213.50		✓
12	Headlamp panel LH	1	\$89.20		✓
13	Headlamp panel RH	1	\$89.20		✓
14	Support panel lower	1	\$387.95		✓
15	Front support panel top garnish	1	\$285.40		✓
16	Front support panel top garnish clip	10	\$35.00		✓
17	Air duct	1	\$195.40		✓
18	Air duct - inlet	1	\$109.75		✓
19	Brace panel	1	\$105.20		✓
20	Condenser	1	\$1,544.70		✓
21	Radiator	1	\$1,841.80		✓
22	Radiator fan motor RH	1	\$455.70		✓
23	Radiator fan motor LH	1	\$491.79		✓

te: If any of the quoted parts are recommended to be repaired, then an additional labour charge

I be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLM 8458 A

Make & Model : TOYOTA PRIUS

Chassis No : JTDKB3FUX03555180

Submit By : Carmen Lim

Year Manufacture : 2017

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH <i>SL</i>	1	\$197.80		<i>X</i>
25	Radiator fan blade RH <i>SL</i>	1	\$219.80		<i>X</i>
26	Radiator fan cowling <i>SL</i>	1	\$287.67		<i>X</i>
<i>S</i> 27	Headlamp LH <i>my car</i>	1	\$2,531.60		<i>✓</i>
28	Headlamp RH <i>SL</i>	1	\$2,531.60		<i>X</i>
<i>S</i> 29	Front bumper <i>BL</i>	1	\$450.80		<i>✓</i>
30	Front bumper clip <i>SL</i>	10	\$40.00		<i>✓</i>
<i>S</i> 31	Front bumper reinforcement - upper <i>BL</i>	1	\$711.50		<i>✓</i>
32	Front bumper reinforcement - lower <i>R</i>	1	\$245.30		<i>X</i>
33	Front bumper side retainer RH <i>BL SL</i>	1	\$107.20		<i>X</i>
<i>S</i> 34	Front bumper side retainer LH <i>DIY</i>	1	\$107.20		<i>✓</i>
<i>S</i> 35	Front bumper upper grille <i>CM</i>	1	\$321.90		<i>✓</i>
36	Front bumper lower grille <i>SL</i>	1	\$148.60		<i>X</i>
<i>S</i> 37	Front bumper emblem <i>SL</i>	1	\$87.10		<i>✓</i>
38	Front bumper tow cover RH <i>SL</i>	1	\$25.70		<i>X</i>
39	Front bumper tow cover LH <i>SL GAT</i>	1	\$25.70	<i>X</i>	<i>X</i>
<i>S</i> 40	Front bumper sponge - upper <i>CM</i>	1	\$89.81		<i>✓</i>
41	Front bumper sponge - lower <i>SL</i>	1	\$135.70		<i>X</i>
42	Fog lamp LH <i>SL</i>	1	\$910.70		<i>X</i>
43	Fog lamp RH <i>SL</i>	1	\$910.70		<i>X</i>
44	Engine under cover <i>SL</i>	1	\$198.30		<i>X</i>
45	Engine under cover clip <i>AN</i>	10	\$35.00		<i>X</i>
<i>S</i> 46	LH front fender <i>BL</i>	1	\$868.70		<i>✓</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLM 8458 A

TOYOTA PRIUS
 JTDKB3FUX03555180

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim
 2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	LH front fender undershield <i>Sm</i>	1	\$195.60		✓
48	LH front fender undershield clip <i>Nu</i>	10	\$25.00		X
49	LHF fender wording "HYBRID" <i>Nu</i>	1	\$44.17		✓
50	Rear windscreen moulding <i>Nu</i>	1	\$97.70		✓
51	Rear windscreen sealant <i>Nu</i>	1	\$50.00		<i>4012</i>
52	Rear number plate <i>Nu</i>	1	\$45.00	S.N	✓
53	Reverse sensor <i>Nu</i>	1	\$200.00	S.N	✓
54	Rear bumper <i>Nu</i>	1	\$497.50		✓
55	Rear bumper clip <i>Nu</i>	10	\$40.00		✓
56	Rear bumper side retainer LH <i>Nu</i>	1	\$112.70		✓
57	Rear bumper side retainer RH <i>Nu</i>	1	\$112.70		✓
58	Rear bumper reinforcement <i>Nu</i>	1	\$398.90		✓
59	Rear bumper lower garnish centre <i>Nu</i>	1	\$582.60		✓
60	Rear bumper lower garnish LH <i>Nu</i>	1	\$149.70		✓
61	Rear bumper lower garnish RH <i>Sm CAA</i>	1	\$149.70	X	X
62	Rear bumper tow cover <i>Nu</i>	1	\$31.70		✓
63	Rear bumper under cover <i>CMA</i>	1	\$355.20		✓
64	Rear bumper under cover clip <i>Nu</i>	4	\$14.00		✓
65	Tail door <i>Nu</i>	1	\$1,122.50		✓
66	Tail door lock <i>Nu</i>	1	\$487.70		✓
67	Tail door emblem <i>Nu</i>	1	\$61.70		✓
68	Wording "PRIUS" <i>Nu</i>	1	\$51.90		✓
69	Wording "HYBRID" <i>Nu</i>	1	\$55.47		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

4216.14

285 S.14

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLM 8458 A

TOYOTA PRIUS
 JTDKB3FUX03555180

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Taildoor spoiler	1	\$1,567.83		X
71	Tail end panel	1	\$596.60		✓
72	Tail end panel garnish	1	\$151.60		✓
73	Tail end panel garnish clip	10	\$35.00		✓
74	Boot weatherstrip	1	\$353.10		✓
75	Spare tyre well panel	1	\$793.15		X
76	Spare tyre board	1	\$566.79		✓
77	Spare tyre compartment sponge LH	1	\$297.67		✓
78	Spare tyre compartment sponge RH	1	\$297.67		X
79	Tail lamp LH - UPPER	1	\$498.75		✓
80	Tail lamp RH - UPPER	1	\$498.75		✓
81	Tail lamp LH - LOWER	1	\$511.60		✓
82	Tail lamp RH - LOWER	1	\$511.60		X
83	Taildoor glass	1	\$598.70		✓
84	Taildoor glass sealant	1	\$50.00		✓
85	Exhaust pipe	1	\$854.10		✓
86	Exhaust pipe mouting	1	\$38.40		✓
87	Exhaust insulator	1	\$267.40		✓
88					
89					
90					
91					
92					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLM 8458 A** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER)	\$2,600.00	1400 1800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER)	\$2,400.00	1600
3	To check wiring	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$350.00	90
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
7	To remove & refit radiator, condenser to assist work load, to top up A/C gas. <i>nn</i>	\$150.00	X
8	To remove & refit rear windscreen.	8120	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Vehicle No. : SLM 8458 A
Make & Model : TOYOTA PRIUS

Submit By : Carmen Lim
Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.