

China Fairing



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLM 8458 A

Not Authorized
1-B.1, 11 By B?

Parts	(a) Cost / List Price Items	\$	32,372.24
	Plus/Less 25%	\$	8,093.06
	Total of Cost / List	\$	24,279.18
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	290.00
Total Parts Cost		\$	24,569.18
Labour			
Total			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennedy
Company : LKK
Survey conducted on : 28/7/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 28/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLM 8458 A**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FUX03555180**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>RM</i>	1	\$45.00	S.N	✓
2	Front number plate garnish <i>CMS</i>	1	\$129.00		✓
3	Bonnet <i>Bu</i>	1	\$812.40		✓
4	Bonnet lock	1	\$130.00		?
5	Bonnet hinge LH	1	\$57.80		?
6	Bonnet hinge RH <i>LM</i>	1	\$57.80		?
7	Bonnet heat insulator <i>RM</i>	1	\$440.12		X
8	Bonnet heat insulator clip <i>RM</i>	10	\$35.00		X
9	Front support panel centre	1	\$338.50		?
10	Front support panel LH	1	\$213.50		?
11	Front support panel RH	1	\$213.50		?
12	Headlamp panel LH	1	\$89.20		?
13	Headlamp panel RH	1	\$89.20		?
14	Support panel lower	1	\$387.95		?
15	Front support panel top garnish	1	\$285.40		?
16	Front support panel top garnish clip	10	\$35.00		?
17	Air duct	1	\$195.40		?
18	Air duct - inlet	1	\$109.75		?
19	Brace panel	1	\$105.20		?
20	Condenser	1	\$1,544.70		?
21	Radiator	1	\$1,841.80		?
22	Radiator fan motor RH	1	\$455.70		?
23	Radiator fan motor LH	1	\$491.79		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLM 8458 A**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FUX03555180**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80		?
25	Radiator fan blade RH	1	\$219.80		?
26	Radiator fan cowling	1	\$287.67		?
27	Headlamp LH <i>my car</i>	1	\$2,531.60		✓
28	Headlamp RH	1	\$2,531.60		?
29	Front bumper <i>my</i>	1	\$450.80		✓
30	Front bumper clip <i>my</i>	10	\$40.00		✓
31	Front bumper reinforcement - upper	1	\$711.50		?
32	Front bumper reinforcement - lower	1	\$245.30		?
33	Front bumper side retainer RH <i>Di-5</i>	1	\$107.20		X
34	Front bumper side retainer LH <i>Di-5</i>	1	\$107.20		✓
35	Front bumper upper grille <i>CM</i>	1	\$321.90		✓
36	Front bumper lower grille	1	\$148.60		?
37	Front bumper emblem <i>my</i>	1	\$87.10		✓
38	Front bumper tow cover RH <i>my</i>	1	\$25.70		X
39	Front bumper tow cover LH <i>CM</i>	1	\$25.70		✓
40	Front bumper sponge - upper <i>CM</i>	1	\$89.81		✓
41	Front bumper sponge - lower	1	\$135.70		?
42	Fog lamp LH	1	\$910.70		?
43	Fog lamp RH	1	\$910.70		?
44	Engine under cover	1	\$198.30		?
45	Engine under cover clip	10	\$35.00		?
46	LH front fender <i>my</i>	1	\$868.70		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLM 8458 A**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKKB3FUX03555180**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	LH front fender undershield <i>Sn</i>	1	\$195.60		✓
48	LH front fender undershield clip <i>Nu</i>	10	\$25.00		X
49	LHF fender wording "HYBRID" <i>Nu</i>	1	\$44.17		✓
50	Rear windscreen moulding <i>Nu</i>	1	\$97.70		✓
51	Rear windscreen sealant <i>Nu</i>	1	\$50.00		<i>Goia</i>
52	Rear number plate <i>Nu</i>	1	\$45.00	S.N	✓
53	Reverse sensor <i>Nu</i>	1	\$200.00	S.N	✓
54	Rear bumper <i>Nu</i>	1	\$497.50		✓
55	Rear bumper clip <i>Nu</i>	10	\$40.00		✓
56	Rear bumper side retainer LH <i>Nu</i>	1	\$112.70		✓
57	Rear bumper side retainer RH <i>Nu</i>	1	\$112.70		✓
58	Rear bumper reinforcement <i>Nu</i>	1	\$398.90		✓
59	Rear bumper lower garnish centre <i>Nu</i>	1	\$582.60		✓
60	Rear bumper lower garnish LH <i>Nu</i>	1	\$149.70		✓
61	Rear bumper lower garnish RH <i>Nu</i>	1	\$149.70		✓
62	Rear bumper tow cover <i>Nu</i>	1	\$31.70		✓
63	Rear bumper under cover <i>Nu</i>	1	\$355.20		✓
64	Rear bumper under cover clip <i>Nu</i>	4	\$14.00		✓
65	Tail door <i>Nu</i>	1	\$1,122.50		✓
66	Tail door lock <i>Nu</i>	1	\$487.70		✓
67	Tail door emblem <i>Nu</i>	1	\$61.70		✓
68	Wording "PRIUS" <i>Nu</i>	1	\$51.90		✓
69	Wording "HYBRID" <i>Nu</i>	1	\$55.47		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLM 8458 A**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FUX03555180**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Taildoor spoiler	1	\$1,567.83		?
71	Tail end panel	1	\$596.60		✓
72	Tail end panel garnish	1	\$151.60		✓
73	Tail end panel garnish clip	10	\$35.00		✓
74	Boot weatherstrip	1	\$353.10		✓
75	Spare tyre well panel	1	\$793.15		?
76	Spare tyre board	1	\$566.79		✓
77	Spare tyre compartment sponge LH	1	\$297.67		✓
78	Spare tyre compartment sponge RH	1	\$297.67		?
79	Tail lamp LH - UPPER	1	\$498.75		✓
80	Tail lamp RH - UPPER	1	\$498.75		✓
81	Tail lamp LH - LOWER	1	\$511.60		✓
82	Tail lamp RH - LOWER	1	\$511.60		?
83	Taildoor glass	1	\$598.70		✓
84	Taildoor glass sealant	1	\$50.00		Posn
85	Exhaust pipe	1	\$854.10		?
86	Exhaust pipe mouting	1	\$38.40		?
87	Exhaust insulator	1	\$267.40		?
88					
89					
90					
91					
92					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLM 8458 A** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER)	\$2,600.00	1100-1400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER, FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER)	\$2,400.00	1600
3	To check wiring	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$350.00	90
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
7	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	?
8	To remove & refit rear windscreen.	8170	✓

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SLM 8458 A**

Submit By : Carmen Lim

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.