

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559/W. GST Reg. No. M2-0020081-X



Final Report

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00	0	451.00
To replace rear silencer with exhaust flap, chrome pipe, clamping bushes and heat insulations etc including to align system and check for leak.	451.00	0	451.00
To replace front exhaust intermediate pipe and support etc including to align exhaust system and conduct checks for leak.	451.00	0	451.00
To replac front end wiring cables including performe and conduct checks for proper function	451.00	0	451.00
Sundries.	150.00	0	150.00
# To replace both front seat crash-active head restraint repair kit including to reset and conduct checks for proper function	451.00	0	451.00
# To replace front left fender	425.00	0	425.00
# To respray front left fender and left roof frame	752.00	0	752.00
# To carry out body cavity preservation.	100.00	0	100.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# ADJUSTABLE BLIND RIVET	3.15	2	0	6.30
# EXPANDING NUT	2.75	2	0	5.50
# BLIND RIVET	1.25	2	0	2.50
# BLIND RIVET	1.25	2	0	2.50
# FASTENING ELEMENTS	11.00	1	0	11.00
RADIATOR	1,032.65	1	0	1,032.65
CLAMPING BUSH	66.80	1	0	66.80
CLAMPING BUSH	66.80	1	0	66.80
LH TAILPIPE TRIM CHROME	185.45	1	0	185.45
# REAR SILENCER BRACKET FRT	57.20	1	0	57.20
SWING SUPPORT	42.90	1	0	42.90
INTERMEDIATE PIPE	577.50	1	0	577.50
REAR SILENCER W/EXHAUST FLAP	2,211.30	1	0	2,211.30
COMPLETE TAIL TRIM	833.60	1	0	833.60
ALUMINIUM ENGINE HOOD	2,371.75	1	0	2,371.75
TAILGATE ALUMINIUM	1,741.00	1	0	1,741.00
# FRT LH SIDE PANEL ALUMINIUM	933.30	1	0	933.30
FRT BUMPER CARRIER	723.05	1	0	723.05
# LH BUMPER GUIDE	16.15	1	0	16.15
FRT BUMPER TOP IMPACT ABSORBER (M)	62.05	1	0	62.05
FRT BUMPER BOTTOM IMPACT ABSORBER (	33.50	1	0	33.50
FRT BUMPER PANEL PRIMED (M)	1,618.50	1	0	1,618.50
REAR BUMPER CARRIER	857.75	1	0	857.75
EXHAUST SUPPORT	108.65	1	0	108.65
REAR BUMPER COVER (M)	268.30	1	0	268.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52098**
Date Estimated : **24/07/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Goh Pui Kiat
22 Newton Road
#15-08

Singapore 307990

- ACCOUNT -

135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV8088H	G459799	31/03/2017	540iA	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
# To replace both front seat crash-active head restraint repair kit including to reset and conduct checks for proper function	451.00	0	451.00
# To replace front left fender	425.00	0	425.00
# To respray front left fender and left roof frame	752.00	0	752.00
# To carry out body cavity preservation.	100.00	0	100.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# ADJUSTABLE BLIND RIVET	3.15	2	0	6.30 <i>net</i>
# EXPANDING NUT	2.75	2	0	5.50 <i>net</i>
# BLIND RIVET	1.25	2	0	2.50 <i>net</i>
# BLIND RIVET	1.25	2	0	2.50 <i>net</i>
# FASTENING ELEMENTS	11.00	1	0	11.00 <i>net</i>
# REAR SILENCER BRACKET FRT	57.20	1	0	57.20 <i>bt</i>
# FRT LH SIDE PANEL ALUMINIUM	933.30	1	0	933.30 <i>bt</i>
# LH BUMPER GUIDE	16.15	1	0	16.15 <i>de</i>
# ADJUSTMENT ELEMENT	6.05	2	0	12.10 <i>dis</i>
# BREAKTHROUGH BUFFER	8.35	1	0	8.35 <i>de</i>
# RIVET	0.45	6	0	2.70 <i>net</i>
# LOCK TOP PART	72.05	1	0	72.05 <i>bt</i>
# LOCK TOP PART	72.05	1	0	72.05 <i>bt</i>
# EXPANDING RIVET D=8MM	1.05	5	0	5.25 <i>net</i>
# REAR SILENCER RH HEAT INSULATION	165.70	1	0	165.70 <i>bt</i>
# CLIP	0.80	5	0	4.00 <i>net</i>
# CONNECTION REAR TOP	147.55	1	0	147.55 <i>bt</i>
# FRT ENGINE BONNET SEAL	33.70	1	0	33.70 <i>net</i>
# UPPER LH ENGINE COMPARTMENT COVER	35.80	1	0	35.80 <i>de</i>
# (DG) REPAIR KIT CRASH ACTIVE HEAD R	163.80	2	0	327.60 <i>act</i>
# PLUG BLACK D=5MM	0.90	10	0	9.00 <i>net</i>
# REP. CABLE ITS HEAD AIRBAG & CTRL U	59.75	1	0	59.75 <i>dis</i>
# SENSOR WIRE FOR SMART OPENER BOTTOM	41.50	1	0	41.50 <i>dis</i>
# REGISTRATION PLATE LAMP	20.00	1	0	20.00 <i>ora</i>
# EXTERNAL AERIAL COMFORT ACCESS	96.35	1	0	96.35 <i>dis</i>
# BLIND RIVET AVIBVLB	0.55	40	0	22.00 <i>net</i>
# SCREW (SF PLUS M5X15)	0.55	5	0	2.75 <i>net</i>

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

# (DG/SL) BODY ADHESIVE K5B (195ML)	326.80	1	0	326.80	all
# PUNCH RIVET N4	0.55	20	0	11.00	all
# (DG) CLEANER R1 (100ML)	26.15	1	0	26.15	all
# (S/L) SEAM SEAL 300ML	33.80	1	0	33.80	all
# (S/L) ANTI FREEZE 1.5 LITRES	20.10	2	0	40.20	all

#

#

SUPPLEMENTARY ITEMS

Total Labour :	1,728.00
Total Parts :	2,610.60
Total Repair Costs less Excess:	4,338.60