



# Exceptional Journeys

Surveyor : Rasul - LKK  
Company : India  
DOA : 23/07/2019  
CSE : Don  
Date of Survey : 13/08/2019

VEHICLE NO : SMJ6014P

MODEL : KIA/ CERATO 1.6 A EX G333

WIP : 54736

Material	:	\$	197.00
Labour	:	\$	1,310.00
Sub-Total	:	\$	1,507.00
Less Excess	:	\$	-
Total	:	\$	1,507.00
GST 7%	:	\$	105.49
Grand Total	:	\$	1,612.49
Finalise By/Date	:	JoJo dtd	27/08/2019

Email :

☒ REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS +        Days ( 1 ) Weekends  
+        Days (        ) Public Holiday  
+ 1 Survey - 13/08/2019 - Tue  
TOTAL DAYS REPAIR TOOK = 4

☒ TP Claim India - SHA4703D

☐ Claim GIA / LTA fee       

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others       

☐ Third Party Report



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NG KAI LI (HUANG KAILI)	Cust No/Name LCV08863/NG KAI LI (HUANG KAILI)
BLK 421 JURONG WEST STREET 42	Reg No/Reg Date SMJ6014P / 13/03/2019
#07-1043	Date In/Mileage 14/08/2019/ 4929
SINGAPORE 640421	Chassis/Package KNAF3416MK5031135 /KC17P
Contact No *Mobile: 91124673	Engine No G4FGJH722210
14/08/	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00081	Cash	27/08/2019/ 19:40	TLD	881 / Jojo Cheng	54736	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW DAMAGED PARTS ON REAR BUMPER FACE						550.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST						80.00
E PNT98000 RESPRAY ON REAR BUMPER AND AFFECTED PORTION						420.00
A 54900099 CHECK ELECTRICAL AND CHASSIS ELECTRICAL SYSTEM						40.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST						200.00
USING HI-SCAN PRO TEST						
M SUNDRY SUNDRIES						20.00
X COVER-RR BUMPER LWR						
Z TEXT			1.00	197.00	00.00	197.00
INDIA TP CLAIM SHA4703D						
DOA: 23/07/2019						
SURVEYOR: RASUL LKK 13/08/2019						
<p>Cycle &amp; Carriage celebrates 120 years. Visit <a href="http://www.cyclecarriage.com/120">www.cyclecarriage.com/120</a> for more info!</p>						
Parts	197.00					
Labour	1,290.00					
Standard Menu	0.00			7% GST on	1507.00	1,507.00
Specialist Job	0.00					105.49
Diagnostics Job	0.00					
Sundry/Others	20.00					
Total(w/o GST)	1,507.00				Total Payable	1,612.49

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
NG KAI LI (HUANG KAILI)	Cust No/Name LCV08863/NG KAI LI (HUANG KAILI)
BLK 421 JURONG WEST STREET 42	Reg No/Reg Date SMJ6014P / 13/03/201
#07-1043	Date In/Mileage / 0
SINGAPORE 640421	Chassis No KNAF3416MK5031135
Contact No Mobile: 91124673	Engine No G4FGJH722210
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	24/07/2019/ 15:47		247 / DonBong	54736
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REPAIR REAR END PANEL				1650.00
E PNT88000	REMOVE AND INSTALL PARKING ASSIST				80.00
E PNT88000	REMOVE AND INSTALL REAR CABIN, SIDE TRIM TO FACILITATE REPAIR WORK				275.00
E PNT98000	PAINT WORK RESPRAY ON REAR END PANEL, REAR BUMPER AND AFFECTED PORTION				1280.00
M SUNDRY	PERFORM RUST PREVENTION				80.00
M SUNDRY	SUPPLY PARKING SENSOR				220.00
A 54900099	CHECK ELECTRICAL AND CHASSIS ELECTRICAL SYSTEM				40.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY	SUNDRIES				50.00
M BRACKET ASSY-RR BPR SIDE UPR,L		1.00	25.00	00.00	25.00
M BRACKET-ASSY RR BPR SIDE UPR,R		1.00	31.00	00.00	31.00
M COVER-RR BUMPER UNDER,RH		1.00	33.00	00.00	33.00
M STAY-RR BUMPER LH		1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH		1.00	65.00	00.00	65.00
M ANTENNA ASSY-SMARTKEY		1.00	46.00	00.00	46.00
M BEAM-RR BUMPER		1.00	318.00	00.00	318.00
M BRACKET-RR BEAM UPR MTG,LH		1.00	9.00	00.00	9.00
M BRACKET-RR BEAM UPR MTG,RH		1.00	9.00	00.00	9.00
M BRACKET-RR BEAM LWR,CTR		1.00	6.00	00.00	6.00
M BRACKET-RR BEAM LWR MTG		2.00	6.00	00.00	12.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG KAI LI (HUANG KAILI)  BLK 421 JURONG WEST STREET 42 #07-1043 SINGAPORE 640421  Contact No Mobile: 91124673	Cust No/Name	LCV08863/NG KAI LI (HUANG KAILI)
	Reg No/Reg Date	SMJ6014P / 13/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5031135
	Engine No	G4FGJH722210
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	24/07/2019/ 15:47		247 / DonBong	54736		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	EXTN WIRING ASSY-BWS	X	} 8svc	1.00	207.00	00.00	207.00
M	LAMP ASSY-SIDE T/SIGNAL,LH	X		1.00	181.00	00.00	181.00
M	LAMP ASSY-SIDE T/SIGNAL,RH	X		1.00	181.00	00.00	181.00
M	COVER-RR BUMPER FOG LAMP,LH	X		1.00	19.00	00.00	19.00
M	COVER-RR BUMPER FOG LAMP,RH	X		1.00	19.00	00.00	19.00
M	CLIP	X		10.00	1.00	00.00	10.00
M	GROMMET ASSY-SCREW	X		2.00	2.00	00.00	4.00
M	COVER-RR BUMPER	repair		1.00	688.00	00.00	688.00
M	COVER-RR BUMPER LWR	ent		1.00	197.00	00.00	197.00
M	COVER-RR BUMPER UNDER,LH	X 8svc		1.00	33.00	00.00	33.00

# Estimate

SURVEYOR NAME: Rajan - 4p 90010068SURVEYOR SIGNATURE: [Signature]DATE: 13/08/19 @ 1400REMARKS: 3 days

Revy before repair  
after repair

Confirm &amp; accepted by

	Nett	6,013.00
7% GST on	6013.00	420.91
Total Payable		6,433.91

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.