

H1

ADVANCE AUTO GARAGE

23 Kaki Bukit Avenue 4
VICOM KAKI BUKIT INSPECTION CENTRE
#04-01 SINGAPORE 415933
Tel: +65 9007 9247
Email: advanceag@hotmail.com
Reg No: 53395571L

TO	: EQ INSURANCE COMPANY LTD	DATE	: 23/07/2019
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<i>Xiao Tony</i>			
VEHICLE DETAILS			
VEHICLE NO	: SLT1978A		
VEHICLE MODEL	: BMW 116D		
CHASSIS NO	:		
ACCIDENT DETAILS	DATE : 23/07/2019		
	TIME : 1120HRS		
THIRD PARTY REQUESTOR / CONTACT	:	XAIVER	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER TOW HOOK COVER <i>Detd</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER BEAM <i>only</i>	1	\$ 450.00	\$ 450.00 <i>200</i>
3	REAR BUMPER REINFORCEMENT BAR <i>Best</i>	1	\$ 715.00	\$ 715.00
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 130.00	\$ 260.00
5	REAR BUMPER REFLECTOR <i>Fit on Ld</i>	2	\$ 150.00	\$ 300.00 <i>150</i>
6	REVERSE SENSOR HOLDER (SET) <i>new</i>	1	\$ 70.00	\$ 70.00 <i>30</i>
7	REAR OUTER TAIL LAMP <i>the new</i>	2	\$ 555.00	\$ 1,110.00
8	REVERSE SENSOR <i>2 piece dngd</i>	2	\$ 290.00	\$ 580.00
9	REAR END PANEL <i>Reps</i>	1	\$ 1,030.00	\$ 1,030.00
10	REAR END PANEL TOP GARNISH <i>Not in</i>	1	\$ 320.00	\$ 320.00
11	REAR EXHAUST MUFFLER <i>Reps</i>	1	\$ 1,250.00	\$ 1,250.00
12	REAR REMOTE ANTENA <i>dngd</i>	1	\$ 120.00	\$ 120.00
13	REAR REMOTE ANTENA BRACKET <i>the new</i>	1	\$ 80.00	\$ 80.00
14	REAR EXHAUST PIPE HEAT SHIELD <i>the new</i>	1	\$ 320.00	\$ 320.00

2135
2028.25

TOTAL PRICE: \$ 6,685.00
LESS 5% \$ 334.25
SUB TOTAL PRICE: \$ 6,350.75

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00

2	REAR BUMPER (MSPORT KIT) <i>Dislike</i>	1	\$ 1,500.00	\$ 1,500.00	1300
3	REAR BUMPER DIFFUSER (MSPORT) <i>Dislike</i>	1	\$ 1,200.00	\$ 1,200.00	900.
4	REAR BUMPER CLIP (SET) <i>me</i>	1	\$ 30.00	\$ 30.00	-
5	REAR EXHAUST PIPE TIP (REMUS) <i>Best</i>	2	\$ 350.00	\$ 700.00	400.
6	REAR END PANEL INSULATION SEAL <i>Me New</i>	1	\$ 120.00	\$ 120.00	+
7	REAR BUMPER REVERSE CAMERA <i>Band</i>	1	\$ 750.00	\$ 750.00	550
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Not in</i>	1	\$ 30.00	\$ 30.00	+
			TOTAL :	\$ 4,380.00	

3230

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	400.	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	500.	
3	LABOUR TO REMOVE AND REFIT REAR EXHAUST MUFFLER	\$ 300.00	x.	
4	WIRING CHECK	\$ 100.00	30	
5	TUFF COAT	\$ 120.00	x	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	60.	
7	LABOUR TO CODE REVERSE CAMERA TO ADAPT TO MODULE TO LINK TO IDRIVE	\$ 300.00	60.	
8	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATIONS	\$ 300.00	100.	

1150

TOTAL: \$ 3,620.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 10,730.75

TOTAL LABOUR COST: \$ 3,620.00

TOTAL REPAIR COST: \$ 14,350.75

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX:

Adrian King
1/s 24/07/19.

03 Days.

total: 6408.25
1/s: 5.1K.