

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 3808S

DATE : 24.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FWS.

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>1st</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>Nuc</i>			\$ 96.50	✓
	Boot Lid Lock Upper <i>NH</i>			\$ 102.60	X
	Boot Lid Lock Lower <i>NH</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>Nuc</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>Nuc</i>			\$ 27.90	✓
	Boot Lid Lamp (LH) <i>mostly broken</i>			\$ 565.60	✓
	Boot Lid Trimboard <i>NH</i>			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00	X
	Bootlid Moulding <i>NH</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>NH</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>NH</i>			\$ 227.90	X
	Rear Bumper <i>broken</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>Crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>NH</i>	\$	80.30	\$ 160.60	X
	Rear Bumper Clip 10 pcs <i>Nuc</i>			\$ 22.00	✓
	Rear Bumper Bracket, LH <i>broken</i>			\$ 35.60	✓
	Rear Bumper Sponge <i>NF</i>			\$ 118.40	X
	Rear Bumper Under Cover <i>distorted / cut</i>			\$ 228.00	✓
	Tail Lamp (LH) <i>Crack</i>			\$ 697.80	✓
	Tail Lamp Quarter Panel (LH) <i>Distorted</i>			\$ 226.50	✓
	Rear Panel <i>Distorted</i>			\$ 526.70	✓
	Rear Panel Garnish <i>NH</i>			\$ 57.70	X
	Rear Panel Lower Panel <i>Distorted</i>			\$ 495.50	✓
	Spare Tyre Holder <i>NH</i>			\$ 223.10	X
	Spare Tyre Panel <i>Distorted</i>			\$ 852.80	✓
	Spare Tyre Panel Cushion <i>NH</i>			\$ 209.05	X
	Rear Towing Hook <i>NH</i>			\$ 94.60	X
	Exhaust Pipe Insulator <i>NH</i>	\$	58.55	\$ 117.10	X
	Exhaust Silencer <i>N/S Distorted O/S NH</i>	\$	967.70	\$ 1,935.40	✓
	Exhaust Pipe Hanger <i>NH</i>	\$	58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>NH</i>			\$ 730.10	X
	Rear Fender With Housing (LH) <i>Distorted</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) <i>NH</i>			\$ 169.30	X
	Rear Fender Air-Duct <i>distorted</i>			\$ 51.60	✓
	Rear Fender Trim Board (LH) <i>NH</i>			\$ 188.75	X
	Rear Windscreen Moulding <i>Nuc</i>			\$ 28.30	✓
	Rear Tyre Rim (RH) <i>1st</i>			\$ 325.30	✓
	Rear Wheel Hub-Cap (RH) <i>1st</i>			\$ 107.10	✓
	Rear Wheelbearing IN & Hub <i>1st</i>			\$ 362.00	✓
	Rear Trailing Arm (RH) <i>1st</i>			\$ 192.00	✓
	Rear Assist (RH) <i>1st</i>			\$ 145.70	✓
	Rear Shock Absorber (RH) <i>1st</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (RH) <i>NH</i>			\$ 81.30	X
	Rear Crossmember <i>NH</i>			\$ 1,021.50	X
	Stabilizer Bar <i>NH</i>			\$ 199.60	X
	Stabilizer Link <i>NH</i>			\$ 85.90	X

SHA 3808S

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Upper Arm (RH) <i>chassis</i>			\$ 335.75	<i>✓</i>
	Rear Lower Arm (RH) <i>chassis</i>			\$ 353.80	<i>✓</i>
	Rear Knuckle Arm (RH) <i>chassis</i>			\$ 545.60	<i>✓</i>