

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

GREEN FOREST LANDSCAPE PTE LTD
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

TP China.
Jale.

24th July 2019

Accident date: 22nd JULY 2019

Estimated repair cost for vehicle no: SJS8617A Toyota Wish 1.8A '09 (COE 2029)

S/n	Qty	Items	U/price	Amount
1	1	Rear tail lamp-LH		\$640.10 X
2	2	Rear tail lamp clips	\$12.90	\$25.80 X
3	1	Rear Bumper		\$1,377.00 566.10
4	1	Rear Bumper Side Bracket		\$55.60
5	1	Rear Bumper reverse sensor		\$300.00 X
6	4	Rear bumper clips	\$5.00	\$20.00
7	1	Rear fender LH		\$979.55 X
8	1	Rear fender inner trim board-LH		\$870.00 X
9	1	rear fender mud -shiled -LH		\$68.10 X
10	2	rear fender mud shiled clips	\$12.90	\$25.80 X
11	1	Rear door		\$1,150.00
12	1	rear door inner rubber -LH		\$115.20 X
13	1	Rear door lower hinges		\$158.20 X
14	1	Rear shock absorber-LH		\$332.40 X
15	1	rear wheel bearing		\$180.00 X
16	1	rear Axle		\$2,000.00 X
17	1	Rear tire-LH		\$300.00 X
18	1	Rim-LH		\$400.00

2191.70

Subtotal :-

\$8,997.75

labour charges

1643.77

To remove & re-fix cushion

\$100.00 50

To remove & re-fix rear door -LH Fittings.

\$200.00 80

To remove & re-fix LH rear undercarriage with axle

\$380.00 X

To remove & re-fix fender side glass

\$120.00 X

Gum

\$50.00 X

To check wheel alignment computer

1290 \$120.00 80

To Check Wiring System

\$60.00 30

Tuff kote

\$100.00 50

Towing charges

\$100.00 X

Panel beating

\$1,000.00 400

Spray painting

\$1,000.00 600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer

Subtotal :-

\$3,230.00

Total :-

\$12,227.75