



Date of Accident : 11 July 2019

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
**GST Regn. No. : M2-8922054-2**

1 Defu Lane 6 Singapore  
 Tel : 68585151 ( 24 Hours )  
 GST Regn. No. : M2-8

Confirmed on 25/07/19  
 P/P 1000/-  
 3dr.  
 2dr.

2R - Honda Civic 1.6L VTI Auto

Date : 24 July 2019

Estimate To Repair SJJ9472R - Honda Civic 1.6L VTI Auto  
Chassis No : JHMFD46208S202257

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	o/s rear door	\$ 776.80
02	1 pc	o/s rear door chrome moulding	\$ 101.80
03	1 pc	rear bumper	\$ 638.00
04	4 ps	rear bumper clips holders @ \$3.80	\$ 15.20
05	1 pc	o/s rear bumper side retainer	\$ 14.60
06	10 pc	rear bumper faster clips @ \$3.80	\$ 38.00
07	1 pc	o/s rear fender	\$ 741.50
08	1 pc	o/s rear fender inner trim	\$ 145.90
09	6 pc	rear fender inner trim clips @ \$4.00	\$ 24.00
			\$ 2,495.80
		Less 20 %	\$ 499.16
			\$ 1,996.64
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		To transfer of door fittings and perform water seepage test.	\$ 150.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00
04		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 1,930.00
		Total	\$ 3,926.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
Signature:  
Date: