



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SLG6338H

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **35396**
Reg No/Reg Date **SLG6338H / 26/09/2016**
Date In/Mileage **30/07/2019 / 28871**
Chassis No **WDD2462422401154**
Engine No **27091030972701**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **027 787 Mountain Gr/ 041 111 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	26/08/2019/ 16:21	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

M. BPN SUN
POLICY NO/ACC DATE : 200483003 // 24-07-2019
DRIVE IN: 24-07-2019 // TP CAR NO: SHA911E (FIRST CAPITAL INSURANCE)
DATE IN/DATE SURVEY: 30-07-2019 // LKK RASUL
BY/AUTHORIZED ON : SITHARA // 25-07-2019

X	PLUG	2.00	6.63	00.00	13.26
X	CABLE STRAP HOLDER	1.00	2.51	00.00	2.51
X	PLUG	4.00	3.80	00.00	15.20
X	LH/R GASKET F LIGHT HOUSING	1.00	24.70	00.00	24.70
X	RH/R GASKET F LIGHT HOUSING	1.00	24.70	00.00	24.70

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **80.37** **5.63**
Nett 80.37
Total Payable 86.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany