



Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

25 JUL 2019

ESTIMATE

Page/No. : 1 of 4

Estimate No. : b1 52069
Date Estimated : 22/07/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -
Lee Mei Ling (Li Meiling)
22 Penshurst Place

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 556438

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL6648Z	DZ36040	07/10/2016	5281A00	0

DESCRIPTION

Replacing rear bumper panel

Spray rear bumper

To check electrical wiring systems at the front section
for proper function including adjustments of headlights

Sundries

5281A00 Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	VALUE
850	1,275.00
934	1,038.00
150	177.00
net	80.00

Total Labour 1: 2,570.00

DESCRIPTION

MOUNT REAR RH
REAR CENTER GUIDE
COVER BUMPER REAR
REAR BUMPER PANEL PRIMED (PDC)
BUMPER PDC SENSOR (300 ALPINWEISS)

QTY	PRIC	VALUE
1	192.15	192.15
1	72.20	72.20
1	134.85	134.85
1	1,603.45	1,603.45
1	368.80	368.80

Total Parts : 2,371.45

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 118199999 Claim No.

Date & Time 11/8/2019 Excess S\$

Surveyor's Name Tanpin Sign

Surveyor's Tel 97485749 Authorised Yes/No

Authorised Date 'up' Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No FML Yes/No

Surveyor's E-mail tanpin@chartis.com

No. of Working Days Recommend 03 days

Labour 1	:	2,570.00
Parts	:	2,371.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	345.90
Grand Total	:	5,287.35



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : b1 52069
Date Estimated : 22/07/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -
Lee Mei Ling (Li Meiling)
22 Penshurst Place

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 556438

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL6648Z	WBASZ62050DZ36040	07/10/2016	528iA GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To made good rear bumper , replace bumper carrier and cover including remove and install body parts in order to carry out painting job.	850.00	0.00	850.00 ✓
To respray rear bumper.	934.00	0.00	934.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0.00	150.00 ✓
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER	857.75	1.00	0.00	857.75 ✓
# REAR BUMPER COVER (M)	267.25	1.00	0.00	267.25 ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,125.00
Total Labour & Parts :	3,139.00
Deduction for Excess :	
Total Repair Costs less Excess:	3,139.00
GST @7%:	219.73
Grand Total :	3,358.73

LOSS OF USE=\$100 X 3 DAYS
LTA SEARCH FEE=\$7.45.

DD	DD PARTY	DATE	WORKING DAYS
FAX TO FAX NO	Tanfakh	11/10/19	3
FAX TO FAX NO	Ukr		
FAX TO FAX NO			
FAX TO FAX NO			
FAX TO FAX NO			
FAX TO FAX NO			
FAX TO FAX NO			
FAX TO FAX NO			
FAX TO FAX NO			

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : b1 52069
Date Estimated : 22/07/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -
Lee Mei Ling (Li Meiling)
22 Penshurst Place

Singapore 556438

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL6648Z	WBASZ62050DZ36040	07/10/2016	528iA GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# REAR BUMPER CARRIER	857.75	1.00	0.00	857.75 <i>bt</i>
# REAR BUMPER COVER (M)	267.25	1.00	0.00	267.25 <i>de</i>

SUPPLEMENTARY ITEMS

Total Labour :
Total Parts : 1,125.00
Total Labour & Parts : 1,125.00
Deduction for Excess :