

ASS. REC. BY:

SPK

REF:

NS/INC19013169/Est352

ASSIGNMENT

From:

Date:

25/7/19

Veh No:

SHC 42334

Yr Regn:

9/4/14

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SHC 42334

Make:

Toyota Mus

C.C.

1798

at Workshop m/s

SMRT

Colour:

Maroon

A/C:

Insured / Std / NI / NA

of

Woodlands Depot

Sp Reading

526617

T/Radio:

Insured / Std / NI / NA

Insured:

SJP3607C

Eng/No:

Policy No.

5108056430 8/3/19-19/5/20

C/No:

JTD KN 364805740775

Claims No.

MT/1054575-002

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

41

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fima2a

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

days

Res.:

Yes or No

D.O.A.

22/7/19

D.O.I.

25/7/19

Lum Sum:

%

3 Val:

Yes or No

Survey held at

SMRT

CA / REV / REP. / 24 HRS

apd

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/8/19

Finalize Claim \$3000, 6 repn days -
C\$ 5,968.18 Red - 67% >

07/19/2019

SJP 3697C

RECEIVED 19 AUG 2019

16/8/2019

Date/Time, File Page to?

19/08/19



Prel. Report



Final Report

1) Typ:4

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

3 + P8 \$

Photos

Other:

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Wheel end (\$

Report Form:

Long Sum / L.B. 3,000/- L/S

TP Claims against NTUC Income: Follow-Through Survey

Date : 16/08/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1035664-002	SMRT TAXIS PTE LTD	SHB 63M	SKW 1461U	13/03/2019	\$ 11,100.66	\$ 2,650.00
2	MT/1054579-002	SMRT TAXIS PTE LTD	SHC 4233H	SJP 3607C	22/07/2019	\$ 8,968.18	\$ 3,000.00
3	MT/1057600-002	COMFORT TRANSPORTATION PTE LTD	SHC 3085A	GBH 1832T	08/08/2019	\$ 8,727.84	\$ 4,450.00
4	MT/1056745-002	CITYCAB PTE LTD	SHB 3063T	PC 6827L	04/08/2019	\$ 1,863.68	\$ 1,157.68

Claim received from LKK Auto

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="22/07/2019 09:39"/>
Vehicle No.(For Motor)	<input type="text" value="SJP3607C"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5108056430		CARZONRENT PTE LTD	201605659R	GPC	drivo CLASSIC	SJP3607C	SJP3607C	08/03/2019	19/03/2020

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 16 August 2019 8:55 AM
To: Steve Chen (LKK Auto)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SHB63M Finalize

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Thursday, 15 August 2019 7:20 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Shirley Hiew (LKK Auto)
Subject: SHB63M Finalize

Dear Poh Suan,

We confirm the finalize \$2650 (L/S, before GST). 4 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/07/2019 09:58
Date Of Accident 22/07/2019 18:45
Exact Location Of Accident MARTIN ROAD JUNCTION RODYK STREET
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC4233H
Insured/Policyholder
Name Of Registered Owner SMRT TAXIS PTE LTD
Co Reg No 198905369K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-80000000
Vehicle Particulars
Manufacturer TOYOTA
Model PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-19093197MFSH
Cover Note Number
Driver
Name of Driver GOON TUCK KAY ALAIN
NRIC No S7007477Z
Date Of Birth 04/02/1970
Occupation OUTDOOR
Date Of Driving Pass 18/08/1994
Driving Experience 24 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-80000000
Fax Number
Contact Number
Email Address NOEMAIL

Address	80
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG MARTIN ROAD AT THE LEFT LANE WITH A PASSENGER ON BOARD WHEN THE VEHICLE SJP3607C SUDDENLY DASHED OUT FROM RODYK STREET AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP3607C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	WILSON LEE LIANG WEE
NRIC/Passport Number	S7638848B
Contact Number	
Address	
Postcode	


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

ARNASALAM CHETTY RD



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

369K

Vehicle Details

Vehicle No.:

SHC4233H

Vehicle to be Exported:

No

Intended Deregistration Date:

25 Jul 2019

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS TAXI (SMRT)

Primary Colour:

Maroon

Manufacturing Year:

2014

Engine No.:

2ZR5979270

Chassis No.:

JTDKN36U805740775

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$33,120.00

Original Registration Date:

09 Apr 2014

First Registration Date:

09 Apr 2014

Transfer Count:

0

Actual ARF Paid:

\$8,368.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

08 Apr 2022

PARF Rebate Amount:

\$5,857.00

Intended COE Rebate Details

COE Expiry Date:

08 Apr 2022

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$59,871.00

COE Rebate Amount:

\$20,244.00

Total Rebate Amount:

\$26,101.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Jul 2019

OK

Case Details

Case Reference Number : TAX/07/19/2084
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4233H

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7779-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income
 Insurance Co-operative Ltd
 Accident Date and Time : 22/07/2019 10:45 AM
 Vehicle Age(In Months) : 63

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval				Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓	BR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓	MC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓	MC
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓	BR
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Givr	✗	NAI
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Givr	✗	NAI
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	✓	X R
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓	MC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓	MC
One Time Key In	Main		6505527	QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	0	0	Not Givr	✗	NAI
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Givr	✗	NAI
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Not Givr	✗	NAI

Total Spare Part Cost 4,725.42

Surveyor Total 1,292.41

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TYRE	1	126.74	126.74	25.00	95.05	Replace	0	0	Not Giv	X NM
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	X NM
One Time Key In	Main		6505487	DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace	/ DO
One Time Key In	Main		6505607	MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair	X R
One Time Key In	Main		6505349	WHEEL HUB REAR	1	489.40	489.40	25.00	367.05	Replace	0	0	Check	X NM

Total Spare Part Cost 4,725.42

Surveyor Total 1,292.41

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,780.34

Final Sur Total 1,033.93

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	1,014.00	900	
Total:			1,014.00	900.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
2	Main	TO RESPRAY REAR FENDER LH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	50	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	150	
5	Main	TO RESPRAY REAR DOOR LH	378.00	200	
Total:			1,494.00	800.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	nc
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	nc

			Recommendation(\$)	Adjustment(\$)	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	593.76	593.76	APC
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	nn SN
6	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	APC
7	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	APC
8	Main	TO REMOVE / REFIT SEAT	120.00	0	
9	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	APC
10	Main	TO REMOVE AND REFIT TYRE	120.00	20	APC
11	Main	TO WASH AND VACUUM	60.00	0	
12	Main	TO REPLACE SUNDRY PARTS	100.00	30	APC
Total:			1,734.76	783.76	

10371.50x

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,780.34	1,033.93
Total Labour Cost	1,014.00	900.00
Total Spray Painting	1,494.00	800.00
Other	1,734.76	783.76
Overall Total	8,023.10	3,517.69
Lump Sum Repair Option		
Lump Sum Total	8,000.00	3,500.00
Surveyor Approved Amount		3,500.00
No of Repair Days*	7	6
Remarks		
Surveyor Name		STEVE CHEN
Signature		

L/S repair, take after spray. Finalize sent to
stevechen@lkkauto.com.

STEVE CHEN

Save Clear

29/7/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

25/07/2019



Acknowledged by Repairer

Signature:

Date:



Section A - Accident Details

Registration Number	SHC4233H
Case Reference Number	TAX/07/19/2084
Registration Date	9/4/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	GOON TUCK KAY ALAIN
Type of Accident	Head To Side
Accident Date and Time	22/7/2019 6:45 PM
Accident Reported Date and Time	23/7/2019 9:57 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	22/7/2019 7:50 PM
Replacement Vehicle issued?	No
Job Card Number	24102507
Special Instruction to ARC, if any	TOWED \$40 /NTUC - LKK
Prepared Date and Time	24/7/2019 9:52 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$900.00
Total Spray Cost	\$1,494.00	\$800.00
Total Spare Part Cost	\$4,725.42	\$1,292.41
Total Other Cost	\$1,734.76	\$7.69
TOTAL COST	\$8,968.18	\$3,000.00
Lump Sum Total	\$0.00	\$3,000.00 (L/S)
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	25/07/2019 4:03 PM	25/07/2019 2:21 PM
Signature		
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0090	Invoice Number	
Quotation Date	07.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$900.00
Total Labour	\$1,014.00	\$900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,494.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$776.17)
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$593.76	\$593.76
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$30.00
Total Other Costs	\$1,734.76	\$7.59

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6505548		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace

	52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X
	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
	61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R
		STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace	/
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	/
6505527	62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
6505487	67004-47080	DOOR RR/LH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	/
6505607	75852-47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	R
6505349	42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Check	X
Total				\$6,054.25		\$1,292.41			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1292.41
 + 900.00
 + 1583.76

3776.17

- 202

3020.94

42 \$3000/-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19013169/Esf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 23-08-2019



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 3607C	Veh. Inspected	SHC 4233H
Policy No.	5108056430	Coverage (\$)	0.00
Claim No.	MT/1054579-002	Excess (\$)	0.00
Assign From		Assign Date	25/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U805740775	Colour	MAROON
Odometer	526617	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	FIRENZA	5 mm
L/H Front Tyre	195/55 R15	FIRENZA	5 mm
R/H Rear Tyre	195/55 R15	FIRENZA	5 mm
L/H Rear Tyre	195/55 R15	FIRENZA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/07/2019	Inspection Date	25/07/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4233H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	BROKEN	458.60	343.95
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	BROKEN	94.80	71.10
1	DOOR RR/LH (DISC 25%)	DENTED	954.50	715.88
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	QUARTER GLASS RR/LH	NOT NECESSARY	168.10	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	TAIL LAMP LH	NOT NECESSARY	548.40	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL DISC	NOT NECESSARY	1,484.20	-
1	WHEEL HUB REAR	NOT NECESSARY	489.40	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
1	MOULDING BODY, LH	TO REPAIR SEE LABOUR	673.60	-
1	ADVERTISEMENT STICKER (SN)	NECESSARY	593.76	593.76
1	SOLAR FILM (SN)	NOT NECESSARY	125.00	-
			6,847.50	1,886.17
LABOUR				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF FENDER RR/LH AND MOULDING BODY, LH.			1,014.00	900.00
SPRAY PAINT.			1,494.00	800.00
TOWING CHARGE.			56.00	-
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING.			120.00	60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)			120.00	20.00

Report Ref No. NS/INC19013169/Esf3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	20.00
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS, WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	20.00
	TO REMOVE AND REFIT TYRE.		120.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.		100.00	30.00
			3,524.00	1,890.00
GRAND TOTAL			10,371.50	3,776.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,000.00

Report Ref No. NS/INC19013169/Esf3s2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.