

12/03/2000

ASS. REC. BY:

REF: CS/FCI/9013173/Ktd3n2 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

CWS

From (Person): Serene Ter

of

FCI

Date/Time: 11:31am @ 26/7/19

Estimated Cost:

Bill to:

OD ☒ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 4821D

Insured:

SH 7819S

at Workshop n/s

Esteem performance

Tel:

87990066

of

Blk 5033 Amk Ind. park 2 # 01-251/259

Policy No:

Claim No:

D19004848MFS4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/7/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 11:48am @ 26/7/19

Person Contacted:

Carmen

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction
	Insured (✓) Insp: 385 Sin Ming Drive
	SLS 4821D - X
	SH 7819S - CC3/IT1/9009497/Kleb3
29/7/19 @ 11:42am	Revised preli advise via email.
	11/8 @ 880.72 Carfax (Red: 3033.31; 77%)

ASS. REC. BY:

REF:

12021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLS 48210

Yr Regn:

09.17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toyota Pro

c.c.

1788

Colour:

m. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

171753

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FUXO 3570617

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

24/7/19

D.O.I.

26/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to

RECEIVED 8 AUG 2019

Date/Time, File Pass to?



Prell. Report



Final Report

Date/Time, File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

130

Transportation:

50

S + RS. SI

50

Fines:

13

Others

TOTAL

243

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum (I.B.I): (\$

\$880.72



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004848MFSH

Date: 29/7/2019

Our Ref: CS/FCI19013173/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 4821D

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/7/2019 at the premises of M/s Esteem Performance have the following to report: -

Workshop Estimate Amount	: S\$	<u>3,914.03</u>
Revised Estimate Amount	: S\$	<u>702.30</u>
"Check" Items Amount	: S\$	<u>822.30</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-07-2019	Our Ref No. D19004848MFSH
Accident Date	24-07-2019	Claim Type. Third Party
Insured Vehicle	SH7819S	Third Party Vehicle. SLS4821D
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 87990066	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 29 July 2019 11:42 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004848MFSH/1
Attachments: PRELI ADVISED OF SLS 4821D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLS 4821D**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 26 July 2019 11:48 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004848MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 26 July 2019 11:31 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004848MFSH/1

Dear Sir/Mdm,

First Car
LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLS 4821 D

Parts	(a) Cost / List Price Items	\$ 2,858.70
	Plus/Less 25%	\$ 714.68
	Total of Cost / List	\$ 2,144.03
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	\$ 200.00
Total Parts Cost		\$ 2,344.03
Labour		\$ 1,570.00
Total		\$ 3,914.03

Not authorized
Repair by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair is started
- To display damaged parts in display
- To provide a written estimate of repair
- To provide a written estimate of total repair cost
- To provide a written estimate of total repair cost
- To provide a written estimate of total repair cost
- To provide a written estimate of total repair cost

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

26/7/19

at

11am

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

K

Date:

26/7/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLS 4821 D
Make & Model : TOYOTA PRIUS
Chassis No. : JTDKB3FUX03570617

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>SL</i>	1	\$200.00	S.N	X
2	Rear bumper <i>SL</i>	1	\$497.50		X
3	Rear bumper clip <i>nn</i>	10	\$40.00		X
4	Rear bumper side retainer LH <i>SL</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>SL</i>	1	\$112.70		X
6	Rear bumper reinforcement <i>RL</i>	1	\$398.90		X
7	Rear bumper lower garnish centre <i>Red / Red</i>	1	\$582.60		—
8	Rear bumper lower garnish LH <i>SL</i>	1	\$149.70		X
9	Rear bumper lower garnish RH <i>SL</i>	1	\$149.70		X
10	Rear bumper tow cover <i>SL/Red</i>	1	\$31.70		✓
11	Tail end panel <i>RL</i>	1	\$596.60		X
12	Tail end panel garnish <i>SL</i>	1	\$151.60		X
13	Tail end panel garnish clip <i>nn</i>	10	\$35.00		X
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013173/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7819S	Veh. Inspected	SLS 4821D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004848MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	26/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FUX03570617	Colour	METALLIC SILVER	
Odometer	171753	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2019	Inspection Date	26/07/2019	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 4821D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	SERVICEABLE	497.50	-
10	REAR BUMPER CLIP	NOT NECESSARY	40.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE	DENTED / CUT	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	SERVICEABLE	149.70	-
1	REAR BUMPER LOWER GARNISH RH	SERVICEABLE	149.70	-
1	REAR BUMPER TOW COVER	DENTED	31.70	31.70
1	TAIL END PANEL	TO REPAIR SEE LABOUR	596.60	-
1	TAIL END PANEL GARNISH	SERVICEABLE	151.60	-
10	TAIL END PANEL GARNISH CLIP	NOT NECESSARY	35.00	-
	LESS 25% DISCOUNT		-714.68	-153.58
			2,144.02	460.72
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL).INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND TAIL END PANEL.		600.00	200.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL).		600.00	220.00
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT REVERSE SENSOR.	NOT NECESSARY	120.00	-
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			1,570.00	420.00

Report Ref No. CS/FCI19013173/Ktd3n2



GRAND TOTAL		3,914.02	880.72
RECOMMENDED COST OF REPAIRS			880.72

Report Ref No. CS/FCI19013173/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.