

ASS. REC. BY:

REF: CS/ICS19013177/Ktd3n2 Special Instruction:

Supervisor: Kenneth

ASSIGNMENT (Office)

From (Person): Desmond Lee of ICS Date/Time: 26/7/19 @ 11:59am

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMM 4030P Insured: SJU 9508P

at Workshop m/s: Trun's Cab Tel: 6287 6666

of NO.2 AMK St - 63

Policy No: Claim No: DMPC1900194H/DL

Sum Insured: Excess:

Make of Veh: D.O.A. 30/06/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:20pm @ 26/7/19 Person Contacted: Candy Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Tel: 6287 6666 ✓
	SMM 4030P - X
	SJU 9508P - X

ASS. REC. BY:

REF: 1CS /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 1/2

days

Res.:

Yes or No

Lump Sum:

1B1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Snm 4030P

Yr Regn:

06, 1P

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prow

c.c

1798

Colour:

m. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

7792

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTOKB 3FU 8030 83530

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

30/8/19

D.O.I.

29/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

B 1113.55 to summit. Confirm with Wai Yin.

RECEIVED 22 AUG 2019

Date/Time, File Pass to?



: Prell. Report

1) 20/8 Typist



: Final Report

Date/Time, File Return to?

Days Of Repair:

1.5

Resurvey No. of Trlp:

-

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

Fees

Others

TOTAL

450
11
461

Report Format :

Lump Sum / I.B.I: (\$

Nivitha (LKK Auto)

From: Desmond Lee Ker Wen (ECICS, Claims) <Desmond_Lee@ecics.com.sg>
Sent: Friday, 26 July 2019 11:59 AM
To: candy.kong@transcab.com.sg
Cc: assignments@lkkauto.com
Subject: RE: ARRANGE FOR SURVEY SMM4030P / Our Claims Ref no: DMPC1900194H/DL
Attachments: img-726094620-0001.pdf

Without prejudice

Dear Candy

LKK will arrange with you on the survey timing.

Hi LKK

Kindly assist.

Best regards
Desmond Lee

Senior Associate | Claims

DID (65) 6303 0167 Tel (65) 6337 4779
Email Desmond_Lee@ecics.com.sg Web www.ecics.com.sg
Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

-----Original Message-----

From: ECICS Claims
Sent: Friday, 26 July 2019 10:24 AM
To: Desmond Lee Ker Wen (ECICS, Claims)
Cc: ECICS Claims
Subject: FW: ARRANGE FOR SURVEY SMM4030P

Dear Desmond

FYNA

Best regards
Crystabelle Tan

Senior Associate | Claims

DID (65) 6303 0190 Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web

https://apc01.safelinks.protection.outlook.com/?url=www.ecics.com.sg&data=02%7C01%7CDesmond_Lee%40ecics.com.sg%7C4ada8851c1424c33c20808d7117054cd%7C590913dd11e641cab2b3178d5591d1bd%7C0%7C0%7C636997046497889179&sdata=ky%2FszbbYBf%2BMV9XtHLkylf4XSO40VPBbs9cYsEQ74dc%3D&reserved=0
Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]

Sent: Friday, 26 July, 2019 9:50 AM

To: ECICS Claims

Subject: ARRANGE FOR SURVEY SMM4030P

DEAR ALL,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY

Please arrange for survey as below :

SJU9508P - 30.06.2019 at 1625Hrs - SMM4030P

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate

Thks & Rdgs

Candy Kong

Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

This email has been checked for viruses by AVG.

https://apc01.safelinks.protection.outlook.com/?url=https%3A%2F%2Fwww.avg.com&data=02%7C01%7CDesmond_Lee%40ecics.com.sg%7C4ada8851c1424c33c20808d7117054cd%7C590913dd11e641cab2b3178d5591d1bd%7C0%7C0%7C636997046497889172&sdata=905sAOpA%2BuACGp%2BX7Y91vpehngkgipreLvP4O1QyZR0%3D&reserved=0

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 20 August 2019 2:36 PM
To: Denise Tay (LKKAuto)
Subject: FW: SMM 4030P / FIRST CAPITAL / DOA: 30/06/2019
Attachments: SMM 4030P EST.pdf

WITHOUT PREJUDICE

Dear Denise

Amount confirmed \$ 1,113.55 (before GST).

Will send you're the photo after I get it from our workshop.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 15 August, 2019 8:55 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SMM 4030P / FIRST CAPITAL / DOA: 30/06/2019

Dear Wai Yin,

\$1113.55 ok? sent before paint please

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2019 12:57
Date Of Accident	30/06/2019 16:25
Exact Location Of Accident	LORONG 6 TOA PAYOH SLIP ROAD TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM4030P
Insured/Policyholder	
Name Of Registered Owner	TRANS LEASING PTE LTD
Co Reg No	201603575K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93691265

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SMM4030P
Cover Note Number	

Driver

Name of Driver	THAM KEI YEUNG
NRIC No	S7214773A
Date Of Birth	18/04/1972
Occupation	INDOOR
Date Of Driving Pass	22/10/1993
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83551668
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 38 TELOK BLANGAH RISE #04-339 SINGAPORE
Postcode	090038
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SHEEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	SHEEN
Phone Number	81232987
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU9508P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JAMES CAI BINGHUI
NRIC/Passport Number	S7185330F
Contact Number	91871055

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquires by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Long 6 Ton payload slip Road towards P/E

Vehicle
A - JMC 4030P
B - SUV 400P

Legend
Vehicle Motorcycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30.6.2019 at about 1.45 hrs, I was travelling along
Ton payload Long 6 slip Road towards P/E with 1 passenger.
When I slow down and made a stop to check for the
road damage. Suddenly I felt an impact. Vehicle B
(SUV 400P) hit into my car's rear portion.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Accident Photo



DRIVER NRIC & LICENSE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification No. **S7214773A**

Name **THAM KEI YEUNG**

Birth Date **18 Apr 1972**
Valid Until **19 Aug 2008**

NRIC No. **S7214773A**

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7214773A**

Name **THAM KEI YEUNG**

Chinese **陳啟榮**

Race **CHINESE**

Date of Birth **18-04-1972** Sex **M**

Country of Birth **SINGAPORE**

NRIC No. **S7214773A**

Land Transport Authority

VOCATIONAL LICENCE

Licence No. **S7214773A**

Name **THAM KEI YEUNG**

Issue Date **16/08/13**

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 1 Motor Cars - 3000kg with -17 passengers, excluding 27 Oct 1997
of the driver, and other motor vehicles - 3000kg

Issue Date **16/08/2013**

Licence No. **S7214773A**

NRIC No. **S7214773A**

Issue Date **16-01-2018**

APT BLK 28 YELON BLANGAN HSE
#02-228
SINGAPORE 090028

This card is not transferrable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sui Ming Drive, Singapore 675791.

Type	Description	Issue Date
02	TAXI VI	16/08/2013

POVL/TDVL
25 680 18000
759774

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMM 4030P

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

*Not Authored**Reserve Bk paint
81113.55***SMM 4030P**

JTDKB3FU603083530

TOYOTA

PRIUS

30.6.2019

ECICS

27.6.2019

PART**LIST**

1	1	REAR BUMPER	\$	<i>N</i>	458.60	<i>X</i>
2	1	REAR BUMPER RE-INFORCEMENT	\$	<i>Bk</i>	318.80	<i>X</i>
3	1	REAR BUMPER TOWING COVER	\$	<i>Sn</i>	14.70	<i>X</i>
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>Red / Sn</i>	552.60	<i>✓</i>
5	1	ANTENNA, ELECTRICAL KEY	\$	<i>Sn</i>	61.40	<i>X</i>
6	1	REAR BUMPER SIDE RETAINER LH	\$	<i>Sn</i>	112.70	
7	1	REAR BUMPER SIDE RETAINER RH	\$	<i>Sn</i>	112.70	
8	1	REAR TAILGATE	\$	<i>N</i>	1,547.27	
9	1	REAR TAILGATE OUTER GARNISH	\$	<i>Sn</i>	910.40	
10	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>Sn</i>	54.70	
11	1	COVER, REAR COMBINATION LAMP, LH	\$	<i>Sn</i>	54.70	
12	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>Sn</i>	93.60	
13	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>Sn</i>	93.60	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>Sn</i>	55.40	
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>Sn</i>	55.40	
16	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>Sn</i>	254.40	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>Sn</i>	51.20	
18	1	REAR TAILGATE WEATHERSTRIP	\$	<i>Sn</i>	365.20	
19	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	<i>N</i>	641.50	
20	1	TAILLAMP LOWER RH	\$	<i>Sn</i>	548.40	
21	1	TAILLAMP UPPER RH	\$	<i>Sn</i>	557.90	
22	1	REAR BUMPER SIDE RH	\$	<i>Sn</i>	232.00	
23	1	REAR BUMPER SIDE LH	\$	<i>Sn</i>	232.00	
24	1	TAILLAMP LOWER LH	\$	<i>Sn</i>	548.40	
25	1	TAILLAMP UPPER LH	\$	<i>Sn</i>	557.90	
26	1	REAR RH FENDER PANEL	\$	<i>N</i>	836.70	
27	1	REAR LH FENDER PANEL	\$	<i>N</i>	836.70	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMM 4030P

28	1	LINER, REAR WHEEL HOUSE, LH	\$	<i>N</i>	138.10	}	<i>X</i>
29	1	LINER, REAR WHEEL HOUSE, RH	\$	<i>N</i>	138.10		
30	1	BOARD, BACK DOOR TRIM	\$	<i>Sn</i>	220.70		
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>Sn</i>	351.10		
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>Sn</i>	351.10		
33	1	COVER, FLOOR UNDER, NO.1	\$	<i>Sn</i>	172.60		
34	1	COVER, FLOOR UNDER, NO.2	\$	<i>Sn</i>	238.70		
35	1	COVER, REAR FLOOR	\$	<i>N</i>	226.80		
TOTAL			\$		11,996.07		
25%			\$		2,999.02		
			\$		8,997.05		

Special Nett

1	1SET	PARKING AID	\$	<i>Sn</i>	700.00	}	<i>X</i>
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	22.00		
3	2	REAR WINDSCREEN SEALANT	\$	<i>nn</i>	80.00		
4	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00		
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00		
6	1	REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i>	47.00		
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i>	52.90		
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i>	53.50	}	<i>gain</i>
9	1	REAR BUMPER PROTECTOR	\$	<i>nn</i>	100.00		
10	1	REAR WHEEL RIM	\$	<i>Sn</i>	1,570.55	}	<i>X</i>
11	1	REAR WHEEL RIM COVER	\$	<i>Sn</i>	175.80		
12	1	SPARE WHEEL RIM	\$	<i>Sn</i>	1,570.55		
13	1	SPARE WHEEL RIM COVER	\$	<i>Sn</i>	175.80		
14	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00		
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i>	35.00		
TOTAL			\$		4,818.10		

TOTAL PARTS \$ 13,815.15

LABOUR

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign
The Same

\$ 4,500.00 *200%*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMM 4030P

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00 X
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 2201
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	nn 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X

TOTAL \$ 11,720.00

Over All Total \$ 25,535.15

This Repair Order is valid only if:
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a 'Without Prejudice' basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized by Repairer:
Signature:
Date:

1 1/2 days

(PART-BY-PART) Repair Days

~~15~~ Days

1 1/2 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19013177/KTD3N2

Date: 10/09/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SMM4030P	Insured Vehicle No :	SJU9508P
Date of Loss:	30/06/2019	Nature of Claim:	TP
		Claim No:	DMPC1900194H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4030P	Engine No:	2ZR2C54072
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU603083530
Reg. Date:	27/06/2019 (Man. Year: 2018)	Odometer:	7792 km
Colour:	Metallic Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,815.15	693.55	13,121.60	94.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,720.00	420.00	11,300.00	96.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	25,535.15	1,113.55	24,421.60	95.64
+ GST 7.00/7.00% (\$\$)	1,787.46	77.95	1,709.51	95.64
Nett Amount (\$\$)	27,322.61	1,191.50	26,131.11	95.64

INSPECTION

Date of Assignment:	26/07/2019	
Date Inspected:	29/07/2019	Inspected At: Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2019)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM4030P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	458.60 FL	*- FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	14.70 FL	*- FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Dented/Cut	552.60 FL	*552.60 FL
5	1		*ANTENNA,ELECTRICAL KEY	Serviceable	61.40 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
8	1		*REAR TAILGATE	Repair	1,547.27 FL	*- FL
9	1		*REAR TAILGATE OUTER GARNISH	Serviceable	910.40 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
11	1		*COVER,REAR COMBINATION LAMP,LH	Serviceable	54.70 FL	*- FL
12	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	93.60 FL	*- FL
13	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	93.60 FL	*- FL
14	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	55.40 FL	*- FL
15	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	55.40 FL	*- FL
16	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
17	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	51.20 FL	*- FL
18	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
19	1		*PANEL SUB-ASSY,BODY LOWER BACK (REAR END PANEL)	Repair	641.50 FL	*- FL
20	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
21	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
22	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
23	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*- FL
24	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
25	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
26	1		*REAR RH FENDER PANEL	Repair	836.70 FL	*- FL
27	1		*REAR LH FENDER PANEL	Repair	836.70 FL	*- FL
28	1		*LINER,REAR WHEEL HOUSE,LH	Repair	138.10 FL	*- FL
29	1		*LINER,REAR WHEEL HOUSE,RH	Repair	138.10 FL	*- FL
30	1		*BOARD,BACK DOOR TRIM	Serviceable	220.70 FL	*- FL
31	1		*PANEL ASSY,DECK TRIM SIDE,RH	Serviceable	351.10 FL	*- FL
32	1		*PANEL ASSY,DECK TRIM SIDE,LH	Serviceable	351.10 FL	*- FL
33	1		*COVER,FLOOR UNDER,NO.1	Serviceable	172.60 FL	*- FL
34	1		*COVER,FLOOR UNDER,NO.2	Serviceable	238.70 FL	*- FL
35	1		*COVER,REAR FLOOR	Repair	226.80 FL	*- FL
36	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
37	1		*SET REAR BUMPER CLIP	Not Necessary	22.00 FS	*- FS
38	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*WINDSCREEN MOULDING	Not	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary Not Necessary	100.00 FS	*- FS
41	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
42	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
43	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
44	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
45	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*- FS
46	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
47	1		*SPARE WHEEL RIM	Serviceable	1,570.55 FS	*- FS
48	1		*SPARE WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
49	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
50	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,814.17	911.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,999.02	217.85
Total Parts (\$\$)	13,815.15	693.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,500.00	200.00
2	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00
5	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
12	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
14	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
Gross Labour Cost (\$\$)			11,720.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >