

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

#

SUPPLEMENTARY ITEMS

Total Labour :	7,947.00
Total Parts :	9,055.65
Total Labour & Parts :	17,002.65
Deduction for Excess :	
Total Repair Costs less Excess:	17,002.65
GST @7%:	1,190.19
Grand Total :	18,192.84

	OD	M.O. PARTS	DATE	WORKING DAYS
FAX TO FAX NO		ianfikh LKK	13/9/19	7
FAX TO FAX NO				
FAX TO FAX NO				
CONFIRMED DATE				
PLEASE FINLISE BY _____				

LOSS OF USE = \$120 X 9 DAYS
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52106**
Date Estimated : **25/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Chua Chai Thian
34 Jalan Kelulut

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 809051

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH2829R	DD87068	23/11/2012	740LiA	0

DESCRIPTION	ACCOUNT:		NETT
	ORIGINAL PRICE	DISC. %	
To replace front bumper and attachments, front left fender, front left wheel housing cover and left support etc including to make good front bonnet and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	3,825.00	0	3,825.00
To respray front bumper, front bonnet and front left fender.	3,164.00	0	3,164.00
To replace left Technology LED headlight and left fog lamp	408.00	0	408.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00
To carry out body cavity preservation.	100.00	0	100.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00
Sundries.	150.00	0	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT LH FENDER	1,236.65	1.00	0	1,236.65
LH SIDE PANEL HEADLIGHT HOLDER	34.25	1.00	0	34.25
LH RUBBER STRIP	54.00	1.00	0	54.00
FRT BUMPER TRIM PRIMED (PDC/SIDEVIE	1,540.90	1.00	0	1,540.90
# EMBLEM GROMMET	0.80	2.00	0	1.60
BMW EMBLEM	71.25	1.00	0	71.25
# LH SPACER	8.05	1.00	0	8.05
LH SUPPORT	260.35	1.00	0	260.35
FRT LH COVER WHEELHOUSING FRT	139.85	1.00	0	139.85
# LH HIGH PRESSURE NOZZLE	183.80	1.00	0	183.80
LH HEADLIGHT WITH LED TECHNOLOGY	5,062.80	1.00	0	5,062.80
# LH LED FOGLAMP	441.95	1.00	0	441.95
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00	0	20.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52106**
Date Estimated : **25/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Chua Chai Thian
34 Jalan Kelulut

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 809051

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH2829R	DD87068	23/11/2012	740LiA	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# EMBLEM GROMMET	0.80	2.00	0	1.60
# LH SPACER	8.05	1.00	0	8.05
# LH HIGH PRESSURE NOZZLE	183.80	1.00	0	183.80
# LH LED FOGLAMP	441.95	1.00	0	441.95
#				
#				
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	635.40
Total Labour & Parts :	635.40